

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19009469/AKA3N2

Date: 21/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100492769-02

Claimant
Vehicle No : GBE9495X **Insured Vehicle No :** SGQ833R

Date of Loss: 16/05/2019 **Nature of Claim:** TP **Claim No:** 9241895762SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE9495X		
Make & Model:	NISSAN NV200, 1.6 DX (A)	Engine No:	K9KC400D055481
Reg. Date:	12/05/2016 (Man. Year: 2016)	Chassis No:	VSKYBAM20Z0125040
Colour:	Silver	Odometer:	113747 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14C	Rear Tyre Size:	175/70 R14C
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,173.60	2,264.69	1,908.91	45.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	1,360.00	670.00	33.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,203.60	3,624.69	2,578.91	41.57
Approved Total (Overridden) (S\$)		2,900.00		
Nett Amount (S\$)	6,203.60	2,900.00	3,303.60	53.25
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
Nett Liability (S\$)		3,200.00		

INSPECTION

Date of Assignment: 28/05/2019

Date Inspected: 28/05/2019 Inspected At:

Ho Beng Trading (HQ)
Blk 3020A #01-33, Ubi Road 1
Singapore 408714

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID L/H	Distorted	1,253.10 F	*1,253.10 FL
2	1		*REAR BOOT LID L/H LOWER HINGE	Not Necessary	131.80 F	*- FL
3	1		*REAR BOOT LID L/H WINDSCREEN SEAL	Necessary	98.00 F	*98.00 FL
4	1		*REAR BUMPER	Deformed	460.80 F	*460.80 FL
5	2		*REAR BUMPER SIDE BRACKET	Necessary	70.40 F	*70.40 FL
6	10		*REAR BUMPER CLIPS	Necessary	65.00 F	*30.00 FL
7	1		*REAR BUMPER SIDE REFLECTOR	Not Necessary	41.60 F	*- FL
8	1		*REAR BUMPER INNER SPONGE	Cracked	88.90 F	*88.90 FL
9	10		*REAR BOOT LID R/H INNER TRIM BOARD CLIPS	Not Necessary	55.00 F	*- FL
10	1		*REAR BOOT LID L/H INNER LOCK LOWER	Damaged	91.80 F	*91.80 FL
11	1		*REAR BOOT LID L/H INNER LOCK TOP	Not Necessary	102.00 F	*- FL
12	1		*REAR BOOT LID LOGO	Necessary	45.60 F	*45.60 FL
13	1		*REAR BOOT LID INNER RUBBER	Not Necessary	143.60 F	*- FL
14	1		*REAR TAIL LAMP -LH	Not Necessary	203.40 F	*- FL
15	1		*REAR END PANEL TOP GARNISH	Deformed	55.50 F	*55.50 FL
16	1		*REAR EXHAUST	Not Necessary	766.00 F	*- FL
17	1		*REAR MUD FLAP -LH	Not Necessary	131.10 F	*- FL
18	1		*REAR BUMPER REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
19	1		*REAR BOOT LID NV200 LOGO	Necessary	30.00 FS	*30.00 FS
20	1		*REAR BOOT LID EMBLE LOGO	Necessary	50.00 FS	*50.00 FS
21	1		*REAR BOOT LID 70KM LOGO	Necessary	20.00 FS	*10.00 FS
22	1		*REAR BOOT LID 6 PAX LOGO	Not Necessary	20.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,173.60	2,484.10
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	219.41
Total Parts (\$)	4,173.60	2,264.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
2	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	80.00
3	GUM	New	50.00	50.00
4	TO REMOVE & REFIX REAR EXHAUST	New	200.00	0.00
5	TO CHECK WIRING	New	60.00	30.00
6	TUFF KOTE	New	100.00	50.00
7	PANEL BEATING	New	700.00	600.00
8	SPRAY PAINTING	New	700.00	500.00
Gross Labour Cost (\$\$)			2,030.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >