



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 3033T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	DISTORTED	880.00	880.00
1	FRONT BUMPER SIDE RETAINER (CONSISTENT)	CUT	80.00	80.00
1	FRONT BUMPER FROG LAMP COVER (CONSISTENT)	MISSING	320.00	320.00
1	FRONT BUMPER LAMP (CONSISTENT)	CUT	330.00	330.00
1	FRONT BUMPER GARNISH TOP (CONSISTENT)	CRACKED	280.00	280.00
1	HEADLAMP (CONSISTENT)	DISTORTED	1,550.00	1,550.00
1	FRONT SUPPORT PANEL (CONSISTENT)	* CHECK	980.00	-
1	FRONT GRILLE (CONSISTENT)	* CHECK	480.00	-
1	FRONT GRILLE CHROME (CONSISTENT)	CRACKED	380.00	380.00
1	FRONT BONNET (CONSISTENT)	BUCKLED	820.00	820.00
1	FRONT BONNET RUBBER (CONSISTENT)	TORN	120.00	120.00
1	FRONT WHEEL HOUSE EXTENSION (CONSISTENT)	* CHECK	380.00	-
1	FRONT WHEEL HOUSE (CONSISTENT)	TO REPAIR SEE LABOUR	880.00	-
1	FRONT FENDER LH (CONSISTENT)	BUCKLED	480.00	480.00
1	FRONT FENDER GARNISH LH (CONSISTENT)	MISSING	250.00	250.00
14	FRONT FENDER CLIPS (CONSISTENT)	NECESSARY	70.00	70.00
1	FRONT FOG LAMP (CONSISTENT)	* CHECK	400.00	-
1	HEADLAMP WASHES (CONSISTENT)	DISTORTED	380.00	380.00
1	FRONT SHOCK ABSORBER (CONSISTENT)	* CHECK	420.00	-
1	FRONT KNUCKLE ARM (CONSISTENT)	* CHECK	680.00	-
1	FRONT LOWER ARM (CONSISTENT)	* CHECK	480.00	-
1	FRONT WHEEL BEARING (CONSISTENT)	DAMAGED	360.00	360.00
1	FRONT WHEEL HUB (CONSISTENT)	* CHECK	320.00	-
1	STEERING RACK (CONSISTENT)	NOT NECESSARY	2,880.00	-
1	TIE ROD END (CONSISTENT)	NOT NECESSARY	180.00	-
1	STABLIZE LINKAGE (CONSISTENT)	NOT NECESSARY	120.00	-
1	FRONT DRIVE SHAFT (CONSISTENT)	NOT NECESSARY	1,780.00	-
1	REAR WHEEL BEARING HUB (CONSISTENT)	NOT NECESSARY	480.00	-
			16,760.00	6,300.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
2	SPORT RIMS (SN) (CONSISTENT)	CUT (1 PCS ONLY)	680.00	300.00
			680.00	300.00
	<u>LABOUR</u>			
	CHASSIS ALIGNER .		380.00	200.00
	TO REMOVE AND INSTALL ,CUT AND WELD FRONT BUMPER ,HEADLAMP,SUPPORT PANEL WHEEL HOUSE ETC AND STRAIGHTEN CHASSIS FRAME .INCLUSIVE OF THE REPAIR OF FRONT WHEEL HOUSE .		1,800.00	800.00
	TO REMOVE AND INSTALL FRONT DESKBOARD TO FACILATE REPAIR.	NOT NECESSARY	480.00	-
	TO REMOVE AND INSTALL FRONT WINDSCREEN .	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT CARPET AND CUSHION .	NOT NECESSARY	300.00	-
	TO REMOVE AND INSTALL FRONT UNDERCARRIAGE.	* CHECK	580.00	-
	TO REMOVE AND INSTALL BEARING HUB .	* CHECK	200.00	-
	TO APPLY PUTTY ,PRIMER AND RESPRAY PAINT ON DAMAGED SECTION .		1,200.00	850.00
	TO APPLY ANTIRUST ON AFFECTED AREA.		300.00	60.00
	WHEEL ALIGNMENT.		120.00	60.00
			5,480.00	1,970.00
GRAND TOTAL			22,920.00	8,570.00

RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$4,920.00 NETT)			8,570.00
--	--	--	-----------------

Report Ref No. CC4/ASM19009482/Ggs3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.