

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19009485/UBA3Q2
Date: 09/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100476545
Claimant
Vehicle No : FBK5061J **Insured Vehicle No :** GBF1743C
 Date of Loss: 09/05/2019 Nature of Claim: TP Claim No: 3238259331SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBK5061J**
 Make & Model: YAMAHA YBR125, 123cc (M) Engine No: E3F5E040671
 Reg. Date: 03/10/2015 (Man. Year: 2015) Chassis No: LBPRES101000055563
 Colour: Orange Odometer: 58272 km
 Engine Capacity: 124 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 2.75-18 Rear Tyre Size: 90-90-18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	274.00	29.00	245.00	89.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	325.00	305.00	20.00	6.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	599.00	334.00	265.00	44.24
Approved Total (Overridden) (S\$)		250.00		
(S\$)	599.00	250.00	349.00	58.26
+ GST 7.00/7.00% (S\$)	41.93	17.50	24.43	58.26
Nett Amount (S\$)	640.93	267.50	373.43	58.26
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 29/05/2019
 Date Inspected: 29/05/2019 Inspected At: Ban Hock Hin Co. Pte Ltd (HQ)
 No. 6 Defu Lane 4
 Singapore 539410
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*CRASH BAR	Repair	195.00 F	*- F	
2	1		*FOOTREST REAR ASSY LH	Cut	15.00 F	*15.00 F	
3	1		*LEVER CLUTCH	Not Necessary	15.00 F	*- F	
4	1		*MIRROR LH	Not Necessary	35.00 F	*- F	
5	1		*RUBBER FOOTREST FRONT	Torn	14.00 F	*14.00 F	
					Total Parts (S\$)	274.00	29.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR-FOR DISMANTLE AND ASSEMBLING OF PARTS QUOTED	New	35.00	35.00
2	SPRAY PAINT FIBRE BOX	New	220.00	200.00
3	SPRAY PAINT FRONT FENDER	New	35.00	35.00
4	TRANSPORT CHARGES	New	35.00	35.00
			Gross Labour Cost (\$\$)	305.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >