

ASS. REC. BY:

REF: CS/MKG 1900 94991 K&L352

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Monica Chung Pk 24h of MSG Date/Time: 29.5.19 13:48 p.m.

Estimated Cost: Bill to:

OD-TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLK 366 L

Insured: SBN 3328M

at Workshop m/s Esteem Performa

Tel: 64841221 (65662.112)

of 385 Sin Ming Drive

Policy No: P 27749752DMA

Claim No: 594572

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 25.5.2019

CA / REV / REP. / REV 24 HRS

"rup"

H.O.D. Endorsement:

Date/Time: 29.5.19 3:48 p.m.

Person Contacted: Jenny

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (V)
	SLK 366 L - MBA / MSG 1900925514	D.O.A. - 25/05/2019
	SBN 3328M - NBA / MSG 1900926514	D.O.A. - 25/05/2019
03/06/19	@ 17:04 pm revised IA to Monica Monica Chung via memo.	

Surveyor

ASSIGNMENT

From: Date: 31.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SIK 3665L
at Workshop m/s Esteem Performance
of 385 sin min Drive

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SIK 3665L Yr Regn: 01, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Prius C.C. 1798

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 110153 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTD KB3FU 903544347

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Pirelli 195/65R15

R: Giti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 2 mm

L/Bal. 6 mm

L/Bal. 2 mm

D.O.A. 25/5/19

D.O.I. 31/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
19/07/19	Continued P/P \$ 2,032.06 @ 3 days with Kenneth. (\$ 4,654.10 Red - 70%)

RECEIVED 24 JUL 2019

22/7/2019

Date/Time, File Pass to? 24/07/19

1) Typ: 4

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee: 150

Transportation:

S + RS, SI

Photos

Others

11

TOTAL

Report Format :

Lump Sum 1.B.1 (\$ 2,032.06 P/P)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2019 10:45		29 May 2019 13:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:

GOH LENG KHIANG, ID: S1287743I

Main Claimant:

Grab Rentals Pte Ltd, Co. Reg. No.: 201617200G

Vehicle Reg. No.:

SLK3665L

Date of Loss:

25/05/2019 16:00 - :59
[23 Months and 29 Days From
LTA Reg Date (Man Yr)]

Claim Type:

TP / 594572

Policy/Cover Note No.:

P27749752DMA (Comprehensive)
Coverage: 19/09/2018 -
18/09/2019

Vehicle Reg. No. (Insured):

SBN3328M

Policy No. (Claimant):

Repairer:

Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive, 575718 Sin Ming - Tel:

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/05/2019]

Driver/Custodian (Insured):

GOH LENG KHIANG (), NRIC: S1287743I Email:

Adj Asg. Remarks:

PRS, survey by today, on WP, Liab: dispute, TP Agree on SJE - assign LKK. Contact: Jenny @ 6484 1221.

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: jenny chong <jenny@esteemperf.com.sg>
Sent: Tuesday, 23 July 2019 6:55 PM
To: Shirley Hiew (LKK Auto)
Cc: SUR
Subject: Re: SLK 3665L Date of Loss: 25/05/2019

Dear Shirley

We are agreed to closed at \$2032.06 and 3 days

Thank you



Freundliche Grüße / Best Regards

Jenny Chong

Senior Operation Executive | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221

F: 6484 7829

E: jenny@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com



On Mon, Jul 22, 2019 at 2:03 PM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Jenny,

Please confirm P/P \$ 2,032.06/3 days before GST.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 03 Jun 2019

Preliminary Advice

Insured Vehicle No	: SBN3328M	Accident Date	: 25/05/2019
TP Vehicle No	: SLK3665L	Assignment Date	: 29/05/2019
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 3 days
Date of Inspection	: 31/05/2019		
Inspection At	: Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive Singapore 575718		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,686.16
Revised Amount	:S\$	2,305.40
Check Items (Estimated)	:S\$	2,359.77
Total	:S\$	4,665.17

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/05/2019 14:30
Date Of Accident	25/05/2019 03:00
Exact Location Of Accident	CP OF 25 TELOK BLANGAH CRESCENT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK3665L
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 1.8 CVT
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29114756MKF
Cover Note Number	

Driver

Name of Driver	TOH LAY KIM
NRIC No	S7719650A
Date Of Birth	21/07/1977
Occupation	OUTDOOR
Date Of Driving Pass	12/09/2003
Driving Experience	15 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-90606611
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE DATE AND TIME MENTIONED I HAD PARKED MY VEHICLE AT THE SAID MENTIONED CARPARK. AS I WAS ABOUT TO DRIVE OUT OF THE CARPARK LOT, I WAS VEHICLE B COMING FROM MY LEFT AND GAVE WAY TO HIM. SEEING VEHICLE B DROVE PASSED MY VEHICLE, I INCHED SLOWLY. THAT WAS WHEN I SAW VEHICLE B MADE A STOP. AND SUDDENLY MADE A REVERSED MOVE TOWARDS MY DIRECTION. SEEING THAT I STOPPED MY VEHICLE AND WHEN I SAW VEHICLE B KEPT ON REVERSING, I HONKED AT THE DRIVER FEW TIMES BUT VEHICLE KEPT ON COMING TOWARDS MY STATIONARY VEHICLE AND HIT THE FRONT RIGHT PORTION OF MY VEHICLE. THIS INCIDENT WAS CAPTURED IN A IN CAR VIDEO OF VEHICLE NO. SMG1881B, WHO AS AT THE SCENE AND WHO HAD FORWARDED THE FOOTAGE TO ME. NO ONE WAS INJURED, STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	RETRIEVING
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBN3328M
Vehicle Make/Model/Colour	MERCEDES BENZ C180
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	GOH LENG KHIANG
NRIC/Passport Number	
Contact Number	96261986
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquires by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve the use of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (ii) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (iii) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER
Hashim Kamari

Policyholder's Signature / Date & Time: Driver's Signature (if driver is not the policyholder) / Date & Time: Witnessed by Reporting Centre Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

ON THE DATE AND TIME MENTIONED I HAD PARKED MY VEHICLE AT THE SAID MENTIONED CARPARK. AS I WAS ABOUT TO DRIVE OUT OF THE CARPARK LOT, I WAS VEHICLE B COMING FROM MY LEFT AND GAVE WAY TO HIM. SEEING VEHICLE B DROVE PASSED MY VEHICLE , I INCHED SLOWLY. THAT WAS WHEN I SAW VEHICLE B MADE A STOP. AND SUDDENLY MADE A REVERSED MOVE TOWARDS MY DIRECTION. SEEING THAT I STOPPED MY VEHICLE AND WHEN I SAW VEHICLE B KEPT ON REVERSING, I HONKED AT THE DRIVER FEW TIMES BUT VEHICLE KEPT ON COMING TOWARDS MY STATIONARY VEHICLE AND HIT THE FRONT RIGHT PORTION OF MY VEHICLE. THIS INCIDENT WAS CAPTURED IN A IN CAR VIDEO OF VEHICLE NO. SMG1881B, WHO AS AT THE SCENE AND WHO HAD FORWARDED THE FOOTAGE TO ME. NO ONE WAS INJURED, STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
HASHIM BIN KAMARI

MARS Officer:



Registered Owner or Driver's Signature

Job Complete Date/Time:

27 May 2019 at 12:22 PM

Date/Time:

MSIG-LKK

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom
Vehicle Inspection Centre
(575718)

Claim Reference: SLK3665L
Assessment number: 006219
Version: 1810
Date calculated: 27/05/2019 6:56 PM

Full Report
Registration: SLK3665L
Printed: 27/05/2019 6:56 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	Carmen SG	Currency:	SGD
Claim Reference:	SLK3665L	Date of Incident:	25/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	PRIUS IV
Sub Model:	BASE MODEL
Model Sheet Number:	70 P5 01
Registration:	SLK3665L
VIN number:	
Odometer:	

Model Specs

TWO COAT METALLIC

mon 10
4/6/19

Not Ashwin
Repairing B4 paint
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom
Vehicle Inspection Centre
(575718)

Claim Reference: SLK3665L
 Assessment number: 006219
 Version: 1810
 Date calculated: 27/05/2019 6:56 PM

Full Report
 Registration: SLK3665L
 Printed: 27/05/2019 6:56 PM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h		
			WU	Price SGD	
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS		15.0	75.00	✓
B040)	R + R LEFT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	5.00	✓
B040)	RENEW RIGHT HEADLAMP ASSY (BUMPER REMOVED) NOT INCLUDED: ADJUST HEADLAMPS		2.0	10.00	✓
NO NUMBER	ADJUST HEADLAMPS		2.0	10.00	✓
B110	RENEW R/F WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: R + R WING, CONVERT ATTACHED PARTS		7.0	35.00	X
B131)	RENEW R/FRONT PANEL CARRIER		2.0	10.00	X
B140)	R + R LOWER FRONT PANEL CROSSMEMBER		2.0	10.00	✓

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom
Vehicle Inspection Centre
(575718)

Claim Reference: SLK3665L

Assessment number: 006219

Version: 1810

Date calculated: 27/05/2019 6:56 PM

Full Report

Registration: SLK3665L

Printed: 27/05/2019 6:56 PM

Code	Description	WU	Price SGD
B131)	RENEW R/RADIATOR CARRIER	3.0	15.00 ✓
B125	RENEW UPPER FRONT PANEL CROSSMEMBER	4.0	20.00 ✓
B010)	R + R FRONT BUMPER REINFORCEMENT	3.0	15.00 ✓
B010)	R + R FRONT BUMPER LOWER REINFORCEMENT	2.0	10.00 ✓
B010)	R + R FRONT ACTIVE AIR INTAKE GRILL	1.0	5.00 ✓
B161)	RENEW R/F WHEELHOUSE EXTENSION	13.0	65.00 ✓
851091)	R + R WINDSCREEN WASHER TANK	1.0	5.00 ✓
M010)	R + R CONDENSER	8.0	40.00 ✓
B100	R + R R/SILL TRIM	3.0	15.00 ✓
M020	RENEW RADIATOR	19.0	95.00 ✓
Labour Cost		Hrs	WU
Panel / Mechanical Labour		8.80	88.0
Total of Labour		630	440.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	R/F WING NEW PART PAINTING	10.0
	R/RADIATOR BRACKET SURFACE PAINT	4.0
	R/F PANEL SUPPORT SURFACE PAINT	4.0
	R/F INN W-HOUSE EXT SURFACE PAINT	4.0
	R/F BUMPER COVER NEW PART PAINT K1R	3.0
	FRONT BUMPER NEW PART PAINT K1R	15.0
	BONNET SURFACE PAINT	9.0
	RIGHT FRONT DOOR SURFACE PAINT	8.0

Paint Material Per Part

Code	Description	Price SGD
0742	R/F WING NEW PART PAINTING	19.61
0990	R/RADIATOR BRACKET SURFACE PAINT	1.25
1024	R/F PANEL SUPPORT SURFACE PAINT	1.25
1186	R/F INN W-HOUSE EXT SURFACE PAINT	0.75
0278	R/F BUMPER COVER NEW PART PAINT K1R	0.49
0283	FRONT BUMPER NEW PART PAINT K1R	76.26
0471	BONNET SURFACE PAINT	26.64
1482	RIGHT FRONT DOOR SURFACE PAINT	20.67

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom
Vehicle Inspection Centre
(575718)

Claim Reference: SLK3665L
 Assessment number: 006219
 Version: 1810
 Date calculated: 27/05/2019 6:56 PM

Full Report
 Registration: SLK3665L
 Printed: 27/05/2019 6:56 PM

Labour Cost - Paint	Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint				57.0	
Preparation Main Work Metal			1.10	11.0	55.00
Preparation Comp. Work Plastic			0.50	5.0	25.00
Total		10 WU/h	7.30	73.0	365.00

4.30 43 240

Material Cost - Paint	Price SGD
New Part Painting	19.61
New Part Painting - Plastic K1R	76.75
Surface-/Blend Paint	50.56
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	174.02

26.26
47.31
150.67

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0253	FRONT LWR AIR GRILLE	53112 47240		148.60	X
0260	FRT NO PLATE REINF	52114 47190		129.00	X
0278	R/F BUMPER COVER	52127 47907		25.70	X
0283	FRONT BUMPER	52119 47962		450.80	✓
0339	FRT LWR BUMPER REINF	52132 47010		245.30	X
0340	FRT BUMPER REINF	52021 47110		711.50	X
0346	FRT BUMPER ABSORBER	52611 47140		89.81	X
0349	FRT LWR BUMP ABSORB	52618 47090		135.70	X
0410	FRONT GRILLE	53101 47081		321.90	X
0431	FRONT MANUFACT BADGE	75310 47060		87.10	✓
0562	RIGHT HEADLAMP ASSY	81145 47691		2,531.60	X
0742	R/F WING	53801 47080		868.70	X
0812	R/F WING BADGE	75374 47140		44.17	X
0842	R/F WHEELHOUSE COVER	53875 47070		185.64	✓
0990	R/RADIATOR BRACKET	53202 47901		213.50	X
1024	R/F PANEL SUPPORT	53213 47050		387.95	X
1186	R/F INN W-HOUSE EXT	53705 47901		107.20	X
1436	WASHER CONTAINER	85315 47160		195.60	✓
8784	FRONT LWR ENGINE CVR	51420 47030		198.30	X
1001	FRONT BUMPER CLIP	FRT BUMPER CLIP		40.00	✓
1002	RHF UNDERSHIELD CLIP	RHF SHIELD CLIP		25.00	✓

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom
Vehicle Inspection Centre
(575718)

Claim Reference: SLK3665L
 Assessment number: 006219
 Version: 1810
 Date calculated: 27/05/2019 6:56 PM

Full Report
 Registration: SLK3665L
 Printed: 27/05/2019 6:56 PM

Code	Description	Part Number	Supplier	Price SGD
1003	RH FOG LAMP	RH FOG LAMP		910.70 ✓
1004	ENG COVER CLIP	ENG COVER CLIP		35.00 X
f: OEM Parts				
n: Non-OEM Parts				
u: Used parts				
Savings				0.00
Subtotal				8,088.77
Subtotal Discount(+30.00%)				-2,426.63
Total				5,662.14 ✓

Extras

Code	Description	Price SGD
1000	FRONT NUMBER PLATE	45.00* X
Total Extras		45.00 ✓

Final Calculation

	SGD	SGD
Parts		
Total Discount(+30.00%)	8,088.77	
	-2,426.63	
Total Parts		5,662.14 ✓
Labour Time Base 10 WU/h		
Total 88.0 WU X 50.00 SGD/h	440.00	
Total of Labour		440.00 ✓
Total Of Extras		45.00 ✓
Paint Work Time Base 10 WU/h		
Labour Cost 73.0 WU X 50.00 SGD/h	365.00	
Material Cost	174.02	
Total Paint Including Material		539.02 ✓ 390.67
Repair Cost Excludes GST		6,686.16 ✓
GST (+7.0%)		468.03
Repair Cost Included GST		7,154.19

**Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom
Vehicle Inspection Centre
(575718)**

Claim Reference: SLK3665L

Assessment number: 006219

Version: 1810

Date calculated: 27/05/2019 6:56 PM

Full Report

Registration: SLK3665L

Printed: 27/05/2019 6:56 PM

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom
Vehicle Inspection Centre
(575718)

Claim Reference: SLK3665L

Assessment number: 006219

Version: 1810

Date calculated: 17/07/2019 7:49 PM

Full Report
Registration: SLK3665L
Printed: 17/07/2019 7:50 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	Carmen SG	Currency:	SGD
Claim Reference:	SLK3665L	Date of Incident:	25/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	PRIUS IV
Sub Model:	BASE MODEL
Model Sheet Number:	70 P5 01
Registration:	SLK3665L

VIN number:

Odometer:

Model Specs

TWO COAT METALLIC

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom
Vehicle Inspection Centre
(575718)

Claim Reference: SLK3665L
 Assessment number: 006219
 Version: 1810
 Date calculated: 17/07/2019 7:49 PM


Full Report
 Registration: SLK3665L
 Printed: 17/07/2019 7:50 PM

Vehicle Condition

Vehicle Status
 Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS		15.0	75.00
B040)	R + R LEFT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	5.00
B040)	R + R RIGHT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	5.00
NO NUMBER	ADJUST HEADLAMPS		2.0	10.00
531041)	R + R RIGHT FRONT WHEELHOUSE SHELL		1.0	5.00
531041A)	R + R L/- AND R/WHEELHOUSE SHELL		2.0	10.00
B140)	R + R LOWER FRONT PANEL CROSSMEMBER		2.0	10.00
B125	RENEW UPPER FRONT PANEL CROSSMEMBER		4.0	20.00
B010)	R + R FRONT BUMPER REINFORCEMENT		3.0	15.00
B010)	R + R FRONT BUMPER LOWER REINFORCEMENT		2.0	10.00

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom
Vehicle Inspection Centre
(575718)

Claim Reference: SLK3665L
 Assessment number: 006219
 Version: 1810

Date calculated: 17/07/2019 7:49 PM

Full Report
 Registration: SLK3665L
 Printed: 17/07/2019 7:50 PM

Code	Description	WU	Price SGD
B010)	R + R FRONT ACTIVE AIR INTAKE GRILL	1.0	5.00
851091)	R + R WINDSCREEN WASHER TANK	1.0	5.00
M010)	R + R CONDENSER	8.0	40.00
M020	RENEW RADIATOR	19.0	95.00
420018)	R + R RIGHT FRONT WHEEL	1.0	5.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		6.30	63.0
Total of Labour			315.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	FRONT BUMPER NEW PART PAINT K1R	15.0
	BONNET SURFACE PAINT	9.0
	RIGHT FRONT DOOR SURFACE PAINT	8.0

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1R	76.26
0471	BONNET SURFACE PAINT	26.64
1482	RIGHT FRONT DOOR SURFACE PAINT	20.67

Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint			32.0	
Preparation Main Work Metal		1.10	11.0	55.00
Preparation Comp. Work Plastic		0.50	5.0	25.00
Total	10 WU/h	4.80	48.0	240.00

Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom
Vehicle Inspection Centre
(575718)

Claim Reference: SLK3665L

Assessment number: 006219

Version: 1810

Date calculated: 17/07/2019 7:49 PM

Full Report

Registration: SLK3665L

Printed: 17/07/2019 7:50 PM

Material Cost - Paint

New Part Painting - Plastic K1R

Surface-/Blend Paint

Material-constant Metal

Material-constant Plastic

Total

Price SGD

76.26

47.31

18.10

9.00

150.67

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01
				Price SGD
0283	FRONT BUMPER	52119 47962		450.80
0431	FRONT MANUFACT BADGE	75310 47060		87.10
0842	R/F WHEELHOUSE COVER	53875 47070		185.64
1436	WASHER CONTAINER	85315 47160		195.60
1001	FRONT BUMPER CLIP	FRT BUMPER CLIP		40.00
1002	RHF UNDERSHIELD CLIP	RHF SHIELD CLIP		25.00
1003	RH FOG LAMP910.7	RH FOG LAMP		910.70
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,894.84
u: Used parts	Subtotal Discount(+30.00%)			-568.45
	Total			1,326.39

**Esteem Performance Pte Ltd
385 Sin Ming Drive, Vicom
Vehicle Inspection Centre
(575718)**

Claim Reference: SLK3665L
Assessment number: 006219
Version: 1810

Date calculated: 17/07/2019 7:49 PM

Full Report
Registration: SLK3665L
Printed: 17/07/2019 7:50 PM

Final Calculation

	SGD	SGD
Parts		
Total Discount(+30.00%)	1,894.84	
	-568.45	
Total Parts		1,326.39
Labour Time Base 10 WU/h		
Total 63.0 WU X 50.00 SGD/h	315.00	
Total of Labour		315.00
Paint Work Time Base 10 WU/h		
Labour Cost 48.0 WU X 50.00 SGD/h	240.00	
Material Cost	150.67	
Total Paint Including Material		390.67
Repair Cost Excludes GST		2,032.06
GST (+7.0%)		142.24
Repair Cost Included GST		2,174.30

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: SLK3665L
Assessment number: 006219
Version: 1810

Date calculated: 19/07/2019 11:56 AM

Full Report
Registration: SLK3665L
Printed: 19/07/2019 11:56 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	SLK3665L	Date of Incident:	25/05/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	PRIUS IV
Sub Model:	BASE MODEL
Model Sheet Number:	70 P5 01
Registration:	SLK3665L

VIN number:

Odometer:

Model Specs

TWO COAT METALLIC

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: SLK3665L
 Assessment number: 006219
 Version: 1810

Date calculated: 19/07/2019 11:56 AM

Full Report
 Registration: SLK3665L
 Printed: 19/07/2019 11:56 AM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS		15.0	75.00
B040)	R + R LEFT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	5.00
B040)	R + R RIGHT HEADLAMP (BUMPER REMOVED) DOES NOT INCLUDE: ADJUST HEADLAMP		1.0	5.00
NO NUMBER	ADJUST HEADLAMPS		2.0	10.00
531041)	R + R RIGHT FRONT WHEELHOUSE SHELL		1.0	5.00
531041A)	R + R L/- AND R/WHEELHOUSE SHELL		2.0	10.00
B140)	R + R LOWER FRONT PANEL CROSSMEMBER		2.0	10.00
B125	RENEW UPPER FRONT PANEL CROSSMEMBER		4.0	20.00
B010)	R + R FRONT BUMPER REINFORCEMENT		3.0	15.00
B010)	R + R FRONT BUMPER LOWER REINFORCEMENT		2.0	10.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: SLK3665L
 Assessment number: 006219
 Version: 1810
 Date calculated: 19/07/2019 11:56 AM

Full Report
 Registration: SLK3665L
 Printed: 19/07/2019 11:56 AM

Code	Description	WU	Price SGD
B010)	R + R FRONT ACTIVE AIR INTAKE GRILL	1.0	5.00
851091)	R + R WINDSCREEN WASHER TANK	1.0	5.00
M010)	R + R CONDENSER	8.0	40.00
M020	RENEW RADIATOR	19.0	95.00
420018)	R + R RIGHT FRONT WHEEL	1.0	5.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		6.30	63.0
Total of Labour			315.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	FRONT BUMPER NEW PART PAINT K1R	15.0
	BONNET SURFACE PAINT	9.0
	RIGHT FRONT DOOR SURFACE PAINT	8.0

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1R	76.26
0471	BONNET SURFACE PAINT	26.64
1482	RIGHT FRONT DOOR SURFACE PAINT	20.67

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	50.00 SGD/h			
Time Paint			32.0	
Preparation Main Work Metal		1.10	11.0	55.00
Preparation Comp. Work Plastic		0.50	5.0	25.00
Total	10 WU/h	4.80	48.0	240.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: SLK3665L
 Assessment number: 006219
 Version: 1810

Date calculated: 19/07/2019 11:56 AM

Full Report
 Registration: SLK3665L
 Printed: 19/07/2019 11:56 AM

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1R	76.26
Surface-/Blend Paint	47.31
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	150.67

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0283	FRONT BUMPER	52119 47962		450.80
0431	FRONT MANUFACT BADGE	75310 47060		87.10
0842	R/F WHEELHOUSE COVER	53875 47070		185.64
1436	WASHER CONTAINER	85315 47160		195.60
1001	FRONT BUMPER CLIP	FRT BUMPER CLIP		40.00
1002	RHF UNDERSHIELD CLIP	RHF SHIELD CLIP		25.00
1003	RH FOG LAMP910.7	RH FOG LAMP		910.70
1004	ENG COVER CLIP	ENG COVER CLIP		0.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,894.84
u: Used parts	Subtotal Discount(+30.00%)			-568.45
	Total			1,326.39

Extras

Code	Description	Price SGD
1000	FRONT NUMBER PLATE	0.00*

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference: SLK3665L
Assessment number: 006219
Version: 1810

Date calculated: 19/07/2019 11:56 AM

Full Report
Registration: SLK3665L
Printed: 19/07/2019 11:56 AM

Final Calculation

	SGD	SGD
Parts	1,894.84	
Total Discount(+30.00%)	-568.45	
Total Parts		1,326.39
Labour Time Base 10 WU/h		
Total 63.0 WU X 50.00 SGD/h	315.00	
Total of Labour		315.00
Total Of Extras		0.00
Paint Work Time Base 10 WU/h		
Labour Cost 48.0 WU X 50.00 SGD/h	240.00	
Material Cost	150.67	
Total Paint Including Material		390.67
Repair Cost Excludes GST		2,032.06
GST (+7.0%)		142.24
Repair Cost Included GST		2,174.30

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2019 10:45		29 May 2019 13:48 Edit Adj Rpt	S\$2,032.06 Edit Estimates	S\$2,032.06 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GOH LENG KHIANG, ID: S12877431		
Main Claimant:	Grab Rentals Pte Ltd, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLK3665L	Date of Loss:	25/05/2019 16:00 - :59 [28 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 594572	Policy/Cover Note No.:	P27749752DMA (Comprehensive) Coverage: 19/09/2018 - 18/09/2019
Vehicle Reg. No. (Insured):	SBN3328M	Policy No. (Claimant):	
		Excess:	
Repairer:	Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive, 575718 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 28/06/2019]		
Driver/Custodian (Insured):	GOH LENG KHIANG (), NRIC: S12877431 Email:		
Adj Asg. Remarks:	PRS, survey by today. on WP. Liab: dispute. TP Agree on SJE - assign LKK. Contact: Jenny @ 6484 1221.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

*SLK3665L (594572)

[SBN3328M]

TP

Grab Rentals Pte Ltd

May 25 2019 4:00PM

[GOH LENG KHIANG]

Esteem Performance Pte Ltd - Sin Ming

Upload Documents Upload Photos Compose New Letter

View View in Browser

Video				1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	03/06/19 10:11	Video - Accident- 3P	i	Load MP4	
Assessment Reports				1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/06/19 17:04	Adjuster Immediate Advice	i	Load HTM	
Photos/Images				3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/07/19 14:04	General View	i	Load JPG	
2	22/07/19 14:04	General View	i	Load JPG	
3	22/07/19 14:04	General View	i	Load JPG	
4	22/07/19 14:04	General View	i	Load JPG	
5	22/07/19 14:04	General View	i	Load JPG	
6	22/07/19 14:04	General View	i	Load JPG	
7	22/07/19 14:04	General View	i	Load JPG	
8	22/07/19 14:04	General View	i	Load JPG	
9	22/07/19 14:04	General View	i	Load JPG	
10	22/07/19 14:04	General View	i	Load JPG	
11	22/07/19 14:04	General View	i	Load JPG	
12	22/07/19 14:04	General View	i	Load JPG	
13	22/07/19 14:06	Reinspection Photo	i	Load JPG	
14	22/07/19 14:06	Reinspection Photo	i	Load JPG	
Documentation				1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	28/05/19 10:48	OI SBN3328M E-File Report	i	Load PDF	
2	28/05/19 10:48	PRI from Esteem Performance Pte Ltd	i	Load PDF	
3	28/05/19 14:57	TP SLK3665L E-file report	i	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	29/05/19 12:48	audatex report	i	Load PDF	
2	29/05/19 12:49	email to joseph to audatex report	i	Load PDF	
3	29/05/19 13:46	Outsource Instruction	i	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/07/19 13:58	AUDATEX.pdf	i	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19009499/KSD3S2
Date: 24/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: P27749752DMA
 Claimant Vehicle No: SLK3665L Insured Vehicle No: SBN3328M
 Date of Loss: 25/05/2019 Nature of Claim: TP Claim No: 594572

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK3665L**
 Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRR987110
 Reg. Date: 13/01/2017 (Man. Year: 2016) Chassis No: JTDKB3FU903544347
 Colour: Metallic Pearl White Odometer: 110153 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Rovelov 6 mm Rear Left Side: Giti 2 mm
 Front Right Side: Rovelov 6 mm Rear Right Side: Giti 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,707.14	1,326.39	4,380.75	76.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	979.02	705.67	273.35	27.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,686.16	2,032.06	4,654.10	69.61
+ GST 7.00/7.00% (S\$)	468.03	142.24	325.79	69.61
Nett Amount (S\$)	7,154.19	2,174.30	4,979.89	69.61

INSPECTION

Date of Assignment: 29/05/2019
 Date Inspected: 31/05/2019 Inspected At: Esteem Performance Pte Ltd - Sin Ming (HQ)
 385 Sin Ming Drive
 Singapore 575718
 Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jul 2019)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK3665L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LWR AIR GRILLE	Serviceable	148.60 FL	*- FL
2	1		*FRT NO PLATE REINF	Serviceable	129.00 FL	*- FL
3	1		*R/F BUMPER COVER	Serviceable	25.70 FL	*- FL
4	1		*FRONT BUMPER	Cracked	450.80 FL	*450.80 FL
5	1		*FRT LWR BUMPER REINF	Repair	245.30 FL	*- FL
6	1		*FRT BUMPER REINF	Repair	711.50 FL	*- FL
7	1		*FRT BUMPER ABSORBER	Serviceable	89.81 FL	*- FL
8	1		*FRT LWR BUMP ABSORB	Serviceable	135.70 FL	*- FL
9	1		*FRONT GRILLE	Serviceable	321.90 FL	*- FL
10	1		*FRONT MANUFACT BADGE	Necessary	87.10 FL	*87.10 FL
11	1		*RIGHT HEADLAMP ASSY	Serviceable	2,531.60 FL	*- FL
12	1		*R/F WING	Repair	868.70 FL	*- FL
13	1		*R/F WING BADGE	Not Necessary	44.17 FL	*- FL
14	1		*R/F WHEELHOUSE COVER	Distorted	185.64 FL	*185.64 FL
15	1		*R/RADIATOR BRACKET	Repair	213.50 FL	*- FL
16	1		*R/F PANEL SUPPORT	Repair	387.95 FL	*- FL
17	1		*R/F INN W-HOUSE EXT	Repair	107.20 FL	*- FL
18	1		*WASHER CONTAINER	Dented	195.60 FL	*195.60 FL
19	1		*FRONT LWR ENGINE CVR	Serviceable	198.30 FL	*- FL
20	1		*FRONT BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
21	1		*RHF UNDERSHIELD CLIP	Necessary	25.00 FL	*25.00 FL
22	1		*RH FOG LAMP	Mtg Cracked	910.70 FL	*910.70 FL
23	1		*ENG COVER CLIP	Not Necessary	35.00 FL	*- FL
24	1		*FRONT NUMBER PLATE	Serviceable	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,133.77	1,894.84
- List Item Discount on L Items 30.00/30.00% (\$\$)	2,426.63	568.45
Total Parts (\$\$)	5,707.14	1,326.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOTAL LABOUR.	New	440.00	315.00
2	PAINT WORK: LABOUR COST.	New	365.00	240.00
3	PAINT WORK: MATERIAL COST.	New	174.02	150.67
Gross Labour Cost (\$\$)			979.02	705.67

Report was unsubmitted during this print-out.

< END OF ESTIMATES >