

ASS. REC. BY:

REF: CS/FCI/9009514/1Ksd3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person):

Sitharam

of

FCI

Date/Time:

10/11/2019/5/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 3143G

Insured:

SHC 7185T

at Workshop m/s

Feteem performance

Tel:

65662112

of

385 Sin Ming Drive

Policy No:

Claim No:

D19003500MTF84

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/5/2019

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

11/11/2019/5/19

Person Contacted:

CarmenVehicle: IN OUT

Date/Time	Action/Instruction	Estimate
	<u>SLJ 3143G-X</u>	
	<u>SHC 7185T-C04/ASM18W452G/Klen3</u>	<u>DVA: 7/3/2018</u>
<u>30/05/19</u>	<u>@ 16:38 pm revised PA to Sitharam via email.</u>	
<u>28/6</u>	<u>@ 4068.35 Car from</u>	
	<u>(@ 4,132.24 Red - 50%)</u>	

ASS. REC. BY:

REF:

1907/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res:

Yes or No

Lum Sum:

1.81

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 / File pass to

Veh No:

SLT 3143C Yr Regn: 12, 16

Type: M. Car M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Priv

C.C.

1798

Colour:

M. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

261443

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FUH03539884

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

5

mm

L/Bal.

7

mm

L/Bal.

5

mm

D.O.A.

28/5/19

D.O.A.

29/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 28 JUN 2019

Date/Time, File Pass to?

28/06/19

1) Typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation

S + PS SI

Fees

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

Lump Sum (L.B.) (\$

4,068.35 p/p

160

50

50 + 50

22

332



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003500MFSH

Date: 30 May 2019

Our Ref: CS/FCI19009514/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLJ 3143G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 29/05/2019 at the premises of M/s Esteem Performance Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 7,994.42</u> .
Revised Estimate Amount	: <u>S\$ 5,151.17</u> .
"Check" Items Amount	: <u>S\$ 1,070.96</u> .
Market Value	: <u>S\$</u> .
LTA Reimbursement Value	: <u>S\$</u> .
Nett Value	: <u>S\$</u> .

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 4 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	28-05-2019	Our Ref No. D19003500MFSH
Accident Date	28-05-2019	Claim Type. Third Party
Insured Vehicle	SHC7185T	Third Party Vehicle. SLJ3143G
Survey Location	385, SIN MING DRIVE (INSIDE VICOM)	
Contact Person.	JENNY CHONG	
Contact No.	65662112/ 0	Fax No. 62593326
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 30 May 2019 4:38 PM
To: 'Sithara'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19003500MFSH/1
Attachments: SLJ 3143G- Preli Advise .pdf

Dear Sithara,

Enclosed preliminary revised of vehicle SLJ 3143G.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 29 May 2019 11:17 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003500MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 29 May 2019 10:11 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003500MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLJ 3143 G

Parts	(a) Cost / List Price Items	\$	5,843.22
	Plus/Less 25%	\$	1,460.81
	Total of Cost / List	\$	4,382.42
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	4,582.42
Labour		\$	3,412.00
Total		\$	7,994.42

4588.59

8200.59

The above total will be subjected to 7% G.S.T.

Not Authorized

Resurvey B4 paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor

Kenneth

Company

LKK

Survey conducted on

29/5/19

at

Remarks By Surveyor

8198.59 ✓

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.(b) Recommended Days of Repair : 04 day(s)(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : LeDate: 29/5/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLJ 3143 G**
Make & Model : **TOYOTA PRIUS**
Chassis No. : **JTDKB3FUX03539884**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Sn</i>	1	\$200.00	S.N	X
2	Rear bumper <i>CM</i>	1	\$497.50		✓
3	Rear bumper clip <i>Sn</i>	10	\$40.00		✓
4	Rear bumper side retainer LH <i>Sn</i>	1	\$112.70		X
5	Rear bumper side retainer RH <i>Di</i>	1	\$112.70		✓
6	Rear bumper lower centre garnish <i>CM</i>	1	\$582.60		✓
7	Rear bumper lower garnish RH <i>CM</i>	1	\$149.70		✓
8	Rear bumper reinforcement <i>R</i>	1	\$398.90		✓
9	Rear bumper tow cover <i>CM</i>	1	\$31.70		✓
10	Rear bumper under cover <i>Sn</i>	1	\$355.20		X
11	Rear bumper under cover clip <i>Sn</i>	4	\$14.00		X
12	Wording "hybrid" <i>Sn</i>	1	\$55.47		✓
13	Wording "Prius" <i>Sn</i>	1	\$51.90		✓
14	Tail door plate garnish <i>CM</i>	1	\$782.50		✓
15	Tail door plate garnish clip <i>Sn</i>	10	\$35.00		✓
16	Boot weatherstrip <i>Sn</i>	1	\$353.10		X
17	Tail lamp RH - Upper <i>Sn</i>	1	\$498.75		X
18	Tail lamp RH - Lower <i>CM</i>	1	\$511.60		✓
19	Exhaust pipe <i>R</i>	1	\$954.10		X
20	Exhaust pipe mounting <i>Sn</i>	1	\$38.40		X
21	Exhaust insulator <i>Sn</i>	1	\$267.40		X
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLJ 3143 G** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, RHR FENDER, END PANEL)	\$1,200.00	750 500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, RHR FENDER, END PANEL)	\$1,200.00	750
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor	\$120.00	50
5	To tuff coat. <i>nn</i>	\$150.00	X
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60
7	To transfer door mechanism & components <i>nn</i>	\$150.00	X
8	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
9	To remove & refit exhaust system to assist work load. <i>nn</i>	\$150.00	X
10	Towing fee <i>BH</i>	\$120.00	95

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5035 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.
 Tel : 6484 1221 Fax : 6484 7829
 385 Sin Ming Drive (Inside Vicom) Singapore 575718.
 Tel : 6753 2112 Fax : 6451 0394
 Co. Reg No. : 200005485N GST Reg No. : 20-0005485-N

Spare Parts

Vehicle No. : SLJ 3143 G
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FUX03539884

Submit By : CARMEN LIM
 Year Manufacture : 2016
 Engine No. :
Cost / List

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper side seal RH <i>CR1</i>	1	\$87.30		<i>—</i>
2	Rear bumper under cover RH <i>CM</i>	1	\$187.60		<i>—</i>
3		1			
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		1			
21		1			
22		1			
23		1			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

274.90



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19009514/Ksd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-07-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7185T	Veh. Inspected	SLJ 3143G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003500MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	29/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDKB3FUX03539884	Colour	METALLIC PEARL WHITE	
Odometer	261443	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	7 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	7 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/05/2019	Inspection Date	29/05/2019	
Survey held at	385 SIN MING DRIVE			
Repairer	ESTEEM PERFORMANCE PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 3143G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CRACKED	497.50	497.50
10	REAR BUMPER CLIP	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	112.70	-
1	REAR BUMPER SIDE RETAINER RH	DISTORTED	112.70	112.70
1	REAR BUMPER LOWER CENTRE GARNISH	CRACKED	582.60	582.60
1	REAR BUMPER LOWER GARNISH RH	CRACKED	149.70	149.70
1	REAR BUMPER REINFORCEMENT	BENT	398.90	398.90
1	REAR BUMPER TOW COVER	CRACKED	31.70	31.70
1	REAR BUMPER UNDER COVER	SERVICEABLE	355.20	-
4	REAR BUMPER UNDER COVER CLIP	NOT NECESSARY	14.00	-
1	WORDING "HYBRID"	NECESSARY	55.47	55.47
1	WORDING "PRIUS"	NECESSARY	51.90	51.90
1	TAIL DOOR PLATE GARNISH	CRACKED	782.50	782.50
10	TAIL DOOR PLATE GARNISH CLIP	NECESSARY	35.00	35.00
1	BOOT WEATHERSTRIP	SERVICEABLE	353.10	-
1	TAIL LAMP RH-UPPER	SERVICEABLE	498.75	-
1	TAIL LAMP RH-LOWER	CRACKED	511.60	511.60
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	954.10	-
1	EXHAUST PIPE MOUNTING	SERVICEABLE	38.40	-
1	EXHAUST INSULATOR	SERVICEABLE	267.40	-
1	REAR BUMPER SIDE SEAL RH (ADDITIONAL)	CRACKED	87.30	87.30
1	REAR BUMPER UNDER COVER RH (ADDITIONAL)	CRACKED	187.60	187.60
	LESS 25% DISCOUNT		-1,529.53	-881.12
			4,588.59	2,643.35
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
			200.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,TAIL DOOR,RHR FENDER,END PANEL).INCLUSIVE OF THE REPAIR OF EXHAUST PIPE.		1,200.00	500.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,TAIL DOOR,RHR FENDER,END PANEL).		1,200.00	750.00
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REFIT REVERSE SENSOR.		120.00	50.00
	TO TUFF COAT.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIT SPARE TYRE,SPARE TYRE BOARD,CARPET TRIM TO ASSIST WORK LOAD.		150.00	60.00
	TO TRANSFER DOOR MECHANISM & COMPONENTS.	NOT NECESSARY	150.00	-
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT EXHAUST SYSTEM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
	TOWING FEE.		120.00	45.00
			3,410.00	1,425.00
	GRAND TOTAL		8,198.59	4,068.35
	RECOMMENDED COST OF REPAIRS			4,068.35

Report Ref No. CS/FCI19009514/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.