

ASS. REC. BY:

REF:

CS/FI/19009588/Agd3

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

(WS)

From (Person): Serene Ler

of

FCI

Date/Time: 5:18pm 29/5/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SMA 5872H

Insured:

SHB 6289P

at Workshop m/s

N-S Automotive

Tel:

68420051

of

21caki Bukit Ave #01-18

Policy No:

Claim No:

D19003507MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 27/05/2019

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

9:43am 30/5/19

Person Contacted:

Zi ting

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate

✓

SMA 5872H - X

SHB 6289P - NS/INC/6019391/H/vbm 2 D.O.A: 10/10/2016

31/5/19 @ 1:57pm Informed Serene Ler, we are pending estimate from repairer.

18/9/19 @ 10:30am revised to Serene Ler by email.

US \$ 9900, 10 days (RED \$ 6759.91, 39%)

429



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003507MFSH

Date: 18 September 2019

Our Ref: CS/FCI19009588/Aqd3

The Motor Claims Department
MS First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SMA 5872H .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/05/2019 at the premises of M/s N-51 AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ 16,159.91 .
Revised Estimate Amount	: S\$ 9,900.00 (Lump Sum) .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	28-05-2019	Our Ref No. D19003507MFSH
Accident Date	27-05-2019	Claim Type. Third Party
Insured Vehicle	SHB6289P	Third Party Vehicle. SMA5872H
Survey Location	2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB	
Contact Person.	ZI TING	
Contact No.	68420051/ 0	Fax No. 67410510
Survey Type	WITHOUT PREJUDICE: NO EST. COR	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	N-51 AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 31 May 2019 11:57 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003507MFSH/1

Dear Serene,

Please be informed that we have inspected the vehicle SMA 5872H on 30/05/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 30 May 2019 9:46 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003507MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 29 May 2019 5:18 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003507MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 18 September 2019 10:30 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003507MFSH/1
Attachments: CSFC19009588Aqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SMA 5872H.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Friday, 31 May 2019 11:57 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003507MFSH/1

Dear Serene,

Please be informed that we have inspected the vehicle SMA 5872H on 30/05/2019.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 30 May 2019 9:46 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003507MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 94787759

TP 1st Cap
Xiao Chan

ESTIMATE

Repair Code : CLM15269

Date in : 27/05/2019

Vehicle Num. : SMA5872H

Model : TOYOTA SIENNA HYBRID 1.5X CVT

Chassis/Eng# : NHP1707127167/1NZ8554062

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Distorted</i>	1	950.00	<i>485</i> ✓ 950.00
REAR BUMPER CENTER PROTECTOR GARNISH <i>Deformed.</i>	1	207.00	✓ 207.00
REAR BUMPER REFLECTOR L/R <i>cracked</i>	2	85.00	✓ 170.00
REAR BUMPER SIDE PROTECTOR GARNISH L/R <i>Dehd</i>	2	151.00	✓ 302.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	90.00	✓ 180.00
REAR BUMPER TOW HOOK COVER <i>Deformed.</i>	1	25.00	✓ 25.00
REAR DECK TOP TRIM BOARD <i>new</i>	1	686.00	X 686.00
REAR END PANEL 'INNER' <i>Distorted</i>	1	607.00	✓ 607.00
REAR END PANEL 'OUTER' <i>Distorted</i>	1	599.00	✓ 599.00
REAR END PANEL TOP GARNISH <i>Deformed</i>	1	207.00	✓ 207.00
REAR EXHAUST GASKET <i>new</i>	1	58.00	X 58.00
REAR FENDER INNER TRIM BOARD L/R <i>Deformed.</i>	2	709.00	✓ 1,418.00
REAR SPARE WHEEL PANEL <i>Brcked</i>	1	778.70	✓ 778.70
REAR SPARE WHEEL PANEL CARRIER BRACKET <i>new</i>	1	223.65	X 223.65
REAR SPARE WHEEL TOOL BOX <i>Deformed</i>	1	519.00	✓ 519.00
REAR SPARE WHEEL TOOL BOX TOP TRIM BOARD L/R <i>new</i>	2	378.00	X 756.00
REAR TAILGATE <i>Distorted</i>	1	1785.00	<i>1286</i> ✓ 1,785.00
REAR TAILGATE 'HYBRID SYNERGY DRIVE' EMBLEM <i>new</i>	1	61.00	✓ 61.00

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 94787759

ESTIMATE

Repair Code : CLM15269

Date in : 27/05/2019

Vehicle Num. : SMA5872H

Model : TOYOTA SIENTA HYBRID 1.5X CVT

Chassis/Eng# : NHP1707127167/1NZ8554062

REAR TAILGATE 'LOGO' EMBLEM <i>Not</i>	1	110.00	✓	110.00
REAR TAILGATE DAMPER L/R <i>Damaged</i>	2	225.00	✓	450.00
REAR TAILGATE INNER PULL HANDLE <i>Cracked</i>	1	48.00	✓	48.00
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>Not New</i>	2	19.00	✗	38.00
REAR TAILGATE INNER TRIM BOARD <i>Cracked</i>	1	455.00	✓	455.00
REAR TAILGATE LOCK OUTER OPENER SWITCH <i>Damaged</i>	1	207.00	✓	207.00
REAR TAILGATE MECHANISM LOCK <i>Damaged</i>	1	265.00	✓	265.00
REAR TAILGATE NUMBER PLATE LAMP L/R <i>Not New</i>	2	68.00	✗	136.00
REAR TAILGATE OUTER GARNISH <i>Cracked</i>	1	167.00	✓	167.00
REAR TAILGATE REFLECTOR L/R <i>Cracked</i>	2	281.00	✓	562.00
REAR TAILGATE WEATHER STRIP <i>Not</i>	1	385.00	✓	385.00
REAR TAILGATE WINDSCREEN MOULDING L/R <i>3 new</i>	2	45.00	✓	90.00
REAR TAILGATE WINDSCREEN SEAL (TOP & LOWER)	2	45.00	✓	90.00
REAR TAILGATE WIPER MOTOR <i>Damaged</i>	1	655.00	✓	655.00
REAR TAILLAMP L/R <i>Cracked</i>	2	425.00	✓	850.00
REAR TAILLAMP LOWER BRACKET L/R <i>Cracked</i>	2	83.10	✓	166.20

*** This is a computer-generated document which requires no signature.***

page 2

11344.90
8508.67



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 94787759

ESTIMATE

Repair Code : CLM15269

Date in : 27/05/2019

Vehicle Num. : SMA5872H

Model : TOYOTA SIENTA HYBRID 1.5X CVT

Chassis/Eng# : NHP1707127167/1NZ8554062

		Subtotal before discount	14,206.55
Percentage discount 25%			3,551.64
		Sub-total 1	10,654.91
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00
REAR BUMPER REVERSE SENSOR - SET <i>Damaged</i>	1	250.00	200 250.00
REAR END PANEL TOP GARNISH CLIPS - SET <i>new</i>	1	20.00	✓ 20.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <i>new</i>	2	50.00	60 100.00
REAR SPARE WHEEL CARRIER INSULATOR MAT <i>new</i>	1	150.00	✓ 150.00
REAR TAILGATE CAMERA <i>Damaged</i>	1	400.00	✓ 400.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1	80.00	30 80.00
REAR TAILGATE NUMBER PLATE <i>crackd</i>	1 <i>1035</i>	25.00	✓ 25.00
REAR TAILGATE NUMBER PLATE HOLDER <i>crackd</i>	1	50.00	30 50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>	1	20.00	10 20.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	60.00	✓ 60.00
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	30.00	20 60.00
		Subtotal before discount	1,265.00
Percentage discount 0%			0.00
		Sub-total 2	1,265.00
		Parts-total	11,919.91

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 94787759

ESTIMATE

Repair Code : CLM15269

Date in : 27/05/2019

Vehicle Num. : SMA5872H

Model : TOYOTA SIENTA HYBRID 1.5X CVT

Chassis/Eng# : NHP1707127167/1NZ8554062

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	30	60.00
To remove, reinstall tailgate windscreen	✓	120.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80	150.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1200	1,600.00
To remove and reinstall exhaust pipe.	✓	80.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2870	1200 2,000.00
To apply anti-rust chemical on repaired and replaced panel.	60	150.00
To remove, reinstall tailgate mechanism and check for function	✓	80.00
Labour Total		4,240.00
Parts & Labour Total		16,159.91

*** This is a computer-generated document which requires no signature.***

page 4

total 12413.67
H/S. 9.9K
09 Days
9.9K
102p



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19009588/Aqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 23-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 6289P	Veh. Inspected	SMA 5872H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003507MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	29/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	NHP1707127167	Colour	GREEN	
Odometer	98381	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	HABILEAD	6 mm	
L/H Front Tyre	185/60 R15	HABILEAD	6 mm	
R/H Rear Tyre	185/60 R15	HABILEAD	6 mm	
L/H Rear Tyre	185/60 R15	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/05/2019	Inspection Date	30/05/2019	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 5872H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED	950.00	485.00
1	REAR BUMPER CENTER PROTECTOR GARNISH	DEFORMED	207.00	207.00
2	REAR BUMPER REFLECTOR L/R @\$85.00	CRACKED	170.00	170.00
2	REAR BUMPER SIDE PROTECTOR GARNISH L/R @\$151.00	DEFORMED	302.00	302.00
2	REAR BUMPER SIDE RETAINER L/R @\$90.00	NECESSARY	180.00	180.00
1	REAR BUMPER TOW HOOK COVER	DEFORMED	25.00	25.00
1	REAR DECK TOP TRIM BOARD	NOT NECESSARY	686.00	-
1	REAR END PANEL "INNER"	DISTORTED	607.00	607.00
1	REAR END PANEL "OUTER"	DISTORTED	599.00	599.00
1	REAR END PANEL TOP GARNISH	DEFORMED	207.00	207.00
1	REAR EXHAUST GASKET	NOT NECESSARY	58.00	-
2	REAR FENDER INNER TRIM BOARD L/R @\$709.00	DEFORMED	1,418.00	1,418.00
1	REAR SPARE WHEEL PANEL	BUCKLED	778.70	778.70
1	REAR SPARE WHEEL PANEL CARRIER BRACKET	NOT NECESSARY	223.65	-
1	REAR SPARE WHEEL TOOL BOX	DEFORMED	519.00	519.00
2	REAR SPARE WHEEL TOOL BOX TOP TRIM BOARD L/R @\$378.00	NOT NECESSARY	756.00	-
1	REAR TAILGATE	DISTORTED	1,785.00	1,286.00
1	REAR TAILGATE "HYBRID SYNERGY DRIVE" EMBLEM	NECESSARY	61.00	61.00
1	REAR TAILGATE "LOGO" EMBLEM	NECESSARY	110.00	110.00
2	REAR TAILGATE DAMPER L/R @\$225.00	DAMAGED	450.00	450.00
1	REAR TAILGATE INNER PULL HANDLE	CRACKED	48.00	48.00
2	REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R @\$19.00	NOT NECESSARY	38.00	-
1	REAR TAILGATE INNER TRIM BOARD	CRACKED	455.00	455.00
1	REAR TAILGATE LOCK OUTER OPENER SWITCH	DAMAGED	207.00	207.00
1	REAR TAILGATE MECHANISM LOCK	DAMAGED	265.00	265.00
2	REAR TAILGATE NUMBER PLATE LAMP L/R @\$68.00	NOT NECESSARY	136.00	-
1	REAR TAILGATE OUTER GARNISH	CRACKED	167.00	167.00
2	REAR TAILGATE REFLECTOR L/R @\$281.00	CRACKED	562.00	562.00
1	REAR TAILGATE WEATHER STRIP	CUT	385.00	385.00

Report Ref No. CS/FCI19009588/Aqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR TAILGATE WINDSCREEN MOULDING L/R @\$45.00	NECESSARY	90.00	90.00
2	REAR TAILGATE WINDSCREEN SEAL (TOP & LOWER) @\$45.00	NECESSARY	90.00	90.00
1	REAR TAILGATE WIPER MOTOR	DAMAGED	655.00	655.00
2	REAR TAILLAMP L/R @\$425.00	CRACKED	850.00	850.00
2	REAR TAILLAMP LOWER BRACKET L/R @\$83.10	CRACKED	166.20	166.20
	LESS 25% DISCOUNT		-3,551.64	-2,836.23
			10,654.91	8,508.67
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
2	SET REAR FENDER INNER TRIM BOARD CLIPS L/R @\$50.00 (SN)	NECESSARY	100.00	60.00
1	REAR SPARE WHEEL CARRIER INSULATOR MAT (SN)	NECESSARY	150.00	150.00
1	REAR TAILGATE CAMERA (SN)	DAMAGED	400.00	400.00
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	80.00	30.00
1	REAR TAILGATE NUMBER PLATE (SN)	CRACKED	25.00	25.00
1	REAR TAILGATE NUMBER PLATE HOLDER (SN)	DEFORMED	50.00	30.00
1	SET REAR TAILGATE OUTER GARNISH CLIPS (SN)	NECESSARY	20.00	10.00
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
2	SET REAR TAILLAMP CLIPS L/R @\$30.00 (SN)	NECESSARY	60.00	20.00
			1,265.00	1,035.00
	<u>LABOUR</u>			
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR.		60.00	30.00
	TO REMOVE,REINSTALL TAILGATE WINDSCREEN.		120.00	120.00
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR).		150.00	80.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID,REAR END PANEL,REAR FENDER (L/R),SPARE TYRE PANEL AND REAR BUMPER.		1,600.00	1,200.00
	TO REMOVE AND REINSTALL EXHAUST PIPE.	NOT NECESSARY	80.00	-

Report Ref No. CS/FCI19009588/Aqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		2,000.00	1,300.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		150.00	60.00
	TO REMOVE, REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION.		80.00	80.00
			4,240.00	2,870.00
GRAND TOTAL			16,159.91	12,413.67
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,900.00

Report Ref No. CS/FCI19009588/Aqd3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.