

ASS. REC. BY:

REF:

CFI19009591 / Ktd3n2 Special Instruction:

Sponsor:

Kenneth

ASSIGNMENT (Office)

CWS

From (Person):

Joanne Yong

of

FCI

Date/Time:

29/5/19 5:42pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 881J

Insured:

SHA 3767B

at Workshop m/s

Transcarb

Tel:

0287 6666

of

No. 2 Amle st - 63

Policy No:

Claim No:

D19003540MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/05/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

10:47am 30/5/19

Person Contacted:

Amenda

Vehicle IN/OUT

Date/Time	Action/Instruction
	SHD 881J - X
	SHA 3767B - NS/INC100 22663 / Drl.
31/5/19 @ 12:16pm	VENUED to Joanne Yong by email.

REF: FCI

ASSIGNMENT

From:

Date:

30/5/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHD 381 J

at Workshop m/s

Trunscab

of

No. 2 Amk St-63

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

043 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1 up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 381 J

Yr Regn:

05, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude C.C.

19P5

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

42668P

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL 15AUC 282354

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

R/Bal.

S

mm

Rear

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

28/5/19

D.O.I.

30/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	11 Sm 8405d (Red: 89147.15; 950%)
	Confirm with Wai Yin.
	RECEIVED 07 JUN 2019

Date/Time, File Pass to?



: Preli. Report



: Final Report

116 Typist

Date/Time, File Return to?

2)

Report Format:

TP

Lump ☒ / LRD: \$

40507

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + FS: \$

Photos

Other:

TOTAL

350



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003540MFSH

Date: 31 May 2019

Our Ref: CS/FCI19009591/Ktd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 381T.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/05/2019 at the premises of M/s TRANS-CAB. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>93,197.15</u> .
Revised Estimate Amount	: S\$ <u>5,047.29</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear & front portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	29-05-2019	Our Ref No. D19003540MFSH
Accident Date	28-05-2019	Claim Type. Third Party
Insured Vehicle	SHA3767B	Third Party Vehicle. SHD381J
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	AMANDA TAY	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 31 May 2019 12:16 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003540MFSH/1
Attachments: CSFCI19009591Ktd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SHD 381T.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 30 May 2019 10:42 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003540MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 29 May 2019 5:42 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003540MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Denise Tay (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Tuesday, 4 June 2019 2:32 PM
To: Denise Tay (LKKAUTO)
Subject: FW: SHD 381T / TP / FIRSTCAPITAL / DOA: 28/5/2019 -- AAD1905-257
Attachments: shd 381t.pdf

Hi Denise

We confirmed COR amount \$ 4,050.00 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Monday, 3 June, 2019 12:13 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: SHD 381T / TP / FIRSTCAPITAL / DOA: 28/5/2019

Dear Wai Yin,

Please check and confirm lump sum \$4050, 5days

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD381J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	28 May 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002840
Chassis No.:	VF1ABL15AUC282354
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	31 May 2016
First Registration Date:	31 May 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2024
PARF Rebate Amount:	\$14,998.00

Intended COE Rebate Details

COE Expiry Date:	30 May 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$36,463.00
COE Rebate Amount:	\$22,813.00
Total Rebate Amount:	\$37,811.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 28 May 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 381J**AAD1905-257**

Not Wholes
1/1 Sep @ 4050/-

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHD 381J

VF1ABL15AUC282354

RENAULT

LATITUDE

28.5.19

FIRST CAPITAL

31/5/2016

		PART
1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	BOOT REAR
14	1	BOOT FINISHER
15	1	BOOT WHEATERSTRIP
16	1	BOOT REFLECTOR LAMP LH
17	1	BOOT REFLECTOR LAMP RH
18	1	BOOT BADGE 'RENAULT'
19	1	BOOT BADGE
20	1	BOOT STRUT LH
21	1	BOOT STRUT RH
22	1	BOOT HINGE LH
23	1	BOOT HINGE RH
24	1	BOOT INNER TRIM
25	1	BOOT SWITCH
26	1	BOOT LOCK
27	1	BOOT LOCK CATCH
28	2	LICENCE PLATE LAMP
29	2	BOOT RUBBER PLUG
30	1	FENDER PANEL INNER TRIM REAR LH

		LIST
\$	<i>Bu</i>	1,108.46 ✓
\$	<i>CM/ru</i>	768.84 ✓
\$	<i>SL</i>	113.47 X
\$	<i>SL</i>	135.97 X
\$	<i>SL</i>	44.99 X
\$	<i>SL</i>	43.61 X
\$	<i>SL</i>	135.97 X
\$	<i>SL</i>	44.99 X
\$	<i>SL</i>	43.61 X
\$	<i>R</i>	777.52 ✓
\$	<i>R</i>	225.95 ✓
\$	<i>Di</i>	225.95 ✓
\$	<i>R</i>	2,872.68 X
\$	<i>SL</i>	470.06
\$	<i>SL</i>	323.05
\$	<i>SL</i>	493.35
\$	<i>SL</i>	493.35
\$	<i>ru</i>	225.36
\$	<i>ru</i>	225.36
\$	<i>SL</i>	276.08
\$	<i>SL</i>	276.08
\$	<i>R</i>	367.84
\$	<i>R</i>	367.84
\$	<i>SL</i>	586.45
\$	<i>R</i>	168.13
\$	<i>R</i>	202.67
\$	<i>R</i>	74.40
\$	<i>SL</i>	50.52
\$	<i>SL</i>	221.81
\$	<i>SL</i>	671.45

X

Trans-cab Auto Services Pte Ltd**AAD1905-257**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 381J

31	1	FENDER PANEL REAR LH	\$	N	3,299.13	}	X
32	1	WHEELARCH REAR LH	\$	SL	543.47		
33	1	FENDER PANEL INNER TRIM REAR RH	\$	SL	671.45		
34	1	FENDER PANEL REAR RH	\$	N	3,299.13		
35	1	WHEELARCH REAR RH	\$	SL	543.47		
36	1	TAILLAMP RH	\$	SL	552.55		
37	1	TAILLAMP PANEL RH	\$	N	986.70		
38	1	TAILLAMP LH	\$	SL	552.55		
39	1	TAILLAMP PANEL LH	\$	N	986.70		
40	1	OUTER PANEL REAR (End Panel)	\$	B, N	1,471.77	}	X
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	SL	404.56		
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	N	2,189.88		
43	1	SPARE WHEEL PANEL TRIM	\$	SL	612.21		
44	1	EXHAUST REAR	\$	N	7,489.05		
45	1	EXHAUST CAP REAR	\$	N	230.49		
46	1	BUMPER COVER FRT	\$	N	1,259.42		
47	1	BUMPER SPOILER FRT	\$	SL	181.75		
48	1	BUMPER ABSORBER FRT	\$	SL	394.68	}	X
49	1	BUMPER RETAINER FRT LH	\$	SL	151.41		
50	1	BUMPER SUPPORT FRT	\$	SL	123.88		
51	1	BUMPER RETAINER FRT RH	\$	SL	150.77		
52	1	BUMPER SUPPORT FRT	\$	SL	123.88		
53	1	BUMPER UNDERTRAY FRT	\$	SL	472.83		
54	1	BUMPER GRILLE LOWER FRT	\$	SL	266.80		
55	1	BUMPER FOG LAMP GRILLE LH	\$	SL	207.21		
56	1	BUMPER FOG LAMP GRILLE RH	\$	SL	207.21		
57	1	BUMPER BEAM FRT	\$	N	914.08		
58	1	TOW COVER FRT	\$	SL	28.61		
59	1	RADIATOR GRILLE	\$	SL	1,707.78		
60	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	SL	225.36		
61	1	RADIATOR GRILLE FRAME	\$	SL	1,353.75		
62	1	FRAME FULL SUPPORT PANEL	\$	SL	615.90		
63	1	FRAME FULL SUPPORT BRACKET	\$	N	89.79		
64	1	FRONT BRACE PANEL	\$	N	177.22		
65	1	HORN	\$	SL	314.17		
66	1	HORN BRACKET	\$	N	40.45		
67	1	HEADLAMP LH	\$	SL	1,184.43		
68	1	HEADLAMP RH	\$	SL	1,184.43		

Trans-cab Auto Services Pte Ltd**AAD1905-257**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 381J

69	1	HEADLAMP PANEL FRT LH	\$	152.15
70	1	HEADLAMP PANEL FRT RH	\$	152.15
71	1	BONNET	\$	1,941.63
72	1	BONNET INSULATOR	\$	405.73
73	1	BONNET STRUT LH	\$	88.61
74	1	BONNET STRUT RH	\$	88.61
75	1	BONNET HINGE LH	\$	348.31
76	1	BONNET HINGE RH	\$	348.31
77	1	BONNET LOCK	\$	305.48
78	1	BONNET CABLE	\$	119.19
79	1	BONNET CABLE COVER	\$	161.03
80	1	BONNET SEAL OUTER	\$	92.36
81	1	BONNET SEAL INNER	\$	157.28
82	1	FENDER PANEL FRT LH	\$	783.83
83	1	WHEELARCH FRT LH	\$	278.84
84	1	FENDER BRACKET LOWER LH	\$	15.79
85	1	FENDER INSULATOR LH	\$	130.84
86	1	FENDER INSULATOR RH	\$	130.84
87	1	FENDER PANEL FRT RH	\$	783.83
88	1	WHEELARCH FRT RH	\$	278.84
89	1	FENDER BRACKET LOWER RH	\$	15.79
90	1	WIPER RESERVOIR	\$	348.25
91	1	WIPER RESERVOIR NECK	\$	136.11
92	1	WIPER RESERVOIR MOTOR	\$	270.06
93	1	AIR CLEANER LOWER	\$	271.26
94	1	AIR CLEANER HOSE	\$	76.14
95	1	BASE BATTERY TRAY	\$	363.40
96	1	AIR CLEANER BOX	\$	464.20
97	1	TURBO DUCT	\$	1,027.80
98	1	A/C HEATER VALVE	\$	484.50
99	1	SUBFRAME OUTER FRT	\$	2,652.45
100	1	SUBFRAME BRACKET OUTER LH	\$	92.36
101	1	SUBFRAME BRACKET OUTER RH	\$	92.36
102	1	ENGINE UNDERTRAY	\$	564.98
103	1	A/C CONDENSER	\$	2,020.37
104	1	A/C CONDENSER GARNISH LH UPPER	\$	39.67
105	1	A/C CONDENSER GARNISH RH UPPER	\$	39.67
106	1	A/C CONDENSER GARNISH LH	\$	58.81

X Sec

Trans-cab Auto Services Pte Ltd**AAD1905-257**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 381J

107	1	A/C CONDENSER GARNISH RH	\$	59.60
108	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	208.39
109	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	658.72
110	1	A/C PIPE COMPRESSOR	\$	334.29
111	1	A/C PIPE	\$	658.72
112	1	A/C COMRPESSOR	\$	2,684.61
113	1	AIR COOLER	\$	792.60
114	1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13
115	1	AIR INTERCOOLER HOSE (Short)	\$	375.14
116	1	TRANSMISSION COOLER	\$	1,219.30
117	1	TRANSMISSION COOLER PAD	\$	17.96
118	1	RADIATOR	\$	1,202.20
119	2	RADIATOR STUD UPPER	\$	14.41
120	2	RADIATOR BUSH UPPER	\$	50.12
121	2	RADIATOR MTG LOWER	\$	55.85
122	1	RADIATOR FAN COWLING	\$	820.54
123	1	RADIATOR FAN MOTOR LH	\$	967.36
124	1	RADIATOR FAN MOTOR RH	\$	1,479.46
125	1	RADIATOR TANK	\$	324.62
127	1	RADIATOR HOSE UPPER	\$	240.56
128	1	RADIATOR HOSE LOWER	\$	491.18
129	1	RADIATOR TANK HOSE	\$	61.18

X Sn

TOTAL	\$	76,757.50
10%	\$	7,675.75
	\$	69,081.75

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	na	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	na	24.20	X

Trans-cab Auto Services Pte Ltd**AAD1905-257**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 381J

12	1	BOOT INNER TRIM CLIP	\$	na	45.00	}	X
13	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00		
14	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00		
15	1	FENDER INNER TRIM CLIP LH	\$	na	28.00		
16	1	FENDER INNER TRIM CLIP RH	\$	na	28.00		
17	1	TAILLAMP CLIP RH	\$	na	5.00		
18	1	TAILLAMP CLIP LH	\$	na	5.00		
19	2	REAR WINDSCREEN SEALANT	\$	na	80.00		
20	1	WINDSCREEN MOULDING	\$	na	100.00		
21	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00		
22	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	}	X
23	1	SPARE TYRE	\$	sn	330.00		
24	1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00		
25	1SET	BUMPER CLIP FRT	\$	na	66.00		
26	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00		
27	1	BUMPER SUPPORT CLIP FRT LH	\$	sn	10.50		
28	1	BUMPER BRACKET CLIP FRT RH	\$	sn	12.00		
29	1	BUMPER SUPPORT CLIP FRT RH	\$	sn	10.50		
30	1	TOW COVER FRT	\$	sn	14.50		
31	1SET	RADIATOR GRILLE SCREW	\$	na	16.00		
32	1SET	BUMPER GRILLE LOWER CLIP	\$	sn	69.00	}	X
33	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	sn	70.00		
34	2	FRAME FULL SUPPORT PANEL NUT	\$	sn	20.00		
35	2	FRAME FULL SUPPORT PANEL STUD	\$	sn	30.00		
36	1	Windscreen moulding	\$	sn	100.00		
37	1	FRONT WINDSCREEN SEALANT	\$	sn	253.80		
38	1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	sn	100.00		
39	1SET	Front licence plate with holder	\$	Rel	80.00		
40	1	WHEELARCH CLIP FRT LH	\$	na	30.50		
41	1	WHEELARCH CLIP FRT RH	\$	na	30.50		
42	2	BONNET STRUT L70Y	\$	sn	88.61	}	X
43	6	BONNET INSULATOR CLIP L70Y	\$	na	7.30		
44	2	BONNET CABLE COVER SCREW L70Y	\$	na	10.85		
45	2	BONNET CABLE CLIP L70Y	\$	na	6.31		
46	1	BOOT STICKER "Trans-cab"	\$	na	30.00		
47	1	BOOT STICKER "6555-3333"	\$	na	30.00		
TOTAL			\$		3,315.40		

Trans-cab Auto Services Pte Ltd**AAD1905-257**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 381J

To supply and re-do rear luggage floor panel insulation padding.	\$	un	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	5	380.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	5	380.00	X
To repair and realign rear exhaust pipe.	\$	5	170.00	X
To check steering geometry and computer wheel alignment	\$	7	220.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	5	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	5	380.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	5	340.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	L	180.00	X
To transfer of front bonnet fittings, attachment and perform water seepage test.	\$	5	180.00	X
To replace, refix and top up coolant for radiator.	\$	L	170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	5	180.00	X
To transfer of front windscreen fittings and conduct water seepage test.	\$	5	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	5	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1905-257**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 381J**TOTAL PARTS \$ 72,397.15****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	4401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	4001
To Rust-Proofing Of The Affected Areas.	\$	~ 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	~ 380.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To vacuum, replace, refix and recharge air condenser	\$	~ 380.00	X

Trans-cab Auto Services Pte Ltd

AAD1905-257

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 381J

TOTAL	\$	20,800.00
-------	----	-----------

Over All Total	\$	93,197.15
----------------	----	-----------

Repair Days (PART BY PART)

~~30~~ DAYS

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To reserve before the work is done
- To handle damages and to reserve
- Parts and materials
- To handle the work and to reserve
- To handle the work and to reserve
- To handle the work and to reserve
- To handle the work and to reserve
- To handle the work and to reserve

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19009591/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-06-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3767B	Veh. Inspected	SHD 381J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003540MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	29/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VF1ABL15AUC282354	Colour	METALLIC WHITE / RED	
Odometer	426669	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/05/2019	Inspection Date	30/05/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 8

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 381J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	CRACKED / DENTED	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	DISTORTED	225.95	225.95
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE "RENAULT"	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	TO REPAIR SEE LABOUR	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-

Report Ref No. CS/FCI19009591/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	BUMPER COVER FRT	TO REPAIR SEE LABOUR	1,259.42	-
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-

Report Ref No. CS/FCI19009591/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE "RENAULT"	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	HORN	SERVICEABLE	314.17	-
1	HORN BRACKET	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH	SERVICEABLE	1,184.43	-
1	HEADLAMP RH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	SERVICEABLE	152.15	-
1	HEADLAMP PANEL FRT RH	SERVICEABLE	152.15	-
1	BONNET	SERVICEABLE	1,941.63	-
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	SERVICEABLE	348.31	-
1	BONNET HINGE RH	SERVICEABLE	348.31	-
1	BONNET LOCK	SERVICEABLE	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	FENDER PANEL FRT LH	SERVICEABLE	783.83	-
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-

Report Ref No. CS/FCI19009591/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	FENDER PANEL FRT RH	SERVICEABLE	783.83	-
1	WHEELARCH FRT RH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	WIPER RESERVOIR	SERVICEABLE	348.25	-
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	AIR CLEANER HOSE	SERVICEABLE	76.14	-
1	BASE BATTERY TRAY	SERVICEABLE	363.40	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	TURBO DUCT	SERVICEABLE	1,027.80	-
1	A/C HEATER VALVE	SERVICEABLE	484.50	-
1	SUBFRAME OUTER FRT	SERVICEABLE	2,652.45	-
1	SUBFRAME BRACKET OUTER LH	SERVICEABLE	92.36	-
1	SUBFRAME BRACKET OUTER RH	SERVICEABLE	92.36	-
1	ENGINE UNDERTRAY	SERVICEABLE	564.98	-
1	A/C CONDENSER	SERVICEABLE	2,020.37	-
1	A/C CONDENSER GARNISH LH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH	SERVICEABLE	59.60	-
1	A/C PIPE CONDENSER TO COMPRESSOR	SERVICEABLE	208.39	-
1	A/C PIPE CONDENSER TO EXPENSION VALVE	SERVICEABLE	658.72	-
1	A/C PIPECOMPRESSOR	SERVICEABLE	334.29	-
1	A/C PIPE	SERVICEABLE	658.72	-
1	A/C COMPRESSOR	SERVICEABLE	2,684.61	-
1	AIR COOLER	SERVICEABLE	792.60	-
1	AIR INTERCOOLER HOSE (LONG)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT)	SERVICEABLE	375.14	-
1	TRANSMISSION COOLER	SERVICEABLE	1,219.30	-

Report Ref No. CS/FCI19009591/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TRANSMISSION COOLER PAD	SERVICEABLE	17.96	-
1	RADIATOR	SERVICEABLE	1,202.20	-
2	RADIATOR STUD UPPER	SERVICEABLE	14.41	-
2	RADIATOR BUSH UPPER	SERVICEABLE	50.12	-
2	RADIATOR MTG LOWER	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	-
1	RADIATOR TANK	SERVICEABLE	324.62	-
1	RADIATOR HOSE UPPER	SERVICEABLE	240.56	-
1	RADIATOR HOSE LOWER	SERVICEABLE	491.18	-
1	RADIATOR TANK HOSE	SERVICEABLE	61.18	-
	LESS 10% DISCOUNT		-7,675.75	-435.25
			69,081.75	3,917.29
<u>SPECIAL NETT ITEMS</u>				
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-

Report Ref No. CS/FCI19009591/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547)(SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-
1	SET BUMPER CLIP FRT (SN)	NOT NECESSARY	66.00	-
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	253.80	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	DENTED	80.00	45.00
1	WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	30.50	-
2	BONNET STRUT L70Y (SN)	SERVICEABLE	88.61	-
6	BONNET INSULATOR CLIP L70Y (SN)	NOT NECESSARY	7.30	-
2	BONNET CABLE COVER SCREW L70Y (SN)	NOT NECESSARY	10.85	-
2	BONNET CABLE CLIP L70Y (SN)	NOT NECESSARY	6.31	-
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
			3,315.39	210.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		7,500.00	440.00

Report Ref No. CS/FCI19009591/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME. }		7,500.00	400.00
	INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR,BOOT REAR,BOOT HINGE LH,BOOT HINGE RH,BOOT SWITCH,BOOT LOCK,BOOT LOCK CATCH,FENDER PANEL REAR LH,FENDER PANEL REAR RH,TAILLAMP PANEL RH,TAILLAMP PANEL LH,SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL),EXHAUST REAR,EXHAUST CAP REAR,BUMPER COVER FRT,BUMPER BEAM FRT,FRAME FULL SUPPORT BRACKET,FRONT BRACE PANEL AND HORN BRACKET. }		-	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT,VACUUM AND CHARGE-IN-GAS.	NOT NECESSARY	380.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-

Report Ref No. CS/FCI19009591/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:8 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	340.00	-
	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	-
	TO TRANSFER OF FRONT BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	-
	TO REPLACE, REFILL AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	-
	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
			20,800.00	920.00
GRAND TOTAL			93,197.14	5,047.29
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,050.00

Report Ref No. CS/FCI19009591/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.