

ASS. REC. BY:

REF: CS/SMD 11009603/ Ksd3n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Agnus Chan Shu Hui of SMD Date/Time: 30.5.19 14:20pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJG 4823K Insured: XD 8817C

at Workshop m/s NGS Motorsport Tel: 96955547

of BIK-10 AMK Ind PK 2A

Policy No: DQ MTHCVE000643 Claim No: CMTD1901483

Sum Insured: Excess:

Make of Veh: D.O.A. 21.3.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 30.5.19 2:30pm Person Contacted: Evelyn NG Vehicle IN/OUT

Date/Time	Action/Instruction Estimate (✓)
	SJG 4823K - ✓
	XD 8817C

ABS. REG. BY:

REF: SMO

ASSIGNMENT

From:

Date:

4/6/2019

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJG 4823K

at Workshop m/s

NGS Motorsports

of Blk 10 Amk Ind. park 2A #02-01

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{Imp}

6/23

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJG 4823K

Yr Regn:

07/08

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

MPV

Make:

Honda Stream

c.c

1799

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp Reading

175767

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RNG 106P063

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ NH / S/Rim / STD A/Rim or

Tyre Size:

Triangle 205/55R16
Hankook

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

6

mm

L/Bal.

8

mm

L/Bal.

6

mm

D.O.A.

22/3/19

D.O.I.

4/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/6

11pm @ 27501 email Cakob
(@ 1.313.28 Red - 32%)

RECEIVED 07 JUN 2019

date of Accident 21/3/2019

Date/Time, File Pass to?

07/06/19

1)

Typist



: Preli. Report



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

Survey Fee:

Transportation:

\$ + RS: \$1

Photos

Other:

TOTAL

250

11

261

Report Format:

Lump Sum / L.B.F: (\$ 2,750/- 45)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 07 Jun 2019

Preliminary Advice

Insured Vehicle No	: XD8817C	Accident Date	: 21/03/2019
TP Vehicle No	: SJG4823K	Assignment Date	: 30/05/2019
Make	: HONDA STREAM	Est. Duration of Repair	: 6 days
Date of Inspection	: 04/06/2019		
Inspection At	: Ngs Motorsport Pte Ltd (HQ) Blk 10 Ang Mo Kio Ind Pk 2A, #05-18 AMK AutoPoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,063.28
Revised Amount	:S\$	3,427.04
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,427.04

Lump Sum Repair	:S\$	2,750.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Mar 2019		30 May 2019 14:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CA TRANSPORTATION & WAREHOUSING PTE LTD, Co. Reg. No.: 199200740D								
Main Claimant:	MARIC & ASSOCIATES PTE LTD, Co. Reg. No.: 201828898W								
Vehicle Reg. No.:	SJG4823K	Date of Loss:	21/03/2019 22:00 - :59						
Claim Type:	TP / CMTD1901483	Policy/Cover Note No.:	D18MTHCVE000643 (Comprehensive)						
Vehicle Reg. No. (Insured):	XD8817C	Policy No. (Claimant):							
		Excess:							
Repairer:	Ngs Motorsport Pte Ltd (HQ) Blk 10 Ang Mo Kio Ind Pk 2A, #05-18 AMK AutoPoint, 568047 Ang Mo Kio - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/06/2019]								
Driver/Custodian (Insured):	CHEW SOI LIANG (), NRIC: S0179733F, Tel: +6584363955 Email:								
Adj Asg. Remarks:	EVELYN NG 96955547								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
☐ ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Thursday, 6 June 2019 3:44 PM
To: Shirley Hiew (LKK Auto)
Subject: FW: Finalised for SJG 4823K

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Evelyn Ng <evelynnngstrading@gmail.com>
Sent: Thursday, 6 June 2019 12:04 PM
To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Subject: Re: Finalised for SJG 4823K

Hi Kenneth,

Confirm @\$2750 & 6 working days . Thank you.

NGS Trading
Evelyn Ng
Blk 10 Ang Mo Kio Ind Park 2a
#02-01 AMK AutoPoint
Singapore 568047
Tel : 64815727
Fax: 64815772

On 6 Jun 2019, at 08:25, Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com> wrote:

Attach finalised for SJG 4823K. Kenneth
<SJG 4823K.pdf>

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047

Tel :9695 5547 Fax: 6481 5727 e-mail : evelynngstrading@gmail.com

Reg No: 201812604N

Your Ref: CMTD1901483/AGC

Our Ref: MS20180426

Sompo Insurance Singapore Pte Ltd

50 Raffles Place,

#05-01/06 Singapore Land Tower

Singapore 048623

Attn: Motor Claims Dept

Not Authorized
11 Sep @ 2750h
Resurvey After Paint
6day

Dear Sir,

RE: Accident on 22/03/2019@22:30Hrs

Involving SJG4823K & XD8817C

Claims Against Veh XD8817C

We submit herewith our direct claim estimate quotation as follow:-

Replacement parts - Honda Stream

1	Frt Door Assy RH	894.50	B	\$	922.20	✓
1	Rear Door Assy RH		B	\$	897.80	✓
1	Side Mirror RH		CM	\$	481.80	✓
1	Side Mirror Glass RH		RM	\$	58.60	x
2	Frt Door Sticker RH/LH		RM	\$ 48.60	\$ 97.20	✓
1	Frt Fender RH - Repair					
1	Rear Fender RH - Repair					
2	Frt Door Sticker RH/LH		RP	\$	97.20	

To remove all damaged part with all necessary component/attachment

Straighten chassis member, repair/reshape dented body panel..

Replace damaged part. Refit into position.

To spray paint replace/repair body part

\$ 1,200.00 860

Transfer both Frt & Rr door mechanism.

\$ 200.00 120

\$ 4,063.28

Any other parts which necessitate repair or renewal will incur additional charged.

Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully.

NGS MOTORSPORT PTE LTD

EVELYN NG

The Repairer of Motor Vehicle must Notify

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19009603/KSD3N2
Date: 10/06/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTHCVE000643
Claimant Vehicle No :	SJG4823K	Insured Vehicle No :	XD8817C
Date of Loss:	21/03/2019	Nature of Claim:	TP
		Claim No:	CMTD1901483

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJG4823K	Engine No:	R18A1776528
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	RN61069063
Reg. Date:	01/07/2008 (Man. Year: 2008)	Odometer:	175767 km
Colour:	Metallic Silver		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Triangle 8 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Triangle 8 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,063.28	1,897.04	166.24	8.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,530.00	470.00	23.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,063.28	3,427.04	636.24	15.66
Approved Total (Overridden) (S\$)		2,750.00		
Nett Amount (S\$)	4,063.28	2,750.00	1,313.28	32.32

INSPECTION

Date of Assignment:	30/05/2019	
Date Inspected:	04/06/2019	Inspected At:
		Ngs Motorsport Pte Ltd (HQ)
		Blk 10 Ang Mo Kio Ind Pk 2A, #05-18
		AMK AutoPoint
		Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jun 2019)
Parts:	M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG4823K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR ASSY RH	Bent	922.20 FL	*894.50 FL
2	1		*REAR DOOR ASSY RH	Bent	897.80 FL	*897.80 FL
3	1		*SIDE MIRROR RH	Cracked	481.80 FL	*481.80 FL
4	1		*SIDE MIRROR GLASS RH	Serviceable	58.60 FL	*- FL
5	2		*FRT DOOR STICKER RH/LH	Necessary	97.20 FL	*97.20 FL
6	1		*FRT FENDER RH (NPA)	Repair	0.00 FL	*- FL
7	1		*REAR FENDER RH (NPA)	Repair	0.00 FL	*- FL
8	2		*FRT DOOR STICKER RH/LH	Repeated	97.20 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,554.80	2,371.30
- List Item Discount on L Items 20.00/20.00% (S\$)	491.52	474.26
Total Parts (S\$)	2,063.28	1,897.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL DAMAGED PART WITH ALL NECESSARY COMPONENT/ATTACHMENT.STRAIGHTEN CHASSIS MEMBER,REPAIR/RESHAPE DENTED BODY PANEL.REPLACE DAMAGED PART,REFIT INTO POSITION.	New	600.00	550.00
2	TO SPRAY PAINT REPLACE/REPAIR BODY PART	New	1,200.00	860.00
3	TRANSFER BOTH FRT & RR DOOR MECHANISM	New	200.00	120.00
Gross Labour Cost (\$\$)			2,000.00	1,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >