



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 1583B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	LH FRONT FENDER (N) (CONSISTENT)	BENT	504.70	504.70
1	LH FRONT FENDER UNDERSHIELD (N) (CONSISTENT)	BUCKLED	200.19	200.19
1	LH FRONT FENDER SIGNAL LAMP (N) (CONSISTENT)	SERVICEABLE	48.50	-
1	LH FRONT DOOR (N) (CONSISTENT)	BENT	1,219.70	1,219.70
1	LH FRONT DOOR HINGE TOP (N) (CONSISTENT)	TO REPAIR SEE LABOUR	65.10	-
1	LH FRONT DOOR HINGE BOTTOM (N) (CONSISTENT)	SERVICEABLE	65.10	-
1	LH FRONT DOOR LOCK (N) (CONSISTENT)	TO REPAIR SEE LABOUR	166.70	-
1	LH FRONT DOOR CATCH (N) (CONSISTENT)	TO REPAIR SEE LABOUR	35.00	-
1	LH FRONT DOOR CHECKER (N) (CONSISTENT)	SERVICEABLE	50.70	-
1	LH FRONT DOOR WEATHERSTRIP (N) (CONSISTENT)	SERVICEABLE	91.80	-
1	LH FRONT DOOR TRIM (N) (CONSISTENT)	SERVICEABLE	481.70	-
1	LHF DOOR OUTER HANDLE (N) (CONSISTENT)	SERVICEABLE	204.70	-
1	LHF DOOR GLASS OUTER MOULDING (N) (CONSISTENT)	SERVICEABLE	95.10	-
1	LHF POWER WINDOW MOTOR (N) (CONSISTENT)	SERVICEABLE	524.40	-
1	LHF POWER WINDOW REGULATOR (N) (CONSISTENT)	SERVICEABLE	85.50	-
1	LH ROCKER PANEL (N) (CONSISTENT)	TO REPAIR SEE LABOUR	1,209.90	-
1	LH FRONT HUP CAP (N) (CONSISTENT)	SERVICEABLE	138.80	-
1	LH REAR HUP CAP (N) (CONSISTENT)	DENTED	138.80	138.80
1	TAIL LAMP LH (N) (CONSISTENT)	CRACKED	236.50	236.50
10	TAIL LAMP CLIP (N) (CONSISTENT)	NECESSARY	100.00	100.00
	LESS 10% DISCOUNT		-566.29	-239.99
			5,096.60	2,159.90
<b><u>SPECIAL NETT ITEMS</u></b>				
10	LH FRONT FENDER UNDERSHIELD CLIP (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	LH FRONT DOOR COMPANY STICKER (SN) (CONSISTENT)	NECESSARY	20.00	20.00
			55.00	55.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA .(LHF FENDER,LHF DOOR ,LHR DOOR,LH SIDE SKIRT,LHR FENDER ,REAR BUMPER).INCLUSIVE OF THE REPAIR OF LH FRONT DOOR HINGE TOP ,LH FRONT DOOR LOCK,LH FRONT DOOR CATCH AND LH ROCKER PANEL .		1,200.00	700.00
	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(LHF FENDER ,LHF DOOR ,LHR DOOR,LH SIDE SKIRT,LHR FENDER ,REAR BUMPER).		1,400.00	1,000.00
	TO CHECK WIRING .		50.00	20.00
	TO REMOVE & REFIT DOOR TRIM ,DOOR GLASS ,WINDOW REGULATOR ,DOOR LOCK TO ASSIST WORK LOAD.}		150.00	60.00
	TO REMOVE & REFIT DOOR GLASS.}		120.00	-
	TO DO WHEEL ALIGNMENT .		120.00	60.00
	TO REMOVE & REFIT INNER SEAT & UPHOLSTERY TO ASSIST WORK LOAD.		250.00	80.00
	TO TUFF COAT.		150.00	60.00
	TO DO ART WORK.	NOT NECESSARY	150.00	-
			3,590.00	1,980.00
	<b>GRAND TOTAL</b>		<b>8,741.60</b>	<b>4,194.90</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,194.90</b>

Report Ref No. CC4/ASM19009612/Kes3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.