

Date: 3/13/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65 6484 1221 Fax: +65 6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **GBJ 1583 B**
Make & Model : **NISSAN NV200**
Chassis No : **VSKYBAM20Z0174574**

Submit By : **Carmen Lim**
Year Manufacture : **2018**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front fender	1	\$504.70	N	✓
2	LH front fender undershield	1	\$200.79	N	✓
3	LH front fender undershield clip	10	\$35.00	N	✓
4	LH front fender signal lamp	1	\$48.50	N	X
5	LH front door	1	\$1,219.70	N	✓
6	LH front door company sticker	1	\$20.00	N	✓
7	LH front door hinge top	1	\$65.10	N	X
8	LH front door hinge bottom	SVC	\$65.10	N	X
9	LH front door lock	1	\$166.70	N	X
10	LH front door catch	1	\$35.00	N	X
11	LH front door checker	1	\$50.70	N	X
12	LH front door weatherstrip	SVC	\$91.80	N	X
13	LH front door trim	1	\$481.70	N	X
14	LHF door outer handle	1	\$204.70	N	X
15	LHF door glass outer moulding	1	\$95.10	N	X
16	LHF power window motor	SVC	\$524.40	N	X
17	LHF power window regulator	SVC	\$85.50	N	X
18	LH rocker panel	1	\$1,209.90	N	X
19	LH front hup cap	1	\$138.80	N	X
20	LH rear hup cap	1	\$138.80	N	✓
21	Tail lamp LH	1	\$236.50	N	✓
22	Tail lamp clip	10	\$100.00	N	✓
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

7399.90
LN: 75



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65 6484 1221 Fax: +65 6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : GBJ 1583 B Submit By : Carmen Lim
Make & Model : NISSAN NV200 Year of Manufacture : 2018

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (LHF FENDER,LHF DOOR,LHR DOOR, LH SIDE SKIRT,LHR FENDER,REAR BUMPER)	\$1,200.00	700
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (LHF FENDER,LHF DOOR,LHR DOOR, LH SIDE SKIRT,LHR FENDER,REAR BUMPER)	\$1,400.00	1000
3	To check Wiring	\$50.00	20
4	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$150.00	60
5	To remove & refit door glass	\$120.00	
6	To do wheel alignment	\$120.00	60
7	To remove & refit inner seal & upholstery to assist work load.	\$250.00	80
8	To tuff coat.	\$150.00	60
9	To do art work. Bill	\$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

1980