

Ax0-LKK



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

GBJ 1583 B

*Not Authorized
Primary Repair*

Parts	(a) Cost / List Price Items	_____
	Plus/Less	_____
	Total of Cost / List	_____
	(b) Nett Price Items	\$ 5,662.90
	Less 10%	\$ 566.29
	Total of Nett Item	\$ 5,096.61
	(c) Special Nett Items	\$ 55.00
Total Parts Cost		\$ 5,151.61
Labour		\$ 3,590.00
Total		\$ 8,741.61

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 31/5/19 at _____

Remarks By Surveyor

- (a) The repair of this vehicle is authorized / is not authorized until further notice.
- (b) Recommended Days of Repair : 06 day(s)
- (c) Resurvey : Required / Not Required Not Required
- (d) Excess : \$ _____
- (e) Signature of surveyor : Lc Date: 31/5/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **GBJ 1583 B**
Make & Model : **NISSAN NV200**
Chassis No : **VSKYBAM20Z0174574**

Submit By : **Carmen Lim**
Year Manufacture : **2018**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front fender	1	\$504.70	N	✓
2	LH front fender undershield	1	\$200.20	N	✓
3	LH front fender undershield clip	10	\$35.00	S.N	✓
4	LH front fender signal lamp	1	\$48.50	N	X
5	LH front door	1	\$1,219.70	N	✓
6	LH front door company sticker	1	\$20.00	S.N	✓
7	LH front door hinge top	1	\$65.10	N	X
8	LH front door hinge bottom	1	\$65.10	N	?
9	LH front door lock	1	\$166.70	N	X
10	LH front door catch	1	\$35.00	N	X
11	LH front door checker	1	\$50.70	N	X
12	LH front door weatherstrip	1	\$91.80	N	?
13	LH front door trim	1	\$481.70	N	X
14	LHF door outer handle	1	\$204.70	N	X
15	LHF door glass outer moulding	1	\$95.10	N	X
16	LHF power window motor	1	\$524.40	N	?
17	LHF power window regulator	1	\$85.50	N	?
18	LH rocker panel	1	\$1,209.90	N	X
19	LH front hup cap	1	\$138.80	N	X
20	LH rear hup cap	1	\$138.80	N	✓
21	Tail lamp LH	1	\$236.50	N	✓
22	Tail lamp clip	10	\$100.00	N	✓
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **GBJ 1583 B** Submit By : **Carmen Lim**
Make & Model : **NISSAN NV200** Year of Manufacture : **2018**

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (LHF FENDER,LHF DOOR,LHR DOOR, LH SIDE SKIRT,LHR FENDER,REAR BUMPER)	\$1,200.00	700
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (LHF FENDER,LHF DOOR,LHR DOOR, LH SIDE SKIRT,LHR FENDER,REAR BUMPER)	\$1,400.00	1000
3	To check Wiring	\$50.00	20
4	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$150.00	60
5	To remove & refit door glass	\$120.00	
6	To do wheel alignment	\$120.00	60
7	To remove & refit inner seat & upholstery to assist work load.	\$250.00	80
8	To tuff coat.	\$150.00	60
9	To do art work. Bill	\$150.00	7

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.