

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



RS AUTOMOTIVE PTE LTD

Workshop : Blk 3006 Ubi Road 1 #01-394 Singapore 408700
Mailing : 109 Pasir Ris Grove, #09-23 The Palette Singapore 518199
Tel No. : 67483032 Fax No. : 67499469
E-Mail : rsautomotive@yahoo.com.sg
Website : www.rsautomotive.com.sg
Tax Reg. No. : 201230654Z Buss. Reg. No. : 201230654Z

SEE FWA ELECTRONICS & ELECTRICAL ENGINEERING

Tax Invoice : 58359

Contact 67438814

Invoice Date : 14/05/2019
Vehicle Num : GBE 740 Y
Make/Model : NISSAN NV-350
Mileage(Km) :
POW/O/RO# :
Ref./Remark :

S/N	Quantity	Particular	Unit Price	Amount S\$
TOTAL COST OF REPAIR				21 100 00

SingDollars Twenty-Two Thousand Five Hundred Seventy-Seven Only

E & O E

Total S\$	21,100 00
GST @ 7% S\$	1,477 00
Amount Due S\$	22,577 00
=====	

Terms Cash

Customer's Signature/Co. Stamp

for RS AUTOMOTIVE PTE LTD

*Goods Sold are not refundable for cash
*Interest Rate of 1.5% per month will be imposed on overDue account(s)
*No Claim will be considered after 7 days from date of job



Practicing Management Consultant (PMC) of SBACC
Approved Training Organisation (ATO) of Workforce Singapore

No.25 Kaki Bukit Road 4
#06-46 Synergy @KB
Singapore 417800
Hotline: 6385 1171

Our reference: 19-4-8221

Date: 5/5/2019

INVOICE NO. 8221

See Fwa Electronics & Electrical Engineering
c/o RS Automotive Pte Ltd
3006 Ubi Road 1 #01-394
Kampong Ubi Industrial Estate
Singapore 408700

Registration No. GBE740Y

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$ 778.00
Total amount			<u>\$ 778.00</u>

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.

L. L. Tan (Ms)
Principal Consultant

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.iaconsultingsg.com

Our reference: 19-4-8221

Date: 5/5/2019

c/o RS Automotive Pte Ltd
3006 Ubi Road 1 #01-394
Kampong Ubi Industrial Estate
Singapore 408700

Dear Sirs

RE: Road Traffic Accident on 12/4/2019
See Fwa Electronics & Electrical Engineering

In accordance with your instructions received in this office on 15/4/2019, we made arrangements to examine the vehicle on 15/4/2019 at above-mentioned address. The following data was recorded:

Vehicle details

Make	Nissan	Registration	GBE740Y
Model	NV350	Chassis	JN1MC2E26Z0003150
Colour	Silver	Gearbox	Manual
Odometer	122472km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

Tyre Depths

Front left	195R15C	85% Yokohama
Front right	195R15C	85% Yokohama
Rear left	195R15C	85% Yokohama
Rear right	195R15C	85% Yokohama

Impact Direction & Area of Damage:



Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$21,100.00 and 14 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.iaconsultingse.com

Our reference 19-4-8221

Date 5/5/2019

Page 2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As Inspected	Repairer's Estimate	Our Adjustment
Nett Items:				
Front dashboard	1	refix	1041.40	0.00
Front head lamp @\$712.50 <i>LH X NN RH - CAA</i>	2	damaged	1425.00	1425.00 <i>248.8 -</i>
Front head lamp panel rh	1	damaged	322.00	322.00 <i>X Repair</i>
Front bumper fog lamp cover @\$107.80 <i>LH X NN RH - CAA</i>	2	damaged	215.60	215.60 <i>107.8 -</i>
Front bumper	1	damaged	688.90	688.90 <i>-</i>
Front bumper fog lamp @\$311.80	2	rh missing lh reuse	623.60	311.80 <i>-</i>
Front bumper side bracket @\$115.00	2	damaged	230.00	230.00 <i>X NN</i>
Front bumper side retainer @\$147.00	2	damaged	294.00	294.00 <i>65.6 -</i>
Front panel	1	damaged	1306.90	1306.90 <i>X Repair</i>
Front lower panel	1	damaged	315.00	315.00 <i>206.5 -</i>
Front corner panel @\$437.00	2	repair	874.00	0.00
Front bumper centre grille	1	damaged	455.10	455.10 <i>219.21</i>
Font radiator grille	1	damaged	476.50	476.50 <i>-</i>
Front radiator grille logo	1	necessary	45.60	45.60 <i>-</i>
Front side mirror assy rh	1	repair	552.40	0.00
Front door @\$1329.50	2	rh bent lh repair	2659.00	1329.50 <i>132.9</i>
Front door weatherstrip rh	1	ripped	175.80	175.80 <i>X NN</i>
Front door inner lock rh	1	serviceable	214.50	0.00
Front door hinge @\$108.10 rh	2	damaged	216.40	216.40 <i>98</i>
Front door trim board rh	1	serviceable	755.90	0.00
Front door pillar outer rh	1	repair	1157.10	0.00
Front door pillar inner rh	1	repair	476.50	0.00
Front step panel rh	1	repair	575.80	0.00
Front step panel cover side rh	1	damaged	202.60	202.60 <i>180.6</i>
Rear side panel rh	1	repair	2658.90	0.00
Sliding door rh	1	damaged	2114.00	2114.00 <i>1795.3</i>
Sliding door outer handle rh	1	damaged	240.72	240.72 <i>X NN</i>

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.iaconsulting.com

Our reference 19-4-8221

Date 5/5/2019

Sliding door rail rh	1	damaged	641.00	641.00	X NN
Aircon cooling coil	1	damaged	2181.50	2181.50	/
Inter cooler	1	damaged	2245.80	2245.80	/ 672.3
Inter cooler pipe	1	damaged	557.00	557.00	X NN
Power steering cooler	1	damaged	856.20	856.20	/ 735.52
Front fender rh	1	damaged	477.80	X 477.80	Repair
Front fender inner garnish rh	1	damaged	168.80	X 168.80	NN
Front air bag	1	damaged	2026.40	2026.40	/
Front safety belt rh	1	damaged	694.20	694.20	/
Front safety belt control unit	1	damaged	747.50	X 747.50	NN
Steering column	1	damaged	350.50	X 350.50	NN
Rear mudflap rh	1	damaged	147.70	X 147.70	NN
Front upper arm rh	1	rebuild	219.50	0.00	
Front lower arm rh	1	rebuild	290.70	0.00	
Front knuckle arm rh	1	rebuild	221.50	0.00	
Front shock absorber rh	1	rebuild	156.70	0.00	
Front aircon blower motor assy	1	malfunction	680.40	680.40	/
Sub- Total costs			32976.42	22140.22	12767.83
Percentage discount : 10%			3297.64	2214.02	
Sub-Total costs for parts			29678.78	19926.20	11491.05

Special Nett Items:

Front bumper clips @\$5.50	10	necessary	55.00	55.00	30
Front number plate	1	damaged	50.00	50.00	25
Front door LTA sticker rh	1	necessary	40.00	40.00	15
Front wheel rim @\$450.00	2	damaged	900.00	900.00	X NN
Front tyre @\$250.00	2	damaged	500.00	400.00	X NN
Sub-Total costs for parts			1545.00	1445.00	70

Parts Repair

*	*	*	0.00	0.00	
Sub- Total costs			0.00	0.00	
Total costs for parts			31223.78	21371.20	

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infomights International Services (Philippines) • IABN Pte Ltd
www.iaconsulting.sg.com

Our reference 19-4-8221

Date 5/5/2019

Page 3

Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	38	\$ 1,710.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$ 1,200.00
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$ 200.00
Remove / replace aircon condenser and refill aircon gas	\$ 45.00	2.5	\$ 112.50
Remove and rebuild front undercarriage works (left & right)	\$ 45.00	5	\$ 225.00
Transfer of existing front door mechanism to new door rh	\$ 45.00	1.8	\$ 81.00
Transfer of existing sliding door mechanism to new door rh	\$ 45.00	1.8	\$ 81.00
Specialist charges -Air bag reset	-	-	\$ 450.00
Wiring and bulb checking	\$ 45.00	0.5	\$ 22.50
Total labour cost			\$ 4,082.00

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and In-house@ IA Research Guidelines respectively.

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.iaconsulting.sg.com

Our reference 19-4-8221

Date 5/5/2019

Section C: Summary Table of Total Repair Cost

Description		Cost	
Damaged Parts Assessment (See section A)		\$21,371.20	
		\$4,274.24	
Further discount	20%		
Recommended cost of parts		\$17,096.96	(1)
Labour Cost Calculation (See section B)		\$4,082.00	(2)
Total Repair Cost (Round off to hundred)		\$21,100.00	(1) + (2)

We would recommend a sum of \$21,100.00 and 14 working days for repair.
No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.


Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)
B.Eng. (Hons, NUS)
Diploma.Mechanical Engineering
NTC-2 Automovite Technology
Sr.MIES, Institution of Engineers, Singapore (#20100091)
MATAI, Maryland Association of Traffic Accident Investigators
IAARS, International Association of Accident Reconstruction Specialists
PMC of Singapore Business Advisors & Consultants Council
ACTA certified Trainer, Singapore
SPRING- Recognised Certification for Management Consultants

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.iaconsulting.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Apr 2019 14:50		16 Apr 2019 10:27 Edit Adj Rpt	S\$11,350.00 Edit Estimates	S\$11,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHEN ZIFEI, ID: S2739016A			
Main Claimant:	SEE FWA ELECTRONICS & ELECTRICAL ENGINEERING, Co. Reg. No.: 21593200E			
Vehicle Reg. No.:	GBE740Y	Date of Loss:	12/04/2019 09:00 - :59 [43 Months and 17 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 590654	Policy/Cover Note No.:	B27633063SMP (Comprehensive) Coverage: 27/12/2018 - 26/12/2019	
Vehicle Reg. No. (Insured):	SKL8320E	Policy No. (Claimant):		
		Excess:	S\$700.00	
Repairer:	RS Automotive Workshop (HQ) 3066 Ubi Road 1, #01-394/384, 408700 Ubi - Tel: 67483032			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 29/05/2019]			
Driver/Custodian (Insured):	CHEN YINGLING (), NRIC: S8673572E Email:			
Adj Asg. Remarks:	SURVEY DISAGREE ON SJE - ASSIGN LKK. LIABILITY:DISPUTE. CONTACT:RICHARD 9182 6089 . on WP.			

ASSOCIATED MAIL RECEIVED
[View All](#) [Compose Case Mail](#)

- MSIG_SG (27/05/2019): Report Send Back Alerts - GBE740Y (TP)

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBE740Y (590654)**

[SKL8320E]

TP

SEE FWA ELECTRONICS & ELECTRICAL ENGINEERING

Apr 12 2019 9:00AM

[CHEN ZIFEI]




































RS Automotive Workshop
















































Upload Documents Upload Photos Compose New Letter














View View in Browser ▼

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
20	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
21	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
22	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
23	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
24	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
25	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
26	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
27	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
28	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
29	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
30	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
31	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
32	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
33	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
34	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
35	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
37	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
38	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
40	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
41	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
43	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
44	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
45	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
46	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
47	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
48	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
49	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
50	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
51	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
52	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
53	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
54	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
55	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
56	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
57	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
58	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
59	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
60	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
61	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
62	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
63	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
64	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
65	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
66	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
67	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
68	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
69	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
70	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
71	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
72	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
73	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
74	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
75	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
76	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
77	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
78	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
79	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
80	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
81	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
82	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
83	18/04/19 10:04	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	18/04/19 10:04	General View	 Load JPG	<input checked="" type="checkbox"/>
85	18/04/19 10:04	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
86	18/04/19 10:04	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/04/19 14:52	Notice of PRI	 Load PDF	
2	15/04/19 15:17	SKL8320E GIA Rpt	 Load PDF	
3	15/04/19 15:18	GBE740Y GIA Rpt	 Load PDF	
4	15/04/19 15:18	SURVEY DISAGREE ON SJE - ASSIGN LKK	 Load PDF	
5	15/04/19 15:18	TP LIST OF SURVEYOR	 Load PDF	
6	27/05/19 15:07	REPAIR BILL, SURVEY BILL, SURVEY REPORT	 Load PDF	
7	27/05/19 15:07	SURVEY PHOTOS 1	 Load PDF	
8	27/05/19 15:07	SURVEY PHOTOS 2	 Load PDF	
9	27/05/19 15:07	SURVEY PHOTOS 3	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/06/19 16:01	PRS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19006735/GTD3S2-1
Date: 28/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: B27633063SMP
Claimant Vehicle No: GBE740Y Insured Vehicle No: SKL8320E
Date of Loss: 12/04/2019 Nature of Claim: TP Claim No: 590654

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE740Y
Make & Model: NISSAN NV350, 2.5 5MT 5DR EURO V (A) Engine No: YD25355465A
Reg. Date: 26/08/2015 (Man. Year: 2014) Chassis No: JN1MC2E26Z0003150
Colour: Silver Odometer: 124472 km
Engine Capacity: 2488 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,223.78	11,561.05	19,662.73	62.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,082.00	2,672.50	1,409.50	34.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	35,305.78	14,233.55	21,072.23	59.68
Approved Total (Overridden) (S\$)		11,350.00		
Nett Amount (S\$)	35,305.78	11,350.00	23,955.78	67.85

INSPECTION

Date of Assignment: 16/04/2019
Date Inspected: 16/04/2019 Inspected At: RS Automotive Workshop (HQ)
3066 Ubi Road 1, #01-394/384
Singapore 408700
Estimated Period of Repair: 10.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Jun 2019)	
Parts:	N/A	NISSAN NV350 2.5 5MT 5DR EURO V (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE740Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DASHBOARD	Refix	1,041.40 FL	*- FL
2	1		*FRONT HEAD LAMP	N/s Not Necessary/O/s Cracked	1,425.00 FL	*348.80 FL
3	1		*FRONT HEAD LAMP PANEL RH	Repair	322.00 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP COVER	N/s Not Necessary/O/s Missing	215.60 FL	*107.80 FL
5	1		*FRONT BUMPER	Damaged	688.90 FL	*688.90 FL
6	1		*FRONT BUMPER FOG LAMP	O/s Missing / N/s Reuse	623.60 FL	*311.80 FL
7	2		*FRONT BUMPER SIDE BRACKET	Not Necessary	230.00 FL	*- FL
8	2		*FRONT BUMPER SIDE RETAINER	Damaged	294.00 FL	*65.60 FL
9	1		*FRONT PANEL	Repair	1,306.90 FL	*- FL
10	1		*FRONT LOWER PANEL	Damaged	315.00 FL	*206.50 FL
11	2		*FRONT CORNER PANEL	Repair	874.00 FL	*- FL
12	1		*FRONT BUMPER CENTRE GRILLE	Damaged	455.10 FL	*219.21 FL
13	1		*FRONT RADIATOR GRILLE	Damaged	476.50 FL	*476.50 FL
14	1		*FRONT RADIATOR GRILLE LOGO	Necessary	45.60 FL	*45.60 FL
15	1		*FRONT SIDE MIRROR ASSY RH	Repair	552.40 FL	*- FL
16	1		*FRONT DOOR	O/s Bent / N/s Repair	2,659.00 FL	*1,232.90 FL
17	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	175.80 FL	*- FL
18	1		*FRONT DOOR INNER LOCK RH	Serviceable	214.50 FL	*- FL
19	2		*FRONT DOOR HINGE	Damaged	216.40 FL	*98.00 FL
20	1		*FRONT DOOR TRIM BOARD RH	Serviceable	755.90 FL	*- FL
21	1		*FRONT DOOR PILLAR OUTER RH	Repair	1,157.10 FL	*- FL
22	1		*FRONT DOOR PILLAR INNER RH	Repair	476.50 FL	*- FL
23	1		*FRONT STEP PANEL RH	Repair	575.80 FL	*- FL
24	1		*FRONT STEP PANEL COVER SIDE RH	Damaged	202.60 FL	*180.60 FL
25	1		*REAR SIDE PANEL RH	Repair	2,658.90 FL	*- FL
26	1		*SLIDING DOOR RH	Damaged	2,114.00 FL	*1,795.30 FL
27	1		*SLIDING DOOR OUTER HANDLE RH	Not Necessary	240.72 FL	*- FL
28	1		*SLIDING DOOR RAIL RH	Not Necessary	641.00 FL	*- FL
29	1		*AIRCON COOLING COIL	Damaged	2,181.50 FL	*2,181.50 FL
30	1		*INTER COOLER	Damaged	2,245.80 FL	*672.30 FL
31	1		*INTER COOLER PIPE	Not Necessary	557.00 FL	*- FL
32	1		*POWER STEERING COOLER	Damaged	856.20 FL	*735.52 FL
33	1		*FRONT FENDER RH	Repair	477.80 FL	*- FL
34	1		*FRONT FENDER INNER GARNISH RH	Not Necessary	168.80 FL	*- FL
35	1		*FRONT AIR BAG	Damaged	2,026.40 FL	*2,026.40 FL
36	1		*FRONT SAFETY BELT RH	Damaged	694.20 FL	*694.20 FL
37	1		*FRONT SAFETY BELT CONTROL UNIT	Not Necessary	747.50 FL	*- FL
38	1		*STEERING COLUMN	Not Necessary	350.50 FL	*- FL
39	1		*REAR MUDFLAP RH	Not Necessary	147.70 FL	*- FL
40	1		*FRONT UPPER ARM RH	Rebuild	219.50 FL	*- FL
41	1		*FRONT LOWER ARM RH	Rebuild	290.70 FL	*- FL
42	1		*FRONT KNUCKLE ARM RH	Rebuild	221.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT SHOCK ABSORBER RH	Rebuild	156.70 FL	*- FL
44	1		*FRONT AIRCON BLOWER MOTOR ASSY	Malfunction	680.40 FL	*680.40 FL
45	10		*FRONT BUMPER CLIPS	Necessary	55.00 FS	*30.00 FS
46	1		*FRONT NUMBER PLATE	Damaged	50.00 FS	*25.00 FS
47	1		*FRONT DOOR LTA STICKER RH	Necessary	40.00 FS	*15.00 FS
48	2		*FRONT WHEEL RIM	Not Necessary	900.00 FS	*- FS
49	2		*FRONT TYRE	Not Necessary	500.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	34,521.42	12,837.83
- List Item Discount on L Items 10.00/10.00% (S\$)	3,297.64	1,276.78
Total Parts (S\$)	31,223.78	11,561.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS.	New	1,710.00	1,000.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL.	New	1,200.00	1,100.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS.	New	200.00	80.00
4	REMOVE / REPLACE AIRCON CONDENSER AND REFILL AIRCON GAS.	New	112.50	100.00
5	REMOVE AND REBUILD FRONT UNDERCARRIAGE WORKS (LEFT & RIGHT)	New	225.00	0.00
6	TRANSFER OF EXISTING FRONT DOOR MECHANISM TO NEW DOOR RH.	New	81.00	60.00
7	TRANSFER OF EXISTING SLIDING DOOR MECHANISM TO NEW DOOR RH.	New	81.00	60.00
8	SPECIALIST CHARGES - AIR BAG RESET.	New	450.00	250.00
9	WIRING AND BULB CHECKING.	New	22.50	22.50
Gross Labour Cost (\$\$)			4,082.00	2,672.50

Report was unsubmitted during this print-out.

< END OF ESTIMATES >