

22/03/2012

ASS. REC. BY:

REF: CS/MSG 190096 23/ Fvd302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Christine Wong

of MSG

Date/Time: 30.5.19 16.36 p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 9884R

Insured: GY 1427G

at Workshop m/s Trans - cab

Tel: 62130998

of 2 Amk Street 63

Policy No: 29067434

Claim No: 594895

Sum Insured:

Excess:

Make of Veh:

D.O.A 28.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 30.5.19 16.36 p.m

Person Contacted: Amanda

Vehicle IN / OUT

Date/Time	Action/Instruction Estimate (✓)
	SHD 9884R - X
	GY 1427R - X
3/6/19	Send preli revised via meimen

Surveyor

ASSIGNMENT

From: _____ Date: 31-5-2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHD 9884R

at Workshop m/s Trans-cab

of 2 Ang Nokio Street 63

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

"up"

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: S110 9884R Yr Regn: 05, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995

Colour: M. White / R/A/C: Insured / Std / NI / NA

Sp. Reading: 647566 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF1ABL15AUC 277540

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

R/Bal. 2 mm

Rear

R/Bal. 8 mm

L/Bal. 7 mm

L/Bal. 8 mm

D.O.A. 28/5/19

D.O.I. 31/5/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt & O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/7 L1 By 8940d to Limit. (Red 72,724.90, 8890)

RECEIVED 02 JUL 2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

2)

1/7-typist

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

300

11

311

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 May 2019		30 May 2019 16:36 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	YI CHUAN METAL WORKS, Co. Reg. No.: 50332400X		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD9884R	Date of Loss:	28/05/2019 13:00 - :59 [60 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 594895	Policy/Cover Note No.:	29067434 (TP, Fire & Theft) Coverage: 13/01/2019 - 31/08/2019
Vehicle Reg. No. (Insured):	GY1427G	Policy No. (Claimant):	
		Excess:	
Repairer:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 31/05/2019]		
Driver/Custodian (Insured):	NG BENG SOON (), NRIC: S1380160F, Tel: +6597560723 Email:		
Adj Asg. Remarks:	Car In. Liab: 100%. Est amt : \$82,124.90. Contact: Amanda @ 6213 0998. Please do not assign to AIS, as per workshop request. on WP. Please contact us ASAP if you cannot attend this assignment.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 03 Jun 2019

Preliminary Advice

Insured Vehicle No	: GY1427G	Accident Date	: 28/05/2019
TP Vehicle No	: SHD9884R	Assignment Date	: 30/05/2019
Make	: RENAULT LATITUDE	Est. Duration of Repair	: 4
Date of Inspection	: 31/5/2019		
Inspection At	: TRANS-CAB AUTO SERVICES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	82,124.90
Revised Amount	:S\$	11,775.32
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,775.32

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD9884R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 May 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001341
Chassis No.:	VF1ABL15AUC277540
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	09 May 2014
First Registration Date:	09 May 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 May 2022
PARF Rebate Amount:	\$8,748.00
Intended COE Rebate Details	
COE Expiry Date:	08 May 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$60,414.00
COE Rebate Amount:	\$22,209.00
Total Rebate Amount:	\$30,957.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 29 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	29/05/2019 10:37
Date Of Accident	28/05/2019 13:30
Exact Location Of Accident	WOODLANDS AVENUE 3
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHD9884R
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
Driver	
Name of Driver	IBRAHIM BIN ANWARUL
NRIC No	S1259344I
Date Of Birth	10/12/1957
Occupation	OUTDOOR
Date Of Driving Pass	13/06/1979
Driving Experience	39 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92778561
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 880 WOODLANDS STREET 82 #04-10
Postcode	730880
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NURHAWANIZAN BINTI ABDULLAH - 90906915 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT PANJANG NORTH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 27 MARSILING DRIVE , POSTCODE: 730027 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-3689999 - FAX NO: 63682383
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Please see the attach Police Report T/20190528/2186.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY1427G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	NG BENG SOON
NRIC/Passport Number	S1380160F

Contact Number 97560723
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name IBRAHIM BIN ANWARUL
Approximate Age
Injuries Sustain
Injured person in which vehicle? SHD9884R
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name NURHAWANIZAN BINTI ABDULLAH
Approximate Age
Injuries Sustain
Injured person in which vehicle? SHD9884R
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Amunda

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

A: 5HD9884R
B: GY14276T

woodland
Avenue 3

The diagram is a hand-drawn site plan on graph paper. It shows a building layout with two main rooms, A and B. Room A is a rectangle on the right, and Room B is a trapezoid to its left. Above Room A is a small rectangular area labeled 'A' with an arrow pointing up. Above Room B is a larger rectangular area labeled 'B' with an arrow pointing up. To the left of these rooms is a curved boundary line. Below the curved boundary is a road labeled 'woodland Avenue 3'. There are three vertical lines representing trees or poles along the road. The drawing is done in black ink on a grid background.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please see the attach police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Amada

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190528/2186

Police Station Of Origin:
Bukit Panjang North NPP
27 Marsiling Drive #01-237 SINGAPORE
730027
Tel No: 1800-3689999

4 of 4
Report No. T/20190528/2186

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: SN 127 L / Sgt 2 MOHAMED FAEZ BIN MOHAMED SAHID  Signature : _____	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 28/05/2019 19:55
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt ONG YONG HOCK Contact No.: 65476436	Classification Of Case:

Authentication Stamp
NP168



**SINGAPORE
POLICE FORCE**



T/20190528/2186

1 of 4

Police Station Of Origin:
Bukit Panjang North NPP
27 Marsiling Drive #01-237 SINGAPORE
730027
Tel No: 1800-3689999

Report No. T/20190528/2186

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/05/2019 19:55	Vide Report No.:	Station Diary No.: 24
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: IBRAHIM BIN ANWARUL		Address: APT BLK 880 WOODLANDS STREET 82 #04-10 SINGAPORE 730880	
ID Type / ID No.: NRIC NO / S1259344I		Contact No.: Home/Office: Mobile: 92778561	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 61	Date of Birth: 10/12/1957	Type of Informant: Driver
Race: Indian		Language: English	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 28/05/2019 13:30	Type of Location: Straight Road
Location: Along Road 1 WOODLANDS AVENUE 3 ALONG WOODLANDS AVE 3 AFTER THE JUNCTION OF WOODLANDS AVE 3 AND WOODLANDS AVE 5				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GY1427G	Lorry				Slightly Damaged	2
SHD9884R	TAXI				Seriously Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190528/2186

2 of 4

Police Station Of Origin:
Bukit Panjang North NPP
27 Marsiling Drive #01-237 SINGAPORE
730027
Tel No: 1800-3689999

Report No. T/20190528/2186

CONTINUATION OF REPORT

Driver			
Name	NG BENG SOON	ID No.	S1380160F
Related Vehicle	GY1427G (Lorry)	Contact No.	97560723
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	IBRAHIM BIN ANWARUL	ID No.	S1259344I
Related Vehicle	SHD9884R (TAXI)	Contact No.	92778561
Hospital/Clinic	HORIZON MEDICAL CENTRE	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	28/05/2019	Date Discharge	28/05/2019
No. of Days granted Medical Leave	07	Degree of Injury	Slight
Passenger			
Name	NURHAWANIZAN BINTI ABDULLAH	ID No.	S7821041I
Related Vehicle	SHD9884R (TAXI)	Contact No.	90906915
Hospital/Clinic	HORIZON MEDICAL CENTRE	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	28/05/2019	Date Discharge	28/05/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On 28/05/2019 at about 1320hrs, I was driving my taxi V1) SHD9884R. After picking up a passenger at Woodlands Causeway Point, I was headed towards Jurong West and was driving along Woodlands Ave 3.

After the junction of Woodlands Ave 3 and Woodlands Ave 5, I was on the right most lane of a 3 lane road going straight. When a lorry V2) GY1427G came from my left, (from the filter lane of Woodlands Ave 5) and inching closer to V1. Suddenly, V2 swerve into my lane and collided onto the front left side of V1. Subsequently, V1 and V2 stopped along the road. I got down from my taxi and discovered that my front left side of the taxi was heavily damage while V2 sustain scratches and dents on its right side.

Traffic Police and Ambulance was not at scene. No pedestrian/cyclist was involved. No Government



**SINGAPORE
POLICE FORCE**



T/20190528/2186

3 of 4

Police Station Of Origin:
Bukit Panjang North NPP
27 Marsiling Drive #01-237 SINGAPORE
730027
Tel No: 1800-3689999

Report No. T/20190528/2186

CONTINUATION OF REPORT

property was damaged. I wish to state that I have an in-car camera on my car.

Afterwards, my passenger and I went to a clinic as we suffered neck pain, back pain and swollen ankle. I was granted 7 days of MC while my passenger granted 5 days of MC.

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9884R

AAD1905-264

Not Wharfedale

11 Sep @ 940d

3/6/19

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 9884R

VF1ABL15AUC277540

RENAULT

LATITUDE

28.5.19

MSIG

9/5/2014

PART		LIST	
1	BUMPER COVER FRT	\$	CM 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	Or 181.75 ✓
1	BUMPER ABSORBER FRT	\$	Tu 394.68 ✓
1	BUMPER RETAINER FRT LH	\$	CM 151.41 ✓
1	BUMPER SUPPORT FRT	\$	SL 123.88 X
1	BUMPER UNDERTRAY FRT	\$	SL 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	SL 266.80 X
1	BUMPER FOG LAMP GRILLE LH	\$	SL 207.21 X
1	BUMPER BEAM FRT	\$	R 914.08 X
1	HEADLAMP LH	\$	CM 1,184.43 ✓
1	HEADLAMP PANEL FRT LH	\$	R 152.15 X
1	FENDER PANEL FRT LH	\$	R 783.83 ✓
1	WHEELARCH FRT LH	\$	MTR 278.84 ✓
1	FENDER BRACKET LOWER LH	\$	R 15.79 X
1	FENDER INSULATOR LH	\$	SL 130.84 X
1	FRONT BRACE PANEL	\$	R 177.22 X
1	RADIATOR GRILLE	\$	M3CM 1,707.78 ✓
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	R 225.36 ✓
1	RADIATOR GRILLE FRAME	\$	CM 1,353.75 ✓
1	FRAME FULL SUPPORT PANEL	\$	SL 615.90 X
1	FRAME FULL SUPPORT BRACKET	\$	R 89.79 X
1	BONNET	\$	R 1,941.63
1	BONNET INSULATOR	\$	SL 405.73
1	BONNET STRUT LH	\$	SL 88.61
1	BONNET STRUT RH	\$	SL 88.61
1	BONNET HINGE LH	\$	R 348.31
1	BONNET HINGE RH	\$	R 348.31
1	BONNET LOCK	\$	R 305.48
1	BONNET CABLE	\$	SL 119.19

Trans-cab Auto Services Pte Ltd**AAD1905-264**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9884R

1	BONNET CABLE COVER	\$	S ₂	161.03	X
1	BONNET SEAL OUTER	\$	S ₂	92.36	
1	BONNET SEAL INNER	\$	S ₂	157.28	
1	AIR CLEANER BOX	\$	S ₂	464.20	
1	AIR CLEANER HOSE	\$	S ₂	175.85	
1	AIR CLEANER LOWER	\$	S ₂	271.26	
1	AUTO COMPUTER	\$	S ₂	5,032.17	
1	INJECTION COMPUTER	\$	S ₂	4,706.30	
1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	S ₂	5,154.52	
1	STEERING PUMP ELECTRIC L70Y	\$	S ₂	2,306.90	
1	STEERING PINION RACK L70Y	\$	S ₂	4,413.11	
1	SUBFRAME OUTER FRT	\$	S ₂	2,652.45	
1	SUBFRAME BRACKET OUTER LH	\$	N	92.36	
1	SUBFRAME BRACKET OUTER RH	\$	N	92.36	
1	ENGINE UNDERTRAY	\$	S ₂	564.98	
1	RADIATOR FAN COWLING	\$	S ₂	820.54	X
1	RADIATOR FAN MOTOR LH	\$	S ₂	967.36	
1	RADIATOR FAN MOTOR RH	\$	S ₂	1,479.46	
1	DOOR PANEL FRT LH	\$	N	2,844.66	
1	DOOR HINGE UPPER LH	\$	N	261.28	
1	DOOR HINGE LOWER LH	\$	N	300.55	
1	DOOR CHECK FRT LH	\$	S ₂	194.77	
1	DOOR LOCK FRT LH	\$	N	908.75	
1	DOOR CATCH FRT LH	\$	S ₂	131.23	
1	DOOR HANDLE OUTER FRT LH	\$	S ₂	477.76	
1	DOOR HANDLE COVER FRT LH	\$	S ₂	13.22	
1	DOOR HANDLE MODULE FRT LH	\$	S ₂	133.60	
1	DOOR REGULATOR FRT LH	\$	N	505.19	
1	DOOR REGULATOR MOTOR FRT LH	\$	S ₂	796.46	
1	DOOR REGULATOR GUIDE FRT LH	\$	S ₂	120.97	
1	DOOR MOULDING FRONT LH	\$	S ₂	176.82	
1	DOOR FINISHER INNER FRONT LH	\$	S ₂	323.44	
1	DOOR FINISHER FRONT LH	\$	S ₂	423.10	
1	DOOR CASING FRONT LH	\$	S ₂	1,509.06	
1	DOOR GRAB HANDLE FRONT LH	\$	S ₂	210.96	
1	DOOR BLIND FRONT LH	\$	S ₂	741.80	
1	DOOR WHEATHESTRIIP FRONT LH	\$	S ₂	410.66	
1	DOOR SEAL FRONT LH	\$	S ₂	162.02	

Trans-cab Auto Services Pte Ltd

AAD1905-264

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9884R

1	DOOR GLASS RUNNER SEAL FRONT LH	\$	Sh	229.31	}	X	
1	DOOR WAIST SEAL OUTER FRONT LH	\$	Sh	334.69			
1	DOOR WAIST SEAL INNER FRONT LH	\$	Sh	115.64			
1	DOOR MIRROR ASSY LH	\$	Sh	1,483.40			
1	DOOR MIRROR GLASS LH	\$	Sh	148.20			
1	DOOR MIRROR BACK COVER LH	\$	Sh	218.46			
1	DOOR HARNESS WIRE LH	\$	Sh	2,670.00			
1	LOWER ARM LH L70Y	\$	Sh	685.76			
1	KNUCKLE ARM LH L70Y	\$	Sh	846.98			
1	ABSORBER FRT LH L70Y	\$	Sh	360.54			
1	DRIVESHAFT LH	\$	M	1,747.45			
1	STABILIZER BAR FRT	\$	Sh	604.65			
1	WHEEL HOUSING PANEL FRNT LH	\$	M	4,682.09			
TOTAL		\$		68,711.55			
10%		\$		6,871.16			
		\$		61,840.40			

Special Nett

1	BUMPER CLIP FRT	\$	M	66.00	}	X
1	BUMPER BRACKET CLIP FRT LH	\$	vn	12.00		
1	BUMPER SUPPORT CLIP FRT LH	\$	vn	10.50		
1	BUMPER GRILLE LOWER CLIP	\$	vn	69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	vn	70.00		
2	FRAME FULL SUPPORT PANEL NUT	\$	vn	20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	vn	30.00		
1	WHEELARCH CLIP FRT LH	\$	vn	30.50		
1	FRONT LEFT TYRE	\$	Sh	300.00		
1	FRONT LEFT TYRE RIM	\$	M	380.00		
1SET	Front licence plate with holder	\$	Sh	80.00	}	X
1	WINDSCREEN SEALANT	\$	vn	253.80		
1	FRONT WINDSCREEN MOULDING	\$	vn	120.00		
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	vn	100.00		
6	BONNET INSULATOR CLIP L70Y	\$	vn	7.30		
2	BONNET STRUT L70Y	\$	Sh	88.61		
2	BONNET CABLE CLIP L70Y	\$	vn	6.31		
2	BONNET CABLE COVER SCREW L70Y	\$	vn	10.85	}	
1SET	RADIATOR GRILLE FRAME CLIP	\$	vn	52.00		

Trans-cab Auto Services Pte Ltd

AAD1905-264

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9884R

1SET	RADIATOR GRILLE SCREW	\$	na	16.00	X
1	FRONT RIGHT TYRE	\$	sn	300.00	X
1	FRONT RIGHT TYRE RIM	\$	na	380.00	✓
1	FRONT DOOR STICKER 'Trans-Cab'	\$	na	80.00	6012
1	FRONT DOOR STICKER 'Classic'	\$	na	80.00	X
1	DOOR CHECK BOLT	\$	sn	22.69	} X
1	DOOR GUIDE SCREW	\$	sn	10.85	
1	DOOR HINGE BOLT	\$	sn	10.85	
1	DOOR HINGE NUT LH	\$	sn	14.60	
1	DOOR CHECK BOLT	\$	sn	22.69	
1	DOOR CHECK NUT	\$	sn	3.75	
1	DOOR LOCK SCREW L70Y	\$	sn	6.12	}
1	DOOR CATCH SCREW L70Y	\$	sn	10.06	
TOTAL		\$		2,664.51	
TOTAL PARTS		\$		64,504.90	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	501
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	na	380.00 X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	na	380.00 X
To transfer of front windscreen fittings and conduct water seepage test.	\$	na	170.00 X
To check steering geometry and computer wheel alignment	\$	220.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00 X

Trans-cab Auto Services Pte Ltd

AAD1905-264

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9884R

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	na 440.00 X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	na 380.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 401
Putty and spray painting of the affected portion.	\$	6,000.00 8801
To Check Electrical Lighting Concerned.	\$	170.00 201
To rust-proofing of the affected areas.	\$	170.00 601
To apply paint protection system (PPS) maintain and enhancement	\$	na 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00 X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	na 380.00 X
To remove and refit air bag system and reset vehicle warning indicators.	\$	na 480.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	na 380.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	na 380.00 X
To check ABS brake efficiency, final checking and testing.	\$	na 380.00 X

TOTAL \$ 17,620.00**Over All Total \$ 82,124.90****LUMP SUM (REPAIR DAY)****20 days****4 days**

LKK Auto Consultant to be notified

- To resurvey before commencing painting
- To display demand notice before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification is allowed
- Supplemental work is subject to the approval from insurance company

Acknowledged by Repairer

Date: / /

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 1 July 2019 4:54 PM
To: Ng Wai Yin; 'calvin.er@transcab.com.sg'
Cc: SUR; jasminetan@transcab.com.sg
Subject: FINALIZE (3 VEHICLES)
Attachments: SHC 5804D (MARKING) .pdf; SHD 5778R (MARKING).pdf; SHD 9884R (MARKING).pdf

Dear Wai Yin,

WITHOUT PREJUDICE

- 1) SHC 5804D-DOA:10/6/19, Lump Sum \$4700 @ 3 working days
- 2) SHD 5778R-DOA:8/6/19 , Finalize amount \$5467.15 @ 3 working days
- 3) SHD 9884R-DOA:28/5/19, Lump Sum \$9400 @ 4 working days (Provides us after paint photos)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 May 2019		30 May 2019 16:36 Edit Adj Rpt	S\$9,400.00 Edit Estimates	S\$9,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YI CHUAN METAL WORKS , Co. Reg. No.: 50332400X								
Main Claimant:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHD9884R	Date of Loss:	28/05/2019 13:00 - :59 [60 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 594895	Policy/Cover Note No.:	29067434 (TP, Fire & Theft) Coverage: 13/01/2019 - 31/08/2019						
Vehicle Reg. No. (Insured):	GY1427G	Policy No. (Claimant):							
		Excess:							
Repairer:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 29/06/2019]								
Driver/Custodian (Insured):	NG BENG SOON (), NRIC: S1380160F, Tel: +6597560723 Email:								
Adj Asg. Remarks:	Car In. Liab: 100%. Est amt : \$82,124.90. Contact: Amanda @ 6213 0998. Please do not assign to AIS, as per workshop request. on WP. Please contact us ASAP if you cannot attend this assignment.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHD9884R (594895)
[GY1427G]
TP
TRANS-CAB SERVICES PTE LTD
May 28 2019 1:00PM
[YI CHUAN METAL WORKS]
Trans-Cab Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print	
1	30/05/19 14:59	Accident Statement <small>From: SC - Reg. No: GY1427G, Claimant: YI CHUAN METAL WORKS</small>		Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	03/06/19 11:09	Adjuster Immediate Advice		Load HTM		

Photos/Images					3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	01/07/19 16:10	General View		Load JPG		<input checked="" type="checkbox"/>
2	01/07/19 16:10	General View		Load JPG		<input checked="" type="checkbox"/>
3	01/07/19 16:10	General View		Load JPG		<input checked="" type="checkbox"/>
4	01/07/19 16:10	General View		Load JPG		<input checked="" type="checkbox"/>
5	01/07/19 16:10	General View		Load JPG		<input checked="" type="checkbox"/>
6	01/07/19 16:10	General View		Load JPG		<input checked="" type="checkbox"/>
7	01/07/19 16:10	General View		Load JPG		<input checked="" type="checkbox"/>
8	01/07/19 16:10	General View		Load JPG		<input checked="" type="checkbox"/>
9	01/07/19 16:10	General View		Load JPG		<input checked="" type="checkbox"/>
10	01/07/19 16:10	General View		Load JPG		<input checked="" type="checkbox"/>
11	01/07/19 16:10	General View		Load JPG		<input checked="" type="checkbox"/>
12	01/07/19 16:10	General View		Load JPG		<input checked="" type="checkbox"/>
13	01/07/19 16:10	General View		Load JPG		<input checked="" type="checkbox"/>
14	01/07/19 16:11	General View		Load JPG		<input checked="" type="checkbox"/>
15	01/07/19 16:11	General View		Load JPG		<input checked="" type="checkbox"/>
16	01/07/19 16:11	General View		Load JPG		<input checked="" type="checkbox"/>
17	01/07/19 16:11	General View		Load JPG		<input checked="" type="checkbox"/>
18	01/07/19 16:11	General View		Load JPG		<input checked="" type="checkbox"/>
19	01/07/19 16:11	General View		Load JPG		<input checked="" type="checkbox"/>
20	01/07/19 16:11	General View		Load JPG		<input checked="" type="checkbox"/>
21	01/07/19 16:11	General View		Load JPG		<input checked="" type="checkbox"/>
22	01/07/19 16:11	General View		Load JPG		<input checked="" type="checkbox"/>
23	01/07/19 16:11	General View		Load JPG		<input checked="" type="checkbox"/>
24	01/07/19 16:11	General View		Load JPG		<input checked="" type="checkbox"/>
25	01/07/19 16:11	General View		Load JPG		<input checked="" type="checkbox"/>
26	01/07/19 16:11	General View		Load JPG		<input checked="" type="checkbox"/>

Documentation					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print	
1	30/05/19 14:59	estimate repair <small>From: SC - Reg. No: GY1427G, Claimant: YI CHUAN METAL WORKS</small>		Load PDF		
2	30/05/19 14:59	TP SHD9884R E-REPORT <small>From: SC - Reg. No: GY1427G, Claimant: YI CHUAN METAL WORKS</small>		Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19009623/KVD3E2

Date: 03/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29067434

Claimant Vehicle No : SHD9884R

Insured Vehicle No : GY1427G

Date of Loss: 28/05/2019

Nature of Claim: TP

Claim No: 594895

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD9884R**

Make & Model: RENAULT LATITUDE, 2.0 L (A)

Engine No: M9R8839C001341

Reg. Date: 09/05/2014 (Man. Year: 2014)

Chassis No: VF1ABL15AUC277540

Colour: Metallic White/Red

Odometer: 647566 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Giti 7 mm

Rear Left Side: Giti 8 mm

Front Right Side: Giti 7 mm

Rear Right Side: Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	64,504.89	10,215.32	54,289.57	84.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,620.00	1,560.00	16,060.00	91.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	82,124.89	11,775.32	70,349.57	85.66
Approved Total (Overridden) (S\$)		9,400.00		
(S\$)	82,124.89	9,400.00	72,724.89	88.55
+ GST 7.00/7.00% (S\$)	5,748.74	658.00	5,090.74	88.55
Nett Amount (S\$)	87,873.63	10,058.00	77,815.63	88.55

INSPECTION

Date of Assignment: 30/05/2019

Date Inspected: 31/05/2019 Inspected At:

Trans-Cab Services Pte Ltd (HQ)
2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG		Version: 1.0 (Last Synchronised: 03 Jul 2019)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9884R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Cracked	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT	Distorted	181.75 FL	*181.75 FL
3	1		*BUMPER ABSORBER FRT	Torn	394.68 FL	*394.68 FL
4	1		*BUMPER RETAINER FRT LH	Cracked	151.41 FL	*151.41 FL
5	1		*BUMPER SUPPORT FRT	Serviceable	123.88 FL	*- FL
6	1		*BUMPER UNDERTRAY FRT	Serviceable	472.83 FL	*- FL
7	1		*BUMPER GRILLE LOWER FRT	Serviceable	266.80 FL	*- FL
8	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
9	1		*BUMPER BEAM FRT	Repair	914.08 FL	*- FL
10	1		*HEADLAMP LH	Cracked	1,184.43 FL	*1,184.43 FL
11	1		*HEADLAMP PANEL FRT LH	Repair	152.15 FL	*- FL
12	1		*FENDER PANEL FRT LH	Bent	783.83 FL	*783.83 FL
13	1		*WHEELARCH FRT LH	Missing	278.84 FL	*278.84 FL
14	1		*FENDER BRACKET LOWER LH	Repair	15.79 FL	*- FL
15	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
16	1		*FRONT BRACE PANEL	Repair	177.22 FL	*- FL
17	1		*RADIATOR GRILLE	Mtg Cracked	1,707.78 FL	*1,707.78 FL
18	1		*RADIATOR GRILLE BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1		*RADIATOR GRILLE FRAME	Cracked	1,353.75 FL	*1,353.75 FL
20	1		*FRAME FULL SUPPORT PANEL	Serviceable	615.90 FL	*- FL
21	1		*FRAME FULL SUPPORT BRACKET	Repair	89.79 FL	*- FL
22	1		*BONNET	Repair	1,941.63 FL	*- FL
23	1		*BONNET INSULATOR	Serviceable	405.73 FL	*- FL
24	1		*BONNET STRUT LH	Serviceable	88.61 FL	*- FL
25	1		*BONNET STRUT RH	Serviceable	88.61 FL	*- FL
26	1		*BONNET HINGE LH	Repair	348.31 FL	*- FL
27	1		*BONNET HINGE RH	Repair	348.31 FL	*- FL
28	1		*BONNET LOCK	Repair	305.48 FL	*- FL
29	1		*BONNET CABLE	Serviceable	119.19 FL	*- FL
30	1		*BONNET CABLE COVER	Serviceable	161.03 FL	*- FL
31	1		*BONNET SEAL OUTER	Serviceable	92.36 FL	*- FL
32	1		*BONNET SEAL INNER	Serviceable	157.28 FL	*- FL
33	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
34	1		*AIR CLEANER HOSE	Serviceable	175.85 FL	*- FL
35	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
36	1		*AUTO COMPUTER	Serviceable	5,032.17 FL	*- FL
37	1		*INJECTION COMPUTER	Serviceable	4,706.30 FL	*- FL
38	1		*RHD HYDRAULIC POWER (ROCK & PINION)	Serviceable	5,154.52 FL	*- FL
39	1		*STEERING PUMP ELECTRIC L70Y	Serviceable	2,306.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*STEERING PINION RACK L70Y	Serviceable	4,413.11 FL	*- FL
41	1		*SUBFRAME OUTER FRT	Serviceable	2,652.45 FL	*- FL
42	1		*SUBFRAME BRACKET OUTER LH	Repair	92.36 FL	*- FL
43	1		*SUBFRAME BRACKET OUTER RH	Repair	92.36 FL	*- FL
44	1		*ENGINE UNDERTRAY	Serviceable	564.98 FL	*- FL
45	1		*RADIATOR FAN COWLING	Serviceable	820.54 FL	*- FL
46	1		*RADIATOR FAN MOTOR LH	Serviceable	967.36 FL	*- FL
47	1		*RADIATOR FAN MOTOR RH	Serviceable	1,479.46 FL	*- FL
48	1		*DOOR PANEL FRT LH	Bent	2,844.66 FL	*2,844.66 FL
49	1		*DOOR HINGE UPPER LH	Repair	261.28 FL	*- FL
50	1		*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
51	1		*DOOR CHECK FRT LH	Serviceable	194.77 FL	*- FL
52	1		*DOOR LOCK FRT LH	Repair	908.75 FL	*- FL
53	1		*DOOR CATCH FRT LH	Serviceable	131.23 FL	*- FL
54	1		*DOOR HANDLE OUTER FRT LH	Serviceable	477.76 FL	*- FL
55	1		*DOOR HANDLE COVER FRT LH	Serviceable	13.22 FL	*- FL
56	1		*DOOR HANDLE MODULE FRT LH	Serviceable	133.60 FL	*- FL
57	1		*DOOR REGULATOR FRT LH	Repair	505.19 FL	*- FL
58	1		*DOOR REGULATOR MOTOR FRT LH	Serviceable	796.46 FL	*- FL
59	1		*DOOR REGULATOR GUIDE FRT LH	Serviceable	120.97 FL	*- FL
60	1		*DOOR MOULDING FRONT LH	Serviceable	176.82 FL	*- FL
61	1		*DOOR FINISHER INNER FRONT LH	Serviceable	323.44 FL	*- FL
62	1		*DOOR FINISHER FRONT LH	Serviceable	423.10 FL	*- FL
63	1		*DOOR CASING FRONT LH	Serviceable	1,509.06 FL	*- FL
64	1		*DOOR GRAB HANDLE FRONT LH	Serviceable	210.96 FL	*- FL
65	1		*DOOR BLIND FRONT LH	Serviceable	741.80 FL	*- FL
66	1		*DOOR WHEATHERSTRIP FRONT LH	Serviceable	410.66 FL	*- FL
67	1		*DOOR SEAL FRONT LH	Serviceable	162.02 FL	*- FL
68	1		*DOOR GLASS RUNNER SEAL FRONT LH	Serviceable	229.31 FL	*- FL
69	1		*DOOR WAIST SEAL OUTER FRONT LH	Serviceable	334.69 FL	*- FL
70	1		*DOOR WAIST SEAL INNER FRONT LH	Serviceable	115.64 FL	*- FL
71	1		*DOOR MIRROR ASSY LH	Serviceable	1,483.40 FL	*- FL
72	1		*DOOR MIRROR GLASS LH	Serviceable	148.20 FL	*- FL
73	1		*DOOR MIRROR BACK COVER LH	Serviceable	218.46 FL	*- FL
74	1		*DOOR HARNESS WIRE LH	Serviceable	2,670.00 FL	*- FL
75	1		*LOWER ARM LH L70Y	Serviceable	685.76 FL	*- FL
76	1		*KNUCKLE ARM LH L70Y	Serviceable	846.98 FL	*- FL
77	1		*ABSORBER FRT LH L70Y	Serviceable	360.54 FL	*- FL
78	1		*DRIVESHAFT LH	Repair	1,747.45 FL	*- FL
79	1		*STABILIZER BAR FRT	Serviceable	604.65 FL	*- FL
80	1		*WHEEL HOUSING PANEL FRONT LH	Repair	4,682.09 FL	*- FL
81	1		*BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
82	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
83	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
84	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
85	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
86	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
87	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
88	1		*WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
89	1		*FRONT LEFT TYRE	Serviceable	300.00 FS	*- FS
90	1		*FRONT LEFT TYRE RIM	Dented	380.00 FS	*380.00 FS
91	1		*SET FRONT LICENSE PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS
92	1		*WINDSCREEN SEALANT	Not Necessary	253.80 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
93	1		*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FS	*- FS
94	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
95	6		*BONNET INSULATOR CLIP L70Y	Not Necessary	7.30 FS	*- FS
96	2		*BONNET STRUT L70Y	Serviceable	88.61 FS	*- FS
97	2		*BONNET CABLE CLIP L70Y	Not Necessary	6.31 FS	*- FS
98	2		*BONNET CABLE COVER SCREW L70Y	Not Necessary	10.85 FS	*- FS
99	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*- FS
100	1		*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
101	1		*FRONT RIGHT TYRE	Serviceable	300.00 FS	*- FS
102	1		*FRONT RIGHT TYRE RIM	Dented	380.00 FS	*380.00 FS
103	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
104	1		*FRONT DOOR STICKER CLASSIC	Not Necessary	80.00 FS	*- FS
105	1		*DOOR CHECK BOLT	Serviceable	22.69 FS	*- FS
106	1		*DOOR GUIDE SCREW	Serviceable	10.85 FS	*- FS
107	1		*DOOR HINGE BOLT	Serviceable	10.85 FS	*- FS
108	1		*DOOR HINGE NUT LH	Serviceable	14.60 FS	*- FS
109	1		*DOOR CHECK BOLT	Serviceable	22.69 FS	*- FS
110	1		*DOOR CHECK NUT	Serviceable	3.75 FS	*- FS
111	1		*DOOR LOCK SCREW L70Y	Serviceable	6.12 FS	*- FS
112	1		*DOOR CATCH SCREW L70Y	Serviceable	10.06 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	71,376.05	11,251.91
- List Item Discount on L Items 10.00/10.00% (\$\$)	6,871.16	1,036.59
Total Parts (\$\$)	64,504.89	10,215.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	6,000.00	500.00
2	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
3	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
4	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
7	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING	New	440.00	0.00
8	TO TRANSFER OF BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
9	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	40.00
10	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	880.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
12	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
13	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
14	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
15	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT, VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
16	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET VEHICLE WARNING INDICATORS	New	480.00	0.00
17	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING	New	380.00	0.00
18	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	0.00
19	TO CHECK ABS BRAKE EFFICIENCY, FINAL CHECKING AND TESTING	New	380.00	0.00
Gross Labour Cost (\$\$)			17,620.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >