











































FormTeam Consultancy Pte Ltd

No.33, Ubi Ave 3
#02-15, Vertex
Singapore 408868

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: motorsurvey@fta.com.sg

Co.Reg No: 200819280D

GST Reg No: 200819280D

Our Reference : RRX17-042075/PRS/KH/RI/CBX/cg
Your Reference: C0429965
Date : 19-Sep-2017

Motor Claims Department
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Attention : Ms Vale Oh

Dear Sir/Mdm,

RE-INSPECTION OF VEHICLE NO . **SGS 1884B**

Pursuant to your instructions on 31 Aug 2017 , we have conducted a reinspection of the above vehicle at Blk 10 Ang Mo Kio Ind Park 2A #03-16 S'568047 on 14 Sep 2017.

We recommend a repair cost of **\$3,350.00** (see report) based on lump sum repair and the estimated duration of repairs would take **05 days**.

We also enclosed our note of charges for your consideration.

Thank you for this assignment.

Your faithfully

FormTeam Consultancy Pte Ltd
Adjusters & Surveyors (Licensed Appraiser)



Chow Bo Xiong
Automobile Appraiser

(Email : chowbx@fta.com.sg)

Encl. Re-inspection Report

FormTeam Consultancy Pte Ltd

AUTOMOBILE ASSESSMENT REPORT

PAGE : 1

Our Reference : RRX17-042075/PRS/KH/RI/CBX/cg

Your Reference : C0429965

Date : 19-Sep-2017

Attention : Ms Vale Oh

TO : Motor Claims Department
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Dear Sir/Madam,

Vehicle No : SGS 1884B
Model : Toyota Wish 1.8A
Mileage : 147491 km
Chassis No : ZNE100352156
Workshop : M/S Ah Chang Motor Service Centre

Pursuant to your instructions on **31 Aug 2017**, we have conducted a reinspection of the above vehicle at **Blk 10 Ang Mo Kio Ind Park 2A #03-16 S'568047** on **14 Sep 2017**.

We are pleased to submit hereunder our adjustment which we trust should serve your purpose: -

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
	<u>PARTS REPLACEMENT-LIST ITEMS</u>				
1	Front Bumper With Lower Grille Assy	Cracked/Dented		859.20	480.15
1	Front Bumper RH Bracket	Bent		44.30	44.30
1	Front Bumper RH Retainer	Bent/Cracked		46.20	46.20
1	Front Bumper LH Fog Lamp Garnish	Not Consistent		88.70	-
1	Front Bumper RH Fog Lamp Garnish	Cracked		88.70	88.70
1	Front Bumper Sponge	Warped/Cut		175.10	175.10
1	Front Grille Assy	Bent/Cut		227.30	182.25
1	Front RH Headlamp	Broken		680.70	680.70
1	Front RH Fender	Deformed		1,180.50	750.00
1	Front RH Fender Inner Cowling	Bent/Necessary		211.50	211.50
1	Front RH Fender Lamp	Bent/Necessary		76.30	76.30
1	Front RH Door Panel	Repair		-	-
1	Front ABS Brake Pump Module Assy	Not Consistent		3,800.10	-

FormTeam Consultancy Pte Ltd

PAGE : 2

Our Reference : RRX17-042075/PRS/KH/RI/CBX/cg

Your Reference : C0429965

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
1	Front RH Wiper Tank	Cracked		89.70	89.70
	List Items Sub-Total			7,568.30	2,824.90
	Original Less 25%			1,892.08	706.23
	Revised Less 25%				
	Discounted Sub-Total			5,676.23	2,118.68
	PARTS REPLACEMENT				
	SPECIAL NETT ITEMS				
10	Front Bumper Clips	Necessary		50.00	50.00
2	Front Bumper LH Fog Lamp	Not Fitted		10.00	-
	Garnish Clips				
2	Front Bumper RH Fog Lamp	Not Fitted		10.00	-
	Garnish Clips				
4	Front Grille Clips	Necessary		20.00	20.00
1	Front RH Sport Rim	Grazed/Cut		650.00	400.00
6	Front RH Fender Inner Cowling	Necessary		20.00	20.00
	Clips				
	Special Nett Sub-Total			760.00	490.00
	Total Parts Amount			6,436.23	2,608.68

FormTeam Consultancy Pte Ltd

PAGE : 3

Our Reference : RRX17-042075/PRS/KH/RI/CBX/cg

Your Reference: C0429965

QTY	DESCRIPTION	SUBMITTED	REVISED
	LABOUR & MISC		
1	Labour for panel beating, cut, weld, straighten front RH affected area and replace accident damaged parts. (including all repair parts)	900.00	600.00
2	To putty and spray painting front RH and front portion.	900.00	800.00
3	To apply anti rust proofing to front RH and front affected area.	100.00	60.00
4	To transfer front RH door glass to new door.	60.00	-
5	To transfer front RH door lock mechanism.	60.00	-
6	To repair, straighten and align front RH door panel.	150.00	-
7	To check door central locking for function.	60.00	-
8	To repair, straighten and align front support panel.	150.00	-
9	To balance front RH wheel.	30.00	30.00
10	To conduct wheel alignment.	60.00	60.00
11	Towing service.	80.00	60.00
	Total Labour Amount	2,550.00	1,610.00
	Total Parts and Labour	8,986.23	4,218.68

1726.91

50.00

1290.00

3066.91

20%

2453.52

4/5-2,450

5 days

FormTeam Consultancy Pte Ltd

PAGE : 4

Our Reference : RRX17-042075/PRS/KH/RI/CBX/cg

Your Reference: C0429965

QTY	DESCRIPTION	SUBMITTED	REVISED
	Our Recommended Repair Cost (see remarks)		
		\$7,200.00	\$3,350.00

REMARKS :

Our recommended Lump Sum Repair Cost is **\$3,350.00** (instead of the submitted repair cost of **\$7,200.00** .In normal circumstances, repairs to the vehicle would take approximately **05 days** to complete. Please find enclosed our note of charges for your kind attention.

Disclaimer


This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **FormTeam Consultancy Pte Ltd** for any reliance on this report by any third party, unless with the permission of the addressee.

Yours faithfully,

FormTeam Consultancy Pte Ltd



Frankie Pang
AMSAE(AUST), AMIRTE, AMSOE,
MASPACI, MSAAA
Licensed Appraiser



Chow Bo Xiong
Automobile Appraiser

VEHICLE DAMAGE INSPECTION REPORT

Our File No: RRX17-042075/PRS/KH
Date: 21/04/2017

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: P1680520
Claimant Vehicle No: SGS1884B Insured Vehicle No: SHC5658J
Date of Loss: 15/04/2017 Nature of Claim: TP Claim No: C0429965

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGS1884B
Make & Model: Engine No: 1ZZ2828017
Reg. Date: 06/03/2007 (Man. Year: 2007) Chassis No: ZNE100352156
Colour: Silver Odometer: 113893 km
Engine Capacity: 1974 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/04/2017
Date Inspected: 19/04/2017 Inspected At: Ah Chang Motor
10 Ang Mo Kio Ind Park 2A
#03-16 Autopoint
Singapore 568047
Estimated Period of Repair: 5.0 days

Adjuster: Liew Kong Ho

Manager: Frankie

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:

Parts: N/A (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: FormTeam Consultancy Pte Ltd/SGS1884B/21/04/2017 11:16

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

FormTeam Consultancy Pte Ltd/SGS1884B/21/04/2017 11:16. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

FormTeam Consultancy Pte Ltd/SGS1884B/21/04/2017 11:16. Not valid without Reference section.
--

< END OF ESTIMATES >













