



Accident Photo



Accident Photo



Accident Photo



Driving License

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7341426A**



 Name
**CHUA YEW SENG DANIEL
(CAI YAOCHENG DANIEL)**

 Race
CHINESE

Date of birth
15-11-1973

Sex
M

Country/Place of birth
SINGAPORE

S7341426A

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number **S7341426A**

 Name
**CHUA YEW SENG DANIEL
(CAI YAOCHENG DANIEL)**

Birth Date **15 Nov 1973**

Issue Date **17 Jul 2012**

 **002088130B**

Driving License

5306527



NRIC No. S7341426A



Date of issue
29-04-2014


Address
APT BLK 544 JELAPANG ROAD
#06-90
SINGAPORE 670544

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 3 Motor Cars \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg	26 May 2000

NP 428A

Licence No. S7341426A



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/10/2018 05:24
Date Of Accident 22/10/2018 13:25
Exact Location Of Accident ALONG PIE/TUAS BEFORE ADAM(EXIT)
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMC1173H
Insured/Policyholder
Name Of Registered Owner DANIEL TAU TING SENG
NRIC No S1436267C
Email Address AARONTAU.WENJIE@GMAIL.COM
Mobile Phone No (LOCAL) +65-96975767
Alternative Phone No OFFICE-96975767

Vehicle Particulars

Manufacturer TOYOTA
Model HARRIER 2.0
Exact Purpose for which vehicle was being used at time of accident PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle? YES
If No, Please state action to be taken
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company EQ INSURANCE COMPANY LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number DMPPHQ18-004403
Cover Note Number N.A.

Driver

Name of Driver AARON TAU WEN JIE
NRIC No S9000992C
Date Of Birth 08/01/1990
Occupation INDOOR
Date Of Driving Pass 29/12/2010
Driving Experience 7 YEARS AND 9 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96975767
Fax Number
Contact Number OFFICE-96975767
Email Address AARONTAU.WENJIE@GMAIL.COM

Address	74 PUNGGOL WALK #05-51
Postcode	828787
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was travelling along PIE/Tuas on the middle lane, car in front of me suddenly jammed brake & came to complete stop. I couldn't stop in time & my car SMC1173H hit onto rear of car SKV9882R. No injuries involved. That's all.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PENDING VIDEO FROM INSURED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKV9882R
Vehicle Make/Model/Colour	TOYOTA/WISH/SIL
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHUA YEW SENG DANIEL
NRIC/Passport Number	S7341426A
Contact Number	93633386
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

SKETCH PL

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHD FADZLY BIN ISMAIL

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was travelling along PIE/Tuas on the middle lane, car in front of me suddenly jammed brake & came to complete stop. I couldn't stop in time & my car SMC1173H hit onto rear of car SKV9882R. No injuries involved. That's all.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHD FADZLY BIN ISMAIL

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

22 October 2018 at 4:05 PM

Date/Time:

22 October 2018 at 4:05 PM

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9000992C



Name
AARON TAU WEN JIE

涂 文 杰

Race
CHINESE

Date of birth Sex
08-01-1990 M

Country of birth
SINGAPORE

S9000992C

REPUBLIC OF SINGAPORE DRIVING LICENCE

S9000992C



AARON TAU WEN JIE


Birth Date 08 Jan 1990
Issue Date 29 Dec 2010

001924461A




Driving License

3664469



NRIC No: S9000992C



Date of issue
18-01-2005

74 PUNGGOL WALK #05-51
SINGAPORE 828787


NRIC No: S9000992C Date: 13/11/2015

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 3 Motor Cars= \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg,	29 Dec 2010

NP 428A

Licence No: S9000992C



PAR Automotive Consultancy

Regn No 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0217-19-TCA

22 April 2019

ACCIDENT VEHICLE SURVEY REPORT

Chua Yew Seng Daniel
Blk 544 Jelepong Road #06-90
Singapore 670544

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SKV9882R	<i>Odometer:</i>	52717km
<i>Make & Model:</i>	Toyota Wish 1.8 CVT	<i>Colour:</i>	Silver
<i>Chassis number:</i>	JTDGG20W70J002879	<i>Date of accident:</i>	22/10/2018
<i>Year of Regn.:</i>	14/10/2015	<i>Date inspected:</i>	29/10/2018
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	03/11/2018

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0217-19-TCA

22 April 2019

ACCIDENT VEHICLE SURVEY REPORT

Chua Yew Seng Daniel
Blk 544 Jelepang Road #06-90
Singapore 670544

VEHICLE INFORMATION:

Vehicle Reg No.:	SKV9882R	Odometer:	52717km
Make & Model:	Toyota Wish 1.8 CVT	Colour:	Silver
Chassis number:	JTDGG20W70J002879	Date of accident:	22/10/2018
Year of Regn.:	14/10/2015	Date inspected:	29/10/2018
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	03/11/2018

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	6mm/Michelin	6mm/Michelin	205/55R16
Rear:	6mm/Michelin	6mm/Michelin	205/55R16

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear and front portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
FRONT BONNET MECHANISM LOCK	1	bent	286.10	286.10 X } nn
FRONT BRACE PANEL	1	bent	182.10	182.10 X } nn
FRONT BUMPER	1	squashed	1,077.50	1,077.50 repair ✓
FRONT BUMPER FOGLAMP COVER CHROME L/R	2	fractured	390.20	390.20 X } sue
FRONT BUMPER FOGLAMP COVER L/R	2	fractured	354.20	354.20 X } sue
FRONT BUMPER FOGLAMP L/R RH-NN	2	fractured - LH	749.70	749.70 374.85
FRONT BUMPER GRILLE GARNISH BRACKET L/R	2	fractured	102.60	102.60 X } nn
FRONT BUMPER GRILLE GARNISH L/R	2	fractured	310.20	310.20 X } nn
FRONT BUMPER INNER SPONGE	1	deformed	174.45	174.45
FRONT BUMPER REINFORCEMENT - No photos	1	bent	329.10	329.10 X NN Δ
FRONT BUMPER SIDE RETAINER L/R	2	necessary	220.70	220.70 ✓ Δ
FRONT GRILLE	1	fractured	253.10	253.10 ✓ Δ
FRONT GRILLE CHROME MOULDING	1	fractured	277.10	277.10 ✓ Δ
FRONT GRILLE UPPER TOP COVER	1	fractured	281.10	281.10 X } nn
FRONT HEADLAMP L/R	2	fractured	2,796.20	2,796.20 X } nn
REAR BUMPER	1	squashed	595.00	595.00
REAR BUMPER BRACKET L/R @48 (RH)	1 pc 2	bent	343.50	343.50 48
REAR BUMPER CORNER BRACKET L/R	2	bent	282.90	282.90 ✓ Δ
REAR BUMPER END SEAL COVER L/R	2	deformed	302.20	302.20 X } nn
REAR BUMPER REFLECTOR L/R LH-NN	2	fractured - RH	283.10	283.10 141.55
REAR BUMPER REVERSE SENSOR HOLDER L/R	2	necessary	242.20	242.20 X } nn
REAR BUMPER REVERSE SENSOR WIRE HARNESS	1	reuse	325.10	0.00 X } nn
REAR BUMPER SIDE RETAINER L/R @89 (RH)	1 pc 2	necessary	282.90	282.90 89
REAR END LOWER PANEL	1	buckled	278.10	278.10 } 540
REAR END PANEL	1	buckled	581.35	581.35 } 540
REAR END PANEL INNER TOP GARNISH	1	fractured	378.10	378.10
REAR EXHAUST GASKET	1	necessary	43.90	43.90 X } nn
REAR EXHAUST RUBBER MOUNTING	3	distorted	516.30	516.30 X } nn
REAR EXHAUST SILENCER BOX	1	bent	781.10	781.10 repair X
REAR FENDER INNER TRIM GARNISH L/R (RH) 655	1 pc 2	deformed	1,563.80	1,563.80 655
REAR INNER TOP DECK BOARD	1	deformed	561.60	561.60 X } nn
REAR INNER TOP DECK BOARD COVER L/R	2	deformed	1,123.20	1,123.20 X } nn
REAR NUMBER PLATE LAMP L/R (RH) @45	1 pc 2	fractured	342.90	342.90 45
REAR RH FENDER	1	repair	972.45	0.00 X } nn
REAR RH FENDER GLASS MOULDING	1	reuse	171.40	0.00 X } nn
REAR SEPARATOR LUGGAGE BOX GARNISH	1	deformed	581.90	581.90 X } nn
REAR SPARE TYRE CARRIER BRACKET	1	bent	172.10	172.10 X } nn
REAR TAILGATE	1	buckled	1,465.10	1,465.10
REAR TAILGATE 'ELEGANCE' EMBLEM	1	necessary	61.10	61.10
REAR TAILGATE 'LOGO' EMBLEM	1	necessary	72.50	72.50
REAR TAILGATE 'VALVEMATIC' EMBLEM	1	necessary	63.90	63.90
REAR TAILGATE DAMPER L/R	2	bent	748.90	748.90 X } nn

PAR Automotive Consultancy

Annex A: Page 2
Report No: 0217-19-TCA-SKV9882R

REAR TAILGATE INNER PULL GARNISH	1	warped	121.35	121.35 49
REAR TAILGATE INNER TRIM GARNISH	1	fractured	545.85	545.85 485
REAR TAILGATE MECHANISM LOCK	1	bent	517.10	517.10 409
REAR TAILGATE OUTER CHROME MOULDING	1	fractured	274.45	274.45
REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R	2	necessary	87.50	87.50 X 11
REAR TAILGATE REFLECTOR L/R @ 304	2	fractured	868.80 748.90	748.90 608
REAR TAILGATE RUBBER GUIDE STOPPER L/R	2	deformed	87.50	87.50 22
REAR TAILGATE WEATHERSTRIP	1	deformed	256 320.00	320.00
REAR TAILGATE WINDSCREEN INNER SEAL COVER L/R	2	reuse	6524.10 131.80	0.00 X 3 11
REAR TAILGATE WINDSCREEN MOULDING (TOP & LOWER)	2	reuse	230.40	0.00 X 1 11
REAR TAILGATE WINDSCREEN MOULDING L/R	2	necessary	220.70	220.70 154
REAR TAILGATE WIPER MOTOR	1	shorted	972.50	972.50 X 1 11
REAR TAILLAMP INNER PANEL L/R @ 245	1 pc 2	buckled	749.70	749.70 245
REAR TAILLAMP L/R @ 395	1 pc 2	fractured	1,163.80	1,163.80 395

Subtotal before discount S\$ 27,092.50 S\$ 25,261.35
Percentage discount 25% and 25% S\$ 6,773.13 S\$ 6,315.34

REAR BUMPER REVERSE SENSOR	2	shorted	760.00	760.00 220
REAR END PANEL ANTENNA SENSOR	1	shorted	180.00	180.00 133
REAR TAILGATE OPENER BUTTON SENSOR	1	shorted	180.00	180.00 X 1 11
Subtotal before discount			S\$ 1,120.00	S\$ 1,120.00
Percentage discount 0% and 0%			S\$ 0.00	S\$ 0.00

FRONT BUMPER CLIPS - SET	1	necessary	50.00	50.00 30
FRONT BUMPER L.E.D LIGHT L/R	2	shorted	360.00	360.00 X 7 11
FRONT GRILLE CLIPS - SET	1	necessary	20.00	20.00 X 1 11
FRONT GRILLE UPPER TOP COVER CLIPS - SET	1	necessary	20.00	20.00 X 1
FRONT NUMBER PLATE	1	bent	25.00	25.00
FRONT NUMBER PLATE HOLDER	1	bent	50.00	50.00 X 1 11
REAR BUMPER CLIPS - SET	1	necessary	50.00	50.00 30
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	necessary	20.00	20.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET	1 pc 2	necessary	100.00	100.00 50
REAR NUMBER PLATE	1	bent	25.00	25.00 35
REAR NUMBER PLATE HOLDER	1	bent	50.00	50.00
REAR RH FENDER GLASS SEALANT	1	reuse	80.00	0.00 X 1 11
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	1	necessary	50.00	50.00 30
REAR TAILGATE OUTER CHROME MOULDING CLIPS - SET	1	necessary	20.00	20.00
REAR TAILGATE REVERSE CAMERA	1	shorted	800.00	800.00 X 7 11
REAR TAILGATE SPOILER CLIPS - SET	1	necessary	30.00	30.00 X 1 11
REAR TAILGATE WINDSCREEN SEALANT	1	necessary	100.00	100.00 60
REAR TAILLAMP CLIPS L/R - SET	1 pc 2	necessary	40.00	40.00 20

Subtotal before discount S\$ 1,890.00 S\$ 1,810.00
Sub-total 3 S\$ 1,890.00 S\$ 1,810.00
Parts-total S\$ 23,329.38 S\$ 21,876.01

LABOUR

To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.

200.00 140.00 ~~60~~

To remove, reinstall tailgate windscreen

200.00 150.00 ~~120~~

To remove, reinstall fender glass

120.00 0.00 ~~120~~

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

150.00 60.00 ~~150~~

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

2,200.00 1,980.00 ~~1000~~

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

150.00 120.00 ~~60~~

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

2,800.00 2,250.00 ~~900~~

To apply anti-rust chemical on repaired and replaced panel.

150.00 120.00 ~~60~~

Labour Total	SS 5,970.00	SS 4,820.00
Parts & Labour Total	SS 29,299.38	SS 26,696.01

2580

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : SS 22,700.00 and the recommended number of working days for the repairs is within 10 day(s).

BJL

B J Loi (I Eng, MIM, AIRTE)
Automotive Appraiser

6524.10
353.00
2580.00

9457.10
20%
7,565.68

1/1-7,550

8 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CS3/EQI18019614/R1qd3s2-1

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 01-07-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMC 1173H	Veh. Inspected	SKV 9882R
Policy No.		Coverage (\$)	0.00
Claim No.	DM18HO02851-JG	Excess (\$)	0.00
Assign From	JOEL GOH	Assign Date	30/05/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH 1.8 CVT	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTDGG20W70J002879	Colour	GREY
Odometer	52716	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R16	MICHELIN	6 mm
L/H Front Tyre	205/55R16	MICHELIN	6 mm
R/H Rear Tyre	205/55R16	MICHELIN	6 mm
L/H Rear Tyre	205/55R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	22/10/2018	Inspection Date	29/10/2018
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 9882R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET MECHANISM LOCK	NOT NECESSARY	286.10	-
1	FRONT BRACE PANEL	NOT NECESSARY	182.10	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,077.50	-
2	FRONT BUMPER FOGLAMP COVER CHROME L/R	SERVICEABLE	390.20	-
2	FRONT BUMPER FOGLAMP COVER L/R	SERVICEABLE	354.20	-
2	FRONT BUMPER FOGLAMP L/R	O/S NOT NECESSARY / N/S FRACTURED	749.70	374.85
2	FRONT BUMPER GRILLE GARNISH BRACKET L/R	NOT NECESSARY	102.60	-
2	FRONT BUMPER GRILLE GARNISH L/R	NOT NECESSARY	310.20	-
1	FRONT BUMPER INNER SPONGE	DEFORMED	174.45	174.45
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	329.10	-
2	FRONT BUMPER SIDE RETAINER L/R	NECESSARY	220.70	220.70
1	FRONT GRILLE	FRACTURED	253.10	253.10
1	FRONT GRILLE CHROME MOULDING	FRACTURED	277.10	277.10
1	FRONT GRILLE UPPER TOP COVER	NOT NECESSARY	281.10	-
1	FRONT HEADLAMP L/R	NOT NECESSARY	2,796.20	-
1	REAR BUMPER	SQUASHED	595.00	595.00
2	REAR BUMPER BRACKET L/R	O/S BENT	343.50	48.00
2	REAR BUMPER CORNER BRACKET L/R	BENT	282.90	282.90
2	REAR BUMPER END SEAL COVER L/R	NOT NECESSARY	302.20	-
2	REAR BUMPER REFLECTOR L/R	O/S FRACTURED	283.10	141.55
2	REAR BUMPER REVERSE SENSOR HOLDER L/R	NOT NECESSARY	242.20	-
1	REAR BUMPER REVERSE SENSOR WIRE HARNESS	NOT NECESSARY	325.10	-
2	REAR BUMPER SIDE RETAINER L/R	O/S NECESSARY	282.90	89.00
1	REAR END LOWER PANEL }	BUCKLED	278.10	540.00
1	REAR END PANEL }		581.35	-
1	REAR END PANEL INNER TOP GARNISH	FRACTURED	378.10	378.10
1	REAR EXHAUST GASKET	NOT NECESSARY	43.90	-
3	REAR EXHAUST RUBBER MOUNTING	NOT NECESSARY	516.30	-

Report Ref No. CS3/EQ18019614/R1qd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST SILENCER BOX	TO REPAIR SEE LABOUR	781.10	-
2	REAR FENDER INNER TRIM GARNISH L/R	O/S DEFORMED	1,563.80	655.00
1	REAR INNER TOP DECK BOARD	NOT NECESSARY	561.60	-
2	REAR INNER TOP DECK BOARD COVER L/R	NOT NECESSARY	1,123.20	-
2	REAR NUMBER PLATE LAMP L/R	O/S FRACTURED	342.90	45.00
1	REAR RH FENDER	NOT NECESSARY	972.45	-
1	REAR RH FENDER GLASS MOULDING	NOT NECESSARY	171.40	-
1	REAR SEPARATOR LUGGAGE BOX GARNISH	NOT NECESSARY	581.90	-
1	REAR SPARE TYRE CARRIER BRACKET	NOT NECESSARY	172.10	-
1	REAR TAILGATE	BUCKLED	1,465.10	1,465.10
1	REAR TAILGATE 'ELEGANCE' EMBLEM	NECESSARY	61.10	61.10
1	REAR TAILGATE 'LOGO' EMBLEM	NECESSARY	72.50	72.50
1	REAR TAILGATE 'VALVEMATIC' EMBLEM	NECESSARY	63.90	63.90
2	REAR TAILGATE DAMPER L/R	NOT NECESSARY	748.90	-
1	REAR TAILGATE INNER PULL GARNISH	WARPED	121.35	49.00
1	REAR TAILGATE INNER TRIM GARNISH	FRACTURED	545.85	485.00
1	REAR TAILGATE MECHANISM LOCK	BENT	517.10	409.00
1	REAR TAILGATE OUTER CHROME MOULDING	FRACTURED	274.45	274.45
2	REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R	NOT NECESSARY	87.50	-
2	REAR TAILGATE REFLECTOR L/R	FRACTURED	748.90	608.00
2	REAR TAILGATE RUBBER GUIDE STOPPER L/R	DEFORMED	87.50	22.00
1	REAR TAILGATE WEATHERSTRIP	DEFORMED	320.00	320.00
2	REAR TAILGATE WINDSCREEN INNER SEAL COVER L/R	NOT NECESSARY	131.80	-
2	REAR TAILGATE WINDSCREEN MOULDING (TOP & LOWER)	NOT NECESSARY	230.40	-
2	REAR TAILGATE WINDSCREEN MOULDING L/R	NECESSARY	220.70	154.00
1	REAR TAILGATE WIPER MOTOR	NOT NECESSARY	972.50	-
2	REAR TAILLAMP INNER PANEL L/R	BUCKLED 1PC ONLY	749.70	245.00
2	REAR TAILLAMP L/R	FRACTURED 1PC ONLY	1,163.80	395.00
	LESS 25% DISCOUNT		-6,773.12	-2,174.70
			20,319.38	6,524.10

Report Ref No. CS3/EQ18019614/R1qd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
SPECIAL NETT ITEMS				
2	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	760.00	220.00
1	REAR END PANEL ANTENNA SENSOR (SN)	SHORTED	180.00	133.00
1	REAR TAILGATE OPENER BUTTON SENSOR (SN)	NOT NECESSARY	180.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
2	FRONT BUMPER L.E.D LIGHT L/R (SN)	NOT NECESSARY	360.00	-
1	SET FRONT GRILLE CLIPS (SN)	NOT NECESSARY	20.00	-
1	SET FRONT GRILLE UPPER TOP COVER CLIPS (SN)	NOT NECESSARY	20.00	-
1	FRONT NUMBER PLATE (SN)	BENT	25.00	25.00
1	FRONT NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
2	SET REAR FENDER INNER TRIM GARNISH CLIPS L/R (SN)	NECESSARY 1SET ONLY	100.00	50.00
1	REAR NUMBER PLATE (SN) }	BENT	25.00	35.00
1	REAR NUMBER PLATE HOLDER (SN) }		50.00	-
1	REAR RH FENDER GLASS SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET REAR TAILGATE INNER TRIM GARNISH CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR TAILGATE OUTER CHROME MOULDING CLIPS (SN)	NECESSARY	20.00	20.00
1	REAR TAILGATE REVERSE CAMERA (SN)	NOT NECESSARY	800.00	-
1	SET REAR TAILGATE SPOILER CLIPS (SN)	NOT NECESSARY	30.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	100.00	60.00
2	SET REAR TAILLAMP CLIPS L/R (SN)	NECESSARY 1SET ONLY	40.00	20.00
			3,010.00	673.00
LABOUR				
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR.		200.00	60.00
	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.		200.00	120.00
	TO REMOVE, REINSTALL FENDER GLASS.	NOT NECESSARY	120.00	-
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUHSION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		150.00	60.00

Report Ref No. CS3/EQ118019614/R1qd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR, PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		2,200.00	1,000.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.		150.00	60.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RECONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND REAR EXHAUST SILENCER BOX.		2,800.00	900.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		150.00	60.00
			5,970.00	2,260.00
GRAND TOTAL			29,299.38	9,457.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,550.00

Report Ref No. CS3/EQ18019614/R1qd3s2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.