

SS. REC. BY: Hue Jie

REF

NTUC NS/IR (17049654) Ad302

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SGW1292Policy No. 5073885207-03 (01/09/2012)Claims No. MT/1046796-002


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB420R Yr Regn: 2 Jul 2014Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798Colour: maroon A/C: Insured / Std / NI / NASp. Reading: 429138 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN36U90S746151Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil (S/Rim) / STD A/Rim orTyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 28/5/19 D.O.I. 30/5/19Survey held at SumitDes. of Damages: (Frt) (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHB 420R - CC3 / AXA 11024666 / R/H C 302 D.O.A - 14/11/2011
	SGW 1292 - x
15/5/19	Finalize Claim \$4900, 7 rep days Cred: 15101.70, 79%

RECEIVED 15 AUG 2019

Date/Time, File Pass to?

1) 15/8 Typist

Date/Time, File Return to?

2) _____

☐ : Prel. Report☒ : Final ReportDays Of Repair: 7Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 160

Transportation: _____

Photos _____

Others _____

TOTAL

160Report Format: TPLump Sum / I.B.I: (\$ 4000)

Denise Tay (LKKAUTO)

From: MTCL@income.com.sg
Sent: Thursday, 15 August 2019 2:48 PM
To: Denise Tay (LKKAUTO)
Subject: REQUEST CLAIM NUMBER

Hi,

Claim created.

With Regards

Samsia
Senior Admin Assistant,
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Thursday, 15 August 2019 11:50 AM
To: MTCL@income.com.sg
Subject: REQUEST CLAIM NUMBER

Dear Sir/Madam,

Request claim number

Date : 15/8/2019

S/No		Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1046796-002	COMFORT DELGRO	SHB 420R	SGW 1289Z	28/5/2019	17:25	20,993.76	4000

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No.(For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	S073885207-03		RADICAL AUTO PTE. LTD.	201501717H	GFT	drive CLASSIC	SGW1289Z	SGW1289Z	09/09/2018	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/05/2019 10:23
Date Of Accident	28/05/2019 17:25
Exact Location Of Accident	PIE TOWARDS CHANGI AIRPORT BEFORE EXIT 17A
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB420R
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-80000000
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	FOO HEE YONG (FU QIXIONG)
NRIC No	S7726475B
Date Of Birth	30/09/1977
Occupation	OUTDOOR
Date Of Driving Pass	11/01/1999
Driving Experience	20 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	13
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG PIE AT THE RIGHT MOST LANE WITH A PASSENGER ON BOARD AND HAD STOPPED DUE TO FRONT VEHICLE SLT1575D STOPPING AS THE TRAFFIC WAS CONGESTED AHEAD. OUT OF SUDDEN, I FELT AN IMPACT FROM BEHIND, THE VEHICLE SGW1289Z FROM BEHIND HAD COLLIDED ONTO THE REAR PORTION OF MY TAXI. DUE TO THE GREAT IMPACT, MY TAXI PUSHED FORWARD AND HIT ONTO THE REAR OF THE VEHICLE SLT1575D. WHEN I ALIGHTED AND CHECKED, I DISCOVERED THAT THERE WAS ANOTHER VEHICLE SKQ7227Y WHICH BEHIND THE VEHICLE SGW1289Z ALSO INVOLVED IN THE ACCIDENT. TOTAL FOUR VEHICLES INVOLVED INCLUDING MINE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGW1289Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KEN HO TENG KENG
NRIC/Passport Number	
Contact Number	
Address	

Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKQ7227Y
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver UNKNOWN
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLT1575Y
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver UNKNOWN
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB420R
Vehicle to be Exported:	No
Intended Deregistration Date:	31 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2014
Engine No.:	2ZR6087533
Chassis No.:	JTDKN36U905746651
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	02 Jul 2014
First Registration Date:	02 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$8,088.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Jul 2022
PARF Rebate Amount:	\$6,066.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jul 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$53,269.00
COE Rebate Amount:	\$20,548.00
Total Rebate Amount:	\$26,614.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 31 May 2019

OK



Case Details

Case Reference Number :

TAX/05/19/2132

Type of Repair : Accident Repair

Vehicle Registration Number : SHB420R

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-7081-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 28/05/2019 09:25 AM

Vehicle Age(In Months) : 58

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair	• X R
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give	• X NAI
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Check	• X NAI
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Check	• X NAI
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Check	• X NAI
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	• / APC
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	1	82.80	Replace	• / GR
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	15.00	Replace	• / DO
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	12.00	Replace	• / DO

Total Spare Part Cost 14,310.70

Surveyor Total 2,946.31

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 11,448.56

Final Sur Total 2,357.05

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	311.10	25.00	233.33	Replace	1	233.33	Replace	✓ COT
One Time Key In	Main			GRILLE RADIATOR LOWER NO.2	1	94.60	94.60	25.00	70.95	Replace	0	0	Not Give	✗ NAI
One Time Key In	Main			GRILLE, RADIATOR	1	310.60	310.60	25.00	232.95	Replace	0	0	Not Give	✗ NAI
One Time Key In	Main			EMBLEM FRONT	1	86.50	86.50	25.00	64.88	Replace	0	0	Not Give	✗ NAI
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0	Check	✗ NAI
One Time Key In	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	✗ NAI
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Check	✗ NAI
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0	Check	✗ NAI
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	0	0	Check	✗ NAI
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0	Not Give	✗ NAI
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	✗ NAI
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	✗ NAI
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Give	✗ NAI
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	✓ 09
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	✓ APC

Total Spare Part Cost

14,310.70

Surveyor Total

2,946.31

Lump Sum Discount (%)

20.00

Lump Sum Dis (%)

20

Final Spare Part Cost

11,448.56

Final Sur Total

2,357.05

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.275	Replace	1	154.275	Replace	• / 00
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace	• / 00
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace	• / 00
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Check	• X NAI
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	• / 00
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	• / 110
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	1	54.15	Replace	• / CR4
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	• X NAI
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace	• / CR4
One Time Key In	Main			BUMPER SEAL, RR LH	1	68.90	68.90	25.00	51.68	Replace	0	0	Not Give	• X NAI
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give	• X NAI
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	• / 00
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	• / 00
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Check	• X NAI
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.925	Replace	1	755.925	Replace	• / 00
Total Spare Part Cost									14,310.70	Surveyor Total 2,946.31				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									11,448.56	Final Sur Total 2,357.05				

UPDATED

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation								Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks	
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.1	1	27.30	27.30	25.00	20.48	Replace	1	20.48	Replace	• / APC	
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	• / APC	
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	• / APC	
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	• / APC	
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.2	1	17.40	17.40	25.00	13.05	Replace	1	13.05	Replace	• / APC	
One Time Key In	Main			MOULDING, BACK WINDOW, LOWER NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	• / APC	
One Time Key In	Main			MOULDING, BACK WINDOW, OUTSIDE LH NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	• / APC	
One Time Key In	Main			MOULDING, BACK WINDOW, OUTSIDE RH NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	• / APC	
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace	• / APC	
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Check	• X N/A	
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0	Check	• X N/A	
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Check	• X N/A	
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	0	0	Not Give	• X N/A	
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Not Give	• X N/A	
One Time Key In	Main			TAILGATE, BOARD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Not Give	• X N/A	

Total Spare Part Cost 14,310.70

Surveyor Total 2,946.31

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 11,448.56

Final Sur Total 2,357.05

04/02/2018

SMRT Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	1	45.22	Replace	✓ CR
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0	Not Give	✓ X NAI
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0	Not Give	✓ X NAI
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	✓ X NAI
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	0	0	Not Give	✓ X NAI
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	0	0	Not Give	✓ X NAI
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0	Not Give	✓ X NAI
One Time Key In	Main			3RD BRAKE LAMP	1	231.30	231.30	10.00	208.17	Replace	0	0	Not Give	✓ X NAI
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	✓ X NAI
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	✓ X NAI
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	✓ X NAI
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	1	34.58	Replace	✓ CR
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	1	90.82	Replace	✓ CR
One Time Key In	Main			REINFORCEMENT, RR	2	34.60	69.20	25.00	51.90	Replace	0	0	Check	✓ X NAI
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	✓ X NAI

Total Spare Part Cost 14,310.70

Surveyor Total 2,948.31

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 11,448.56

Final Sur Total 2,357.05

SMRT Recommendation												Surveyor Approval		
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0	Check	* X NAI
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			CARRIER, SPARE	1	19.70	19.70	25.00	14.77	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			WHEEL, DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.02	Replace	0	0	Check	* X NAI
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	0	0	Check	* X NAI
One Time Key In	Main			TROUGH, BACK DOOR LH	1	110.90	110.90	25.00	83.18	Replace	0	0	Check	* X NAI
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			STICKER DECAL 8555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	* X NAI
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Give	* X NAI

Total Spare Part Cost 14,310.70

Surveyor Total 2,946.31

Lump Sum Discount (%) 20.00

Lump Sum Dls (%) 20

Final Spare Part Cost 11,448.56

Final Sur Total 2,357.05

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	* X / 11/1
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0	Not Give	* X / 11/1
One Time Key In	Main			FENDER LINER FRT/RH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	* X / 11/1
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Not Give	* X / 11/1
Total Spare Part Cost									14,310.70	Surveyor Total				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)				
Final Spare Part Cost									11,448.56	Final Sur Total				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	338.00	200	
2	Main	TO REPAIR REAR PORTION	1,183.00	600	
Total:			1,521.00	800.00	

1321

1000

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200	
2	Main	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0	
3	Main	TO RESPRAY REAR BUMPER	378.00	200	
4	Main	TO RESPRAY TAIL GATE	378.00	200	
5	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	
6	Main	TO RESPRAY REAR SPOILER	180.00	0	
7	Main	TO RESPRAY REAR PANEL	180.00	0	
8	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	
Total:			3,270.00	600.00	


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
9	Main	TO RESPRAY RIM	120.00	0	
10	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	0	
11	Main	TO RESPRAY TROUGH BACK DOOR LH	180.00	0	
12	Main	TO RESPRAY REAR FENDER LH	378.00	0	
13	Main	TO RESPRAY REAR FENDER RH	378.00	0	
Total:			1,270.00 3450	600.00 200	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	55.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40	n/c
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	20	n/c
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
5	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	50	n/c
6	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	n/c
7	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	120.00	30	n/c
8	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120	n/c
9	Main	TO REMOVE AND REFIT WIRE HARNESS	200.00	0	
10	Main	TO REPLACE SUNDRY PARTS	100.00	0	
11	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,416.00	290.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	11,448.58	2,357.05
Total Labour Cost	1,521.00	800.00
Total Spray Painting	3,270.00	600.00

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Other	1,416.00	290.00
Overall Total	17,655.56	4,047.05
Lump Sum Repair Option	☐	☒
Lump Sum Total	17,650.00	4,050.00
Surveyor Approved Amount		4,050.00
No of Repair Days*	12	6
Remarks		I/s repair, photo after paint
Surveyor Name		Here ja
Signature		 31/5/19
Survey Date	30/05/2019	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLYMENT PARTS

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	74X/05/19/2132	Date of Collection	30/5/19
Vehicle No	SHB 420 R	Date of Request	3/6/19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	1 DAY

S/N	Part Number	Part Description	Quantity	Unit Price
	1443,144	Tail Lamp Bracket RH		\$30.70 ✓
	1442	Tail Lamp Bracket LH		\$30.70 ✓
		To Repair Bnd Panel		\$250.00 \$200
		To Repair Bnd Panel		\$150.00 \$100

<<Please submit photographs for damaged parts>>

I, (Name)

PLAIA

(Position)

Do solemnly and sincerely declare that - Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration

[To be signed in front of an authorised witness]



I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PQ / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

Section A - Accident Details

Registration Number	SHB420R
Case Reference Number	TAX/05/19/2132
Registration Date	2/7/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	FOO HEE YONG (FU QIXIONG)
Type of Accident	Head to Rear
Accident Date and Time	28/5/2019 5:25 PM
Accident Reported Date and Time	29/5/2019 9:32 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	28/5/2019 5:31 PM
Replacement Vehicle issued?	No
Job Card Number	24101725
Special Instruction to ARC, if any	TOWED \$40
Prepared Date and Time	29/5/2019 1:52 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,771.00	\$1,000.00
Total Spray Cost	\$3,450.00	\$700.00
Total Spare Part Cost	\$14,359.78	\$2,992.41
Total Other Cost	\$1,416.00	(\$692.41)
TOTAL COST	\$20,993.76	\$4,000.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	13.0	7.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / NTUC
ARC / Surveyor Sign Off Date	30/05/2019 4:16 PM	30/05/2019 1:48 PM
Signature		
Remarks	1/3 repair, photo after paint.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0136	Invoice Number	
Quotation Date	10.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$338.00	\$200.00
TO REPAIR REAR PORTION	\$1,183.00	\$600.00
TO REPAIR RR END PANEL	\$250.00	\$200.00
Total Labour	\$1,771.00	\$1,000.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT BUMPER	\$378.00	\$200.00
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	\$180.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RESPRAY REAR SPOILER	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY RIM	\$120.00	\$0.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$3,450.00	\$700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$40.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$50.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$30.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$120.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00

TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$682.41)
Total Other Costs	\$1,416.00	(\$692.41)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair ✓
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given X
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check X
		57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Check X
		57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Check X
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓
		52114-47140	BRACKET, FR BUMPER	1.00	\$110.40	25.00	\$82.80	Replace	Replace ✓
			NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace ✓
			NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace ✓
		53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	1.00	\$311.10	25.00	\$233.33	Replace	Replace ✓
		53113-47040	GRILLE RADIATOR LOWER NO 2	0.00	\$94.60	0.00	\$0.00	Replace	Not Given X
		53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Not Given X
		75310-47010	EMBLEM FRONT	0.00	\$86.50	0.00	\$0.00	Replace	Not Given X
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check X
		76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given X
		52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Check X
		81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Check X
		61621-47030	TROUGH, BACK DOOR	0.00	\$110.90	0.00	\$0.00	Replace	Check X
		61604-47090	FENDER RR/RH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given X
			SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given X
			STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given X
		65637-47021	FENDER LINER RR/RH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given X
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace ✓
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace ✓
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
		88997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Check X
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace ✓
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		76068-47020	BUMPER LIP COVER RRA/LH	1.00	\$72.20	25.00	\$54.15	Replace	Replace ✓
		76067-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given X
		76691-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace ✓
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given X
		52591-47021	BUMPER SEAL, RR RH	0.00	\$55.70	0.00	\$0.00	Replace	Not Given X

52576-47020	BUMPER SIDE RETAINER R/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	✓
52575-47020	BUMPER SIDE RETAINER R/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	✓
58308-47011	UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Check	✓
67005-47241	TAILGATE ASSY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace	✓
58117-50140	DAM, BACK DOOR GLASS ADHESIVE, NO.1	1.00	\$27.30	25.00	\$20.48	Replace	Replace	✓
75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
68294-47050	DAM, BACK DOOR GLASS ADHESIVE, NO.2	1.00	\$17.40	25.00	\$13.05	Replace	Replace	✓
75575-47020	MOULDING, BACK WINDOW, LOWER NO.2	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
75574-47010	MOULDING, BACK WINDOW, OUTSIDE LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
75573-47090	MOULDING, BACK WINDOW, OUTSIDE RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
	SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	✓
69350-47030	TAILGATE DOOR LOCK	0.00	\$444.10	0.00	\$0.00	Replace	Check	✓
67881-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	0.00	\$0.00	Replace	Check	✓
69415-47020	TAILGATE LOCK, COVER	0.00	\$15.70	0.00	\$0.00	Replace	Check	✓
76801-47070-B0	TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Not Given	✓
69431-47010	STRIKER, BACK DOOR	0.00	\$48.90	0.00	\$0.00	Replace	Not Given	✓
67750-47071-C0	TAILGATE, BOARD ASSY	0.00	\$246.90	0.00	\$0.00	Replace	Not Given	✓
75310-47020	EMBLEM REAR	1.00	\$60.30	25.00	\$45.23	Replace	Replace	✓
	NUMBER PLATE	0.00	\$15.00	0.00	\$0.00	Replace	Not Given	✓
	NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given	✓
75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	✓
75442-47030	NAME PLATE (PRIUS)	0.00	\$60.80	0.00	\$0.00	Replace	Not Given	✓
75443-47030	NAME PLATE (TOYOTA)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	✓
76085-47910	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given	✓
81006-47011	3RD BRAKE LAMP	0.00	\$231.30	0.00	\$0.00	Replace	Not Given	✓
	SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	✓
	STICKER DECAL 6555 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	✓
58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check	✓
64715-47031-B0	END PANEL COVER, DECK TRIM HOLE	1.00	\$46.10	25.00	\$34.58	Replace	Replace	✓
64716-47031-B0	END PANEL COVER, DECK TRIM, RR	1.00	\$121.10	25.00	\$90.83	Replace	Replace	✓
58336-12090	REINFORCEMENT, RR	0.00	\$34.60	0.00	\$0.00	Replace	Check	✓
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check	✓
58311-47071	SPARE TYRE PANEL	0.00	\$667.70	0.00	\$0.00	Replace	Check	✓
64993-47020	BOX, DECK FLOOR, RR	0.00	\$649.70	0.00	\$0.00	Replace	Not Given	✓
58416-47030-B3	BOX, RR FLOOR, BOARD	0.00	\$679.60	0.00	\$0.00	Replace	Not Given	✓
64777-47090	CUSHION, SPARE WHEEL	0.00	\$230.80	0.00	\$0.00	Replace	Not Given	✓
64778-47050	PROTECTOR, SPARE	0.00	\$143.70	0.00	\$0.00	Replace	Not Given	✓
51931-47020	CARRIER, SPARE	0.00	\$119.70	0.00	\$0.00	Replace	Not Given	✓
	TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	✓

	42611-47140	WHEEL, DISC	0.00	\$1,490.20	0.00	\$0.00	Replace	Not Given	X
	52563-47010	TAIL LAMP BRACKET, LH	0.00	\$30.70	0.00	\$0.00	Replace	Check	X
	81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Check	X
	61622-47030	TROUGH, BACK DOOR LH	0.00	\$110.90	0.00	\$0.00	Replace	Check	X
	61602-47091	FENDER RR/LH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given	X
		SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given	X
		STICKER DECAL 6S55 8888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
	65638-47021	FENDER LINER RR/LH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given	X
	52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	X
	52115-47040	BUMPER SUPPORT F/RH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given	X
	53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	X
	53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Not Given	X
Total				\$18,345.36		\$2,946.35			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52562-47010	TAIL LAMP BRACKET, RH	1.00	\$30.70	25.00	\$23.03	Replace	Replace
		52563-47010	TAIL LAMP BRACKET, LH	1.00	\$30.70	25.00	\$23.03	Replace	Replace
Total					61.40		46.06		

2992.41
 + 1000.00
 + 990.00

 4982.41
 - 207

 3985.93
 415 \$4000/-

REQUEST FOR SUPPLYMENT PARTS

Contractor:		WEGA ENGINEERING PTE LTD	
Accident Case Number	74X/05/19/2132	Date of Collection	30/5/19
Vehicle No	SHB 420 R	Date of Request	3/6/19
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	1 DAY

S/N	Part Number	Part Description	Quantity	Unit Price
	1443, 44	Tail Lamp Bracket RH		\$ 30.70 ✓ CRA
	1442	Tail Lamp Bracket LH		\$ 30.70 ✓ CRA
		To Repair Bnd Panel		\$250.00 \$200
		To Repay Bnd Panel		\$150.00 \$100

<<Please submit photographs for damaged parts>>

I, (Name)

ELAN

(Position)

Do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.



Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / (P) / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19009654/Etd3e2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 04-09-2019	
			Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGW 1289Z	Veh. Inspected	SHB 420R	
Policy No.	5073885207-03	Coverage (\$)	0.00	
Claim No.	MT/1046796-002	Excess (\$)	0.00	
Assign From		Assign Date	30/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U905746651	Colour	MAROON	
Odometer	409138	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION, DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/05/2019	Inspection Date	30/05/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 420R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BRACKET, FR BUMPER (DISC 25%)	BROKEN	110.40	82.80
1	BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%)	CUT	311.10	233.33
1	BUMPER REAR (DISC 25%)	DENTED	458.60	343.95
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER REINFORCEMENT REAR (DISC 25%)	DENTED	205.70	154.28
1	ARM SUB-ASSY, RR BUMPER LH (DISC 25%)	DENTED	139.60	104.70
1	ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	DENTED	139.60	104.70
1	BUMPER LIP COVER RR/LH (DISC 25%)	CRUSHED	72.20	54.15
1	BUMPER LIP REAR (DISC 25%)	CRUSHED	228.90	171.68
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	BROKEN	94.80	71.10
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	BROKEN	94.80	71.10
1	TAILGATE ASY (DISC 25%)	DENTED	1,007.90	755.93
1	DAM, BACK DOOR GLASS ADHESIVE, NO. 1 (DISC 25%)	NECESSARY	27.30	20.48
1	TAIL GATE DOOR GLASS MOULDING, LH (DISC 25%)	NECESSARY	29.40	22.05
1	TAIL GATE DOOR GLASS MOULDING, RH (DISC 25%)	NECESSARY	29.40	22.05
1	MOULDING BACK WINDOW, LOWER NO. 1 (DISC 25%)	NECESSARY	29.40	22.05
1	DAM, BACK DOOR GLASS ADHESIVE, NO. 2 (DISC 25%)	NECESSARY	17.40	13.05
1	MOULDING, BACK WINDOW, LOWER NO. 2 (DISC 25%)	NECESSARY	29.40	22.05
1	MOULDING, BACK WINDOW, OUTSIDE LH NO. 2 (DISC 25%)	NECESSARY	29.40	22.05
1	MOULDING, BACK WINDOW, OUTSIDE RH NO. 2 (DISC 25%)	NECESSARY	29.40	22.05
1	EMBLEM REAR (DISC 25%)	NECESSARY	60.30	45.23
1	END PANEL COVER, DECK TRIM HOLE (DISC 25%)	CRUSHED	46.10	34.58
1	END PANEL COVER, DECK TRIM, RR (DISC 25%)	CRUSHED	121.10	90.83
1	TAIL LAMP BRACKET, RH (DISC 25%)	CRACKED	30.70	23.03
1	TAIL LAMP BRACKET, LH (DISC 25%)	CRACKED	30.70	23.03
1	NUMBER PLATE (SN)	DENTED	15.00	15.00
1	NUMBER PLATE FRAME (SN)	DENTED	12.00	12.00
1	SENSOR REVERSE (SN)	BROKEN	180.00	180.00

Report Ref No. NS/INC19009654/Etd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No. 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
3	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	111.00	111.00
1	BUMPER ENERGY ABSORBER FRT	NOT NECESSARY	78.80	-
1	BUMPER REINFORCEMENT FRT	NOT NECESSARY	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	NOT NECESSARY	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH	NOT NECESSARY	250.40	-
1	GRILLE RADIATOR LOWER NO. 2	NOT NECESSARY	94.60	-
1	GRILLE, RADIATOR	NOT NECESSARY	310.60	-
1	EMBLEM FRONT	NOT NECESSARY	86.50	-
1	BUMPER FRT ABSORBER LOWER	NOT NECESSARY	127.70	-
1	BUMPER LIP FRT	NOT NECESSARY	139.60	-
1	TAIL LAMP BRACKET, RH	NOT NECESSARY	30.70	-
1	TAIL LAMP RH	NOT NECESSARY	557.80	-
1	TROUGH, BACK DOOR	NOT NECESSARY	110.90	-
1	FENDER RR/RH	NOT NECESSARY	766.80	-
1	SMRT LOGO	NOT NECESSARY	7.80	-
1	STICKER DECAL 6555 8888	NOT NECESSARY	21.60	-
1	FENDER LINER RR/RH	NOT NECESSARY	141.30	-
1	ANTENNA, ELECTRICAL LOWER REAR	NOT NECESSARY	157.40	-
1	BUMPER LIP COVER RR/RH	NOT NECESSARY	118.10	-
1	BUMPER SEAL, RR LH	NOT NECESSARY	88.90	-
1	BUMPER SEAL, RR RH	NOT NECESSARY	65.70	-
1	UNDER COVER SUBASSY, RR FLOOR	NOT NECESSARY	514.50	-
1	TAILGATE DOOR LOCK	NOT NECESSARY	444.10	-
1	TAILGATE DOOR WEATHER STRIP	NOT NECESSARY	353.40	-
1	TAILGATE LOCK, COVER	NOT NECESSARY	15.70	-
1	TAILGATE OUTSIDE GARNISH	NOT NECESSARY	504.90	-
1	STRIKER, BACK DOOR	NOT NECESSARY	48.90	-
1	TAILGATE, BOARD ASSY	NOT NECESSARY	246.90	-
1	NUMBER PLATE	NOT NECESSARY	15.00	-
1	NUMBER PLATE FRAME	NOT NECESSARY	12.00	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	NAME PLATE (PRIUS)	NOT NECESSARY	60.80	-

Report Ref No. NS/INC19009654/Etd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No. 3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	NAME PLATE (TOYOTA)	NOT NECESSARY	51.90	-
1	SPOILER REAR	NOT NECESSARY	953.70	-
1	3RD BRAKE LAMP	NOT NECESSARY	231.30	-
1	SMRT LOGO	NOT NECESSARY	7.80	-
1	STICKER DECAL 6555 8888	NOT NECESSARY	21.60	-
1	END PANEL	NOT NECESSARY	602.10	-
2	REINFORCEMENT, RR @\$34.60	NOT NECESSARY	69.20	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	SPARE TYRE PANEL	NOT NECESSARY	667.70	-
1	BOX, DECK FLOOR, RR	NOT NECESSARY	649.70	-
1	BOX, RR FLOOR, BOARD	NOT NECESSARY	679.60	-
1	CUSHION, SPARE WHEEL	NOT NECESSARY	230.80	-
1	PROTECTOR, SPARE	NOT NECESSARY	143.70	-
1	CARRIER, SPARE	NOT NECESSARY	19.70	-
1	TYRE	NOT NECESSARY	126.74	-
1	WHEEL, DISC	NOT NECESSARY	1,490.20	-
1	TAIL LAMP BRACKET, LH	NOT NECESSARY	30.70	-
1	TAIL LAMP LH	NOT NECESSARY	548.40	-
1	TROUGH, BACK DOOR LH	NOT NECESSARY	110.90	-
1	FENDER RR/LH	NOT NECESSARY	766.80	-
1	SMRT LOGO	NOT NECESSARY	7.80	-
1	STICKER DECAL 6555 8888	NOT NECESSARY	21.60	-
1	FENDER LINER RR/LH	NOT NECESSARY	141.30	-
1	BUMPER SUPPORT F/LH	NOT NECESSARY	76.40	-
1	BUMPER SUPPORT F/RH	NOT NECESSARY	76.40	-
1	FENDER LINER FRT/RH	NOT NECESSARY	171.70	-
1	FENDER LINER FRT/LH	NOT NECESSARY	171.70	-
1	BUMPER FRT	TO REPAIR SEE LABOUR	482.00	-
			18,604.34	2,992.41
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF BUMPER FRT.		1,771.00	1,000.00

Report Ref No. NS/INC19009654/Etd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No. 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINT.		3,450.00	700.00
	TOWING CHARGE.		56.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	40.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		200.00	20.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO TRANSFER REAR TAILGATE MECHANISM.		120.00	50.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	30.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	30.00
	TO REMOVE AND REFIX REAR WINDSCREEN.		240.00	120.00
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	200.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			6,637.00	1,990.00
GRAND TOTAL			25,241.34	4,982.41
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,000.00

Report Ref No. NS/INC19009654/Etd3e2

CHEN TSUE YEE

Automotive Assessor

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.