

ASS. REC. BY:

REF: CS/CT1900 9658 / Ucd3 n2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)From (Person): Chong Boon Senof CT1Date/Time: 31.5.19 10.51 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBC 4203KInsured: GBF 9171Aat Workshop m/s Liu's BrotherTel: 6741730of BK-1 KKK Bt Ave 6 # 01-01Policy No: DMCVSN 18079219011Claim No: SMM 191020227307

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19.5.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 31.5.19 11.23 pm

Person Contacted:

Susan

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>Estimate CV</u>
	<u>GBC 4203K - CS/MSG 15012/07 / Bt Ave 2</u>
	<u>GBF 9171A - CS/CT1 19009106 / Bt Ave 3</u>

D.O.A. - 15/10/2015

D.O.A. - 19/05/2019

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *C13C 4205*at Workshop m/s *1115*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *24*

IDAC Accident Rpt: _____

Consistent? : Yes or No

G/A / PR Seen: *2*

Consistent? : Yes or No

Est. Repairs: *12*

days

Res: Yes or No

Lum Sum: *20*

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

HA 11035

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: *C13C 4205*Yr Regn: *3 112*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CM*Make: *Nissan cabstar*cc *2953*Colour: *silver*

A/C: Insured / Std / NI / NA

Sp. Reading: *Safety flap*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JN1SC2F2K8085-0314*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *185-R15*R: *165-R13*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *6*

mm

R/Bal. *6/6*

mm

L/Bal. *6*

mm

L/Bal. *6/6*

mm

D.O.A. *19/5/19*D.O.A. *31/5/19*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear &

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*12/6/19**12/6/19 4/5 @ 8800 confirmed with Susan.
(\$ 14,928.40 Red - 63%)*

Date/Time, File Pass to?

12/06/19

1) Typist

Date/Time, File Return to?

2) _____



: Preli. Report



: Final Report

Days Of Repair: *12*Resurvey No. of Trip: *2*

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

) S + RS \$ _____



: Interview (\$ _____)

) Photos: _____



: Tech. Invs (\$ _____)

) Others: _____



: Weekend (\$ _____)

) _____

Report Format :

Lump Sum / I.B.I: (\$ *8,800/- 45*)

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 May 2019		31 May 2019 10:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	METALIS PTE LTD, Co. Reg. No.: 199205491R								
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N								
Vehicle Reg. No.:	GBC4205K	Date of Loss:	19/05/2019 17:00 - :59 [86 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202273C02	Policy/Cover Note No.:	DMCVSN18079219011 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBF9171A	Policy No. (Claimant):	D-18090757MFCV						
		Excess:	S\$0.00						
Repairer:	Liu's Brother Auto Engineering Workshop (Kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/06/2019]								
Driver/Custodian (Insured):	LIM TONG YAM (58 / Male), NRIC: S14163231 Email:								
Adj Asg. Remarks:	please assign MR Marcus Chua for SJE. thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Nissan Cabstar

Price Range

Depreciation

2012

Vehicle Type



Home » Used Cars » SG Motor Link Pte Ltd » Nissan Cabstar

Nissan Cabstar

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price	\$22,800	Lifespan	27-Feb-2032
Depreciation ⓘ	\$8,320 /yr View models with similar depre	Reg Date	28-Feb-2012 (2yrs 8mths 24days COE left)
Mileage	N.A.	Manufactured ⓘ	2011
Road Tax ⓘ	N.A.	Transmission	Manual
Dereg Value ⓘ	\$11,011 as of today (change)	OMV ⓘ	\$33,399
COE ⓘ	\$40,189	ARF ⓘ	\$1,670
Engine Cap	2,953 cc	No. of Owners ⓘ	1
Curb Weight ⓘ	1,800 kg		
Type of Vehicle	Truck		

Features

Rare And Unique 10-Ft Nissan Cabstar Lorry Promotion! View specs of the Nissan Cabstar (2008-2009)

Accessories

Rare Baby Blue Colour In Town. Readily Installed Full Retractable Canopy With Full Checker Plate. Radio/Audio System.

Description

Price Negotiable! 1 Owner! Well Maintained! Retractable Canopy! Door Step Viewing Available! Call Now!

Category

Premium Ad Car

Sta

Compare



Price Chart



Click on the point to view

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

BMW PREMIUM SELECTION.
 CERTIFIED PRE-OWNED BY PERFORMANCE PREMIUM SELECTION.
[Find out more](#)



Nissan Cabstar

Price Range ▼

Depreciation ▼

2012 ▼

Vehicle Type ▼



Home » Used Cars » Bee Huat Credit » Nissan Cabstar

Nissan Cabstar

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price	\$23,388	Lifespan	08-Mar-2032
Depreciation ⓘ	\$8,460 /yr View models with similar depre	Reg Date	09-Mar-2012 (2yrs 9mths 5days COE left)
Mileage	N.A.	Manufactured ⓘ	2011
Road Tax ⓘ	N.A.	Transmission	Manual
Dereg Value ⓘ	\$10,944 as of today (change)	OMV ⓘ	\$34,386
COE ⓘ	\$39,589	ARF ⓘ	\$1,720
Engine Cap	2,953 cc	No. of Owners ⓘ	1
Curb Weight ⓘ	1,800 kg		
Type of Vehicle	Truck		

Features

Powerful And Responsive Diesel Engine, Power Steering, Etc. [View specs of the Nissan Cabstar \(2008-2009\)](#)

Accessories

Full Factory Fitted Accessories.

Description

Only One Careful Owner, Most Popular And Reliable 10 Feet Lorry, Regular Service, Road Tax Till 9/2019, High Trade In And Loan Available.

Category


Status

Available

Resources

[Compare](#)
[tion](#)


Price Chart



[Click on the point to view](#)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Owner ID:

Company

1196N

Vehicle Details

Vehicle No:

GBC4205K

Vehicle to be Exported:

No

Intended Deregistration Date:

28 May 2019

Vehicle Make:

NISSAN

Vehicle Model:

CABSTAR 3.0 5M/T ABS 2DR 2WD TURBO

Primary Colour:

Silver

Manufacturing Year:

2011

Engine No:

7D30297425K

Chassis No:

JN15C2F24ZQ850314

Maximum Power Output:

Open Market Value:

\$34,386.00

Original Registration Date:

15 Mar 2012

First Registration Date:

15 Mar 2012

Transfer Count:

1

Actual ARF Paid:

\$1,720.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

14 Mar 2022

COE Category:

C Goorts Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$39,589.00

COE Rebate Amount:

\$11,035.00

Total Rebate Amount:

\$11,035.00

The information contained herein is correct as at 28 May 2019

OK

LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: GBC4202X190519

Estimate

Customer

Name: China Taiping Insurance (Singapore) Pte Ltd

Address: Motor Claims Department

3 Anson Road #16-00

Springleaf Tower	Singapore 079909
------------------	------------------

Date: 30-05-19

Vehicle No: GBC4205K

Model/Make: Nissan Cabstar 3.0

5 M/T ABS 2DR 2WD Turbo

Item No.	Descriptions Of Parts	Quotation / Estimation	Cost Of Repair
1	Rear Tailgate	\$ 1,688.40	✓
2	Tailgate Inner Aluminium Board	\$ 450.00	SN 350 S.N
3	Tailgate '12 Pax' sticker	\$ 15.00	SN 10 S.N
4	Tailgate '70KM/H' sticker	\$ 15.00	SN 10 S.N
5	Tailgate Lower Panel	\$ 1,440.00	✓
6	Tailgate Lock Latch 02 pcs (@ \$5137.40)	\$ 274.80	12C
7	Tailgate lower 'L' Panel 02 pcs (@ \$5141.60)	\$ 283.20	12C
8	Tailgate Lower "L" Panel Screw 1 set	\$ 30.00	SN X
9	Tailgate lower 'L' Panel stopper 02 pcs (@ \$565.50)	\$ 131.00	12C
10	Tailgate Lower "L" Panel Stopper Screw 1 set	\$ 30.00	SN X
11	Tail Lamp 02 pcs (@ \$5247.20 N)	\$ 494.40	N 12C
12	Bumper Reverse Sensor	\$ 220.00	SN 200 S.N
13	Floor Panel	\$ 4,120.00	X
14	Floor Panel Aluminium Board	\$ 780.00	SN 600 S.N
15	Floor Panel Support	\$ 970.00	X
16	Spare Tyre Carrier	\$ 670.00	X
17	Exhaust Pipe	\$ 960.00	X
18	Engine Water Hose	\$ 390.00	✓
19	Engine Manifold Hose	\$ 667.00	✓
20	Number Plate Lamp	\$ 108.00	X
21	Number Plate "Metal"	\$ 38.00	SN 15 S.N
22	"Corporate" Advertisement & Artwork	\$ 700.00	SN 500 S.N
23	Step Bar	\$ 650.00	SN 400 S.N
24	Rear Rh Sidegate	\$ 2,915.10	✓
25	Sidegate Inner Aluminium Board	\$ 600.00	SN X
26	Sidegate Lock	\$ 370.00	X
27	Sidegate Handle	\$ 188.50	X
	To check front & rear all wiring & electrical component for proper function	\$ 60.00	- 30
	To remove, replace and transfer tailgate & sidegate panel, fitting and mechanism	\$ 220.00	12C X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 2,000.00	- 1800
	To putty & spray painting & including touch up paint on accident affected area	\$ 1,600.00	- 1000
	Remove and refix rear reverse sensor	\$ 100.00	- 50
	To apply Rust Proofing, reseat tuff-coating treatment on accident area	\$ 100.00	- 50
	Remove and refix rear cargo deck assembly & Aluminium Board	\$ 450.00	- 400

Total Parts & Labour of estimate for damaged vehicle	
--	--

\$ 23,728.40

Total amount in Lump Sum Basis for repaired vehicle	
---	--

SDLS:



M/s Liu's Brother Auto Engrg Wks

P-6178-50

102

P-5560.6

C.N-7085.

ky 3360

1968-1970

1003-00
0014

1004

Summ. of factors

not Anticent
able

31/5/19

1/10 = 880

2/3
Wm pvt. Atkiss - 127

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119009658/USD3N2

Date: 17/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN18079219011
Claimant Vehicle No :	GBC4205K	Insured Vehicle No :	GBF9171A
Date of Loss:	19/05/2019	Nature of Claim:	TP
		Claim No:	SNM19D202273C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC4205K		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30297425K
Reg. Date:	15/03/2012 (Man. Year: 2011)	Chassis No:	JN1SC2F24Z0850314
Colour:	Silver	Odometer:	0 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	165R13 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	19,198.40	7,645.65	11,552.75	60.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,530.00	3,360.00	1,170.00	25.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,728.40	11,005.65	12,722.75	53.62
Approved Total (Overridden) (\$\$)		8,800.00		
Nett Amount (\$\$)	23,728.40	8,800.00	14,928.40	62.91

INSPECTION

Date of Assignment:	31/05/2019	
Date Inspected:	31/05/2019	Inspected At:
		Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit Singapore 417883
Estimated Period of Repair:	12.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Jun 2019)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC4205K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	1,688.40 F	*1,450.70 FN
2	1		*REAR TAILGATE LOWER PANEL	Badly Dented	1,440.00 F	*878.10 FN
3	1		*REAR TAILGATE LOCK LATCH	O/s Bent	274.80 F	*137.40 FN
4	1		*REAR TAILGATE LOWER L PANEL	O/s Bent	283.20 F	*141.60 FN
5	1		*REAR TAILGATE LOWER L PANEL STOPPER	O/s Missing	131.00 F	*65.50 FN
6	1		*REAR TAIL LAMP	O/s Broken	494.40 F	*247.20 FN
7	1		*REAR FLOOR PANEL	Repair	4,120.00 F	*- FN
8	1		*REAR FLOOR PANEL SUPPORT	Repair	970.00 F	*- FN
9	1		*REAR SPARE TYRE CARRIER	Not Necessary	670.00 F	*- FN
10	1		*REAR EXHAUST PIPE	Repair	960.00 F	*- FN
11	1		*REAR ENGINE WATER HOSE	Damaged	390.00 F	*390.00 FN
12	1		*REAR ENGINE MANIFUL HOSE	Damaged	667.00 F	*667.00 FN
13	1		*REAR NUMBER PLATE LAMP	Not Necessary	108.00 F	*- FN
14	1		*REAR RH SIDEGATE	Dented/Cracked	2,915.10 F	*2,201.00 FN
15	1		*REAR SIDEGATE LOCK	Not Necessary	370.00 F	*- FN
16	1		*REAR SIDEGATE HANDLE	Not Necessary	188.50 F	*- FN
17	1		*REAR TAILGATE INNER CLUMINIUM BOARD	Dented/Bent	450.00 FS	*350.00 FS
18	1		*REAR TAILGATE 12 PAX STICKER	Necessary	15.00 FS	*10.00 FS
19	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
20	1		*SET REAR TAILGATE LOWER L PANEL SCREW	Not Necessary	30.00 FS	*- FS
21	1		*SET REAR TAILGATE LOWER L PANEL STOPPER SCREW	Not Necessary	30.00 FS	*- FS
22	1		*SET REAR BUMPER REVERSE SENSOR	Cracked	220.00 FS	*200.00 FS
23	1		*REAR FLOOR PANEL ALUMINIUM BOARD	Bent/Buckled	780.00 FS	*600.00 FS
24	1		*REAR NUMBER PLATE METAL	Bent	38.00 FS	*15.00 FS
25	1		*SET REAR CORPORATE ADVERTISEMENT & ARTWORK	Necessary	700.00 FS	*500.00 FS
26	1		*REAR STEP BAR	Distorted	650.00 FS	*400.00 FS
27	1		*REAR SIDEGATE INNER ALUMINIUM BOARD	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc

Sub Total (\$\$)	19,198.40	8,263.50
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	617.85
Total Parts (\$\$)	19,198.40	7,645.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK FRONT & REAR ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	60.00	30.00
2	TO REMOVE, REPLACE AND TRANSFER TAILGATE & SIDE GATE PANEL, FITTING AND MECHANISM	New	220.00	0.00
3	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETC INCLUDING REPAIR CHASSIS	New	2,000.00	1,800.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	1,600.00	1,000.00
5	REMOVE AND REFIX REAR REVERSE SENSOR	New	100.00	50.00
6	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	100.00	80.00
7	REMOVE AND REFIX REAR CARGO DECK ASSEMBLY & ALUMINIUM BOARD	New	450.00	400.00
Gross Labour Cost (S\$)			4,530.00	3,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >