	22/03/2002 ASS. REC. BY:		REFCS3/A16	719009682/6	acd3LV	Special Instruction:		
	Surveyor:	GQ	ASSI	GNMENT (Off	ice)			
Ninn	From (Person)	, chin Lu Yin	of of			Date/Time: 315.19 3.34p.M		
	Estimated Cos	t:		Bill to:				
	To Inspect Ve	hicle No: SLD	2308 L	MV 7 CS	Insur	ed: GBE 3349 A		
		BUKH Road		n synrgy				
	Policy No:	2100434313	10	Claim	No: <del>53</del>	5311082503.54		
1	Sum Insured:			Exce	ess:			
	Make of Veh: (Client's Record					D.O.A. 31.5 - 2019		
	100	REP. / REV 241		acted:MS_L	im	H.O.D. Endorsement:		
	Date/Time	Action/Instruction		imate				
		SLD 2308 L GBE 3349 P						
		Dismartle:						
		After repair:						

.

From Date: 31.5. 2019  Estimpted Cost:   Description Cost:  Descriptio		ar.	COLUMNATION		
Estingted Cost:  OD TTP WISTT RESIDD RESIDNAMINUM To Inspect Vehicle No: SLD 32-0.6 L at Workshop mis APREX metroring or 35 kpt Buth Road 4 # # ol-55 SUNVEY insured: Policy No. Claims No. Sum Insured: Excess: (Clent's Record) Make of Velt:  (Clent's Record) Make of Velt:  (Policy Condition) Remark: The veh had commenced its repair at the time of inspection.  Bat or Market Value:  (Policy Condition) Remark: The veh had commenced its repair at the time of inspection.  Bat or Market Value:  (Policy Condition) Remark: The veh had commenced its repair at the time of inspection.  Bat or Market Value:  (Policy Condition) Remark: The veh had commenced its repair at the time of inspection.  Bat or Market Value:  (Policy Condition) Remark: The veh had commenced its repair at the time of inspection.  Bat or Market Value:  (Policy Condition) Remark: The veh had commenced its repair at the time of inspection.  Bat or Market Value:  (Policy Condition) Remark: The veh had commenced its repair at the time of inspection.  Bat or Market Value:  (Policy Condition) Remark: The veh had commenced its repair at the time of inspection.  Bat or Market Value:  IDAG Accident Rport:  Consistent? Yes or No  Lum Som:  9 3 Val. Yes or No  Lum Som:  9 3 Val. Yes or No  CA / REV / REP. / 24 HRS  Vehicle: IN / OUT  The file? Chassis frame / Body Structure affected due to or  The file? Chassis frame / Body Structure affected due to or  The file? Chassis frame / Body Structure affected due to or  The file? Chassis frame / Body Structure affected due to or  The file? Chassis frame / Body Structure affected due to or  The file? Chassis frame / Body Structure affected due to or  The file? Chassis frame / Body Structure affected due to or  The file? Chassis frame / Body Structure affected due to or  The file? Chassis frame / Body Structure affected due to or  The file? Chassis frame / Body Structure affected due to or  The file? Chassis frame / Body Structure affected due to or  The file? Chassis frame / Body Structure affected due to or  The file? C	35.	hard to the second seco		, +	
Truck / Trailer or  Truck / Trailer or  Truck / Trailer or  Make: Toyled Affice and Affi	From:	Date: 31.5. 2019			
To Inspect Vehicle No: SLD 220% Lat Workshop mis Apex Metholog of 315 kApt Butch Road 4 # 01-55 \$V)NV(V) Sp. Reading 25576 Tr. Radio: Insured 15td / Ni Insured: Policy No.  Claims No.  Sum Insured: Excess: Claims No.  Som Insured: Insured I start of Insured I start	Estimated Cost:		Type: MCas/ M.Cycle / Bus / Van / I	orry / Taxi / Prime Mo	ver/
at Workshop m/s  APEX Methon 9  of 35 Ke/Li Bukith Road 4 # for 55 Stynuloy  Insured:  Policy No.  Claims No.  Sum Insured:  Ciclient's Record)  Make of Veh:  (Client's Record)  Make of Veh:  (Policy Condition)  Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value:  IDAC Accident Rport:  Consistent? 'Yes or No  GIA / PR Seen:  Consistent? 'Yes or No  Lum Sum:  3 Val.: Yes or No  Survey held at  Date / Time  Person Confacted:  Person Confacted:  Person Confacted:  The IDC Chassis frame / Body Structure affected due to or  Add Fee:  Survey held at  Date / Time  Add Fee:  Survey Fee:  Resurvey No. of Trip:  Survey Fee:  Resurvey No. of	OD TP WS TP R	ES / OD RES / EVA / INV / MV	Truck / Trailer or		
Insured:  Policy No.  Claims No.  Sum Insured:  (Client's Record)  Make of Veh:  (Policy Condition)  Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value:  IDAC Accident Rport:  GIA / PR Seen:  Consistent?: Yes or No  GIA / PR Seen:  CA / REV / REP. / 24 HRS  Date / Time  Action / Instruction  Date / Instruction / Instruction  Date / Instruction / Instruction  D	To Inspect Vehicle N	o: SLD 2308 L		attis c.c	1598
Insured: Policy No. Claims No. Sum Insured: Policy Condition  Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No Est. Repairs: Date: Person Contacted:  Date:  Person Contacted:  Date:  Person Contacted:  Date: Date: Person Contacted:  Date: Date: Person Contacted:  Date: Person Contacted: Date: Person Contacted: Date: Person Contacted: Date: Person Contacted: Date: Person Contacted: Date: Person Contacted: Date: Person Contacted: Date: Person Contacted: Date: Person Contacted: Date:	at Workshop m/s	Apex motoring	Colour Silver	A/C: Insured /	Std / NI / NA
Policy No. Claims No. Sum Insured: Excess:   Seeing: Ino@er / Jammed / Leaked / Burnt or   Steering: Ino@er / Jammed / Leaked / Burnt or   Make of Veh:   Seeing: Ino@er / Jammed / Leaked / Burnt or   Modi: Nil / SiRim / STD Ostim or   Tyre Size: F: 205 / SS R16   R:   NIS OJS   Remark: The veh had commenced its   repair at the time of inspection.   Bal. or Market Value:   IDAC Accident Rport:   Consistent? : Yes or No   Est Repairs:   days   Res.: Yes or No   Caf / PR Seen:   Consistent? : Yes or No   Caf / PR Seen:   Gays   Res.: Yes or No   Caf / REV / REP. / 24 HRS   Vehicle: IN / OUT   Date:   Person Contacted:   Vehicle: IN / OUT   Date:   Person Contacted:   Vehicle: IN / OUT   Date:   Person Contacted:   The @rC   Chassis frame / Body Structure affected due to co   Date / Time   Action / Instruction   Date / Time   Action / Instruction   Date / Time   Action / Instruction   Date / Time   Sie Pass 107   : Prell. Report   Date / Time   Resurvey No. of Trip:   Survey Fee:   Resurvey No. of Trip:   Sur	of 25 kati Bu	1kit Road 4 # 01-55 synerg	Sp.Reading 205576	T/Radio: Insured /	Std / NI / NA
Claims No.  Sum Insured:  Claims Record)  Make of Veh:  (Client's Record)  Make of Veh:  (Policy Condition)  Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value:  IDAC Accident Rport:  Consistent?: Yes or No  Est. Repairs:  days Res.: Yes or No  Stat.: Yes or No  Stat.: Yes or No  CA / REV / REP. / 24 HRS  OAL:: Yes or No  Date:  Date / Time Action / Instruction  Date:  Date / Time Action / Instruction  Date:  Preli. Report  Date:  Preli. Report  Date:  Preli. Report  Date:  Sizering: Incoder / Jammed / Leaked / Burnt or  Modi: Nii / SIRim / STD/ORim or  Tyre Size: F: 205 / SS R/16  Bs / DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  TOYO / YOKO or  From  RBal. S  MIS OUS  BS / DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  TOYO / YOKO or  From  RBal. S  MIS OUS  BS / DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  TOYO / YOKO or  From  RBal. S  MIS OUS  BS / DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  TOYO / YOKO or  From  RBal. S  MIS OUS  BS / DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  TOYO / YOKO or  From  RBal. S  MIS OUS  BS / DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  TOYO / YOKO or  From  RBal. S  MIS OUS  RBa. S  MIS OUS  RBa. S  NIS OUS  RBa. S  MIS	Insured:		Eng/No:		
Claims No.  Sum Insured:  Claims Record)  Make of Veh:  (Client's Record)  Make of Veh:  (Policy Condition)  Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value:  IDAC Accident Rport:  Consistent?: Yes or No  Est. Repairs:  days Res.: Yes or No  Stat.: Yes or No  Stat.: Yes or No  CA / REV / REP. / 24 HRS  OAL:: Yes or No  Date:  Date / Time Action / Instruction  Date:  Date / Time Action / Instruction  Date:  Preli. Report  Date:  Preli. Report  Date:  Preli. Report  Date:  Sizering: Incoder / Jammed / Leaked / Burnt or  Modi: Nii / SIRim / STD/ORim or  Tyre Size: F: 205 / SS R/16  Bs / DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  TOYO / YOKO or  From  RBal. S  MIS OUS  BS / DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  TOYO / YOKO or  From  RBal. S  MIS OUS  BS / DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  TOYO / YOKO or  From  RBal. S  MIS OUS  BS / DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  TOYO / YOKO or  From  RBal. S  MIS OUS  BS / DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  TOYO / YOKO or  From  RBal. S  MIS OUS  BS / DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  TOYO / YOKO or  From  RBal. S  MIS OUS  RBa. S  MIS OUS  RBa. S  NIS OUS  RBa. S  MIS	Policy No.		C/No: URO53 RE	EH 10453	8461
Steering: Incord   Leaked   Burnt or Brake:   Incord   Incord   Burnt or Modi: Nil   Sirim   Steering: Incord   Jammed   Leaked   Burnt or Modi: Nil   Sirim   Steering: Incord   Jammed   Leaked   Burnt or Modi: Nil   Sirim   Steering: Incord   Steering: Incord   Jammed   Leaked   Burnt or Modi: Nil   Sirim   Steering: Incord   Steerin					
(Client's Record) Make of Veh:  Modi: Nill / SirRim / STD Oslim or Tyre Size: F: 205 / 55 R/6  R: //  Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No GIA / PR Seen: Gays Res.: Yes or No Cays Res.: Yes or No Cay / REV / REP. / 24 HRS  Date: Person Contacted:  Date / Time		Excess:	Steering: Inorger / Jammed / Leaked	d/Burnt or	
Mode of Veh:    Mode   Nii   S/Rim   STD_OSIm or Tyre Size: F: 205   55 RH6		6	Brake: Inorder / Jammed / Leaked	d/Burnt or	
(Policy Condition)  Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value:  Bal. or Market Value:  IDAC Accident Rport:  Consistent? : Yes or No  GIA / PR Seen:  Consistent? : Yes or No  GIA / PR Seen:  Consistent? : Yes or No  GIA / PR Seen:  Consistent? : Yes or No  Consistent? : Yes or No  GIA / REV / REP. / 24 HRS  Total or Market Value:  Date / Time   Action / Instruction  Date / Ti			Modi: Nil / S/Rim / STD ARim	or	
(Policy Condition)  Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value:  Bal. or Market Value:  IDAC Accident Rport:  Consistent?: Yes or No  GIA / PR Seen:  Consistent?: Yes or No  Est. Repairs:  days Res.: Yes or No  CA / REV / REP. / 24 HRS  Person Contacted:  Date / Time	UNITED TO THE PARTY OF THE PART	v			
Remark: The veh had commenced its repair at the time of inspection.  Bal. or Market Value:  IDAC Accident Rport:  Consistent?: Yes or No  GIA / PR Seen:  Consistent?: Yes or No  Streep held at  Date / Time  Action / Instruction  Date / Time   Return to?  Action / Instruction  Date / Time   Return to?  Add Fee:  Site Insp (\$	(Deline Condition)			11	
repair at the time of inspection.  Bal. or Market Value:  IDAC Accident Rport:  Consistent?: Yes or No  GIA / PR Seen:  Consistent?: Yes or No  Est. Repairs:  days Res.: Yes or No  LUBal.  Survey held at  Des. of Damages: Frt / Rear pois / Nis / UiC / Rooftop or provided due to complete the provided due t	The state of the s	od commenced its N/S O/	THE CONTRACTOR	A / MIC / OHTSU / PIR /	SUMI /
Bal. or Market Value:  IDAC Accident Rport: Consistent?: Yes or No  GIA / PR Seen: Consistent?: Yes or No  Est. Repairs: Adays Res.: Yes or No  LUBal. S mm Ribal. S  D.O.A.  D.O.A.  Survey held at  Des. of Damages: Frt / Rear pols / Nis / U/C / Rooftop or poly  Action / Instruction  Date / Time Action / Instruction  Date / Time Action / Instruction  Date / Time Return to?  Date / Time Return to?  Add Fee: Site Insp (\$ ) Survey Fee: Transportation.  Survey No. of Trip: S Survey Fee: Transportation.  Add Fee: Site Insp (\$ ) Photos  Photos  Report Format: DRK  Rear Ribal. S mm Ribal. S  mm L/Bal. S mm L/Bal. S  D.O.A.  D.O.A.  Survey held at  Des. of Damages: Frt / Rear pols / Nis / U/C / Rooftop or pols / Nis / U/C / R				,,	
DAC Accident Rport: Consistent? : Yes or No  GIA / PR Seen: Consistent? : Yes or No  Est. Repairs: Adays Res.: Yes or No  LUBal. S  D.O.A. D.O.I. 3 / - o.S - o.  D.O.I. 3 / - o.S - o.  LUBal. S  D.O.A. D.O.I. 3 / - o.S - o.  D.O.A. D.O.A. D.O.I. 3 / - o.S - o.  D.O.A. D.O.A. D.O.I. 3 / - o.S - o.  D.O.A. D.O.A. D.O.I. 3 / - o.S - o.  D.O.A. D.O.A. D.O.I. 3 / - o.S - o.  D.O.A. D.O.A. D.O.I. 3 / - o.S - o.  D.O.A. D.O.A. D.O.I. 3 / - o.S - o.  D.O.A. D.O.A. D.O.I. 3 / - o.S - o.  D.O.A. D.O.A. D.O.I. 3 / - o.S - o.  D.O.A. D.O.A. D.O.I. 3 / - o.S - o.  D.O.A. D.O.A. D.O.I. 3 / - o.S - o.  D				Rear	
Date/Time. File Pass to?  Date/Time. File Return to?  Date/Time. File Return to?  Add Fee:  DATE Accident Rport:  Consistent?: Yes or No  Consistent?: Yes or No  Double Accident Rport:  Double Accident Rport:  Double Accident Rport:  Consistent?: Yes or No  Double Accident Rport:  Double Accident Rport:  Double Accident Rport:  Consistent?: Yes or No  Double Accident Rport:  Double Accident Rport:  Double Accident Rport:  Consistent?: Yes or No  Double Accident Rport:  Double Accident Rport:  Double Accident Rport:  Consistent?: Yes or No  Double Accident Rport:  Double Accident Rport:  Double Accident Rport:  Consistent?: Yes or No  Double Accident Rport  Double Accident Report  Double Accident Rport  Double Accident Report  Double Accident Report  Double Accident Report  Double Acciden				1	mn
Est. Repairs:    Survey held at   Survey			L.D.	. (	> mn
Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS  Vehicle: IN/OUT  Date: Person Contacted: Vehicle: IN/OUT  Date / Time   Action / Instruction  Date / Time   Action / Instruction  Date / Time   President			3		1000
Date: Person Contacted: Vehicle: IN / OUT  Date / Time   Action / Instruction   Action / In			14/6	2	. /
Date: Person Contacted: Vehicle: IN / OUT  Date / Time	Lum Sum:			A AND AND A Death	5:30
Date / Time   Action / Instruction    Date / Time   File Pass to?    Date / Time   File Pass to?    Date / Time   File Pass to?    Date / Time   File Return to?    Add Fee:   Site Insp (\$	CA / REV / RE	F. 1 24 HNO	de		op or
Date / Time   Action / Instruction    MU - 2/200    PU - 45 82 ?  NU - 25 800    Date/Time, File Pass to?   : Preli. Report    Date/Time, File Return to?    Date/Time, File Return to?    Add Fee:   : Site Insp (\$ )S + RS,SI    Interview (\$ )   Photos    Report Format : DAR   : Tech, Invs (\$ ) Others	Date:				lue to collision
Date/Time, File Pass to?  Date/Time, File Return to?  Date/Time, File Return to?  Add Fee: Site Insp (\$ )			The proy chassis frame 7 box	*	
Date/Time, File Pass to?  Date/Time, File Pass to?  Preli. Report  Days Of Repair:  Resurvey No. of Trip:  Survey Fee:  Transportation.  Show the pass to?  Interview (\$ ) Photos  Report Format:  Proli. Report  Resurvey No. of Trip:  Transportation.  Show the pass to?  Interview (\$ ) Photos  Others	Date / Time A				
Date/Time, File Pass to?    Preli. Report   Days Of Repair:   S					
Date/Time, File Pass to?    Preli. Report   Days Of Repair:   S					
Date/Time, File Pass to?  : Preli. Report  : Final Report  Days Of Repair:  Resurvey No. of Trip:  Date/Time, File Return to?  Add Fee:  Site Insp (\$ ) _s+Rs_si  Interview (\$ ) Photos  Report Format:  DAR  Tech, Invs (\$ ) Others	M	V-71700			
Date/Time, File Pass to?  : Preli. Report  : Final Report  Date/Time, File Return to?  Add Fee:  : Site Insp (\$ )s+Rs,si  Interview (\$ ) Photos  Report Format:  DAR  Days Of Repair:  Survey Fee:  Interview (\$ ) Photos  Tech, Invs (\$ ) Others	P	V- 45879			
Survey Fee:	N	V- 25800			
1) : Final Report Resurvey No. of Trip: Survey Fee: 18 Date/Time, File Return to?  Add Fee: : Site Insp (\$ ) _s+Rs,si Interview (\$ ) Photos  Report Format : DRR : Tech, Invs (\$ ) Others					
Survey Fee: 18  Date/Time, File Return to?  Add Fee: Site Insp (\$ ) _s+Rs,_si  Interview (\$ ) Photos  Report Format: DAR					
Date/Time, File Return to?  Add Fee: Site Insp (\$ ) _s+Rs,_si Interview (\$ ) Photos  Report Format: DAR Transportation.  Transportation.  S+Rs,_si Interview (\$ ) Photos	Date/Time, File Pass to?	: Preli. Report	Days Of Repair: 5		
Date/Time, File Return to?  Add Fee: Site Insp (\$ ) _s+Rs,_si Interview (\$ ) Photos  Report Format: DRR	1)	: Final Report	Resurvey No. of Trip:	Survey Fee:	180
Report Format: DAR Interview (\$ ) Photos		0		Transportation.	
Report Format: DAR Tech. Invs (\$ ) Others	2)	Add I	ee: Site Insp (\$	)S + RS,SI	
34110			Interview (\$	) Photos	
	Report Format :	DAR	Tech. Invs (\$	) Others	11
Lump Sum / I.B.I: (\$ ) . Weekend (\$ )	Lump Sum / I.B.	1: (\$	: Weekend (\$	)	"1

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adi Rpt	Adj Sub	mitted	Ins Auth'ed	Status	
Main	14 Jun 2019 Edit Reg		31 May 2019 00:00 Edit Adj Rpt					Pending Report Cancel C	for Survey
	Main	Re	ference		Claim Details		Docume	nts	Show All
CLAIM SI	JBFOLDER DE	ETAILS			AND DESCRIPTION OF THE PARTY OF	[Create	ed by adjuster]		
Insured:	ZHENG ZI	HONG TIONG BA	HRU SHUI KUE	H, Co. Reg.	No.: 53018280	K, Tel:	+6599999999		
Main Claimant:	-								
Vehicle Re No.:	g. SLD230	8L			1505/73035/190956	31/05/2	2019 00:00 - :59		
Claim Type	<b>TP</b> / 531	11082503SG			Policy/Cover Note No.:	210043	4313 (Comprehen	sive)	
Vehicle Re No. (Insured):	GBE3349	A			Policy No. (Claimant):				
					Excess:	K-LI D. I	th Wall	- 1	
Repairer:		toring () 25 Kaki l						Manal	
Handling Insurer:	Kianmeng	Pacific Insurance .Chan1@aig.com							
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Handled by )	KING GU	0 QIANG] [Fi	nal Rpt du	ue 12/06/2019
ASSOCIA	TED MAIL RE	CEIVED						View All	Compose Case Ma
AIG_SG		: Request To Upl		port		View A	All   Search Tasks	Create Ne	w Task Complet
			Group Sub	inct Han	dler Assign		Completed C		ited On Done
Due Da	te Priority	Type Task	Group Sub	ject nan	uiei Assigi	ica by	completed c		2011

#### PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC ...

From: Chin, Lee-Ying

To:

assignments, admin-a@lkkauto.com

Cc:

Fong, Andy-SY

Sent:

5/31/2019 3:34:26 PM

Attachments:

SLD2308L vs GBE3349A.PDF

Hi LKK,

Kindly assist to survey.

Thanks.

**Best Regards** Lee Ying, Chin AIG Claims | AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Singapore 079120 Tel +(65) 6419 1947 Lee-Ying.Chin@aig.com | www.aig.sg

#### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



31/05/2019

AIG Asia Pacific Insurance Pte Ltd

AIG Building 78 Shenton Way #07-16 Singapore 079120 Fax: 6415 3727

Dear Sirs

ACCIDENT BETWEEN VEHICLE NO. SLD 2308 L AND VEHICLE NO. GBE 3349 A ON 31/05/2019 @ 0045 Hrs

We are the appointed repair workshop of vehicle no. SLD 2308 L.


We understand that you are the insurer of vehicle no. GBE 3349 A.

The owner of vehicle number SLD 2308 L has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

The vehicle is now at our workshop awaiting for your inspection at the following address: 25 Kaki Bukit Road 4 #01-55 Synergy@KB Singapore 417800 Mobile No. 91690825 / peijie@expresscar.com.sg. Ms Lim

Yours faithfully



#### > Back to OneMotoring

/ehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6882D
Vehicle Details	192000000000000000000000000000000000000
Vehicle No.:	SLD2308L
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1ZRX530114
Chassis No.:	MR053REH104538461
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,452.00
Original Registration Date:	08 Jun 2016
First Registration Date:	08 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$17,452.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Jun 2026
PARF Rebate Amount:	\$13,089.00
Intended COE Rebate Details	07 Jun 2026
COE Expiry Date:	0/ Juli 2020

The information contained herein is correct as at 17 Jun 2019

DOA = 31/5/19

COE Rebate Amount:

Total Rebate Amount:

COE Category: COE Period(Years):

QP Paid:

mv - 71700 pv - 45879 IVU - 25800

m1 = 71 m

Baloner 7 yer / much Depulo 8900 ym 8900in = 741 62300+741+8776 = 7177

A - Car up to 1600cc & 97kW (130bhp)

\$47,020.00

\$32,790.00

\$45,879.00

OK

# SGCARMART.COM

Sign up

**New Cars** 

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



# Loaded windelectably Sweet deals!



TOYOTA ALTIS

Price Range

▼ Depreciation ▼ 2016

Vehicle Type

10

Home » Used Cars » Hua Yang Credit Pte Ltd » Toyota Corolla Altis 1.6A Classic

Toyota Corolla Altis 1.6A Classic

Overview

**Financial** 

Accessories

Similar

Research

Photos

# HUA YANG CREDIT PTE LTD



Price \$68,800

Depreciation (7) \$9,350 /yr

View models with similar depre

Reg Date

19-Feb-2016

(6yrs 4mths 24days COE left)

Mileage

45,000 km (12.5k /yr)

Manufactured (7)

2015

Road Tax

\$742 /yr

Transmission

Auto

Dereg Value

\$43,235 as of today (change)

OMV 7

\$17,804

COE

\$46,651

ARF

\$17,804

**Engine Cap** 

1.598 cc

Power

90.0 kW (120 bhp)

Curb Weight

1,205 kg

No. of Owners

Type of Vehicle

Mid-Sized Sedan

#### **Features**

Reliable 4 Cylinder Inline 16 Valve DOHC Dual VVT-i Valvematic, 120Bhp, 7 Speed (A) Super CVT-i With Sequential, Multi-Function Steering, ABS, Airbags View specs of the Toyota Corolla Altis (2014)

#### Accessories

Leather Seat, Sports Rims, Reverse Camera/Sensors, Factory Fitted Audio With Bluetooth, Auto Headlamps, Fog Lamps, Auto Climate Control.

#### Description

Sporty White, Fully Agent Serviced By Agent. Still Under Warranty. No Further Repair Needed At All. View Now Before Is Gone, Comes With Nice Number 2228 \$!

#### Category

PARE Car

#### Status

Available

#### Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started

Posted on: "11-Auro-7010 | | Jact | Indated on: 24-Sep-2019

Ur Compare

a more Financial info















Shortlist Compare Add note Report Error More Actions

#### Seller Information

Company Hua Yang Credit Pte Ltd dealer's pricelist » 71 vehs sold | 67 vehs available Address 210 Turf Club Road Lot A1 Search cars nearby this location Location Car Mall @ The Grandstand Office No 64625111 Contact Person(s)

84371619

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	31/05/2019 18:31
	31/05/2019 00:45
	YISHUN AVE 5 OPPOSITE BLK 101
Country/State of Loss	SINGAPORE
DI	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SLD2308L
Insured/Policyholder	
Name Of Registered Owner	ASIA EXPRESS CAR RENTAL PTE LTD
	201116882D
	NOEMAIL
Mobile Phone No	(LOCAL) +65-83394793
Alternative Phone No	OFFICE-83394793
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRER USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	B29119902MCX
Cover Note Number	
Driver	
Name of Driver	WAN CHING HSIANG
NRIC No	S7130123J
Date Of Birth	01/09/1971
Occupation	OUTDOOR

Date Of Driving Pass 26/03/2013

6 YEARS AND 2 MONTHS **Driving Experience** 

MALE Gender

(LOCAL) +65-83394793 Mobile Number

Fax Number Contact Number

NOEMAIL **EMail Address** 

Address

APT BLK 543 WOODLANDS DRIVE 16 #08-19

Postcode

730543

OTHER - HIRER

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CROSS JUNCTION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

1

**Details of Police Action** 

Was the accident reported to the police?

Number of Passengers (Including Driver)

YES

If Yes, Please state which Police Station

Police Station Name

10 UBI AVENUE 3

Police Station Address

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

WITH OWNER

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

GBE3349A → (

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

### **DETAILS OF INJURED PERSON 1**

WAN CHING HSIANG Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by

ambulance?

Address Postcode SLD2308L

YES

NO

APT BLK 543 WOODLANDS DRIVE 16

#08-19

730543

#### Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

NEW PERSON NEW PRINCIPAL P

Policyholder's Signature

1-4-14-1-4-14-14-1

Date & Time:

31/5/19

Driver's Signature

(If driver is not the policyholder)

Date & Time:

31/5/19

Reporting Centre Personnel's Signature

Marphe:

NRIC/FIN No.:

SKETCH PLAN		
- 1 - 1 - 1	1 - 1 - 1	101
1 . 1	即	A CL D DOOR
2 1444	1 1 0 5	U 51-250
		B 685 3349
freatil.	I DOTHE	
	1 0 1	
413134	文 1个	
1777 1777	0. 1	102
		Land 1
	S OF THE ACCIDENT	
Refer to Po	like Report.	
		1997
	THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW	
	-	
		-
	7 199	
DECLARATION		
/We declare the forestoing part	ticulars are true in every respect.	
* ( Reg )	Keiney	
8 38 6		
Policyholder's Sandrüre Date & Time:	Driver's Signature (If driver is not the policyholder)	Reporting Centre Personnel's Signature Name:
	Date & Time:	NRIC/FIN NO.:
31/5/14	31/5/19	

#### POLICE REPORT Pg. 1





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 1 of 3 Report No. T/20190531/7007

#### REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 31/05/2019 13:17			Vide Report No.:	Station Diary No.		
Informa	nt's Particu	ulars				
Name of Informant: WAN CHING HSIANG (WEN REN QINGXIANG)			Address: 543 WOODLANDS DRIVE 16 #08-19 SINGAPORE 730543			
ID Type / ID No.: NRIC NO / S7130123J			Contact No.: Home/Office:	Mobile: 83394793		
National SINGAP	ity: ORE CITIZ	EN	Email: VIN_71SG@YAHOO.COM.S	G		
Sex: Male	Age:	Date of Birth: 01/09/1971	Type of Informant: Driver			
Race: Chinese		1	Language: Institution / School Na English			
Occupation:			Driving Licence Information: Class: 2B,3 Date of Expiry:			

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 31/05/2019 00:45	Type of Location: Straight Road
Location: YISHUN AVE	NUE 5			
Weather:		Road Surface:		Road Speed Limit:
Clear		Dry	1	50 Km/h
	- 100	Traffic Control: Not Controlled		50 Km/h Traffic Volume: No Traffic

Details of Vehicle Involved							
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger	
GBE 3349 A	Lorry			White	Slightly Damaged	0	
SLD 2308 L	Car	TOYOTA	altis	Silver	Seriously Damaged	0	

Details of Ve	ehicle Insurance			Selection Control
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLD 2308 L	MSIG INSURANCE (SINGAPORE) PTE. LTD.	B29119902 MCX	25/03/2019	24/03/2020

#### POLICE REPORT Pg. 1





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000

Report No. T/20190531/7007

2 of 3

CONTINUATION OF REPORT

Any Pedestrian II	nvolved: No					
No. of Pedestrian	s Injured: NIL		Use of Ped	lestriar	Cross	ing: NA
Driver		Design of the N			STORY OF	
Name	WAN CHING HSIANG (WEN REN QINGXIANG)		N	ID No.		S7130123J
Related Vehicle	SLD 2308 L (Car)			Contact No.		83394793
Hospital/Clinic	KHOO TECK PUAT I		Class Drivin Licend Expiry	g	Class: 2B,3 Date of Expiry: NIL	
Date Treatment	31/05/2019		Date Disc	narge	31/05	/2019
No. of Days gran	ted Medical Leave	08	Degree of		Slight	

#### Brief Details.

I was travelling along Yishun Ave 5 near to Blk 701 Yishun Ave 5 towards Sembawang Road. Suddenly, a m/lorry GBE 3349 A came out from the car park of Blk 101 Yishun Ave 5 and appeared infront of me. I tried to avoid it but was unable to and hit the side of the lorry. Damages to my m/car SLD 2308 L front bumper, front right side and right side mirror. Injuries substained dizziness, chest pain and left three fingers numbness.

#### POLICE REPORT Pg. 1





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 3 Report No. T/20190531/7007

CONTINUATION OF REPORT

Sketch Plan						
Informant is	not	able	to	provide s	sketch	pla

NP168

naking this report has Pass. No signature is

	INC	Item	-	CO	NI	200
1001	991886	Frt Number Plate	_	CO	N A	Qı
1002	991887	Frt Number Plate Dass	_	_	_	
1003	951289	Frt Number Dlate Comtat	-	_	_	_
1004	991300	Fet Burnier	-		-	
1005	992341	Frt Bumper Clins	-	nes	V	11
1000	331772	Fit Bumper Bracket 6/1/ and	-	chy	1	1/2
1007	991462	Frt Bunner Side Date	$\neg$	case		1
	201210	Frt Bamper Reinforcement		in		1
1010	991318	Frt Bumper Beam		LACT	1	-
1011	991427	Frt Bumper Sponge		ch	10	17
1012	991420	Frt Bumper Protector Frt Bumper Pad			+	+
1013	101363	Frt Bumper Grille Jower				1
	991301	Fit Bumper Grille Jower			13	T
1015	91407	Fit Bumper Lower Spoiler Russer			1	1
	91438	Frt Bumper Sensor		nec	V	17
1017 13	ו 100 בפיי	Fet I LI Days 17				
			_			
			-	5019	1	1
	10000	FILKH Humper For T	-	_	-	_
	21123	ra Grille	-		1	4
	91328	Frt Grille Emblem	+	_	0	1
1024 0	01777	Frt Grille Chrome Moulding	-		0	1
1025 9	92013	Frt Supron Panel	-	_	-	
1026 9	92025	Frt Support Panel Frt Support Panel Top Garnish Cover				
						$\neg$
1028 9	11777 1	Ert Denne C				
1029 195	2515311	ere I LI Una di	-			
	1112011	THE REL Manuallance	- -			_
			- 6	RA	V	1
1033 99	208911	n R H Side Land	+		-	$\dashv$
1034 .90	11328 0	Bunnet Emblem	0	eu	R	7
1033 32	U28711	onnet Lock				
1030 99	0285 B	Jonnet Insulator				
103/ 199	U2731R	anget Iffice Add	+			
1030 33	U2611B	onnet Dannes	6.7	le	R	1
1022 33	0305 IB	Onnet Pulston	+	-	+	-
1041 00	0232 B	onnet Cable	+	-	+	-
1042 99	03118	onnet Stand	+	$\dashv$	+	-
1043 99	0122 A	ir Con Condenser ir Con Fan Assy			+	
	0134 A	ir Con Suction Pipe (Low Pressure)		1	+	$\neg$
			1			
15.10   55(	1133 N	r Con Discharge Pine All 1 -	-	-	-	_
			-	-	-	-
0.40 350	1147111	Con Limit Pins	1	+	+	-
050 990	111 A	Con Receiver Drier	-		-	-
051 995	63" INT	r Con Compressor Assy			+	7
052 995	074 Ra	lintoe				
153 992	738 Rad	liator Courting				
134 335	/42   Rac	ligtor Fan Associ		-		
177 1775	45   Rar	intor fine Ot	_	-	1	
20 9927	58 Rad	liator Hose Ton	_	-	-	1
37 9927	57 Rad	liator Hose Bottom		+	+	-
30 9927	41 Rad	inter Expansion Tout	00	-	1	-
37 2701	JIJAIr	Ouct .	67	1	1	-{
60 9900	70 Air	Cleaner Assy .	_	1-	+	Dr.
01 3300	56 Air	Cleaner Hose	-	1	1	MY
53 9900 53 9917	No Air	Cleaner Resonator	P	T	<b>E</b>	U
04 9917	12 1911	xhaust Manifold		1	-	
55 9910	Salir E	xhaust Manifold Cover		11	1	
12 3210	34 11-11 1-	xhaust Manifold Sensor (Oxygen) ( Exhaust Pipe	1	M	1	25
7 9902	9 Batte	e Estaust Pipe	_	H	0	7
8 99022	4 Batte	TV Cover	7	2	1	1
9 99023	3 Dance	ry Brucket		-	1	,
0 99022	13 12	ry Yniy				

in	ric)				Consiste		r 1	_				0
NA	CI II	10	Iv.		cle No	): -	31	D	-		0	8
107		4C	Item						C	N	AC	Qty
107		205	Fuse	Box							-	40
107		110	Relay	Box						7		
107		053	Wipe	r Was	her T	ink			18	T	V	1
107		150	Wipe	r Was	her Ti	ink Mo	otor				2	1
	6 990	150	Alter	rtator /	V22A							
107	7 992	100	Alter	nator l	Belt							
107	-	660	rowe	r Stee	ring P	ump						
107		009	Powe	r Stee	ring B	elt						
108	9 999	431	Powe	r Stee	ring (	ooler.	Pipe			7		
108	10 392	037	Lows	r Stee	ring H	nse				7		_
-		010	ABS	Pump	Conti	rol Uni	t		$\vdash$	7		-
108		427	Brake	Mast	er Pur	mp Ass	sy			7	-	_
108	5 330	403	Brake	Boos	ter Pu	mm A.	SY		-	+	$\neg$	_
100	4 1 991	005 I	Enpir	o Ton	Car	_				+	-	-
LUO.	3   991	0111	Engin	e Und	er Co	ver				+	7	7
108	0 1.290	946	Engin	e Mou	mtine					+	-	-
103	/ 1 990	949 I	Engin	e Mou	milne	Cat				+	-	$\neg$
1086	8 I. 990	250 I	Engin	e Mou	milno	1 17				+	+	-
100	×   YYO:	2521	Engin	e Man	ntina	DEF			_	+	1	-
1000	o-1 3303	2311	Engin	- Mou	milion	Danie				+	+	-
1092	9922	234	Gear I	Box M	ountie	10 /				+	+	-
1037	1 3313	201	ert L.F.	Char	clo Ma	mara la ma			_	+	+	-
1003	9915	20	rt RI	Chus	sis M	ember	120		cre	1/	7	7
1094	9907	67	rt Ve	rtical (	Cross	Memb	CT			+	+	-
1093	9918	03	LL TO	wer. Cr	ods N	fember				+		$\neg$
.1090	9950	10.07	rt LH	Fende	ĉr.					+	+	$\neg$
1098	9930	72 1	rt LH	Fende	er Inn	er Pane	ol .			1	+	-
1099		47. 1	TI LH	Fende	er Lan	np				1.	1	
1100		40 5	TI LH	Fende	r Pro	lector					1	7
1101		70 1	TLH	Mudf	r Inne	r Shie	ld				1	$\neg$
1102	9951	70 E	et I LI	Mudi	iap		_	1				
1103	9940	25 F	et I II	Din C	Rim			1				
1104	1 3320	05 IF	rt I LI	Trees				-	_			
11102	9950	71 F	rt RH	Fende	r			+	-	1	1	_
1100	1 9917	39 I F	rt RH	Fende	r Inne	r Dane	1	-1	57	14	1/	
1101	99174	14  F	rt RH	Fende	r Lam	m Fail	Vern	_	A4	14	1	
1108	1 3311	12 11	RRH	Fende	r Deal			-	acc.	4	17	-
1109	1 99174	0 IF	rt RH	Fenda	e from	COLUM	d	1	di	-	-	Н
1110	1 AA 1 8 S	4 IF	RH	Mudfl	ar. 73	n.L.	Back	_	deg	4	1/	Н
	1 33200	7 11.1	TRH	Wheet	*D I			T	mel	-	1	-
1112	1 99402	5   Fr	t RH	Rim C	over	**		+	ic ic	1	1	-
1113	1 99506	5 IFr	t RH'	Turn			_	+-		5	7	-
1114	99209	3 Fr	t Wine	dscree	n Olas	33		+		-	-	1
116	99211	7. Fr	t Wine	iscree	n Rub	ber		1			-	1
117	99210	8 11.1	Wine	scree	Moy	lding		T				1
118	99209	8   I-r	Wind	Iscree	Seal	ant		T				1
119	99101	ER	U. Bra	cket								1
120	992140	) E	Wi	* / -				1				1
121	992142	12-1	Wipe	- DI		-		1				1
122	995045	DV.	Wipe	r Blade	c							1
123	991126	171	per l'e	Parel	irnish			L				1
124	990753	Da	hla	ranel				L				
-	992282	CI	moon	U A33	Υ					T		
	992281	1010	AC BO	X Cov	cr							
27	992281	Cilo	AG BO	x Con	ipartn	nent				1		
	994483	200	ering	Wheel	Airba	<u> </u>				1		
	994485	2000	ting '	wheel	Airba	g Sens	or			1		
	990749	Das	nboar	u Airb	ag '							
_	990750	Das	nboar	d Airb	ag Se	nsor						
	990029	Airt	ong Co	intro!	Unit				1	1		
	990864	ral	Jriver	Sent						1	-	
33 9	91922	Frt I	tH Se	at Belt	Assy			-	1	-		
34 9 35 9	91899	Frt f	'assen	ger Sc	at					+	-	
36 9	95182	FrtL	H Se	ut Belt	Assy.					1		
30 1 3	90247	Stick	cer -					-		1		
-							_			Ţ		
										1		
		_								1		
						. /		_	1	T		
							-	_	-	-		

# MOTOR CAR (UC)

(1)Replace ( √) (2)Repair ( X) (1)Check (?) (4)Not Consistent ( NC)

AC INC Item	CON	ΛC	Otv	NAC	INC	Vehicle No: SLD 7		
372 995163 Frt LH Shock Absorber			20			5 Frt RH Shock Absorber	CON	A
73 991944 Frt LH Shock Absorber Mounting				1420	00104	A F-A P.H. Ch.		
174   990632   Frt LH Coil Spring			-	142	00000	4 Frt RH Shock Absorber Mounting	-	
75 995198 Frt LH Knuckle Arm	_	-	-	1430	990037	2 Prt RH Coil Spring		
76 995199 Frt LH Knuckle Arm Bearing			_	143	001944	Frt RH Knuckle Arm		
77 995178 Frt LH Lower Arm				1422	00105	Frt RH Knuckle Arm Bearing	CRY	V
78 995169 Frt LH Upper Arm	1	-	-	1433	99185	Frt RH Lower Arm	BT	D
79 995183 Frt LH Tie Rod			-	1434	992064	Frt RH Upper Arm		
80 995143 Frt LH Drive Shaft			-	1433	992040	Frt RH Tie Rod		
81 990661 Frt LH Control Arm	-	_	_	1430	991692	2 Frt RH Drive Shaft	_	
82 992062 Frt LH Trailing Arm	_	_		1437	990661	Frt RH Control Arm	-	-
83 991848 Frt LH Leaf Spring				1438	992062	2 Frt RH Trailing Arm	_	_
84 991293 Frt LH Brake Disc Rotor				1439	991848	Prt RH Leaf Spring		
85 991281 Frt LH Brake Caliper				1440	991293	Frt RH Brake Disc Rotor		
86 991292 Frt LH Brake Pipe				1441	991281	Frt RH Brake Caliper	-	
87 991287 Frt LH Brake Hose				1442	991292	Frt RH Brake Pipe	-	
88 991295 Fri LH Brake Sensor Wire				1443	991287	Frt RH Brake Hose		
39 991989 Frt Stay Bar Bracket				1444	991295	Frt RH Brake Sensor Wire	-	
90 994455 Steering Rack & Pinion				1445	993720	Rear RH Shock Absorbes	-	_
91 994435 Steering Cross Member				1446	993723	Rear RH Shock Absorber Mounting		
92 994519 Frt Sub Frame				1447	993173	Rear RH Coil Spring	-	
23 992003 Frt Sub Frame				1448	993550	Rear RH Knuckle Arm		
- I would traine woulding				1449	003551	Para PIL K		
		1	$\neg$	1450	002601	Rear RH Knuckle Arm Bearing		
- Con Dar Linkage		$\neg$	$\neg$	1450	002001	Rear RH Lower Arm		
6 990887 Engine Block		+	$\neg$	1451	993885	Rear RH Upper Ann		
7 990890 Engine Block Gasket	1-1-	+	$\dashv$	1452	993322	Rear RH Drive Shaft		
8 990972 Engine Oil Sump	++	-	-	1453	993178	Rear RH Control Arm	1	
9 990960 Engine Oil	+-	+	-	1434	993117	Rear RH Trailing Arm		
0 992224 Gear Box Assy	+	+	$\dashv$	1455	995110	Rear RH Leaf Spring		-
1 992229 Gear Box Gasket	1-	+	$\dashv$	1420	992942	Rear RH Brake Dies Batte	1	
2 992241 Gear Box Oil Sump	1	+	$\dashv$	1437	992938	Rear RH Brake Caliper Assy		-
3   992257   Gear Oil	-	-	$\dashv$	1438	990434	Rear RH Brake Pine	1	$\dashv$
990534 Centre Exhaust Pipe Assy	-	+	-	1459	992947	Rear RH Brake Hose	-	+
19 990532  Centre Exhaust Mounting	<del>                                     </del>	-	-	-				-
1 991134 [Floor Panel	-	4	_					-
993719 Rear LH Shock Almost		-	_	1			-	-
993723 Repr I H Shock About	<del></del>	4	7	1	Xa .		-	-
1 223170 IRear LH Coil Spring		1	Vm	West 1				-
1 9935501Rear 1 H Knowlet 4		+	- <b>∧</b> '	1				-
993551 Rear LH Knuckle Arm David		+	411	-				-
993397 Kear LH Lower Arm	-	+	11	-				-
993884 Rear Left Upper Arm	1	+	-N.	J	-	1		+
995161 Rear LH Drive Shaft		+	-1	Lal	20	\		+
995216 Rear LH Control Arm	_	+	+\rac{1}{2}	1701	1		_	+
993881 Rear LH Trailing Arm	-	+	4	1-1-				+
993573 Rear LH Leaf Spring		-	4	,	,		-	+
992941 Rear LH Brake Disc Rotor		_	1					+
992937 Rear LH Brake Caliper Assy								-
990434 Rear LH Brake Pipe			1					
992946 Rear LH Brake Hose			1					
993819 Rear LH Brake Hose			1					
993820 Rear Sub Frame		1	1		_			
- I want but trame Mounting			1 1					
992813 Rear Anti Roll Bar			1 1		-			
990168 Rear Anti Roll Bar Linkage 990202 Axle Beam			1 1		_			
000170 Page 4 4 1			1 1					
990170 Rear Axle Panhard Rod			1 1		-			
990810 Differential Assy			1 1	_				
992706 Propeller Shaft	_	_	1 1	_				+-

No of Items:\_\_\_\_\_ Assessor: H. ANN

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Subr	nitted	Ins Auth'ed	Status	5	
Main	14 Jun 2019 Edit Reg		31 May 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimate	S\$0.00 View R			Repo	Pending for Surve Report Cancel Case	
	Main	R	eference	Claim	Details		Docume	nts	) 5	show All
CLAIM S	UBFOLDER D	ETAILS			[Ci	reated I	by adjuster]			
Insured:	ZHENG Z	HONG TIONG BA	HRU SHUI KUEH,	Co. Reg. No.: 5	3018280K, T	el: +659	9999999			
Main Claimant:										
Vehicle Re	sLD230	8L		Date			00:00 - :59 and <b>23</b> Days i	From LTA Reg	g Date (N	fan Yr)]
Claim Typ	im Type: <b>TP</b> / 5311082503S0		TP / 5311082503SG			Policy/Cover Note No.: 2100434313 (Comprehensive)				
Vehicle Re No. (Insured):	GBE3349	A			y No. imant):					
				Exce	ess:					
Repairer:	Apex Mo	toring () 25 Kaki	Bukit Road 4, #01-5	55 Synergy @ KB	, 417800 Kaki	Bukit - 7	Tel:			
Handling Insurer:		Pacific Insurand .Chan1@aig.com	e Pte. Ltd. (Expre	ss) - Tel: 65-641	.9-3000 [Ha	andled by	y Chan, Kian-I	Meng]		
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	256-3561 [Han	dled by XING	GUO Q	IANG] [Fin	al Rpt due	12/06	/2019]
ASSOCIA	ATED MAIL RE	CEIVED						View All	Compose	Case Mai
		: Request To Up : No OI GIA Rep	load TP GIA Repor ort	t						
ALL ASS	OCIATED TA	sks <sup>=</sup>			View	All S	Search Tasks	Create New	Task	Complete
Due Da	ate Priority	Type Tasi	Group Subject	ct Handler	Assigned I	Ву	Completed O	n Crea	ted On	Done

#### Claim Documents

\*SLD2308L (5311082503SG) [GBE3349A] TP

# May 31 2019 12:00AM [ZHENG ZHONG TIONG BAHRU SHUI KUEH] **Apex Motoring**

Pho	tos/Images		3 per	page 🔻	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	The state of the s	Thumbnail	-
1	13/06/19 19:29	General View	0	Load JPG	V
2	13/06/19 19:29	General View	0	Load JPG	V
3	13/06/19 19:29	General View	0	Load JPG	V
4	13/06/19 19:29	General View	0	Load JPG	V
5	13/06/19 19:29	General View	0	Load JPG	V
6	13/06/19 19:29	General View	0	Load JPG	V
7	13/06/19 19:29	General View	0	Load JPG	V
В	13/06/19 19:29	General View	0	Load JPG	V
9	13/06/19 19:29	General View	0	Load JPG	V
10	13/06/19 19:29	General View	0	Load JPG	V
11	13/06/19 19:29	General View	0	Load JPG	V
12	13/06/19 19:29	General View	0	Load JPG	V
13	13/06/19 19:29	General View	0	Load JPG	V
14	13/06/19 19:29	General View	0	Load JPG	V
15	13/06/19 19:29	General View	0	Load JPG	V
16	13/06/19 19:29	General View	0	Load JPG	V
17	13/06/19 19:29	General View	0	Load JPG	V
18	13/06/19 19:29	General View	0	Load JPG	V
19	13/06/19 19:29	General View	0	Load JPG	V
20	13/06/19 19:29	General View	0	Load JPG	V
21	13/06/19 19:29	General View	0	Load JPG	V
22	13/06/19 19:29	General View	0	Load JPG	V
23	13/06/19 19:29	General View	0	Load JPG	V
24	13/06/19 19:29	General View	0	Load JPG	V
25	13/06/19 19:29	General View	0	Load JPG	V
26	13/06/19 19:29	General View	0	Load JPG	V
27	13/06/19 19:29	General View	0	Load JPG	V
28	13/06/19 19:29	General View	0	Load JPG	V
29	13/06/19 19:29	General View	0	Load JPG	V
30	13/06/19 19:29	General View	0	Load JPG	V
31	13/06/19 19:29	General View	0	Load JPG	V
32	13/06/19 19:29	General View	0	Load JPG	V
33	13/06/19 19:29	General View	0	Load JPG	V
34	13/06/19 19:29	General View	0	Load JPG	V
35	13/06/19 19:29	General View	0	Load JPG	V
36	13/06/19 19:29	General View	0	Load JPG	V
37	13/06/19 19:29	General View	0	Load JPG	V
38	13/06/19 19:29	General View	0	Load JPG	V
39	13/06/19 19:29	General View	0	Load JPG	V
10	13/06/19 19:29	General View	0	Load JPG	<b>☑</b>
11	13/06/19 19:29	General View	0	Load JPG	V
12	13/06/19 19:29	General View	0	Load JPG	V
13	13/06/19 19:29	General View	0	Load JPG	<b>∀</b>

Pho	tos/Images		3 per page	V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		JPG	_
44	13/06/19 19:29	General View			V
45	13/06/19 19:29	General View	[A ]/ (SECTOR	JPG	V
16	13/06/19 19:29	General View		JPG	V
17	13/06/19 19:29	General View		JPG	V
8	13/06/19 19:29	General View	1000 2000	JPG	V
19	13/06/19 19:29	General View		JPG	V
0	13/06/19 19:29	General View		JPG	✓
51	13/06/19 19:29	General View	1 Load	JPG	✓
52	13/06/19 19:29	General View	1 Load	JPG	V
53	13/06/19 19:29	General View	1 Load	JPG	<b>∀</b>
54	13/06/19 19:29	General View	1 Load	JPG	V
55	13/06/19 19:29	General View	1 Load	JPG	V
56	13/06/19 19:29	General View	1 Load	JPG	V
57	13/06/19 19:29	Photographs of Damaged Parts	1 Load	JPG	V
58	13/06/19 19:29	Photographs of Damaged Parts	1 Load	JPG	V
59	13/06/19 19:29	Photographs of Damaged Parts	1 Load	JPG	V
50	13/06/19 19:29	Photographs of Damaged Parts		JPG	V
51	13/06/19 19:29	Photographs of Damaged Parts		1 JPG	V
62	13/06/19 19:29	Photographs of Damaged Parts		JPG	V
53	13/06/19 19:29	Photographs of Damaged Parts		JPG	V
4	13/06/19 19:29	Photographs of Damaged Parts		JPG	V
55	13/06/19 19:29	Photographs of Damaged Parts		JPG	V
56	13/06/19 19:29	Photographs of Damaged Parts  Photographs of Damaged Parts		JPG	<b>∀</b>
	Total Salara Salara			5000000	1
57	13/06/19 19:29	Photographs of Damaged Parts		JPG	V
8	13/06/19 19:29	Photographs of Damaged Parts		JPG	V
9	13/06/19 19:29	Photographs of Damaged Parts		JPG	V
0	13/06/19 19:29	Photographs of Damaged Parts		JPG	V
71	13/06/19 19:29	Photographs of Damaged Parts		JPG	V
72	13/06/19 19:29	Photographs of Damaged Parts	The state of the s	JPG	V
73	13/06/19 19:29	Photographs of Damaged Parts		JPG	V
74	13/06/19 19:29	Photographs of Damaged Parts	1 Load	JPG	V
75	13/06/19 19:29	Photographs of Damaged Parts	1 Load	JPG	V
76	13/06/19 19:29	Photographs of Damaged Parts	1 Load	JPG	V
77	13/06/19 19:29	Photographs of Damaged Parts	1 Load	JPG	V
78	13/06/19 19:29	Photographs of Damaged Parts	1 Load	JPG	V
79	13/06/19 19:29	Photographs of Damaged Parts	€1 Load	JPG	~
30	13/06/19 19:29	Photographs of Damaged Parts	1 Load	JPG	V
31	13/06/19 19:29	Photographs of Damaged Parts	1 Load	JPG	V
32	13/06/19 19:29	Photographs of Damaged Parts	1 Load	JPG	V
33	13/06/19 19:29	Photographs of Damaged Parts	1 Load	JPG	V
34	13/06/19 19:29	Photographs of Damaged Parts	1 Load	JPG	V
35	13/06/19 19:29	Photographs of Damaged Parts	1 Load	JPG	V
6	13/06/19 19:29	Photographs of Damaged Parts	€ Load	JPG	V
7	13/06/19 19:29	Photographs of Damaged Parts		JPG	V
88	13/06/19 19:29	Photographs of Damaged Parts		JPG	V
39	13/06/19 19:29	Photographs of Damaged Parts		JPG	V
0	13/06/19 19:29	Photographs of Damaged Parts		JPG	<u>V</u>
1	13/06/19 19:29	Photographs of Damaged Parts		JPG	100
2					
	13/06/19 19:29	Photographs of Damaged Parts	1000	JPG	
3	13/06/19 19:30	Photo After Spray		JPG	V
4	13/06/19 19:30	Photo After Spray		JPG	Z
5	13/06/19 19:30	Photo After Spray		JPG	V
6	13/06/19 19:30	Photo After Spray	7 10	JPG	V
7	13/06/19 19:30	Photo After Spray		JPG	V
8	13/06/19 19:30	Photo After Spray	1 Load	JPG	V
99	13/06/19 19:30	Photo After Spray	1 Load	JPG	~

Page 3 of 3

Pho	tos/Images		3 per p	age 🔻	~
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
100	13/06/19 19:30	Photo After Spray	0	Load JPG	$\mathbf{Z}$
101	13/06/19 19:30	Photo After Spray	6	Load JPG	V
102	13/06/19 19:30	Photo After Spray	0	Load JPG	V
103	13/06/19 19:30	Photo After Spray	6	Load JPG	V
104	13/06/19 19:30	Photo After Spray	0	Load JPG	V
105	13/06/19 19:30	Photo After Spray	0	Load JPG	V
106	13/06/19 19:30	Photo After Spray	0	Load JPG	V
107	13/06/19 19:30	Photo After Spray	0	Load JPG	V
108	13/06/19 19:30	Photo After Spray	6	Load JPG	V
109	13/06/19 19:30	Photo After Spray	0	Load JPG	V
Doc	umentation		1 per	page 🔻	V
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	03/06/19 16:53	OI GIA REPORT	6	Load PDF	

# **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19009682/GCD3E2

Date: 07/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100434313

Claimant Vehicle No:

SLD2308L

Insured Vehicle No: GBE3349A

Date of Loss:

31/05/2019

Nature of Claim:

TP

Claim No: 5311082503SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SLD2308L

Make & Model:

TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No:

Chassis No:

1ZRX530114 MR053REH104538461

Reg. Date: Colour:

Silver

Odometer:

205576 km

Engine Capacity:

Market Value/New Car

1598 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

08/06/2016 (Man. Year: 2015)

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size:

205/55 R16

Rear Tyre Size:

No

205/55 R16

Front Left Side:

Dunlop 5 mm

Rear Left Side:

Dunlop 5 mm

Front Right Side:

Dunlop 5 mm

Rear Right Side:

Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

31/05/2019

Date Inspected:

31/05/2019 Inspected At:

Apex Motoring

25 Kaki Bukit Road 4, #01-55 Synergy

@ KB

Singapore 417800

Estimated Period of Repair:

5.0 days

Adjuster: XING GUO QIANG

Manager: **CELINE FONG** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

# REPAIR DETAILS

# Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRT BUMPER	Cut	0.00 F	*-F
2	12	*FRT BUMPER CLIPS	Necessary	0.00 F	*-F
3	1	*FRT BUMPER BRACKET R/H	Crushed	0.00 F	*-F
4	1	*FRT BUMPER SIDE RETAINER R/H	Crushed	0.00 F	*-F
5	1	*FRT BUMPER REINFORCEMENT	Repair	0.00 F	*- F
3	1	*FRT BUMPER SPONGE	Crushed	0.00 F	*- F
7	1	*FRT BUMPER GRILLE LOWER	* Check	0.00 F	*-F
3	1	*FRT BUMPER RUBBER	Necessary	0.00 F	*- F
9	1	*FRT RH BUMPER FOG LAMP COVER	Scratched	0.00 F	*-F
10	1	*FRT RH BUMPER FOG LAMP	* Check	0.00 F	*- F
11	1	*FRT GRILLE	* Check	0.00 F	*-F
12	1	*FRT GRILLE EMBLEM	* Check	0.00 F	*- F
13	1	*FRT GRILLE CHROME MOULDING	* Check	0.00 F	*- F
14	1	*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
15	1	*BONNET	Repair	0.00 F	*- F
16	1	*BONNET HINGE R/H	Repair	0.00 F	*- F
17	1	*RADIATOR EXPANSION TANK	Bent	0.00 F	*- F
18	1	*WIPER WASHER TANK	Bent	0.00 F	*-F
19	1	*WIPER WASHER TANK MOTOR	* Check	0.00 F	*- F
20	1	*ENGINE UNDER COVER	* Check	0.00 F	*-F
21	1	*FRT RH CHASSIS MEMBER	Repair	0.00 F	*- F
22	1	*FRT RH FENDER	Bent	0.00 F	*- F
23	1	*FRT RH FENDER INNER PANEL	Repair	0.00 F	*- F
24	1	*FRT RH FENDER EMBLEM	Necessary	0.00 F	*- F
25	1	*FRT RH FENDER INNER SHIELD	Crushed	0.00 F	*-F
26	1	*FRT RH FENDER EMBLEM	Necessary	0.00 F	*- F
27	1	*FRT RH WHEEL RIM	Scratched	0.00 F	*- F
28	1	*FRT RH TYRE	* Check	0.00 F	*- F
29	1	*FRT RH KNUCKLE ARM BEARING	Crushed	0.00 F	*- F
30	1	*FRT RH LOWER ARM	Bent	0.00 F	*- F
-=Fra	anchise part.		Total Parts (S\$)	0.00	0.00

Adjuster Report Page 3 of 3

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >