

22/03/1982

ASS. REC. BY:

REF: CS3/SM618009100/R1+d3-1

Instruction:

Surveyor

Rasul

ASSIGNMENT (Office)

From (Person):

Goh Paul Wong

of

SMO

Date/Time:

31/05/2019

Estimated Cost:

Bill to:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CS

To Inspect Vehicle No:

SBB10L

Insured:

SKL 6728B

at Workshop m/s

Twincar Automotive

Tel:

6842 0051

of

2 kaki Bukit Ave 2 # 01-17

Policy No:

Claim No:

CMTD1802096

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 16/05/2018

21/05/18 @ Afternoon

H.O.D. Endorsement

CA / REV / REP. / REV 24 HRS

1wp

Date/Time:

5:18pm @ 18/5/18

Person Contacted:

Melody

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SBB10L-x

SKL 6728B-x.

28/5/18

After Repair

lump sum \$5450 (Red: 16650; 75%) 6clump

217- File pass Typist

RECEIVED 02 JUL 2019

08/11/18
Surrey

Phone

REF:


979345

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SBB 10L
at Workshop m/s: TWIN CAR
of: 2, KOKI PARKET AVE 2 #01-17
Insured: Smo
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SBB 10L Yr Regn: 2015 / SGP
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: TOYOTA VELLFIRE c.c. 2453
Colour: WHITE A/C: Insured / Std / NI / NA
Sp. Reading: 37218 T/Radio: Insured / Std / NI / NA
Eng/No: _____

C/No: AGH 30 0020142

Gen. Cond: Good / Bad / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: NII / S/Rim / STD A/Rim or

Tyre Size: F: 235/50R18

R: 1-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm
D.O.A. <u>16/05/18</u>		D.O.I. <u>21/05/18 @ 02:14pm</u>

Survey held at TWIN CAR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Repair Estimate : S\$ 4500 - 5500

* 4 days

2/6/18 Submit PRS Report.

RECEIVED 13 JUN 2018

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$ + RS. \$1

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

#00
60
160

Nivitha (LKK Auto)

From: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>
Sent: Friday, 31 May 2019 3:46 PM
To: Nivitha (LKK Auto); assignments@lkkauto.com; 'SUR'
Subject: RE: Your ref : AKN-ATV-INS-T140-106775-18 ; RE: SBB10L & SKL6728B - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS
Attachments: CMTD1802096 - SCANNED THIRD PARTY SUV 4 of 4.pdf; CMTD1802096 - SCANNED THIRD PARTY SUV 3 of 4.pdf; CMTD1802096 - SCANNED THIRD PARTY SUV 2 of 4.pdf; CMTD1802096 - SCANNED THIRD PARTY SUV 1 of 4.pdf

Dear M/s LKK AUTO,

Following up from the email below, enclosed is the third party survey report.

Please forward the soft copy report once ready, thank you.

Best Regards

Gnoh Pau Loong

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Gnoh, Pau Loong

Sent: Friday, 31 May, 2019 3:44 PM

To: 'Anna Tan' <annatan@visionlawllc.com>

Cc: 'Chin Hui Xin' <huixin@n51.com.sg>; 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>; assignments@lkkauto.com; 'SUR' <sur@lkkauto.com>

Subject: Your ref : AKN-ATV-INS-T140-106775-18 ; RE: SBB10L & SKL6728B - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Without Prejudice

Dear Anna,

With reference to your letter dated 02.01.19, we have clarified with our surveyor, M/s LKK AUTO that post repair inspection was done and due to the high quantum of repair, we will be conducting the paper resurvey.

In the meantime, kindly hold hands and we will revert to you once we have the report.

Please quote our reference : CMTD1802096 when replying, thank you.

By copy to M/s LKK (Your ref : CS3/SMO18009100/R1Z4D3),

Please assist in the above and please forward the soft copy once ready, thank you.

Best Regards

Gnoh Pau Loong

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Chin Hui Xin <huixin@n51.com.sg>

Sent: Friday, 18 May, 2018 5:02 PM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: admin-d@lkkauto.com; assignments@lkkauto.com; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

Subject: Re: SBB10L & SKL6728B - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

Please see attached.

27/05/2019

ASS. REC. BY:

REF: CS3/SM618009100/R1+d3-1

Instruction:

Surveyor

Rasul

ASSIGNMENT (Office)

From (Person):

Gndh Paul Wong

of

SMO

Date/Time:

31/05/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SBB10L

Insured:

SKL 6728B

at Workshop m/s

Twincar Automotive

Tel:

6842 0051

of

2 kaki Bukit Ave 2 # 01-17

Policy No:

Claim No:

CMTD1802096

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/05/2018

CA / REV / REP. / REV 24 HRS

Imp

21/05/18 @ Afternoon

H.O.D. Endorsement

Date/Time

5:18pm @ 18/5/18

Person Contacted:

Melody

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SBB10L-x

SKL 6728B-x.

28/5/18

After Repair

lump sum \$5450- (Red: 16650; 75%) 6clump

[Signature]
1/7/2019

27- File pass Typist

RECEIVED 02 JUL 2019


Signature: *James*

REF:

979345

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SBB 10L
at Workshop m/s: TWIN CAR
of: 2, KOKI PARKET NO 2 #01-17
Insured: Smo
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____



(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SBB 10L Yr Regn: 2015 / SGP
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: TOYOTA VELLFIRE C.C. 2453
Colour: WHITE A/C: Insured / Std / NI / NA
Sp. Reading: 37218 T/Radio: Insured / Std / NI / NA
Eng/No: _____

C/No: AGH 30 0020142

Gen. Cond: Good / at / Poor / Burnt

Steering: 8 / order / Jammed / Leaked / Burnt or

Brake: 8 / order / Jammed / Leaked / Burnt or

Modi: 0 / Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/50R18

R: 1-

0 / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal. <u>6</u>	mm	R/Bal. <u>6</u>	mm
L/Bal. <u>6</u>	mm	L/Bal. <u>6</u>	mm
D.O.A. <u>16/05/18</u>		D.O.I. <u>21/05/18 @ 02:40pm</u>	

Survey held at TWIN CAR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Repair Estimate : S\$ 4500 - 5500

* 4 days

2/6/18 Submit PRS Report.

RECEIVED 13 JUN 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) Date/Time, File Return to?
2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation

) \$ + RS. SI

) Photos

) Others

TOTAL

100
60
160

Report Format :

Lump Sum / I.B.I: (\$)

Nivitha (LKK Auto)

From: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>
Sent: Friday, 31 May 2019 3:46 PM
To: Nivitha (LKK Auto); assignments@lkkauto.com; 'SUR'
Subject: RE: Your ref : AKN-ATV-INS-T140-106775-18 ; RE: SBB10L & SKL6728B - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS
Attachments: CMTD1802096 - SCANNED THIRD PARTY SUV 4 of 4.pdf; CMTD1802096 - SCANNED THIRD PARTY SUV 3 of 4.pdf; CMTD1802096 - SCANNED THIRD PARTY SUV 2 of 4.pdf; CMTD1802096 - SCANNED THIRD PARTY SUV 1 of 4.pdf

Dear M/s LKK AUTO,

Following up from the email below, enclosed is the third party survey report.

Please forward the soft copy report once ready, thank you.

Best Regards

Gnoh Pau Loong

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



Download now @

or

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Gnoh, Pau Loong

Sent: Friday, 31 May, 2019 3:44 PM

To: 'Anna Tan' <annatan@visionlawllc.com>

Cc: 'Chin Hui Xin' <huixin@n51.com.sg>; 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>; assignments@lkkauto.com; 'SUR' <sur@lkkauto.com>

Subject: Your ref : AKN-ATV-INS-T140-106775-18 ; RE: SBB10L & SKL6728B - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Without Prejudice

Dear Anna,

With reference to your letter dated 02.01.19, we have clarified with our surveyor, M/s LKK AUTO that post repair inspection was done and due to the high quantum of repair, we will be conducting the paper resurvey.

In the meantime, kindly hold hands and we will revert to you once we have the report.

Please quote our reference : CMTD1802096 when replying, thank you.

By copy to M/s LKK (Your ref : CS3/SMO18009100/R1Z4D3),

Please assist in the above and please forward the soft copy once ready, thank you.

Best Regards

Gnoh Pau Loong

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Chin Hui Xin <huixin@n51.com.sg>

Sent: Friday, 18 May, 2018 5:02 PM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: admin-d@lkkauto.com; assignments@lkkauto.com; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

Subject: Re: SBB10L & SKL6728B - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

Please see attached.

Regards,
Melody Chin
N-51 Automotive Pte Ltd
Office : 6842 0051
Fax : 6741 0510
www.n51.com.sg



On Fri, May 18, 2018 at 4:39 PM, Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg> wrote:

Our Ref : CMTD1802096

Dear Melody,

We refer to your reply dated 18/05/2018.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Aside to LKK Auto,

Please make arrangement to conduct the survey for SBB10L.

Thank you.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing
SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Chin Hui Xin [mailto:huixin@n51.com.sg]

Sent: Friday, 18 May, 2018 3:33 PM

To: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Cc: Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

Subject: Re: SBB10L & SKL6728B - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

We refer to your list of motor surveyors proposed.

We do not agree to your list of motor surveyors.

Please see attached.

Thank you

Regards,


Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg



On Fri, May 18, 2018 at 11:17 AM, Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg> wrote:

Our Reference: CMTD1802096/GPL

Your Reference: SBB 10L

Without Prejudice

Date: 18 May 2018

Attention:

M/S TWINCAR AUTOMOTIVE PTE LTD

Dear Melody,

ACCIDENT INVOLVING SBB10L & SKL6728B ON 16.05.2018

We refer to your Notice of Accident dated 17/05/2018.

Please be informed that Mr Gnoh Pau Loong is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Chin Hui Xin [<mailto:huixin@n51.com.sg>]

Sent: Thursday, 17 May, 2018 5:10 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: SBB10L & SKL6728B - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors.

Thank you...

Regards,

Melody Chin

TWINCAR Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg



PAR Automotive Consultancy

Regn. No. 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0776-18-TCA

26 November 2018

ACCIDENT VEHICLE SURVEY REPORT

Lim Kar Tian
Blk 816 Tampines Ave 4 #08-253
Singapore 520816

VEHICLE INFORMATION:

Vehicle Reg No.:	SBB10L	Odometer:	37218km
Make & Model:	Toyota Vellfire 2.5A	Colour:	White
Chassis number:	AGH3000020142	Date of accident:	16/05/2018
Year of Regn.:	17/09/2015	Date inspected:	18/05/2018
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	28/05/2018

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	6mm/Bridgestone	6mm/Bridgestone	235/50R18
Rear:	6mm/Bridgestone	6mm/Bridgestone	235/50R18

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

PAR Automotive Consultancy

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
REAR AIRCON COOLING UNIT ASSY	1	fractured	2,009.10	2,009.10 <i>X^{na}</i>
REAR BUMPER	1	squashed	1,800.00	1,800.00 <i>1575</i>
REAR BUMPER REFLECTOR L/R (RH) @116	1pc <i>2</i>	fractured	656.00	656.00 <i>116</i>
REAR BUMPER RETAINER L/R (RH) @97	1pc <i>2</i>	necessary	270.00	270.00 <i>97</i>
REAR BUMPER REVERSE SENSOR (RH) @200	1pc <i>4</i>	shorted	803.60	803.60 <i>400</i>
REAR BUMPER REVERSE SENSOR WIRE HARNESS	+1	snapped	500.40	500.40 <i>X^{sv}</i>
REAR BUMPER TOW HOOK COVER L/R <i>LH-NA</i>	-21	warped	50.00	50.00 <i>25 2</i>
REAR DECK FLOOR MAT	1	deformed	851.70	851.70 <i>X</i>
REAR DECK RAIL CENTER BOX	1	bent	555.90	555.90 <i>X</i>
REAR DECK RAIL GARNISH L/R	2	deformed	530.00	530.00 <i>X</i>
REAR DECK RAIL L/R	2	bent	583.40	583.40 <i>X</i>
REAR END PANEL	1	buckled	798.00	798.00 <i>685</i>
REAR END PANEL ANTENNA SENSOR	1	shorted	195.00	195.00 <i>X^{sv}</i>
REAR END PANEL TOP GARNISH	1	fractured	175.00	175.00 <i>✓</i>
REAR EXHAUST GASKET	1	necessary	25.00	25.00 <i>X</i>
REAR EXHAUST RUBBER MOUNTING	3	distorted	165.00	165.00 <i>X</i>
REAR EXHAUST SILENCER BOX	1	bent	1,100.00	1,100.00 <i>X</i>
REAR FENDER INNER SHIELD L/R	2	reuse	298.00	0.00 <i>X</i>
REAR FENDER INNER TRIM BOARD L/R	2	deformed	1,518.00	1,518.00 <i>X</i>
REAR FLOOR BOARD CENTER	1	deformed	555.90	555.90 <i>X</i>
REAR FLOOR BOARD LH	1	deformed	311.90	311.90 <i>X</i>
REAR FLOOR BOARD RH	1	deformed	311.90	311.90 <i>X</i>
REAR FLOOR BOARD UPPER CENTER	1	deformed	319.50	319.50 <i>X</i>
REAR FLOOR BOARD UPPER LH	1	reuse	319.50	0.00 <i>X</i>
REAR FLOOR BOARD UPPER RH	1	reuse	306.70	0.00 <i>X</i>
REAR FLOOR PANEL	1	repair	650.00	0.00 <i>R</i>
REAR FLOOR PANEL CENTER REINFORCEMENT	1	bent	300.10	300.10 <i>X^{sv}</i>
REAR TAILGATE	1	buckled	1,985.00	1,985.00 <i>1718</i>
REAR TAILGATE 'VELLFIRE' EMBLEM	1	necessary	66.00	66.00 <i>✓</i>
REAR TAILGATE AUTO LOCK POWER MOTOR UNIT	1	shorted	2,265.00	2,265.00 <i>X</i>
REAR TAILGATE DAMPER L/R	2	bent	600.00	600.00 <i>X</i>
REAR TAILGATE HINGES L/R	2	bent	130.00	130.00 <i>X</i>
REAR TAILGATE INNER AUTO LOCK SWITCH	1	shorted	200.90	200.90 <i>X</i>
REAR TAILGATE INNER PULL HANDLE	1	reuse	38.50	0.00 <i>X</i>
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	2	deformed	50.00	50.00 <i>✓</i>
REAR TAILGATE INNER TRIM BOARD	1	fractured	708.00	708.00 <i>550</i>
REAR TAILGATE LOCK BUZZER	1	shorted	119.70	119.70 <i>X</i>
REAR TAILGATE LOCK STRIKER	1	bent	50.00	50.00 <i>X</i>
REAR TAILGATE MECHANISM LOCK	1	bent	768.50	768.50 <i>X</i>
REAR TAILGATE NUMBER PLATE LAMP L/R	2	fractured	130.00	130.00 <i>X</i>
REAR TAILGATE OUTER CHROME GARNISH	1	fractured	1,970.00	1,970.00 <i>X</i>
REAR TAILGATE OUTER LOCK SWITCH	1	shorted	195.70	195.70 <i>X</i>

PAR Automotive Consultancy

REAR TAILGATE POWER SENSOR CLIPS L/R	2	necessary	13.00	13.00	X
REAR TAILGATE POWER SENSOR L/R	2	shorted	883.80	883.80	X } su
REAR TAILGATE REFLECTOR L/R	2	fractured	176.00	176.00	X
REAR TAILGATE WEATHERSTRIP	1	deformed	357.00	357.00	X } 318
REAR TAILGATE WINDSCREEN MOULDING	1	necessary	156.50	156.50	-
REAR TAILLAMP L/R	2	fractured	950.00	950.00	X
REAR TAILLAMP LOWER GARNISH L/R	2	fractured	650.00	650.00	X } su
REAR TAILLAMP LOWER GARNISH RETAINER L/R	2	necessary	130.00	130.00	X
REAR TAILLAMP LOWER GARNISH SIDE STOPPER L/R	2	deformed	50.00	50.00	X

Subtotal before discount S\$ 28,603.20 S\$ 26,990.50

Percentage discount 25% and 25% S\$ 7,150.80 S\$ 6,747.63

Sub-total 1 S\$ 21,452.40 S\$ 20,242.88

REAR BUMPER CLIPS - SET	1	necessary	100.00	100.00	X } su
REAR DECK FLOOR MAT CLIPS - SET	1	necessary	80.00	80.00	X } su
REAR END PANEL TOP GARNISH CLIPS - SET	1	necessary	20.00	20.00	-
REAR FENDER INNER SHIELD CLIPS L/R - SET	2	necessary	100.00	100.00	X
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	2	necessary	160.00	160.00	X } su
REAR FLOOR PANEL INSULATOR MAT	1	necessary	300.00	300.00	X } su
REAR TAILGATE CAMERA	1	shorted	800.00	800.00	X
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	necessary	80.00	80.00	X } 40
REAR TAILGATE NUMBER PLATE	1	reuse	25.00	0.00	X } su
REAR TAILGATE NUMBER PLATE HOLDER	1	reuse	50.00	0.00	X } su
REAR TAILGATE REFLECTOR CLIPS L/R - SET	2	necessary	80.00	80.00	X } su
REAR TAILGATE WINDSCREEN SEALANT	1	necessary	100.00	100.00	X } 60
REAR TAILLAMP CLIPS L/R - SET	2	necessary	80.00	80.00	X } su
REAR TAILLAMP LOWER GARNISH CLIPS L/R - SET	2	necessary	80.00	80.00	X } su

Subtotal before discount S\$ 2,055.00 S\$ 1,980.00

Sub-total 2 S\$ 2,055.00 S\$ 1,980.00

Parts-total S\$ 23,507.40 S\$ 22,222.88

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	180.00	150.00	X } su
To reset system after repair works	400.00	400.00	X } su
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	120.00	80.00	X } 60
To remove, reinstall tailgate windscreen	300.00	150.00	X } 120
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	200.00	60.00	-
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	2,400.00	1,500.00	X } 1000
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	180.00	120.00	X } su
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,900.00	1,250.00	X } 900
To apply anti-rust chemical on repaired and replaced panel.	120.00	20.00	X } 60

Labour Total S\$ 6,800.00 S\$ 3,800.00

Parts & Labour Total S\$ 30,307.40 S\$ 26,022.88

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 22,100.00
and the recommended number of working days for the repairs is within 12 day(s).



B J Loi (I Eng., MIMI, AIRTE)
Automotive Appraiser

4317.37
1701.00
2200.00

6687.37
20%
5349.89

45-5,350

6 days




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS3/SMO18009100/R1td3e2-1		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 02-07-2019		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKL 6728B	Veh. Inspected	SBB 10L	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1802096	Excess (\$)	0.00	
Assign From	GNOH PAU LOONG	Assign Date	31/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VELLFIRE	c.c	2493	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	AGH300020142	Colour	WHITE	
Odometer	37218	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	235/50 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	235/50 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	235/50 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/05/2018	Inspection Date	21/05/2018	
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBB 10L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR AIRCON COOLING UNIT ASSY	NOT NECESSARY	2,009.10	-
1	REAR BUMPER	SQUASHED	1,800.00	1,575.00
2	REAR BUMPER REFLECTOR L/R	O/S FRACTURED	656.00	116.00
2	REAR BUMPER RETAINER L/R	O/S NECESSARY	270.00	97.00
4	REAR BUMPER REVERSE SENSOR	SHORTED-2PCS ONLY	803.60	400.00
1	REAR BUMPER REVERSE SENSOR WIRE HARNESS	SERVICEABLE	500.40	-
2	REAR BUMPER TOW HOOK COVER L/R	O/S WARPED / N/S NOT NECESSARY	50.00	25.00
1	REAR DECK FLOOR MAT	SERVICEABLE	851.70	-
1	REAR DECK RAIL CENTER BOX	SERVICEABLE	555.90	-
2	REAR DECK RAIL GARNISH L/R	SERVICEABLE	530.00	-
2	REAR DECK RAIL L/R	SERVICEABLE	583.40	-
1	REAR END PANEL	BUCKLED	798.00	688.00
1	REAR END PANEL ANTENNA SENSOR	SERVICEABLE	195.00	-
1	REAR END PANEL TOP GARNISH	FRACTURED	175.00	175.00
1	REAR EXHAUST GASKET	SERVICEABLE	25.00	-
3	REAR EXHAUST RUBBER MOUNTING	SERVICEABLE	165.00	-
1	REAR EXHAUST SILENCER BOX	SERVICEABLE	1,100.00	-
2	REAR FENDER INNER SHIELD L/R	SERVICEABLE	298.00	-
2	REAR FENDER INNER TRIM BOARD L/R	SERVICEABLE	1,518.00	-
1	REAR FLOOR BOARD CENTER	SERVICEABLE	555.90	-
1	REAR FLOOR BOARD LH	SERVICEABLE	311.90	-
1	REAR FLOOR BOARD RH	SERVICEABLE	311.90	-
1	REAR FLOOR BOARD UPPER CENTER	SERVICEABLE	319.50	-
1	REAR FLOOR BOARD UPPER LH	SERVICEABLE	319.50	-
1	REAR FLOOR BOARD UPPER RH	SERVICEABLE	306.70	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	650.00	-
1	REAR FLOOR PANEL CENTER REINFORCEMENT	SERVICEABLE	300.10	-
1	REAR TAILGATE	BUCKLED	1,985.00	1,718.00
1	REAR TAILGATE 'VELLFIRE' EMBLEM	NECESSARY	66.00	66.00
1	REAR TAILGATE AUTO LOCK POWER MOTOR UNIT	SERVICEABLE	2,265.00	-
2	REAR TAILGATE DAMPER L/R	SERVICEABLE	600.00	-
2	REAR TAILGATE HINGES L/R	SERVICEABLE	130.00	-

Report Ref No. CS3/SMO18009100/R1td3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE INNER AUTO LOCK SWITCH	SERVICEABLE	200.90	-
1	REAR TAILGATE INNER PULL HANDLE	SERVICEABLE	38.50	-
2	REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	DEFORMED	50.00	50.00
1	REAR TAILGATE INNER TRIM BOARD	FRACTURED	708.00	550.00
1	REAR TAILGATE LOCK BUZZER	SERVICEABLE	119.70	-
1	REAR TAILGATE LOCK STRIKER	SERVICEABLE	50.00	-
1	REAR TAILGATE MECHANISM LOCK	SERVICEABLE	768.50	-
2	REAR TAILGATE NUMBER PLATE LAMP L/R	SERVICEABLE	130.00	-
1	REAR TAILGATE OUTER CHROME GARNISH	SERVICEABLE	1,970.00	-
1	REAR TAILGATE OUTER LOCK SWITCH	SERVICEABLE	195.70	-
2	REAR TAILGATE POWER SENSOR CLIPS L/R	SERVICEABLE	13.00	-
2	REAR TAILGATE POWER SENSOR L/R	SERVICEABLE	883.80	-
2	REAR TAILGATE REFLECTOR L/R	SERVICEABLE	176.00	-
1	REAR TAILGATE WEATHERSTRIP	DEFORMED	357.00	318.00
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	156.50	156.50
2	REAR TAILLAMP L/R	SERVICEABLE	950.00	-
2	REAR TAILLAMP LOWER GARNISH L/R	SERVICEABLE	650.00	-
2	REAR TAILLAMP LOWER GARNISH RETAINER L/R	SERVICEABLE	130.00	-
2	REAR TAILLAMP LOWER GARNISH SIDE STOPPER L/R	SERVICEABLE	50.00	-
	LESS 25% DISCOUNT		-7,150.80	-1,483.63
			21,452.40	4,450.87
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	100.00	50.00
1	SET REARDECK FLOOR MAT CLIPS (SN)	NOT NECESSARY	80.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
2	SET REAR FENDER INNER SHIELD CLIPS L/R (SN)	NOT NECESSARY	100.00	-
2	SET REAR FENDER INNER TRIM BOARD CLIPS L/R (SN)	NOT NECESSARY	160.00	-
1	REAR FLOOR PANEL INSULATOR MAT (SN)	NOT NECESSARY	300.00	-
1	REAR TAILGATE CAMERA (SN)	NOT NECESSARY	800.00	-
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	80.00	40.00
1	REAR TAILGATE NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR TAILGATE NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
2	SET REAR TAILGATE REFLECTOR CLIPS L/R (SN)	NOT NECESSARY	80.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	100.00	60.00
2	SET REAR TAILLAMP CLIPS L/R (SN)	NOT NECESSARY	80.00	-

Report Ref No. CS3/SMO18009100/R1td3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	SET REAR TAILLAMP LOWER GARNISH CLIPS L/R (SN)	NOT NECESSARY	80.00	-
			2,055.00	170.00
	LABOUR			
	TO REMOVE, CHANGE AIR CON PARTS, VACUUMS, REFILL AIR CON GAS.	NOT NECESSARY	180.00	-
	TO RESET SYSTEM AFTER REPAIR WORKS.	NOT NECESSARY	400.00	-
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		120.00	60.00
	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.		300.00	120.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)		200.00	60.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.		2,400.00	1,000.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	180.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		2,900.00	900.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	60.00
			6,800.00	2,200.00
GRAND TOTAL			30,307.40	6,820.87
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,450.00

Report Ref No. CS3/SMO18009100/R1td3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.