

REQUEST FOR SUPPLYMENT PARTS

Contractor:		WEGA ENGINEERING PTE LTD	
Accident Case Number	TAX/05/19/2126	Date of Collection	30/5/19
Vehicle No	SHP 362 D	Date of Request	1/6/19
Vehicle Model	TOYOTA PRIUS 4	Number of Days to Extend (If any)	

S/N	Part Number	Part Description	Quantity	Unit Price
	1397, 98, 99	Fender & L Assy Fr RH		\$933.10 ✓
	1460, 61	Guide Radiator Air RL		\$54.60 ✓
	1466, 67, 68, 69, 70	Front Windscreen Assy		\$1626.40 ✓
	71, 72, 73	Front Windscreen Moulding		\$48.50 ✓
		Windscreen Sealant	2 BTL	\$46.00 ✓
		Coolant		\$12.00 ✓
		To Remove & Refix Windscreen		\$180.00 \$100
	1495, 96, 97	To Repair Pnt Chassis Member		\$350.00 \$200


BUC \$699.83
 DEF \$4095
 CRA \$1219.80
 nec \$33
 nec \$74
 nec \$12.32

<<<Please submit photographs for damaged parts>>>

1. (Name) CHIA

(Position)

Do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....


Signature of person making this declaration
 (To be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff		
Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

(2)

REQUEST FOR SUPPLYMENT PARTS

Contractor:		WEGA ENGINEERING PTE LTD	
Accident Case Number	70X/05/19/2126	Date of Collection	30/5/19
Vehicle No	SHP 362 D	Date of Request	1/6/19
Vehicle Model	TOYOTA PRIUS 4	Number of Days to Extend (If any)	

S/N	Part Number	Part Description	Quantity	Unit Price
	1503104	To Repair Pnt LH Fender		\$200.00 \$200
		To Respray Pnt LH Fender		\$378.00 \$200

<<<Please submit photographs for damaged parts>>>

I, (Name)

CAIA

(Position)

Do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

(4)



Case Details

Case Reference Number :

TAX/05/19/2126

Type of Repair : Accident Repair

Vehicle Registration Number :

SHF362D

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-7088-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 27/05/2019 12:00 PM

Vehicle Age(In Months) : 17

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Quantity	Surveyor Approval		Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace ▼	
One Time Key In	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	1	21.08	Replace ▼	
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace ▼	
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	1	251.70	Replace ▼	
One Time Key In	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	1	65.32	Replace ▼	
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	1	123.75	Replace ▼	
One Time Key In	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	1	74.85	Replace ▼	
One Time Key In	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace ▼	
One Time Key In	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	1	25.00	Replace ▼	

Total Spare Part Cost 35,997.72

Surveyor Total 7,281.25

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 35,997.72

Final Sur Total 7,281.25

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEAL, HOOD TO FR END	1	24.40	24.40	25.00	18.30	Replace	1	18.30	Replace	
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	1	61.72	Replace	
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	1	57.68	Replace	
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace	
One Time Key In	Main			SEAL SUB-ASSY, RH	1	50.20	50.20	25.00	37.65	Replace	1	37.65	Replace	
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	0	0	Not Give	
One Time Key In	Main			APRON SUB-ASSY, FRONT FENDER , RH	1	944.20	944.20	25.00	708.15	Replace	0	0	Not Give	
One Time Key In	Main			MEMBER SUB-ASSY, FR RH	1	2,012.70	2,012.70	25.00	1,509.53	Replace	0	0	Check	
One Time Key In	Main			PAD, FR WHEEL RH	1	57.70	57.70	25.00	43.28	Replace	0	0	Not Give	
One Time Key In	Main			FRONT REINFORCEMENT SIDE RH	1	128.20	128.20	25.00	96.15	Replace	1	96.15	Replace	
One Time Key In	Main			WIPER WASHER INLET	1	55.40	55.40	25.00	41.55	Replace	0	0	Check	
One Time Key In	Main			WIPER WASHER JAR	1	183.60	183.60	25.00	137.70	Replace	0	0	Check	
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	25.00	937.20	Replace	0	0	Not Give	
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give	

Total Spare Part Cost

35,997.72

Surveyor Total

7,281.25

Lump Sum Discount (%)

0.00

Lump Sum Dis (%)

0

Final Spare Part Cost

35,997.72

Final Sur Total

7,281.25

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SENSOR, AIR BAG, FRONT, RH & LH	1	310.50	310.50	10.00	279.45	Replace	0	0	Check	▼
One Time Key In	Main			FENDER SUB-ASSY, FR , LH	1	933.10	933.10	25.00	699.83	Replace	0	0	Not Give	▼
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	0	0	Not Give	▼
One Time Key In	Main			INSULATOR, HOOD	1	393.90	393.90	25.00	295.42	Replace	1	295.42	Replace	▼
One Time Key In	Main			INSULATOR, HOOD CLIP	6	2.30	13.80	25.00	10.35	Replace	6	10.35	Replace	▼
One Time Key In	Main			HINGE ASSY, HOOD, LH	1	57.00	57.00	25.00	42.75	Replace	1	42.75	Replace	▼
One Time Key In	Main			HINGE ASSY, HOOD, RH	1	57.00	57.00	25.00	42.75	Replace	1	42.75	Replace	▼
One Time Key In	Main			LOCK ASSY, HOOD	1	131.10	131.10	25.00	98.32	Replace	0	0	Check	▼
One Time Key In	Main			CABLE ASSY, HOOD	1	53.20	53.20	25.00	39.90	Replace	0	0	Not Give	▼
One Time Key In	Main			MOULDING RH	1	83.30	83.30	25.00	62.47	Replace	0	0	Not Give	▼
One Time Key In	Main			WIPER GARNISH LOUVER SUB-ASSY	1	666.90	666.90	25.00	500.17	Replace	0	0	Not Give	▼
One Time Key In	Main			WIPER GARNISH SHIELD, COWL WATER , LH	1	18.90	18.90	25.00	14.17	Replace	0	0	Not Give	▼
One Time Key In	Main			WIPER GARNISH SHIELD, COWL WATER , RH	1	18.90	18.90	25.00	14.17	Replace	0	0	Not Give	▼
One Time Key In	Main			PILLAR, FRONT BODY, RH	1	339.40	339.40	25.00	254.55	Replace	0	0	Not Give	▼
One Time Key In	Main			COVER SUB-ASSY, FRONT PILLAR , UPR RH	1	96.90	96.90	25.00	72.68	Replace	0	0	Check	▼

Total Spare Part Cost 35,997.72

Surveyor Total 7,281.25

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 35,997.72

Final Sur Total 7,281.25

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			THERMISTOR ASSY	1	68.00	68.00	25.00	51.00	Replace	0	0	Check	▼
One Time Key In	Main			COVER, RADIATOR	1	227.80	227.80	25.00	170.85	Replace	0	0	Check	▼
One Time Key In	Main			SUPPORT S/A UPPER	1	364.90	364.90	25.00	273.67	Replace	0	0	Check	▼
One Time Key In	Main			SUPPORT SUB-ASSY LOWER	1	397.40	397.40	25.00	298.05	Replace	0	0	Check	▼
One Time Key In	Main			SUPPORT S/A LH	1	237.00	237.00	25.00	177.75	Replace	0	0	Check	▼
One Time Key In	Main			SUPPORT S/A RH	1	237.00	237.00	25.00	177.75	Replace	0	0	Check	▼
One Time Key In	Main			BRACE, HOOD LOCK SUPPORT	1	76.20	76.20	25.00	57.15	Replace	0	0	Check	▼
One Time Key In	Main			SUPPORT, RADIATOR UPPER LH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check	▼
One Time Key In	Main			SUPPORT, RADIATOR UPPER RH	1	76.70	76.70	25.00	57.53	Replace	0	0	Check	▼
One Time Key In	Main			UNIT, HEADLAMP , LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Check	▼
One Time Key In	Main			UNIT, HEADLAMP , RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303.01	Replace	▼
One Time Key In	Main			COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Check	▼
One Time Key In	Main			HORN ASSY, HIGH	1	112.80	112.80	10.00	101.52	Replace	0	0	Check	▼
One Time Key In	Main			HORN ASSY, LOW	1	112.80	112.80	10.00	101.52	Replace	0	0	Check	▼
One Time Key In	Main			AIR CON CONDENSER ASSY	1	1,317.70	1,317.70	25.00	988.28	Replace	1	988.28	Replace	▼
Total Spare Part Cost									35,997.72	Surveyor Total 7,281.25				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									35,997.72	Final Sur Total 7,281.25				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TUBE & ACCESSORY	1	574.40	574.40	25.00	430.80	Replace	0	0	Check	▼
One Time Key In	Main			HOSE SUB-ASSY, DISCHARGE	1	337.10	337.10	25.00	252.83	Replace	0	0	Check	▼
One Time Key In	Main			HOSE SUB-ASSY, SUCTION	1	541.90	541.90	25.00	406.42	Replace	0	0	Check	▼
One Time Key In	Main			PIPE SUB-ASSY, SUCTION	1	389.60	389.60	25.00	292.20	Replace	0	0	Check	▼
One Time Key In	Main			AIR CON COMPRESSOR ASSY	1	2,887.80	2,887.80	10.00	2,599.02	Replace	0	0	Check	▼
One Time Key In	Main			COOLANT	1	12.30	12.30	0.00	12.30	Replace	0	0	Check	▼
One Time Key In	Main			GUIDE, RADIATOR AIR	1	93.90	93.90	25.00	70.43	Replace	0	0	Check	▼
One Time Key In	Main			GUIDE, RADIATOR AIR , UPPER	1	44.70	44.70	25.00	33.53	Replace	0	0	Check	▼
One Time Key In	Main			GUIDE, RADIATOR AIR , LH	1	58.80	58.80	25.00	44.10	Replace	0	0	Check	▼
One Time Key In	Main			GUIDE, RADIATOR AIR , RH	1	54.60	54.60	25.00	40.95	Replace	0	0	Check	▼
One Time Key In	Main			SEAL, RADIATOR TO RH	1	24.80	24.80	25.00	18.60	Replace	0	0	Check	▼
One Time Key In	Main			RADIATOR ASSY	1	1,841.10	1,841.10	25.00	1,380.82	Replace	0	0	Check	▼
One Time Key In	Main			GROMMET (FOR RADIATOR LOWER SUPPORT)	2	12.70	25.40	25.00	19.05	Replace	0	0	Check	▼
One Time Key In	Main			CUSHION, (FOR RADIATOR UPPER SUPPORT)	2	9.80	19.60	25.00	14.70	Replace	0	0	Check	▼
One Time Key In	Main			FAN RADIATOR , LH	1	181.80	181.80	25.00	136.35	Replace	0	0	Check	▼
Total Spare Part Cost									35,997.72	Surveyor Total 7,281.25				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									35,997.72	Final Sur Total 7,281.25				

SMRT Recommendation												Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FAN RADIATOR , RH	1	233.00	233.00	25.00	174.75	Replace	0	0	Check	▼
One Time Key In	Main			FAN SHROUD RADIATOR	1	219.30	219.30	25.00	164.48	Replace	0	0	Check	▼
One Time Key In	Main			MOTOR, COOLING FAN , LH	1	543.50	543.50	10.00	489.15	Replace	0	0	Check	▼
One Time Key In	Main			MOTOR, COOLING FAN , RH	1	443.40	443.40	10.00	399.06	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, RADIATOR , NO.1	1	42.60	42.60	25.00	31.95	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, RADIATOR , NO.2	1	40.20	40.20	25.00	30.15	Replace	0	0	Check	▼
One Time Key In	Main			TANK, RESERVE SEALED W/O CAP	1	127.00	127.00	25.00	95.25	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, WATER BYPASS , NO.1	1	37.40	37.40	25.00	28.05	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, WATER BYPASS , NO.2	1	37.40	37.40	25.00	28.05	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, WATER BYPASS , NO.3	1	20.10	20.10	25.00	15.08	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, WATER BYPASS , NO.4	1	13.20	13.20	25.00	9.90	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, WATER BYPASS , NO.8	1	37.90	37.90	25.00	28.42	Replace	0	0	Check	▼
One Time Key In	Main			PIPE, WATER BYPASS , NO.1	1	11.00	11.00	25.00	8.25	Replace	0	0	Check	▼
One Time Key In	Main			PIPE, WATER BYPASS , NO.2	1	11.00	11.00	25.00	8.25	Replace	0	0	Check	▼
One Time Key In	Main			PIPE, WATER BYPASS, NO.3	1	56.40	56.40	25.00	42.30	Replace	0	0	Check	▼

Total Spare Part Cost

35,997.72

Surveyor Total

7,281.25

Lump Sum Discount (%)

0.00

Lump Sum Dis (%)

0

Final Spare Part Cost

35,997.72

Final Sur Total

7,281.25

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PIPE, RADIATOR	1	32.90	32.90	25.00	24.67	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, RADIATOR , NO.3	1	29.60	29.60	25.00	22.20	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, WATER BYPASS, NO.5	1	13.20	13.20	25.00	9.90	Replace	0	0	Check	▼
One Time Key In	Main			PIPE, WATER BYPASS, NO.5	1	51.80	51.80	25.00	38.85	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, WATER BYPASS, NO.6	1	13.20	13.20	25.00	9.90	Replace	0	0	Check	▼
One Time Key In	Main			INVERTER WATER PUMP ASSY	1	432.00	432.00	10.00	388.80	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, HV WATER PUMP INLET	1	37.90	37.90	25.00	28.42	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, HV WATER PUMP OUTLET	1	29.60	29.60	25.00	22.20	Replace	0	0	Check	▼
One Time Key In	Main			TANK ASSY, INVERTER RESERVE	1	371.30	371.30	25.00	278.48	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, INVERTER COOLING INLET	1	43.10	43.10	25.00	32.33	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, INVERTER COOLING OUTLET	1	29.60	29.60	25.00	22.20	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, INVERTER RADIATOR INLET	1	40.70	40.70	25.00	30.53	Replace	0	0	Check	▼
One Time Key In	Main			COOLER, MOTOR COOLING	1	249.10	249.10	10.00	224.19	Replace	0	0	Check	▼
One Time Key In	Main			WIRE, ENGINE ROOM MAIN	1	6,138.00	6,138.00	10.00	5,524.20	Replace	0	0	Not Give	▼
One Time Key In	Main			INLET, AIR CLEANER, NO 1	1	130.50	130.50	25.00	97.88	Replace	0	0	Check	▼

Total Spare Part Cost 35,997.72

Surveyor Total 7,281.25

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 35,997.72

Final Sur Total 7,281.25

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			INLET, AIR CLEANER, NO 2	1	93.90	93.90	25.00	70.43	Replace	0	0	Check	▼
One Time Key In	Main			INLET, AIR CLEANER, NO 3	1	35.30	35.30	25.00	26.47	Replace	0	0	Check	▼
One Time Key In	Main			CLAMP (FOR AIR CLEANER HOSE , NO.2)	1	9.00	9.00	25.00	6.75	Replace	0	0	Check	▼
One Time Key In	Main			CLAMP (FOR AIR CLEANER INLET , NO.1)	2	7.10	14.20	25.00	10.65	Replace	0	0	Check	▼
One Time Key In	Main			CLAMP (FOR RESONATOR INTAKE AIR)	1	7.10	7.10	25.00	5.32	Replace	0	0	Check	▼
One Time Key In	Main			HOSE, AIR CLEANER , NO.1	1	62.10	62.10	25.00	46.58	Replace	0	0	Check	▼
One Time Key In	Main			RESONATOR, INTAKE AIR	1	14.90	14.90	25.00	11.18	Replace	0	0	Check	▼
One Time Key In	Main			BRACKET, AIR CLEANER	1	26.90	26.90	25.00	20.17	Replace	0	0	Check	▼
One Time Key In	Main			AIR CLEANER ASSY	1	956.20	956.20	25.00	717.15	Replace	0	0	Check	▼
One Time Key In	Main			TUBE, UNION (FOR AIR CLEANER HOSE)	1	19.40	19.40	25.00	14.55	Replace	0	0	Check	▼
One Time Key In	Main			BODY ASSY, THROTTLE	1	1,942.40	1,942.40	10.00	1,748.16	Replace	0	0	Check	▼
One Time Key In	Main			MANIFOLD, INTAKE	1	867.70	867.70	25.00	650.78	Replace	0	0	Check	▼
One Time Key In	Main			COVER ASSY, ENGINE UNDER CENTER SET	1	452.80	452.80	25.00	339.60	Replace	0	0	Check	▼
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Check	▼
One Time Key In	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	1	518.33	Replace	▼

Total Spare Part Cost 35,997.72

Surveyor Total 7,281.25

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 35,997.72

Final Sur Total 7,281.25

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			ABSORBER, FR BUMPER LOWER	1	117.00	117.00	25.00	87.75	Replace	1	87.75	Replace	▼
One Time Key In	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	1	178.88	Replace	▼
One Time Key In	Main			EXTENSION SUBASSY, LH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	▼
One Time Key In	Main			EXTENSION SUBASSY, RH	1	116.30	116.30	25.00	87.22	Replace	0	0	Check	▼
One Time Key In	Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	1	819.18	Replace	▼
One Time Key In	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.07	Replace	0	0	Check	▼
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	1	703.80	Replace	▼
Total Spare Part Cost									35,997.72	Surveyor Total		7,281.25		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost									35,997.72	Final Sur Total		7,281.25		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	1,521.00	1,000	
Total:			1,521.00	1,000.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO REPSRAY FRONT HOOD	378.00	200	
3	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0	
4	Main	TO RESPRAY RADIATOR SUPPORT LOWER	180.00	0	
5	Main	TO RESPRAY FRT MEMBER,RH	180.00	0	
Total:			2,790.00	600.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
6	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
7	Main	TO RESPRAY FRONT FENDER LH	378.00	0	
8	Main	TO RESPRAY APRON PANEL RH	180.00	0	
9	Main	TO RESPRAY FRONT DOOR RH	378.00	0	
10	Main	TO RESPRAY FRONT PILLAR RH	180.00	0	
Total:			2,790.00	600.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	125.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	20	
4	Main	TO TOP UP A/C GAS	120.00	50	
5	Main	TO ALIGN CHASSIS	350.00	0	
6	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	0	
7	Main	TO REMOVE AND REFIT WIRE HARDESS	300.00	0	
8	Main	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	50	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0.00	
10	Main	TO WASH AND VACUUM	60.00	0	
Total:			1,806.00	140.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	35,997.72	7,281.25
Total Labour Cost	1,521.00	1,000.00
Total Spray Painting	2,790.00	600.00
Other	1,806.00	140.00

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Overall Total	42,114.72	9,021.25
Lump Sum Repair Option		
Lump Sum Total	0.00	9,021.25
Surveyor Approved Amount		9,021.25
No of Repair Days*	12	6
Remarks	-	p/p repair, photo before paint.

Surveyor Name

Hwee jie

Signature



Survey Date

30/05/2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI19009691/Jha3

Date: 04/06/2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHF 362D


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30/05/2019 at the premises of M/s SMRT Automotive Services Pte Ltd (Woodlands) and have the following to report:-

Workshop Estimate Amount	: S\$	42,114.72
Revised Estimate Amount	: S\$	9,021.25
"Check" Items Amount	: S\$	18,970.08
Total (Including Check Items)	: S\$	27,991.33
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

ONG HWEE JIE
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHF362D
Vehicle to be Exported:	No
Intended Deregistration Date:	31 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	22R8258272
Chassis No.:	JTDKB3FU603576608
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	14 Dec 2017
First Registration Date:	14 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Dec 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	13 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$27,903.00
Total Rebate Amount:	\$31,653.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 31 May 2019

OK

Mei Kwan (LKKAUTO)

From: Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>
Sent: Tuesday, 4 June, 2019 10:55 AM
To: Mei Kwan (LKKAUTO)
Cc: Tan Kah Leong
Subject: RE: Direct Settlement - Accident Involving SLP5542T (OI : CTI - TBA) and SHF362D (TP : LKK REF - CC3/CTI19009691/Jha3) on 27/05/2019
Attachments: INSD SLP5542T GIA REPORT.PDF
Categories: HMK

Without Prejudice

Dear Mei Kwan,

Noted your email.

Attached our insured's GIA report as per your request.

Thank you.

Ong Chin Kiat
Assistant Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6174 | F: (65) 6224 7174 / 6224 7478

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 4 June, 2019 10:34 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>; CS A Team <cs-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving SLP5542T (OI : CTI - TBA) and SHF362D (TP : LKK REF - CC3/CTI19009691/Jha3) on 27/05/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SHF 362D at M/s SMRT Automotive Services Pte Ltd (Woodlands) on a WP basis and TP repairer proposed for a direct settlement.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI19009691/Jha3s2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 20-02-2020	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLP 5542T	Veh. Inspected	SHF 362D
Policy No.	DMPCSN30474218011	Coverage (\$)	0.00
Claim No.	SNM19D202429/C02/TKL	Excess (\$)	0.00
Assign From		Assign Date	30/05/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU603576608	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/05/2019	Inspection Date	30/05/2019
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 362D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER ,FR BUMPER (DISC 25%)	BROKEN	495.50	371.63
1	COVER ,FR BUMPER RH (DISC 25%)	MISSING	28.10	21.08
10	CLIPS PIECE ,FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	GRILLE SUB-ASSY (DISC 25%)	BROKEN	335.60	251.70
1	EMBLEM ASSY FRONT (DISC 25%)	NECESSARY	87.10	65.33
1	GRILLE ,RADIATOR (DISC 25%)	BROKEN	165.00	123.75
1	BRACKET ,FR BUMPER (DISC 25%)	BROKEN	99.80	74.85
1	SEAL ,HOOD TO FR END (DISC 25%)	NECESSARY	24.40	18.30
1	SUPPORT ,FR BUMPER LH (DISC 25%)	BROKEN	82.30	61.73
1	SUPPORT ,FR BUMPER RH (DISC 25%)	BROKEN	76.90	57.68
1	EMBLEM ,SIDE PANEL (HYBRID) (DISC 25%)	NECESSARY	52.90	39.68
1	SEAL SUB-ASSY ,RH (DISC 25%)	NECESSARY	50.20	37.65
1	FRONT REINFORCEMENT SIDE (DISC 25%)	DENTED	128.20	96.15
1	INSULATOR ,HOOD (DISC 25%)	CRUSHED	393.90	295.43
6	INSULATOR ,HOOD CLIP @\$2.30 (DISC 25%)	NECESSARY	13.80	10.35
1	HINGE ASSY ,HOOD ,LH (DISC 25%)	BENT	57.00	42.75
1	HINGE ASSY ,HOOD ,RH (DISC 25%)	BENT	57.00	42.75
1	AIR CON CONDENSER ASSY (DISC 25%)	DENTED	1,317.70	988.28
1	REINFORCEMENT FRONT UPPER (DISC 25%)	DENTED	691.10	518.33
1	ABSORBER ,FR BUMPER LOWER (DISC 25%)	CRUSHED	117.00	87.75
1	REINFORCEMENT FRONT LOWER (DISC 25%)	DENTED	238.50	178.88
1	HOOD SUB-ASSY (DISC 25%)	DENTED	938.40	703.80
1	WIPER WASHER JAR (DISC 25%)	DEFORMED	183.60	137.70
1	SUPPORT S/A UPPER (DISC 25%)	BUCKLED	364.90	273.68
1	SUPPORT S/A RH (DISC 25%)	BENT	237.00	177.75
1	SUPPORT S/A LH (DISC 25%)	BENT	237.00	177.75
1	BRACE ,HOOD LOCK SUPPORT (DISC 25%)	BENT	76.20	57.15
1	SUPPORT ,RADIATOR UPPER RH (DISC 25%)	BENT	76.70	57.53
1	RADIATOR ASSY (DISC 25%)	BUCKLED	1,841.10	1,380.83
1	FAN SHROUD RADIATOR (DISC 25%)	CRACKED	219.30	164.48
1	MOTOR ,COOLING FAN ,RH (DISC 25%)	JAMMED	443.40	332.55

Report Ref No. CC3/CT119009691/Jha3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	MOTOR ,COOLING FAN ,LH (DISC 25%)	JAMMED	543.50	407.63
1	FAN RADIATOR ,RH (DISC 25%)	CRACKED	233.00	174.75
1	INLET ,AIR CLEANER ,NO 1 (DISC 25%)	CRACKED	130.50	97.88
1	INLET ,AIR CLEANER ,NO 2 (DISC 25%)	DEFORMED	93.90	70.43
1	INLET ,AIR CLEANER ,NO 3 (DISC 25%)	CRACKED	35.30	26.48
1	AIR CLEANER ASSY (DISC 25%)	CRACKED	956.20	717.15
1	FENDER SUB-ASSY ,FR RH (DISC 25%)	BUCKLED	933.10	699.83
1	GUIDE ,RADIATOR AIR,RH (DISC 25%)	DEFORMED	54.60	40.95
1	WINDSCREEN FRONT GLASS SUB ASSY (DISC 25%)	CRACKED	1,626.40	1,219.80
1	WINDSCREEN FRONT MOULDING TOP FRONT (DISC 25%)	NECESSARY	44.00	33.00
1	UNIT ,HEADLAMP ,RH (DISC 10%)	BROKEN	2,558.90	2,303.01
1	LAMP ASSY ,FOG ,RH (DISC 10%)	BROKEN	910.20	819.18
1	FAN RADIATOR ,LH (DISC 5%)	CRACKED	181.80	172.71
1	NUMBER PLATE (SN)	BENT	35.00	35.00
1	NUMBER PLATE FRAME (SN)	BROKEN	25.00	25.00
2	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	74.00	74.00
1	COOLANT (SN)	NECESSARY	12.32	12.32
1	LINER ,FR FENDER ,RH	NOT NECESSARY	198.40	-
1	APRON SUB-ASSY ,FRONT FENDER ,RH	NOT NECESSARY	944.20	-
1	MEMBER ,SUB-ASSY ,FR RH	NOT NECESSARY	2,012.70	-
1	PAD ,FR WHEEL RH	NOT NECESSARY	57.70	-
1	WIPER WASHER INLET	NOT NECESSARY	55.40	-
1	WIPER WASHER JAR	NOT NECESSARY	183.60	-
1	PANEL SUB-ASSY ,FRONT DOOR RH	NOT NECESSARY	1,249.60	-
1	STICKER DECAL SMRT (DOOR)	NOT NECESSARY	60.00	-
2	SENSOR ,AIR BAG,FRONT ,RH & LH	NOT NECESSARY	310.50	-
1	FENDER SUB-ASSY ,FR,LH	NOT NECESSARY	933.10	-
1	EMBLEM ,SIDE PANEL (HYBRID)	NOT NECESSARY	52.90	-
1	LOCK ASSY ,HOOD	NOT NECESSARY	131.10	-
1	CABLE ASSY ,HOOD	NOT NECESSARY	53.20	-
1	MOULDING RH	NOT NECESSARY	83.30	-
1	WIPER GARNISH LOUVER SUB-ASSY	NOT NECESSARY	666.90	-

Report Ref No. CC3/CTI19009691/Jha3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WIPER GARNISH SHIELD COWL WATER ,LH	NOT NECESSARY	18.90	-
1	WIPER GARNISH SHIELD COWL WATER ,RH	NOT NECESSARY	18.90	-
1	PILLAR ,FRONT BODY ,RH	NOT NECESSARY	339.40	-
1	COVER SUB-ASSY ,FRONT PILLAR ,UPR RH	NOT NECESSARY	96.90	-
1	THERMISTOR ASSY	NOT NECESSARY	68.00	-
1	COVER ,RADIATOR	NOT NECESSARY	227.80	-
1	SUPPORT S/A UPPER	NOT NECESSARY	364.90	-
1	SUPPORT SUB-ASSY LOWER	NOT NECESSARY	397.40	-
1	SUPPORT S/A LH	NOT NECESSARY	237.00	-
1	SUPPORT S/A RH	NOT NECESSARY	237.00	-
1	BRACE ,HOOD LOCK SUPPORT	NOT NECESSARY	76.20	-
1	SUPPORT ,RADIATOR UPPER LH	NOT NECESSARY	76.70	-
1	SUPPORT ,RADIATOR UPPER RH	NOT NECESSARY	76.70	-
1	UNIT ,HEADLAMP ,LH	NOT NECESSARY	2,558.90	-
1	COMPUTER SUB-ASSY ,HEADLAMP ,RH NO.1	NOT NECESSARY	486.40	-
1	HORN ASSY ,HIGH	NOT NECESSARY	112.80	-
1	HORN ASSY ,LOW	NOT NECESSARY	112.80	-
1	TUBE & ACCESSORY	NOT NECESSARY	574.40	-
1	HOSE SUB-ASSY ,DISCHARGE	NOT NECESSARY	337.10	-
1	HOSE SUB-ASSY SUCTION	NOT NECESSARY	541.90	-
1	PIPE SUB-ASSY ,SUCTION	NOT NECESSARY	389.60	-
1	AIR CON COMPRESSOR ASSY	NOT NECESSARY	2,887.80	-
1	COOLANT	NOT NECESSARY	12.30	-
1	GUIDE ,RADIATOR AIR	NOT NECESSARY	93.90	-
1	GUIDE ,RADIATOR AIR,UPPER	NOT NECESSARY	44.70	-
1	GUIDE ,RADIATOR AIR ,LH	NOT NECESSARY	58.80	-
1	GUIDE ,RADIATOR AIR ,RH	NOT NECESSARY	54.60	-
1	SEAL ,RADIATOR TO RH	NOT NECESSARY	24.80	-
1	RADIATOR ASSY	NOT NECESSARY	1,841.10	-
1	GROMMET (FOR RADIATOR LOWER)	NOT NECESSARY	12.70	-
1	CUSHION (FOR RADIATOR UPPER)	NOT NECESSARY	9.80	-
1	FAN RADIATOR ,LH	NOT NECESSARY	181.80	-
1	FAN RADIATOR ,RH	NOT NECESSARY	233.00	-

Report Ref No. CC3/CT119009691/Jha3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FAN SHROUD RADIATOR	NOT NECESSARY	219.30	-
1	MOTOR ,COOLING FAN LH	NOT NECESSARY	543.50	-
1	MOTOR ,COOLING FAN RH	NOT NECESSARY	443.40	-
1	HOSE ,RADIATOR ,NO.1	NOT NECESSARY	42.60	-
1	HOSE ,RADIATOR ,NO.2	NOT NECESSARY	40.20	-
1	TANK ,RESERVE SEALED W/O CAP	NOT NECESSARY	127.00	-
1	HOSE ,WATER BYPASS ,NO.1	NOT NECESSARY	37.40	-
1	HOSE ,WATER BYPASS ,NO.2	NOT NECESSARY	37.40	-
1	HOSE ,WATER BYPASS ,NO.3	NOT NECESSARY	20.10	-
1	HOSE ,WATER BYPASS ,NO.4	NOT NECESSARY	13.20	-
1	HOSE ,WATER BYPASS ,NO.8	NOT NECESSARY	37.90	-
1	PIPE ,WATER BYPASS ,NO.1	NOT NECESSARY	11.00	-
1	PIPE ,WATER BYPASS ,NO.2	NOT NECESSARY	11.00	-
1	PIPE ,WATER BYPASS ,NO.3	NOT NECESSARY	56.40	-
1	PIPE,RADIATOR	NOT NECESSARY	32.90	-
1	HOSE,RADIATOR ,NO.3	NOT NECESSARY	29.60	-
1	HOSE,WATER BYPASS,NO.5	NOT NECESSARY	13.20	-
1	PIPE,WATER BYPASS,NO.5	NOT NECESSARY	51.80	-
1	HOSE,WATER BYPASS,NO.6	NOT NECESSARY	13.20	-
1	INVERTER WATER PUMP ASSY	NOT NECESSARY	432.00	-
1	HOSE ,HV WATER PUMP INLET	NOT NECESSARY	37.90	-
1	HOSE ,HV WATER PUMP OUTLET	NOT NECESSARY	29.60	-
1	TANK ASSY ,INVERTER RESERVE	NOT NECESSARY	371.30	-
1	HOSE ,INVERTER COOLING INLET	NOT NECESSARY	43.10	-
1	HOSE ,INVERTER COOLING OUTLET	NOT NECESSARY	29.60	-
1	HOSE ,INVERTER RADIATOR INLET	NOT NECESSARY	40.70	-
1	COOLER ,MOTOR COOLING	NOT NECESSARY	249.10	-
1	WIRE ,ENGINE ROOM MAN	NOT NECESSARY	6,138.00	-
1	INLET ,AIR CLEANER ,NO 1	NOT NECESSARY	130.50	-
1	INLET ,AIR CLEANER ,NO 2	NOT NECESSARY	93.90	-
1	INLET ,AIR CLEANER ,NO 3	NOT NECESSARY	35.30	-
1	CLAMP (FOR AIR CLEANER HOSE NO.2)	NOT NECESSARY	9.00	-
1	CLAMP (FOR AIR CLEANER HOSE NO.1)	NOT NECESSARY	7.10	-

Report Ref No. CC3/CTI19009691/Jha3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CLAMP (FOR RESONATOR INTAKE AIR)	NOT NECESSARY	7.10	-
1	HOSE ,AIR CLEANER NO.1	NOT NECESSARY	62.10	-
1	RESONATOR ,INTAKE AIR	NOT NECESSARY	14.90	-
1	BRACKET ,AIR CLEANER	NOT NECESSARY	26.90	-
1	AIR CLEANER ASSY	NOT NECESSARY	956.20	-
1	TUBE ,UNION (FOR AIR CLEANER HOSE)	NOT NECESSARY	19.40	-
1	BODY ASSY ,THROTTLE	NOT NECESSARY	1,942.40	-
1	MANIFOLD ,INTAKE	NOT NECESSARY	867.70	-
1	SET COVER ASSY ,ENGINE UNDER CENTER	NOT NECESSARY	452.80	-
1	ABSORBER ,FR BUMPER	NOT NECESSARY	70.30	-
1	EXTENSION SUBASSY,LH	NOT NECESSARY	116.30	-
1	EXTENSION SUBASSY,RH	NOT NECESSARY	116.30	-
1	COVER ASSY ,ENGINE	NOT NECESSARY	180.10	-
1	FENDER SUB-ASSY ,FR RH	TO REPAIR SEE LABOUR	933.10	-
			52,583.72	13,787.64
	LABOUR			
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF FENDER SUB-ASSY ,FR RH .		2,071.00	1,400.00
	SPRAY PAINT.		3,168.00	800.00
	TOWING CHARGE.		126.00	90.00
	TO CHECK WIRING AND SYSTEM FUNCTION .		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		200.00	20.00
	TO TOP UP A/C GAS.		120.00	50.00
	TO ALIGN CHASSIS.	NOT NECESSARY	350.00	-
	TO CHECK & RESET SYSTEM FUNCTION .	NOT NECESSARY	350.00	-
	TO REMOVE AND REFIT WIRE HARDESS.	NOT NECESSARY	300.00	-
	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER.		120.00	50.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM .	NOT NECESSARY	60.00	-
	TO REMOVE /REFIT WINDSCREEN.		120.00	100.00
			7,165.00	2,530.00

Report Ref No. CC3/CTI19009691/Jha3s2



GRAND TOTAL		59,748.72	16,317.64
RECOMMENDED COST OF REPAIRS			16,317.64

Report Ref No. CC3/CTI19009691/Jha3s2

ONG HWEE JIE
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.