

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19009720/GGA3Q2

**Date:** 31/08/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> FBC2692A	<b>Insured Vehicle No :</b>	SHD7245Z
Date of Loss: 21/05/2019	Nature of Claim: TP	Claim No: MCT19050902

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBC2692A		
Make & Model:	YAMAHA T135, 135cc	Engine No:	5YP208194
Reg. Date:	22/01/2008 (Man. Year: 2007)	Chassis No:	5YP208194
Colour:	Blue	Odometer:	30308 km
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	70/90 R17	Rear Tyre Size:	80/70 R17
Front Left Side:	Dunlop 2 mm	Rear Left Side:	Dunlop 2 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,332.60	1,481.10	851.50	36.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	730.00	180.00	550.00	75.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,062.60</b>	<b>1,661.10</b>	<b>1,401.50</b>	<b>45.76</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>3,062.60</b>	<b>1,300.00</b>	<b>1,762.60</b>	<b>57.55</b>
<b>+ Loss of Use (4.0 x S\$20.00/day) (S\$)</b>		80.00		
<b>+ Other Costs (S\$)</b>		50.00		
<b>Nett Liability (S\$)</b>		<b>1,430.00</b>		

### INSPECTION

Date of Assignment:	31/05/2019	
Date Inspected:	31/05/2019 Inspected At:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 Singapore 569622
Estimated Period of Repair:	4.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 05 Dec 2019)	
<b>Parts:</b>	N/A	YAMAHA T135 135cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBC2692A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEAD LAMP	Cracked	250.00 FL	*250.00 FL
2	1		*HANDLE BAR	Not Necessary	135.00 FL	*- FL
3	1		*HEAD LAMP COVER	Scratched	195.00 FL	*195.00 FL
4	1		*FRONT MUDGUARD	Repair	265.00 FL	*- FL
5	1		*BRAKE LEVER	Cut	69.00 FL	*69.00 FL
6	1		*SET HANDLE BAR GRIP RH	Cut	130.00 FL	*130.00 FL
7	1		*EXHAUST GUARD-CHROME	Cut	220.00 FL	*220.00 FL
8	1		*EXHAUST GUARD	Cut	190.00 FL	*190.00 FL
9	1		*FRONT RH SIGNAL	Cracked	115.00 FL	*115.00 FL
10	1		*REAR MUDGUARD	Not Necessary	235.00 FL	*- FL
11	1		*FOOTREST	Bent	95.00 FL	*95.00 FL
12	1		*FOOTREST RUBBER	Deformed	65.00 FL	*65.00 FL
13	1		*KICKSTART	Jammed	135.00 FL	*135.00 FL
14	1		*KICKSTART SHAFT	Necessary	165.00 FL	*165.00 FL
15	1		*REAR BOX	Not Necessary	280.00 FS	*- FS
16	1		*REAR NUMBER PLATE	Bent	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,559.00</b>	<b>1,644.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	226.40	162.90
<b>Total Parts (\$\$)</b>	<b>2,332.60</b>	<b>1,481.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TOWING FEE	New	40.00	0.00
2	REMOVE & REPLACE NECESSARY PARTS,ALIGN & ETC	New	200.00	150.00
3	CHECK FORK ALIGNMENT	New	60.00	30.00
4	SUPPLY BODY DECAL STICKER	New	80.00	0.00
5	TO CHECK ENGINE (STALLED AFTER BIKE DOWN)	New	350.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>730.00</b>	<b>180.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >