

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19009744/GKA3Q2

**Date:** 08/04/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100453908

**Claimant**  
**Vehicle No :** SLU9400S **Insured Vehicle No :** SLA4374Y

Date of Loss: 06/12/2018 Nature of Claim: TP Claim No: 3111650399SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLU9400S</b>	Engine No:	G4LCHU897203
Make & Model:	HYUNDAI ACCENT, 1.4 (A)	Chassis No:	KMHCU41BTJU403669
Reg. Date:	19/12/2017 (Man. Year: 2017)	Odometer:	35747 km
Colour:	Silver		
Engine Capacity:	1368 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	650.00	340.00	310.00	47.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>650.00</b>	<b>340.00</b>	<b>310.00</b>	<b>47.69</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	45.50	23.80	21.70	47.69
<b>Nett Amount (\$\$)</b>	<b>695.50</b>	<b>363.80</b>	<b>331.70</b>	<b>47.69</b>
<b>+ Car Rental (2.0 x S\$100.00/day) (\$\$)</b>		200.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>565.80</b>		

### INSPECTION

Date of Assignment: 21/01/2020

Date Inspected: 21/01/2020 Inspected At:

Hock Wah Motor Workshop Pte Ltd  
(Bedok)  
Blk 3011, Bedok Industrial Park E.,  
#01-2008/2010/2012  
Singapore 489977

Estimated Period of Repair: 2.0 days

**Adjuster:** XING GUO QIANG**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (NPA)	Repair	0.00 FS	*- FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (S\$)</b>					<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	150.00	100.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	300.00	200.00
3	ANTI-RUST COATING	New	50.00	0.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	40.00
<b>Gross Labour Cost (\$\$)</b>			<b>650.00</b>	<b>340.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >