



Case Details

Case Reference Number : TAX/05/19/2137
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5850A

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-7097-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : EQ Insurance Company Ltd
 Accident Date and Time : 30/05/2019 12:15 AM
 Vehicle Age(In Months) : 17

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	0.00	Repair ▾	
One Time Key In	Main			FENDER SUB-ASSY, FR, RH	1	933.10	933.10	25.00	699.83	Replace	1	0.00	Repair ▾	
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace ▾	nel
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	0	0.00	Not Give ▾	uu
One Time Key In	Main			COVER SUB-ASSY, FRONT PILLAR, UPR RH	1	96.90	96.90	25.00	72.68	Replace	0	0.00	Not Give ▾	uu
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW, RH	1	1,373.50	1,373.50	10.00	1,236.15	Replace	1	1,236.1	Replace ▾	CRA
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	89.50	89.50	25.00	67.13	Replace	1	67.13	Replace ▾	mls
Total Spare Part Cost									2,635.89		Surveyor Total		1,342.95	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		0.00	
Final Spare Part Cost									2,635.89		Final Sur Total		1,342.95	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	338.00	200.00	
Total:			338.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200.00	
2	Main	TO RESPRAY FRONT FENDER RH	378.00	200.00	
3	Main	TO RESPRAY VIEW MIRROR	180.00	50.00	
Total:			936.00	450.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20.00	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00	
3	Main	TO REMOVE AND REFIX WING MIRROR	120.00	50.00	
4	Main	TO WASH AND VACUUM	60.00	0.00	
Total:			360.00	70.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,635.89	1,342.95
Total Labour Cost	338.00	200.00
Total Spray Painting	936.00	450.00
Other	360.00	70.00
Overall Total	4,269.89	2,062.95
Lump Sum Repair Option		
Lump Sum Total	0.00	2,062.95
Surveyor Approved Amount		2,062.95

	Estimator Assesment(\$)	Surveyor Assesment(\$)
No of Repair Days*	3	2
Remarks	-	p/p repair, photo before paint.
Surveyor Name		Hwee jie
Signature		
Survey Date	31/05/2019	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: