

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : NTUC INCOME INSURANCE CO-OPERATIVE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTHQ/TP/1905/012
Policy No:	pvmc2019-00002197	Date of Loss:	09/05/2019
Vehicle Reg. No.:	FBM6064J	Driveable?	yes
Driver Age:	19-02-1990	Third Party Vehicle No.:	SGH2991B
Any Injuries?	yes	Contact No:	97981404
Insured/Claimant:	MUHAMMAD HAFIZ BIN IBRAHIM	Driver:	MUHAMMAD HAFIZ BIN IBRAHIM

Make/Model:	Yamaha, FJR1300 - JYARP13A00	Vehicle Reg. Date:	06/01/2014
Vehicle Colour:	GREY	Engine Number:	MK916293
Chassis No:	RFGLNA701DS006309	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: COLLISION - HEAD ON COLLISION
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	7,191.90
Miscellaneous Items	858.00
Labour	920.00
Paintwork Labour	450.00
Towing	0.00
Gross Total(\$\$):	9,419.90
GST 7.00%(\$\$):	659.39
Nett Amount(\$\$):	10,079.29

This claim is handled by: Sky Toh T C

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT HEADLAMP <i>Xnn</i>	0.00	900.00	-10.00	810.00
2	1	FRONT HEADLAMP FAIRING <i>CRA</i>	0.00	450.00	-10.00	405.00
3	1	FRONT HEADLAMP FAIRING CENTRE CHROME <i>rec</i>	0.00	95.00	-10.00	85.50
4	1	FRONT HEADLAMP CENTRE FAIRING <i>CRA</i>	0.00	230.00	-10.00	207.00
5	1	FRONT HEADLAMP LOGO <i>rec</i>	0.00	53.00	-10.00	47.70
6	1	FRONT HEADLAMP BRACKET <i>Xnn</i>	0.00	83.00	-10.00	74.70
7	1	FRONT HEADLAMP INNER FAIRING <i>Xnn</i>	0.00	430.00	-10.00	387.00
8	1	FRONT SIDE LAMP LH <i>Xnn</i>	0.00	208.00	-10.00	187.20
9	1	FRONT SIDE LAMP RH <i>scr</i>	0.00	208.00	-10.00	187.20
10	1	FRONT SIDE MIRROR LH <i>Xnn</i>	0.00	130.00	-10.00	117.00
11	1	FRONT SIDE MIRROR RH <i>CRA</i>	0.00	130.00	-10.00	117.00
12	1	FRONT SIDE MIRROR SIGNAL LAMP LH <i>Xnn</i>	0.00	70.00	-10.00	63.00
13	1	FRONT SIDE MIRROR SIGNAL LAMP RH <i>CRA</i>	0.00	70.00	-10.00	63.00
14	1	FRONT SIDE MIRROR GLASS RH <i>mis</i>	0.00	87.00	-10.00	78.30
15	1	FRONT SIDE MIRROR GARNISH LH <i>Xnn</i>	0.00	38.00	-10.00	34.20
16	1	FRONT SIDE MIRROR GARNISH RH <i>mis</i>	0.00	38.00	-10.00	34.20
17	1	FRONT TOP VISOR <i>Xnn</i>	0.00	160.00	-10.00	144.00
18	1	FRONT TOP VISOR LOWER FAIRING <i>scr</i>	0.00	145.00	-10.00	130.50
19	1	FRONT FENDER <i>scr</i>	0.00	180.00	-10.00	162.00
20	1	FRONT FORK LH <i>Xnn</i>	0.00	280.00	-10.00	252.00
21	1	FRONT FORK RH <i>Xnn</i>	0.00	280.00	-10.00	252.00
22	1	FRONT WHEEL DISC ROTOR <i>Xnn</i>	0.00	265.00	-10.00	238.50
23	1	FRONT WHEEL BRAKE CALIPER <i>Xnn</i>	0.00	380.00	-10.00	342.00
24	1	FRONT BALANCER RH <i>scr</i>	0.00	25.00	-10.00	22.50
25	1	FRONT HANDLE BAR <i>Xnn</i>	0.00	240.00	-10.00	216.00
26	1	FRONT STEERING STEM <i>Xnn</i>	0.00	55.00	-10.00	49.50
27	1	FRONT BRAKE LEVER RH <i>scr</i>	0.00	28.00	-10.00	25.20
28	1	FRONT CENTRE INNER FAIRING <i>CRA</i>	0.00	480.00	-10.00	432.00
29	1	FRONT STEP GARNISH RH <i>Xnn</i>	0.00	110.00	-10.00	99.00
30	1	FRONT RADIATOR FAIRING <i>CRA</i>	0.00	420.00	-10.00	378.00
31	1	FRONT CENTRE LOWER FAIRING <i>Xnn</i>	0.00	370.00	-10.00	333.00
32	1	RADIATOR <i>Xnn</i>	0.00	445.00	-10.00	400.50
33	1	RADIATOR BRACKET <i>Xnn</i>	0.00	78.00	-10.00	70.20
34	1	REAR EXHAUST PIPE PROTECTOR <i>scr</i>	0.00	160.00	-10.00	144.00
35	1	REAR FAIRING RH <i>scr</i>	0.00	320.00	-10.00	288.00
36	1	REAR HANDLE RH <i>scr</i>	0.00	140.00	-10.00	126.00
37	1	FRONT SEAT TOP BACKING CUSHION <i>Xnn</i>	0.00	210.00	-10.00	189.00

Total Parts (\$\$) 7,191.90

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT WHEEL RIM <i>nnx</i>	0.00	353.00	0.00	353.00 <i>X</i>
2	1	FRONT NUMBER PLATE <i>rec</i>	0.00	45.00	0.00	45.00 <i>20</i>
3	1	REAR BOX (METAL) <i>scr</i>	0.00	380.00	0.00	380.00 <i>250</i>
4	1	REAR BOX BRACKET (1 SET) <i>nnx</i>	0.00	80.00	0.00	80.00 <i>X</i>

Sub Total (\$\$) 858.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 20
2	1	To Remove and Refit, Straighten and Re-adjust Exhaust Pipe and Rear Exhaust Silencer and Mountings.	180.00	180.00	0.00	180.00 50
3	1	To Pressure Test Air Con Condenser and Radiator For Leakage.	120.00	120.00	0.00	120.00 X
4	1	Towing Charges.	80.00	80.00	0.00	80.00 40
5	1	To Conduct Wheel Balancing	60.00	60.00	0.00	60.00 50
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	450.00	450.00	0.00	450.00 300

Gross Labour Cost (\$\$) 920.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	50.00	50.00	0.00	50.00 30
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	400.00	400.00	0.00	400.00 X

Gross Labour Cost (\$\$) 450.00

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hwee Jie - LKK

3/6/19

L/S 4 days.