

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
 Tel: 67139400 Fax: 67138415
 Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G



Not Authorized
2/5
4100
3/6/19
changed Author
QUOTATION: HQQ000003

SJJ5751L**ASLAM SYED****ZARRAR**

2 BEDOK RESERVOIR VIEW

#07-02479232

TEL : 91808142

DATE	:	03-JUN-2019
MAKE	:	TOYOTA
MODEL	:	AXIO 1.5 XA
CHASSIS NO	:	NZE1416072418
ENGINE NO	:	1NZC957503
SERVICE ADVISOR	:	YVONNEWONG
PAGE	:	1 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
LIST ITEM			
1	BOOT LID	721.50 X	
1	BOOT LID LOCK	94.50 X	
1	BOOT LID MOULDING	272.80 X	
1	BOOT LID LOGO	57.80 X	
1	BOOT LID EMBLEM AXIO	48.17	
1	TAILLAMP LHS	359.40 X	
1	TAILLAMP RHS	359.40	
1	TAILLAMP PANEL RH	18.40	
1	REAR BUMPER	454.20	
1	REAR BUMPER SIDE RETAINER RH	96.60	
1	REAR BUMPER SIDE RETAINER LHS	96.60 X	
1	REAR BUMPER SPONGE	180.00 X	
1	REAR BUMPER BRACKET RHS	65.00	
1	REAR BUMPER BRACKET LHS	0.00 X	
1	SPARE TYRE TOP BOARD	562.50	
1	SPARE TYRE PANEL	820.90	
1	REAR END PANEL	513.20	
1	REAR END PANEL TOP GARNISH	198.90	
10	REAR BUMPER LOCK CATCH	184.00 X	
1	EXHAUST HEAT SHIELD	143.90 X	
1	EXHAUST MUFFLER	815.90 X	
Sub Total		5,998.67	

50%

3137.27
50%
1568.63
0.00

SPECIAL NETT

10	REAR END PANEL TOP GARNISH CLIPS	50.00 X
10	REAR BUMPER CLIPS	50.00
1	REAR END PANEL SEALANT	50.00

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
 Tel: 67139400 Fax: 67138415
 Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**QUOTATION: HQQ000003**

SJJ5751L
ASLAM SYED
ZARRAR

2 BEDOK RESERVOIR VIEW
 #07-02479232
 TEL : 91808142

DATE : 03-JUN-2019
 MAKE : TOYOTA
 MODEL : AXIO 1.5 XA
 CHASSIS NO : NZE1416072418
 ENGINE NO : 1NZC957503
 SERVICE ADVISOR : YVONNEWONG
 PAGE : 2 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	REVERSE SENSOR <i>1 set</i>	<i>shud</i> 250.00 <i>200</i>	
1	TAILLAMP INNER SEAL LH	<i>11</i> 50.00 <i>X</i>	
1	TAILLAMP INNER SEAL RHS	<i>11</i> 50.00 <i>X</i>	
1	BOOT LID SEALANT	<i>11</i> 50.00 <i>X</i>	
Sub Total		550.00	0.00

LABOUR

1	TO CHECK WIRING SYSTEM AFTER DISCONNECT AND CONNECT	100.00 <i>30</i>	
1	TO DISMANTLE & INSTALL BOOT LID COMPONENT	<i>11</i> 180.00 <i>X</i>	
1	TO DISMANTLE & INSTALL REVERSE SENSOR	100.00 <i>50</i>	
1	TO APPLY UNDERCOATING FOR RUSTPROOFING	100.00 <i>60</i>	
1	TO DISMANTLE & INSTALL EXHAUST PIPE AND ALIGNMENT	<i>11</i> 200.00 <i>X</i>	
1	TO PANEL BEATING AND STRAIGHTEN PARTS ON ACCIDENT AREA.	1,000.00 <i>✓</i>	
1	TO SPRAY PAINTING ON ACCIDENT AREA.	1,200.00 <i>1100</i>	
Sub Total		2,880.00	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

p-1568.63
S.N-300.00
1,168.63
4128.63

Acknowledged by Repairer	SUB-TOTAL	9,428.67	0.00
Signature:	GST - 7 %	660.01	0.00
Date:	TOTAL	10,088.68	0.00

ABWIN SERVICE PTE LTD

Prepared By