



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 1386T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF PARTS	TO REPAIR SEE LABOUR		
	REAR DOOR N/S (CONSISTENT)		1,450.00	-
			1,450.00	-
	LABOUR			
	LABOUR FOR PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR DOOR N/S. TO PUTTY & SPRAY PAINTING.		200.00	50.00
			300.00	200.00
			500.00	250.00
GRAND TOTAL			1,950.00	250.00
RECOMMENDED COST OF REPAIRS				250.00

Report Ref No. CC4/ASM19009805/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.