



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD ISUZU TBC (YP3374X)
Date of Loss	16 May 2019
Time of Loss	13.35
Loss Description	YQ877B (INSD) C/W YP3374X (TP)
Comment	

Workshop Details

Total Rebate Amount	12592
Nett Loss Amount	\$31,408.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# YP3374X

Registration State SINGAPORE

Mileage 19181

Purchase Date

dd/mm/yyyy



Registration Date *

28/06/2016



Age of Vehicle

2

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2016

Make

TPVD ISUZU

ISUZU

Model

TBC

NHR85AUE4A R1

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

ZHAI XIANRONG

Date of Birth

dd/mm/yyyy



Age

0

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No		JAANHR85EG7100149
Engine No		4JJ12M4696
Engine Capacity		2999
Sum Insured		0
Market Value		44000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	0	
Driver License #		
License Type		
License Issue Date		dd/mm/yyyy 
License Expiration Date		dd/mm/yyyy 
Address	96J JALAN SENANG, 418489, Singapore	
Address type	Personal Correspondence	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Unknown	
Marital status	Unknown	
Identification #	G8640070M	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

07/06/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

185R15C

Rear Tyre Size

185R14

Front left side

JOURNEY6mm

Rear left side

JOURNEY6mm

Front right side

JOURNEY6mm

Rear right side

JOURNEY6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No



SERVICE REQUESTS

MESSAGES

CLAIMS

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		FRONT PANEL	Dented	0	440	No		15			374	Reviewing	
		0	1		FRONT GRILLE	Cracked	0	302	No		15			256.7	Reviewing	
		0	1		FRONT BUMPER	Bent	0	353	No		15			300.05	Reviewing	
		0	1		FRONT L/H WIPER NOZZLE	Serviceable	0	0	No		15			0	Deny	
		0	1		FRONT R/H SIDE MIRROR	Cracked	0	98	No		15			83.3	Reviewing	
		0	1		FRONT R/H SIDE MIRROR ARM	Bent	0	226	No		15			192.1	Reviewing	
		0	1		FRONT R/H SIDE PANEL	Bent	0	185	No		15			157.25	Reviewing	
		0	1		FRONT R/H HEADLAMP	Cracked	0	273	No		15			232.05	Reviewing	
		0	10		CLIPS	Necessary	0	3	No		15			25.5	Reviewing	

Labour

Add Approve Deny Submit All											
EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE	
		0	LABOUR FOR CHECKING ON WIRING	0	50	0	0	Reviewing			
		0	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF FRONT BUMPER, PANEL, GRILLE, SIDE PANEL, SIDE MIRROR ARM & HEADLAMP	0	900	0	0	Reviewing			
		0	SPRAY PAINTING & PUTTY OF FRONT PANEL, GRILLE, BUMPER, SIDE PANEL	0	800	0	0	Reviewing			
		0	LABOUR FOR CHECKING ON AIRCON PIPE & TOP UP GAS					Deny			



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNTADJUSTED
AMOUNT

COMMENT

REMOVE



0

DAYS
OF
REPAIR
: 4
DAYS

Reviewing

0





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim Amount

\$3,370.95

CATEGORY

ESTIMATE

ADJUSTED

Spare Parts

\$0.00

\$1,620.95

Labour

\$0.00

\$1,750.00

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	FINAL LUMP SUM	Reviewing	2700		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim
Amount

\$0.00

Adjusted Claim Amount

\$2,700.00

CATEGORY

ESTIMATE

ADJUSTED

Miscellaneous

\$0.00

\$2,700.00

Submit for Review