

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SMA3502P

Chassis No : JHMGK3850JX222656

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : CHUA BENG HOCK

Ins Policy No. :

Date of Accident : 31/5/2019

Document No. : SQT19002409

Date : 3. Jun 2019

Customer No. : WZI007

Svc Advisor : IVAN TEO BOON KIAT

Engine No : L13B11030741

Date | Time : 3. Jun 2019 9:31:00 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHUA BENG HOCK OWNER INSURER: AVIVA LTD ACC DATE: 31/05/2019 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA TP VEH: SHD3373M						
68100-TAR-U10ZZ	TAILGATE COMP BUC /	1	730.60	25	547.95	38.36	586.31
74440-T5A-003	WEATHERSTRIPTAILGATE DEF /	1	92.30	25	69.22	4.85	74.07
74890-T5A-A11	GARNISH ASSY,RR LICENCE nux	1	105.50	25	79.12	5.54	84.66
75722-T5L-T01	EMBLEMRR. nec /	1	10.90	25	8.17	0.57	8.74
04715-T5A-J50ZZ	FACE,RR.BUMPER DEF /	1	492.70	25	369.52	25.87	395.39
71502-T5A-J60	COVER,R.RR.BUMPER nux	1	20.70	25	15.52	1.09	16.61
71507-T5A-J60	COVER,L.RR.BUMPER nux	1	20.70	25	15.52	1.09	16.61
71505-T5A-J50	GARNISH,RR.BUMPER nux	1	38.30	25	28.72	2.01	30.73
71503-T5A-J50	COVER,RR.EXPI FIN nux	1	9.30	25	6.97	0.49	7.46
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE nec /	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE nec /	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER nec /	7	2.30	25	12.07	0.84	12.91
33500-T5A-J02	TAILLIGHT ASSY,R. nux	1	223.90	25	167.92	11.75	179.67
33550-T5A-J02	TAILLIGHT ASSYL. nux	1	223.90	25	167.92	11.75	179.67
34150-T5A-J01	LIGHT ASSYR.LID nux	1	81.70	25	61.27	4.29	65.56
34155-T5A-J01	LIGHT ASSYL.LID nux	1	81.70	25	61.27	4.29	65.56
66100-TAR-T00ZZ	PANEL COMPRR. ?	1	320.40	25	240.30	16.82	257.12
73127-TY0-000	RUBBER CWINDSHIELD DAMPER nux nec /	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER nux nec /	2	6.50	25	9.75	0.68	10.43

Printed on 3/6/2019 12:14:09 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SMA3502P

Chassis No : JHMGK3850JX222656

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : CHUA BENG HOCK

Ins Policy No. :

Date of Accident : 31/5/2019

Document No. : SQT19002409

Date : 3. Jun 2019

Customer No. : WZ1007

Svc Advisor : IVAN TEO BOON KIAT

Engine No : L13B11030741

Date | Time : 3. Jun 2019 9:31:00 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73226-SZW-000	DAMPERSTD 5X5 <i>nec ✓</i>	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>nec ✓</i>	1	60.00		60.00	4.20	64.20
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>shorted ✓</i>	1	320.00		320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>nn x</i>	1	45.00		45.00	3.15	48.15
Sum Item					2326.47	162.87	2,489.34
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00 ✓		560.00	39.20	599.20
BOSUN	SUNDRIES	1	100.00 <i>30</i>		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00 <i>120</i>		180.00	12.60	192.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00 <i>280</i>		450.00	31.50	481.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00 <i>280</i>		450.00	31.50	481.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00 <i>320</i>		560.00	39.20	599.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00 X		560.00	39.20	599.20
BOJSE	BODY JOINT SEALANT.	1	180.00 X		180.00	12.60	192.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00 X		180.00	12.60	192.60
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	1	2800.00 <i>1120</i>		2800.00	196.00	2996.00
BOBC	BODY UNDERSIDE COATING (N)	1	180.00 X		180.00	12.60	192.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00 X		560.00	39.20	599.20
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00 <i>80</i>		100.00	7.00	107.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2700.00 <i>900</i>		2700.00	189.00	2889.00
Sum Labor					9560.00	669.20	10,229.20

Survey By Hue Jie - LKK

Date & Time 25/6/19

Excess -

Status P/P 4 days

Signature [Signature]

Total Amount 11,886.47 832.07 12,718.54

Total (Inclusive of GST)

12,718.54

Printed on 3/6/2019 12:14:09 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: