



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM19009865/Bga3q2 Date: 09/12/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 5503Y	Veh. Inspected	SJR 8043K	
Policy No.	P1680520	Coverage (\$)	0.00	
Claim No.	S9M01OMX	Excess (\$)	0.00	
Assign From		Assign Date	04/06/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI AVANTE	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KMH DU41BR9U783163	Colour	SILVER	
Odometer	158413 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/60 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/60 R15	GOODRIDE	6 mm	
L/H Rear Tyre	195/60 R15	GOODRIDE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	26/05/2019	Inspection Date	13/06/2019	
Survey held at	160 SIN MING DRIVE #01-14			
Repairer	TEAM AUTOPRO PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	