7/16/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG19009886/KBA3Q2

Date:

16/07/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100503357

Claimant Vehicle No: SCZ6361X 14/04/2019 Date of Loss:

Insured Vehicle No: Nature of Claim:

SLL7499T TP

Claim No:

5758131233SG

MRHGD85906P010108

L15A24801984

597501 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCZ6361X

Make & Model: HONDA CITY, 1.5 (M)

22/11/2006 (Man. Year: 2006) Reg. Date:

Colour: Metallic Grey

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes

Footbrake (Serviceable):

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable): Yes

Engine Modification: Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size: 175/65 R14 175/65 R14

Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm Front Right Side: Rear Right Side: Yokohama 7 mm Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		461.28	461.28	0.00	0.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		900.00	720.00	180.00	20.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	1,361.28	1,181.28	180.00	13.22
	Approved Total (Overridden) (S\$)		950.00		

Nett Amount (S\$) 1,456.57	1,016.50	440.07	30.21
+ GST 7.00/7.00% (S\$) 95.29	66.50	28.79	30.21
(S\$) 1,361.28	950.00	411.28	30.21

INSPECTION

Date of Assignment: 04/06/2019

Cheng Hoe Motor Pte Ltd (Yishun) Date Inspected: 07/06/2019 Inspected At:

Blk 1019 #01-374/382, Yishun Industrial Park A

Singapore 768761

Estimated Period of Repair: 3.0 days

Adjuster:	KENNETH KONG	Manager:	CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	481.90 FL	*481.90 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Distorted	23.90 FL	*23.90 FL
3	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
4	1		*REAR BOOT INNER LOCK	Dented	49.80 FL	*49.80 FL
F=Fra	anchise	e part. L=ListItemDisc.		Sub Total (S\$)	576.60	576.60
				- List Item Discount on L Items 20.00/20.00% (S\$)	115.32	115.32
				Total Parts (S\$)	461.28	461.28

Report was unsubmitted during this print-out.

7/16/2021 Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No Particulars	Lab.Type	Repairer's	Amount
Labour Items			
1 REMOVE & REFIX REAR BUMPER ASSY ,KNOCK & REPAIR REAR PANEL & REALIGN THE SAME	New	400.00	320.00
2 PUTTY & RESPRAY ON REAR BUMPER ,REAR PANEL	New	500.00	400.00
	Gross Labour Cost (S\$)	900.00	720.00
Report was unsubmitted during this print-ou	ut.		

< END OF ESTIMATES >