

ASS. REC. BY:

REF:

CO/FC119009890/KSD3 12

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person):

Joanne Yong

of

FCI

Date/Time:

04/6/19

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLR 9815A

Insured:

SAB 4187M

at Workshop n/s

LH EXPRESS

Tel:

90089959

of

AMC

Policy No:

Claim No:

019003510 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

26/5/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

1wp

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

SLR 9815A *

SAB 4187M *

06/06/19

@ 15:14 pm revised PA to Joanne Yong via email

13/6

LI By 81900d email & confirm
(\$ 2,345.84 Red - 55%)

ASS. REC. BY:

REF: FCZ/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2-3

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

File pass to

Veh No:

SLQ 9815A

Yr Regn:

07 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Tucson

C.C.

1591

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

30899

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KM HJ3812VJ4536329

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

26/5/19

D.O.A.

4/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 13 JUN 2019

Date/Time, File Pass to?

13/06/19

1) Type

Date/Time, File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

2

Survey Fee

Transportation

) S + R.S. Si

) Fines

) Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

\$ 1,700/- 45

135

50

30+50

19

304



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003510MFSH

Date: 06 June 2019

Our Ref: CS/FCI19009890/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 9815A .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/06/2019 at the premises of M/s LH Express Motor Trading and have the following to report:-

Workshop Estimate Amount	: S\$ 4,245.84
Revised Estimate Amount	: S\$ 1,433.00
"Check" Items Amount	: S\$ 1,803.50
Total	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion .



Comments/ Present Status:

Damages Consistent.
Repair days: 2 - 3 days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	28-05-2019	Our Ref No. D19003510MFSH
Accident Date	26-05-2019	Claim Type. Third Party
Insured Vehicle	SHB4187M	Third Party Vehicle. SLQ9815A
Survey Location	BLK 5038 #01-405 ANG MO KIO INDUSTRIAL PARK 2	
Contact Person.	MELODY	
Contact No.	0/ 90089959	Fax No. 63373700
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

Ln
PSC

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LH EXPRESS MOTOR TRADING	Attention. NIL
Cc : TP Solicitor	CHEONGHOH LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 6 June 2019 3:14 PM
To: 'Joanne Yong Lai fong'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19003510MFSH/1
Attachments: SLQ 9815A - Preli Advise .pdf

Dear Joanne,

Enclosed preliminary revised of vehicle SLQ 9815A.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 4 June 2019 3:09 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <JoanneYong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003510MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 4 June 2019 12:02 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <JoanneYong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003510MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

LH Express Motor Trading

Blk 5038 #01-405, Ang Mo Kio Ind. Park 2

Singapore 569541.

Email: dycolhomtortrading@gmail.com

Tel: 64817221. Fax: 64455393.

Lim Chin Wee

Blk 5038 Ang Mo Kio Industrial Park 2 #01-405

Singapore 569541.

Vehicle No : SLQ 9815 A
Chassis No : KMHJ3812VJU536329
Make : Hyundai Tucson 1.6
Year : 2017

*Not Authorise
Lim B?
Resurvey After Paint
- 3 days*

Lim B 19 Oct

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1	Rear Bumper	<i>CMB</i> \$690.00 <i>2</i>
1	Rear Bumper Reflector LH	<i>SL</i> \$128.00 <i>X</i>
1	Rear Bumper Lower Garnish	<i>Dal Bu</i> \$380.00 <i>✓</i>
1	Rear Bumper Side Retainer LH	<i>SL</i> \$48.00 <i>X</i>
1	Rear End Panel	<i>SL</i> \$530.00 <i>X</i>
1	Rear Taillamp Assy LH	<i>SL</i> \$326.60 <i>X</i>
1	Rear Bumper Reinforcement	<i>CMB</i> \$425.00 <i>2</i>
1 set	Rear Bumper Clips	<i>SL</i> \$40.00 <i>✓</i>
		<i>20%</i> \$2,567.60
		Less 10% \$256.76
		\$2,310.84

Labour Charges

To remove and replaced damaged parts including straightening repositioning replacement parts.

\$800.00 *30d*

Supply Paint Material and necessary items. To respray replaced and other affected panels

\$600.00 *45d*

Reconnect wiring at the damage section and check for proper functions.

\$75.00 *20d*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

To carry out antirust treatment on affected panels.

22 \$80.00 X

To installed reverse censor.

\$60.00 ✓

Special Neet Item

2pcs Rear Reverse

Seash

\$160.00

Seash \$320.00

✓
24

Grand Total :

\$4,245.84



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19009890/Ksd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 17-06-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4187M	Veh. Inspected	SLQ 9815A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003510MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	04/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI TUCSON (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHJ3812VJU536329	Colour	METALLIC GREY	
Odometer	30899	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	BRIDGESTONE	9 mm	
L/H Front Tyre	235/55 R18	BRIDGESTONE	9 mm	
R/H Rear Tyre	235/55 R18	BRIDGESTONE	9 mm	
L/H Rear Tyre	235/55 R18	BRIDGESTONE	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/05/2019	Inspection Date	04/06/2019	
Survey held at	LH EXPRESS MOTOR TRADING BLK 5038 ANG MO KIO AVE 3 #01-405 ANG MO KIO IND. PARK 2 SINGAPORE 569541			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 9815A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CRACKED	690.00	690.00
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	128.00	-
1	REAR BUMPER LOWER GARNISH	DENTED / BUCKLED	380.00	380.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	48.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	530.00	-
1	REAR TAILLAMP ASSY LH	SERVICEABLE	326.60	-
1	REAR BUMPER REINFORCEMENT	CRACKED	425.00	425.00
1	SET REAR BUMPER CLIPS	NECESSARY	40.00	40.00
	LESS 10% DISCOUNT		-256.76	-
	LESS 20% DISCOUNT		-	-307.00
			2,310.84	1,228.00
SPECIAL NETT ITEMS				
2	REAR REVERSE SENSOR @\$160.00 (SN)	SCRATCHED	320.00	320.00
			320.00	320.00
LABOUR				
	TO REMOVE AND REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING REPOSITIONING REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	300.00
	SUPPLY PAINT MATERIAL AND NECESSARY ITEMS.TO RESPRAY REPLACED AND OTHER AFFECTED PANELS.		600.00	450.00
	RECONNECT WIRING AT THE DAMAGE SECTION AND CHECK FOR PROPER FUNCTIONS.		75.00	20.00
	TO CARRY OUT ANTIRUST TREATMENT ON AFFECTED PANELS.	NOT NECESSARY	80.00	-
	TO INSTALLED REVERSE SENSOR.		60.00	60.00
			1,615.00	830.00
GRAND TOTAL			4,245.84	2,378.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,900.00

Report Ref No. CS/FCI19009890/Ksd3n2



Report Ref No. CS/FCI19009890/Ksd3n2

A handwritten signature in black ink, consisting of the letters 'KSC' in a stylized, cursive script.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.