

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119009894/EVD3E2

Date: 28/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30965319011

Claimant Vehicle No : SKE9388R

Insured Vehicle No : SKK9761P

Date of Loss: 16/05/2019

Nature of Claim: TP

Claim No: SNM19D202510-CHEONGML

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKE9388R**

Make & Model: HONDA ODYSSEY, 2.4 (A)

Engine No: K24W72041462

Reg. Date: 24/10/2017 (Man. Year: 2017)

Chassis No: JHMRC1890HC204126

Colour: Grey

Odometer: 18764 km

Engine Capacity: 2356 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,624.44	3,560.93	2,063.51	36.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,650.00	8,280.00	4,370.00	34.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,274.44	11,840.93	6,433.51	35.20
+ GST 7.00/7.00% (S\$)	1,279.21	828.87	450.34	35.20
Nett Amount (S\$)	19,553.65	12,669.80	6,883.85	35.20

INSPECTION

Date of Assignment: 07/06/2019

Date Inspected: 06/06/2019 Inspected At:

Kah Motor Co Sdn Bhd (Ubi)
NO. 255 ALEXANDRA ROAD
SINGAPORE 159937

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jun 2019)

Parts: M1-MPV HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKE9388R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL COMPL.FR.DOOR	Dented	850.44 FS	*850.44 FS
2	1		*TAPE SETL.FR.DOOR SASH INNER	Necessary	36.48 FS	*36.48 FS
3	1		*TAPE SETL.RR.DOOR SASH INNER	Necessary	54.24 FS	*54.24 FS
4	1		*GLASSL.QUARTAR	Not Necessary	429.11 FS	*- FS
5	2		*RUBBERRR QTR W/SHIELD	Not Necessary	18.43 FS	*- FS
6	1		*SEALL.QUARTER GLASS	Not Necessary	33.34 FS	*- FS
7	1		*CLIP AQTR.	Not Necessary	2.85 FS	*- FS
8	1		*CLIPQUARTER WINDSHIELD A	Not Necessary	3.61 FS	*- FS
9	1		*CLIPL	Not Necessary	3.61 FS	*- FS
10	1		*WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS
11	1		*PANEL SET,L.RR.OUTER	Dented	944.20 FS	*944.20 FS
12	1		*GARNISH ASSYL.SLIDE DOOR LWR	Crushed	258.49 FS	*258.49 FS
13	1		*GARNISH ASSYL.WHEEL ARCH (REAR)	Crushed	34.20 FS	*34.20 FS
14	1		*DISK ALUMINIUM WHEEL 17X7J	Not Necessary	869.25 FS	*- FS
15	1		*FACERR.BUMPER	Not Necessary	539.88 FS	*- FS
16	7		*CLIP, BUMPER	Not Necessary	15.29 FS	*- FS
17	1		*SPACERL.RR.BUMPER SIDE	Not Necessary	18.14 FS	*- FS
18	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
19	1		*PANEL COMPL.SLIDE DOOR	Dented	950.47 FS	*950.47 FS
20	1		*MOLDINGL.SLIDE DOOR RETAINER	Crushed	91.77 FS	*91.77 FS
21	1		*TAPE,L.FR.DOOR SASH UPPER	Necessary	35.43 FS	*35.43 FS
22	1		*GARNISH ASSYL.FR.DOOR LOWER	Crushed	275.21 FS	*275.21 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **5,624.44** **3,560.93**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER	New	180.00	180.00
2	BODY JOINT SEALANT	New	80.00	80.00
3	BODY UNDERSIDE COATING	New	350.00	350.00
4	APPLY BODY UNDERSIDE COATING	New	450.00	350.00
5	REMOVE & INSTALL REVERSE SENSORS - 4PCS	New	180.00	0.00
6	REMOVE & INSTALL RR.L QTR GLASS	New	380.00	0.00
7	RESET VEHICLE SMART ENTRY SYSTEM	New	560.00	480.00
8	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	560.00	560.00
9	REMOVE & TRANSFER ITEMS TO NEW RR L SLIDING DR	New	560.00	560.00
10	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST	New	560.00	560.00
11	CUT & RENEW RR L FENDER. KNOCK FRL DR, REPL RR BUM	New	5,000.00	2,800.00
12	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (5P)	New	3,000.00	1,800.00
13	REMOVE AND RENEW WHEEL	New	50.00	0.00
14	TO PERFORM FR MULTI SENSING CAMERA AIMING	New	560.00	560.00
15	WHEEL ALIGNMENT X4	New	180.00	0.00
Gross Labour Cost (S\$)			12,650.00	8,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >