

22/03/2011

ASS. REC. BY:

REF:

OS/FCI/9009974/Ked3⁷²

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Henry Kao

of

FCI

Date/Time: 2:37pm @ 6/6/19

Estimated Cost:

Bill to:

OD - TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 59654 SHC 56954

Insured:

SHA 0867R

at Workshop m/s

Thurs - Ceib

Tel:

62876666

of

No. 2 Amc. 84-63

Policy No:

Claim No:

D19003663 MPSTH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

(Client's Record)

02/06/2019

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

2:49pm @ 6/6/19

Person Contacted:

Candy

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SHC 56954 - X	
	SHA 0867R - CG3 / AIG / 8W4627 / Klub 342	JA. 7/3/2018
07/06/19	@ 16:58 pm	revised PA to Henry via email.

ASS. REC. BY:

REF:

1021

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Soon:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

File pass to

117 612 @ 0350h to 1min-1

(S 51, 916-87 Red - 89%)

RECEIVED 03 JUL 2019

Veh No:

96
SHC 5834

Yr Regn:

08, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

584386

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 282210

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Inorder / Jammed / Leaked / Burnt or

Brake:

Inorder / Jammed / Leaked / Burnt or

Mod:

M/S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

R/Bal.

3

mm

Rear

R/Bal.

2

mm

L/Bal.

3

mm

L/Bal.

8

mm

D.O.A.

3/6/19

D.O.I.

6/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S 1st & 2nd

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

03/07/19



Prel. Report

1)

Type



Final Report

Date/Time, File Return to?

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation

S - RS - SI

F - RS

Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$ 6,350/- Hs

350



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003663M1331

Date: 07 June 2019

Our Ref: CS/FCI1900997337813

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5965Y

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/06/2019 at the premises of M/s Trans-Cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>58,266.87</u>
Revised Estimate Amount	: S\$ <u>19,619.51</u>
"Check" Items Amount	: S\$ <u>5,098.87</u>
Total	: S\$ _____
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damages

The vehicle sustained damages
at the o/s front portion & rear carriage
affected due to collision



Comments/ Present Status

Damages Consistent.
Repair days: 3 days

Yours faithfully,
Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	04-06-2019	Our Ref No. D19003663MFSH
Accident Date	03-06-2019	Claim Type. Third Party
Insured Vehicle	SHA0867R	Third Party Vehicle. SHC5695Y
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Wednesday, 3 July 2019 11:56 AM
To: 'Shirley Hiew (LKK Auto)'
Subject: FW: TCS REF: AAD1906-019--Accident involving SHC 5965Y & SHA 0867R on 03/06/2019
Attachments: ESTIMATE MARKED.pdf

Hi Shirley

We confirmed COR amount \$ 6,350 (b4 GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Monday, 1 July, 2019 4:04 PM
To: 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>
Subject: FW: TCS REF: AAD1906-019--Accident involving SHC 5965Y & SHA 0867R on 03/06/2019

RE-SEND

Dear Wai Yin,

Please confirm final fig \$ 6,350.00 (lump sum) @ 3 days of repairs before GST.

Thank you,
Best Regards,
Shirley Hiew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 7 June 2019 4:58 PM
To: 'Henry Kao Cai Jie'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19003663MFSH/1
Attachments: SHC 5965Y - Preli Advise .pdf

Dear Henry,

Enclosed preliminary revised of vehicle SHC 5965Y.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(689933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 6 June 2019 2:59 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003663MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(689933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 6 June 2019 2:37 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003663MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHC5965Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Jun 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002829
Chassis No.:	VF1ABL15AUC282210
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	03 Aug 2015
First Registration Date:	03 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Aug 2023
PARF Rebate Amount:	\$14,998.00

Intended COE Rebate Details

COE Expiry Date:	02 Aug 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,236.00
COE Rebate Amount:	\$26,147.00
Total Rebate Amount:	\$41,145.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Jun 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHC 5965Y**AAD1906-019***Not Notified
L1 Smg & 63504*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHC 5965Y

VF1ABL15AUC282210

RENAULT

LATITUDE

3.6.19

FIRST CAPITAL

3/8/2015

PART		LIST	
1	BUMPER COVER FRT	\$	1,259.42
1	BUMPER SPOILER FRT	\$	181.75
1	BUMPER ABSORBER FRT	\$	394.68
1	BUMPER RETAINER FRT RH	\$	151.41
1	BUMPER SUPPORT FRT	\$	123.88
1	BUMPER UNDERTRAY FRT	\$	472.83
1	BUMPER GRILLE LOWER FRT	\$	266.80
1	BUMPER FOG LAMP GRILLE RH	\$	207.21
1	BUMPER BEAM FRT	\$	914.08
1	HEADLAMP RH	\$	1,184.43
1	HEADLAMP PANEL FRT RH	\$	152.15
1	FENDER PANEL FRT RH	\$	783.83
1	WHEELARCH FRT RH	\$	278.84
1	FENDER BRACKET LOWER RH	\$	15.79
1	FENDER INSULATOR RH	\$	130.84
1	TOW COVER FRT	\$	28.61
1	FRONT BRACE PANEL	\$	177.22
1	RADIATOR GRILLE	\$	1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	225.36
1	RADIATOR GRILLE FRAME	\$	1,353.75
1	FRAME FULL SUPPORT PANEL	\$	615.90
1	FRAME FULL SUPPORT BRACKET	\$	89.79
1	BONNET	\$	1,941.63
1	BONNET INSULATOR	\$	405.73
1	BONNET STRUT LH	\$	88.61
1	BONNET STRUT RH	\$	88.61
1	BONNET HINGE LH	\$	348.31
1	BONNET HINGE RH	\$	348.31
1	BONNET LOCK	\$	305.48
1	BONNET CABLE	\$	119.19

Trans-cab Auto Services Pte Ltd**AAD1906-019**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5965Y

1	BONNET CABLE COVER	\$	Su	161.03	✓
1	BONNET SEAL OUTER	\$	Su	92.36	✓
1	BONNET SEAL INNER	\$	Su	157.28	X
1	DOOR PANEL FRT RH	\$	M	2,844.66	—
1	DOOR HINGE UPPER RH	\$	D.I	261.28	—
1	DOOR HINGE LOWER RH	\$	D.I	300.55	—
1	DOOR CHECK FRT RH	\$	Su	194.77	X
1	DOOR LOCK FRT RH	\$	N	908.75	
1	DOOR CATCH FRT RH	\$	N	131.23	
1	DOOR HANDLE OUTER FRT RH	\$	Su	477.76	
1	DOOR HANDLE COVER FRT RH	\$	Su	13.22	
1	DOOR HANDLE MODULE FRT RH	\$	Su	133.60	
1	DOOR REGULATOR FRT RH	\$	N	505.19	
1	DOOR REGULATOR MOTOR FRT RH	\$	Su	796.46	
1	DOOR REGULATOR GUIDE FRT RH	\$	Su	120.97	
1	DOOR MOULDING FRONT RH	\$	Su	176.82	
1	DOOR FINISHER INNER FRONT RH	\$	Su	323.44	
1	DOOR FINISHER FRONT RH	\$	Su	423.10	
1	DOOR CASING FRONT RH	\$	Su	1,509.06	
1	DOOR GRAB HANDLE FRONT RH	\$	Su	210.96	
1	DOOR BLIND FRONT RH	\$	Su	741.80	
1	DOOR WHEATHESTRIIP FRONT RH	\$	Su	410.66	
1	DOOR SEAL FRONT RH	\$	Su	162.02	
1	DOOR GLASS RUNNER SEAL FRONT RH	\$	Su	229.31	
1	DOOR WAIST SEAL OUTER FRONT RH	\$	Su	334.69	
1	DOOR WAIST SEAL INNER FRONT RH	\$	Su	115.64	
1	DOOR MIRROR ASSY RH	\$	Su	1,483.40	✓
1	DOOR MIRROR GLASS RH	\$	Su	148.20	
1	DOOR MIRROR BACK COVER RH	\$	Su	218.46	✓
1	LOWER ARM RH L70Y	\$	D.I	685.76	
1	KNUCKLE ARM RH L70Y	\$	R	846.98	
1	ABSORBER FRT RH L70Y	\$	R	360.54	—
1	DRIVESHAFT RH	\$	N	1,747.45	X
1	STABILIZER BAR FRT	\$	Su	604.65	<
2	STABILIZER LINK FRT	\$	Su	117.22	X
1	ROCKER PANEL INNER GARNISH RH	\$	Su	466.51	X
1	ROCKER PANEL INNER RH	\$	N	1,024.79	<
1	ROCKER PANEL OUTER RH	\$	N	1,184.99	X

Trans-cab Auto Services Pte Ltd

AAD1906-019

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5965Y

1	ROCKER PANEL CENTER RH	\$	<i>7</i>	990.25	X
1	WIPER RESERVOIR MOTOR	\$	<i>5</i>	270.06	X
1	WIPER RESERVOIR	\$	<i>5</i>	348.25	X
1	WIPER RESERVOIR NECK	\$	<i>5</i>	136.11	X
1	DOOR HARNESS WIRE RH	\$	<i>5</i>	2,670.00	X
1	STEERING PINION RACK L70Y	\$	<i>7</i>	4,413.11	X
TOTAL		\$		43,815.55	
10%		\$		4,381.55	
		\$		39,433.99	

Special Nett

1	FRONT DOOR STICKER 'Trans-cab'	\$	<i>7</i>	80.00	<i>6000</i>
1	FRONT DOOR STICKER 'Classic'	\$	<i>7</i>	80.00	<i>1500</i>
1	BUMPER CLIP FRT	\$	<i>7</i>	66.00	X
1	BUMPER BRACKET CLIP FRT RH	\$	<i>7</i>	12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>7</i>	10.50	X
1	BUMPER GRILLE LOWER CLIP	\$	<i>7</i>	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>7</i>	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>7</i>	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>7</i>	30.00	X
1	WHEELARCH CLIP FRT RH	\$	<i>7</i>	30.50	X
1	FRONT RIGHT TYRE	\$	<i>7</i>	300.00	<i>3000</i>
1	FRONT RIGHT TYRE RIM	\$	<i>7</i>	380.00	X
1SET	Front licence plate with holder	\$	<i>5</i>	80.00	X
1SET	RADIATOR GRILLE SCREW	\$	<i>5</i>	16.00	
1SET	RADIATOR GRILLE FRAME CLIP	\$	<i>7</i>	52.00	
1	WINDSCREEN SEALANT	\$	<i>7</i>	253.80	
1	FRONT WINDSCREEN MOULDING	\$	<i>7</i>	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>7</i>	100.00	
6	BONNET INSULATOR CLIP L70Y	\$	<i>7</i>	7.30	
2	BONNET STRUT L70Y	\$	<i>7</i>	88.61	
2	BONNET CABLE CLIP L70Y	\$	<i>7</i>	6.31	X
2	BONNET CABLE COVER SCREW L70Y	\$	<i>7</i>	10.85	
TOTAL		\$		1,882.88	

TOTAL PARTS \$ 41,316.87**LABOUR**

Trans-cab Auto Services Pte Ltd**AAD1906-019**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5965Y

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	5001
Putty and spray painting of the affected portion.	\$	6,000.00	6601
To rust-proofing of the affected areas.	\$	170.00	601
To transfer of front windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	601
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	2201
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	601
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X

Trans-cab Auto Services Pte Ltd**AAD1906-019**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5965Y

To apply paint protection system (PPS) maintain and enhancement	\$	nn	380.00	X
Towing Fees	\$		150.00	501
To check ABS and brake efficiency, final checking and testing.	\$	nn	380.00	X
To remove and refit air bag system and reset vehicle warning indicators.	\$	nn	480.00	X
TOTAL	\$		16,950.00	
Over All Total	\$		58,266.87	

LUMP SUM (REPAIR DAY)~~20~~ DAYS

3 day,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal resolicitation(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19009974/Ksd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-07-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 867R	Veh. Inspected	SHC 5965Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003663MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	06/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VF1ABL15AUC282210	Colour	METALLIC WHITE / RED	
Odometer	584384	Steering	JAMMED	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	3 mm	
L/H Front Tyre	215/60 R16	GITI	3 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/06/2019	Inspection Date	06/06/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5965Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER FRT	SERVICEABLE	1,259.42	-
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	HEADLAMP RH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT RH	BENT	783.83	783.83
1	WHEELARCH FRT RH	CRACKED	278.84	278.84
1	FENDER BRACKET LOWER RH	SERVICEABLE	15.79	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE "RENAULT"	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	TO REPAIR SEE LABOUR	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	DOOR PANEL FRT RH	BENT	2,844.66	2,844.66
1	DOOR HINGE UPPER RH	DISTORTED	261.28	261.28
1	DOOR HINGE LOWER RH	DISTORTED	300.55	300.55
1	DOOR CHECK FRT RH	SERVICEABLE	194.77	-
1	DOOR LOCK FRT RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT RH	TO REPAIR SEE LABOUR	131.23	-
1	DOOR HANDLE OUTER FRT RH	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT RH	TO REPAIR SEE LABOUR	505.19	-
1	DOOR REGULATOR MOTOR FRT RH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT RH	SERVICEABLE	120.97	-
1	DOOR MOULDING FRONT RH	SERVICEABLE	176.82	-
1	DOOR FINISHER INNER FRONT RH	SERVICEABLE	323.44	-
1	DOOR FINISHER FRONT RH	SERVICEABLE	423.10	-
1	DOOR CASING FRONT RH	SERVICEABLE	1,509.06	-
1	DOOR GRAB HANDLE FRONT RH	SERVICEABLE	210.96	-
1	DOOR BLIND FRONT RH	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP FRONT RH	SERVICEABLE	410.66	-
1	DOOR SEAL FRONT RH	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL FRONT RH	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER FRONT RH	SERVICEABLE	334.69	-

Report Ref No. CS/FCI19009974/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR WAIST SEAL INNER FRONT RH	SERVICEABLE	115.64	-
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
1	DOOR MIRROR GLASS RH	SERVICEABLE	148.20	-
1	DOOR MIRROR BACK COVER RH	SERVICEABLE	218.46	-
1	LOWER ARM RH L70Y	DISTORTED	685.76	685.76
1	KNUCKLE ARM RH L70Y	BENT	846.98	846.98
1	ABSORBER FRT RH L70Y	BENT	360.54	360.54
1	DRIVESHAFT RH	TO REPAIR SEE LABOUR	1,747.45	-
1	STABILIZER BAR FRT	SERVICEABLE	604.65	-
2	STABILIZER LINK FRT	SERVICEABLE	117.22	-
1	ROCKER PANEL INNER GARNISH RH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER RH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	1,184.99	-
1	ROCKER PANEL CENTER RH	TO REPAIR SEE LABOUR	990.25	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	270.06	-
1	WIPER RESERVOIR	SERVICEABLE	348.25	-
1	WIPER RESERVOIR NECK	SERVICEABLE	136.11	-
1	DOOR HARNESS WIRE RH	SERVICEABLE	2,670.00	-
1	STEERING PINION RACK L70Y	TO REPAIR SEE LABOUR	4,413.11	-
	LESS 10% DISCOUNT		-4,381.56	-636.24
			39,434.00	5,726.20
	SPECIAL NETT ITEMS			
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER "CLASSIC" (SN)	NECESSARY	80.00	15.00
1	BUMPER CLIP FRT (SN)	NOT NECESSARY	66.00	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-

Report Ref No. CS/FC119009974/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WHEELARCH CLIP FRT RH (SN)	NECESSARY	30.50	30.50
1	FRONT RIGHT TYRE (30%)(SN)	PUNCTURE	300.00	90.00
1	FRONT RIGHT TYRE RIM (SN)	BENT	380.00	380.00
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	SET RADIATOR GRILLE SCREW (SN)	SERVICEABLE	16.00	-
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	253.80	-
1	FRONT WINDSCREEN MOULDING (SN)	NOT NECESSARY	120.00	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
6	BONNET INSULATOR CLIP L70Y (SN)	NOT NECESSARY	7.30	-
2	BONNET STRUT L70Y (SN)	NOT NECESSARY	88.61	-
2	BONNET CABLE CLIP L70Y (SN)	NOT NECESSARY	6.31	-
2	BONNET CABLE COVER SCREW L70Y (SN)	NOT NECESSARY	10.85	-
			1,882.87	575.50
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,HEADLAMP PANEL FRT RH,FRONT BRACE PANEL,FRAME FULL SUPPORT PANEL,FRAME FULL SUPPORT BRACKET,BONNET,BONNET HINGE LH,BONNET HINGE RH,BONNET LOCK,DOOR LOCK FRT RH,DOOR CATCH FRT RH,DOOR REGULATOR FRT RH,DRIVESHAFT RH,ROCKER PANEL INNER RH,ROCKER PANEL OUTER RH,ROCKER PANEL CENTER RH AND STEERING PINION RACK L70Y.		6,000.00	500.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	660.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-

Report Ref No. CS/FCI19009974/Ksd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.		380.00	220.00
	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.		170.00	20.00
	TO TRANSFER OF BONNET FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TOWING FEES.		150.00	50.00
	TO CHECK ABS AND BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET VEHICLE WARNING INDICATORS.	NOT NECESSARY	480.00	-
			16,950.00	1,650.00
	GRAND TOTAL		58,266.87	7,951.70
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,350.00

Report Ref No. CS/FCI19009974/Ksd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.