

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19009983/KKS3N2

**Date:** 20/07/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant**

**Vehicle No :** SKW7836H

**Insured Vehicle No :** SJV2388J

Date of Loss: 01/06/2019

Nature of Claim: TP

Claim No: 0428516554SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW7836H**

Make & Model: HONDA VEZEL, 1.5 (A)

Engine No: HIDDEN

Reg. Date: 01/11/2015 (Man. Year: 2015)

Chassis No: RU11105442

Colour: Metallic Pearl White

Odometer: 118775 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,178.64	4,133.68	5,044.96	54.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	1,580.00	1,070.00	40.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,828.64</b>	<b>5,713.68</b>	<b>6,114.96</b>	<b>51.70</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,550.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,828.64</b>	<b>4,550.00</b>	<b>7,278.64</b>	<b>61.53</b>
<b>+ Car Rental (10.0 x S\$120.00/day + 7.00% GST) (S\$)</b>		1,284.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>5,836.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,800.00</b>		

### INSPECTION

Date of Assignment: 04/06/2019

Date Inspected: 04/06/2019 Inspected At:

Autoworx House - Sin Ming (HQ)  
176 SIN MING DRIVE #02-01  
Singapore 575721

Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	1,264.90 FL	*1,100.90 FL
2	1		*REAR BOOT LOCK	Distorted	316.20 FL	*198.50 FL
3	1		*REAR BOOT OUTER GARNISH	Mtg Cracked	564.70 FL	*399.20 FL
4	1		*REAR BOOT INNER TRIM	Serviceable	515.40 FL	*- FL
5	1		*REAR BOOT EMBLEM VEZEL	Necessary	67.50 FL	*67.50 FL
6	1		*REAR BOOT EMBLEM LOGO	Serviceable	62.80 FL	*- FL
7	1		*REAR BOOT LAMP	Mtg Cracked	675.20 FL	*380.60 FL
8	1		*REAR TAIL LAMP	Serviceable	598.70 FL	*- FL
9	1		*REAR BOOT LOCK CATCH	Dented	48.10 FL	*48.10 FL
10	1		*REAR BUMPER	Bent	895.70 FL	*508.50 FL
11	2		*REAR BUMPER SIDE COVER	Serviceable	875.20 FL	*- FL
12	2		*REAR BUMPER SIDE RETAINER	Serviceable	128.80 FL	*- FL
13	1		*REAR WHEEL ARCH PROTECTOR	N/S Buckled	419.40 FL	*245.80 FL
14	1		*REAR BUMPER REFLECTOR	N/S Cracked	633.40 FL	*151.00 FL
15	1		*REAR END INNER PANEL	No such part	577.60 FL	*- FL
16	1		*REAR END OUTER PANEL	Bent	549.70 FL	*491.30 FL
17	1		*REAR END PANEL GARNISH	Dented	473.20 FL	*146.30 FL
18	1		*REMOTE LOCK SENSOR	Cracked	350.80 FL	*180.00 FL
19	1		*REAR BUMPER LOWER DUST COVER	Deformed	315.60 FL	*199.40 FL
20	1		*REMOTE LOCK BUZZER	Serviceable	215.40 FL	*- FL
21	1		*WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
22	1		*SET REAR BUMPER BODY KIT	Broken	1,080.00 FS	*600.00 FS
23	1		*REVERSE SENSOR	Cracked	400.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,088.30</b>	<b>4,957.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,909.66	823.42
<b>Total Parts (\$\$)</b>	<b>9,178.64</b>	<b>4,133.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE ,KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS	New	1,100.00	600.00
2	TO CHECK WIRING SYSTEM	New	60.00	20.00
3	TO APPLY PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	1,100.00	750.00
4	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	150.00	60.00
5	TO APPLY WATER PROOF SEALANT ON AFFECTED AREAS	New	100.00	30.00
6	TO REMOVE REAR WINDSCREEN GLASS TO ENABLE REPAIR	New	140.00	120.00
<b>Gross Labour Cost (S\$)</b>			<b>2,650.00</b>	<b>1,580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >