

TPAIG.

Jasper.

SF? 2382D 2009 Sept.

Hyundai Avante 1591cc

KMHDK41BMAU893127.

	Front Bumper	Deformed	452 ✓
	Front Bumper Clips.	Nec	30 ✓
	Front Bumper Side Holder RH.	Nec	35 ✓
list: 953	Front Bumper Sponge	2	145 +
len 20%: 762.40	Front Bumper Reinforcement.	Nec	274 +
S.N: 400	Front Bumper Fog Lamp RH.	Nec	243 +
Labour: 810.	Headlamp RH	Nec	480 +
Total: 1972.40	Front RH Fender.	Buckled	436. ✓
L/S: 1550	Front RH wheel Rim.	cut	650/sn 400/sn)
04 Days.			

Panel Bending

~~600~~ 300

Spray Painting

~~600~~ 400

~~50~~ 30

Wiring.

To perform wheel alignment.

~~150~~ 80.

LKK Auto Consent to hence notify the Reparer of the following:

- To resurvey before and after painting
- To display and repair parts upon resurvey
- Parts price to be agreed to prior to repair
- Third party insurance to be arranged on a "basis"
- No illegal work to be carried out
- Suppliers to be approved and is subject to final approval by the Insurance Company

Acknowledged by Reparer

Signature:

Date: