

ASS. REC. BY:

REF:

CS/CTI19010056/Usd3n2

Special Instruction:

Summary:

Marcus

ASSIGNMENT (Office)

From (Person):

Chang Sun En

of

CTI

Date/Time: 7/6/19 @ 1:09pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 6543X

Insured:

GP GB 7979M

at Workshop m/s

Liu's Brother

Tel:

67411730

of

1 Kaki Bukit Ave 6 #01-01

Policy No:

DM(VSN)6308718022

Claim No:

SNM19D202456C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

1:47pm @ 7/6/19

Person Contacted:

Sugen

Vehicle IN / OUT

Date/Time	Action/Instruction	Estimate
	GBC 6543X - CS/FCI/7006787/Kr 6302	DOA: 30/3/2017
	GB 7979M - X	

(08/11/13) wef

REF:

ASS. REC. BY: *Marcus*

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *G9C6543*at Workshop m/s *11u's Bro*

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *34k.*

QAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: *2* Consistent? : Yes or NoEst. Repairs: *7* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA 23337

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

G9C6543X Yr Regn: *5, 13*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *(M)*

Make:

*Toyota Hiace*C.C. *2882*

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

141211

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

*JTFHT02P200114819*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *In order* / Jammed / Leaked / Burnt orBrake: *In order* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim or

Tyre Size:

F:

195-215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

A + Stone

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

30/5/19

D.O.I.

4/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*4 yrs**10/6/19 L/S #6050 confirmed with Susan.**(\$ 10,713.70 Red - 64%)*

RECEIVED 11 JUN 2019

Date/Time, File Pass to?

1) *11/06/19*

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final ReportDays Of Repair: *7*

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

) \$ + RS \$

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I. (\$ *6,050/- H/S*)

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified)		07 Jun 2019 13:09 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N
Vehicle Reg. No.:	GBC6543X
Claim Type:	TP
Vehicle Reg. No. (Insured):	GB7979M
	Policy/Cover Note No.:
	Policy No. (Claimant): 19093298MFCV
	Excess: S\$0.00
Repairer:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/06/2019]

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

[> Back to OneMotoring](#)

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 31 May 2019 / 15:42:47

Receipt Date/Time : 31 May 2019 / 15:42:47

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190531-002433

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GP7979M As at 30 May 2019/09:00:00 Insurance Co: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD				
1	Insurance Enquiry - GP7979M Enquiry Fee 20190531154141284532	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx4559	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931. Tel: 6741-1730 / 731. Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBC6543X190530

Estimate**Customer**

Name: China Taiping Insurance (Singapore) Pte Ltd

Address: Motor Claims Department

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Date: 31-05-19

Vehicle No: GBC6543X

Model/Make: Toyota Hiace

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>806/470 1925-10</i>	\$2,050.00	
2	Tailgate Lock <i>DS/SM</i>	\$394.90	
3	Tailgate Rubber <i>twi</i>	\$387.90	
4	Tailgate Lock Striker <i>11</i>	\$20.50	X
5	Tailgate Number Plate Outer Garnish <i>11</i>	\$397.00	X
6	Tailgate Number Plate (Metal Plate) <i>best</i>	\$35.00	SN 15 S.N
7	Tailgate "Toyota Logo" Motif <i>rec</i>	\$70.50	+
8	Tailgate "70 KM/H" Sticker <i>rec</i>	\$15.00	SN 10 S.N
9	Tailgate "8 PAX" Sticker <i>rec</i>	\$15.00	SN 10 S.N
10	Tailgate Inner Lock <i>Repro</i>	\$359.00	X
11	Tailgate Inner Trim Board <i>cne</i>	\$248.20	+
12	Tailgate Inner Trim Board Clips 1 set <i>rec</i>	\$50.00	SN 1 S.N
13	Tail Lamp L 02 pcs (@ \$365.10) <i>n/s cne</i>	\$730.20	1 pc
14	Tail Lamp Panel 02 pcs (@ \$936.20) <i>n/s 10 408-10</i>	\$1,872.40	1 pc
15	Floor Panel <i>Beam top plate best</i>	\$189.00	+
16	Floor Panel Top Wooden Board <i>cne</i>	\$650.00	SN 400 S.N
17	Corner Panel Outer 02 pcs (@ \$165.80) <i>ns</i>	\$331.60	X
18	Corner Panel Inner 02 pcs (@ \$477.50) <i>R</i>	\$955.00	X
19	Corner Panel Garnish 02 pcs (@ \$75.00) <i>n/s De</i>	\$150.00	1 pc
20	Corner Panel Garnish Bracket 02 pcs (@ \$31.50) <i>11</i>	\$63.00	X
21	Bumper <i>DIS</i>	\$599.30	+
22	Bumper Clips 1 set <i>rec</i>	\$48.00	SN 40 S.N
23	Bumper Side Retainer 02 pcs (@ \$65.10) <i>11</i>	\$130.20	X
24	Bumper Side Bracket 04 pcs (@ <i>best</i>)	\$404.00	+
25	Bumper Accessories Garnish <i>cne</i>	\$250.00	SN 150 S.N
26	Bumper Reverse Sensor <i>shot</i>	\$220.00	SN 200 S.N
27	End Panel Inner <i>rec</i>	\$936.20	X
28	End Panel Outer <i>Body D</i>	\$566.10	+
29	End Panel Sealant <i>rec</i>	\$50.00	SN 1 S.N
30	End Panel Top Steel Plate <i>Repro</i>	\$166.50	X
31	Spare Tyre Carrier <i>11</i>	\$345.20	X
32	Tailgate Windscreen Glass Moulding <i>ns</i>	\$219.00	X
33	Tailgate Windscreen Glass Sealant <i>rec</i>	\$50.00	SN 40 S.N
34	"Corporate" Advertisement Sticker <i>rec</i>	\$400.00	SN 100 S.N

C/F Balance --->

\$13,323.70

LKK Auto Consultants hence notify the Repairs of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



M/s Liu's Brother Auto Engrg Wks

P-5633.20

252

P-4224.90

S.N-1065.00

10km-2280.00

7569.90

252

6052

not Attached

4/6/19

6050/2

7dy.

Take photo Harap

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 | Tel: 6741-1730 / 731. Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBC6543X190530

Estimate

Customer

Page 02 - 02

Name: China Taiping Insurance (Singapore) Pte Ltd

Date: 31-05-19

Address: Motor Claims Department

Vehicle No: GBC6543X

3 Anson Road #16-00

Model/Make: Toyota Hiace

Springleaf Tower Singapore 079909

Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance --->	\$ 13,323.70	
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	60
	Remove and refix rear reverse sensor	\$ 100.00	50
	To check all wiring & electrical component for proper function	\$ 80.00	30
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts E	\$ 1,500.00	1000
	To putty & spray painting & including touch up paint on accident area	\$ 1,400.00	900
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	✓
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 120.00	100
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	60

Total Parts & Labour of estimate for damaged vehicle

\$ 16,763.70

2280

Total amount in Lump Sum Basis for repaired vehicle

SDLS: _____



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19010056/USD3N2

Date: 17/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN16308718022	
Claimant Vehicle No :	GBC6543X	Insured Vehicle No :	GP7979M	
Date of Loss:	30/05/2019	Nature of Claim:	TP	Claim No: SNM19D202456C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC6543X	Engine No:	1KD2292225
Make & Model:	TOYOTA HIACE, 2.0 (M)	Chassis No:	JTFHT02P200114819
Reg. Date:	28/05/2013 (Man. Year: 2013)	Odometer:	141211 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Austone 6 mm	Rear Left Side:	Austone 6 mm
Front Right Side:	Austone 6 mm	Rear Right Side:	Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	13,323.70	5,289.90	8,033.80	60.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,440.00	2,280.00	1,160.00	33.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,763.70	7,569.90	9,193.80	54.84
Approved Total (Overridden) (S\$)		6,050.00		
Nett Amount (S\$)	16,763.70	6,050.00	10,713.70	63.91

INSPECTION

Date of Assignment:	07/06/2019
Date Inspected:	04/06/2019 Inspected At:

Liu's Brother Auto Engineering
Workshop (HQ)
BLK 1 KAKI BUKIT AVE 6, #01-01
AUTO BAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Jun 2019)
Parts:	N/A TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC6543X)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	2,050.00 F	*1,925.10 FL
2	1		*REAR TAILGATE LOCK	Dented/Jammed	394.90 F	*394.90 FL
3	1		*REAR TAILGATE RUBBER	Twisted	387.90 F	*387.90 FL
4	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	20.50 F	*- FL
5	1		*REAR TAILGATE NUMBER PLATE OUTER GARNISH	Not Necessary	397.00 F	*- FL
6	1		*REAR TAILGATE TOYOTA LOGO MOTIF	Necessary	70.50 F	*70.50 FL
7	1		*REAR TAILGATE INNER LOCK	Repeated	359.00 F	*- FL
8	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	248.20 F	*248.20 FL
9	1		*REAR TAIL LAMP L	N/s Cracked	730.20 F	*365.10 FL
10	1		*REAR TAIL LAMP PANEL	N/s Dented	1,827.40 F	*408.10 FL
11	1		*REAR FLOOR PANEL TOP PLATE	Bent	189.00 F	*189.00 FL
12	2		*REAR CORNER PANEL OUTER	No such part	331.60 F	*- FL
13	2		*REAR CORNER PANEL INNER	Repair	955.00 F	*- FL
14	1		*REAR CORNER PANEL GARNISH	N/s Deformed	150.00 F	*75.00 FL
15	2		*REAR CORNER PANEL GARNISH BRACKET	Not Necessary	63.00 F	*- FL
16	1		*REAR BUMPER	Distorted	599.30 F	*599.30 FL
17	2		*REAR BUMPER SIDE RETAINER	Not Necessary	130.20 F	*- FL
18	4		*REAR BUMPER SIDE BRACKET	Bent	404.00 F	*404.00 FL
19	1		*REAR END PANEL INNER	Repair	936.20 F	*- FL
20	1		*REAR END PANEL OUTER	Badly Dented	566.10 F	*566.10 FL
21	1		*REAR END PANEL TOP STEEL PLATE	Repeated	166.50 F	*- FL
22	1		*REAR SPARE TYRE CARRIER	Not Necessary	345.20 F	*- FL
23	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	No such part	219.00 F	*- FL
24	1		*REAR TAILGATE NUMBER PLATE (METAL PLATE)	Bent	35.00 FS	*15.00 FS
25	1		*REAR TAILGATE 70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
26	1		*REAR TAILGATE 8 PAX STICKER	Necessary	15.00 FS	*10.00 FS
27	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*50.00 FS
28	1		*REAR FLOOR PANEL TOP WOODEN BOARD	Cracked	650.00 FS	*400.00 FS
29	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*40.00 FS
30	1		*REAR BUMPER ACCESSORIES GARNISH	Cracked	250.00 FS	*150.00 FS
31	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
32	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
33	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
34	1		*REAR CORPORATE ADVERTISEMENT STICKER	Necessary	400.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 13,323.70 6,698.20
 - List Item Discount on L Items 0.00/25.00% (S\$) 0.00 1,408.30

Total Parts (S\$) 13,323.70 5,289.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM	New	80.00	60.00
2	REMOVE AND REFIX REAR REVERSE SENSOR	New	100.00	50.00
3	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	30.00
4	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETC	New	1,500.00	1,000.00
5	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AREA	New	1,400.00	900.00
6	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	80.00
7	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS	New	120.00	100.00
8	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	60.00
Gross Labour Cost (S\$)			3,440.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >