

HONG AUTO SERVICES

2 Kaki Bukit Avenue 2, #01-28 Auto Hub @ Kaki Bukit Singapore 417921

PACIFIC REEF
2 KAKI BUKIT AVE 2
01-28
Singapore 417921

TPAXA
Cecilia.

07th JUNE 2019

Accident date: 06th JUNE 2019

Estimated repair cost for vehicle no: GBA2209Z TOYOTA HIACE

S/n	Qty	Items	U/price	Amount	
1	1	Front head lamp -LH <i>smashed</i>		\$310.40	✓
2	1	head lamp bracket <i>NEAR</i>		\$92.50	+
3	1	front panel <i>Distorted</i>		\$1,169.90	✓
4	1	Front bumper <i>Distorted</i>		\$634.58	✓
5	2	Front bumper side bracket <i>NE</i>	\$38.20	\$76.40	✓
6	8	Front bumper clips <i>NE</i>	\$12.90	\$103.20	30 ✓
7	1	front bumper center moulding <i>NE</i>		\$188.20	+
8	1	front bumper number plate <i>NE</i>		\$50.00	+
9	2	front bumper bracket <i>NE</i>	\$185.00	\$370.00	+
10	1	Front bumper reinforcement <i>Best</i>		\$380.10	✓
11	1	Front bumper side lamp -LH <i>NE</i>		\$105.20	+
12	1	Front grille <i>Cracked</i>		\$454.25	✓
13	1	front grille logo <i>NE</i>		\$42.10	✓
14	1	Front radiator <i>Distorted</i>		\$1,152.20	✓
15	1	Front radiator water tank <i>NE</i>		\$380.20	+
16	1	Radiator fan motor assy <i>Damaged</i>		\$850.00	✓
17	1	Front air cond condenser <i>NE</i>		\$1,102.20	+
18	1	front water tank <i>Behind</i>		\$280.00	✓
19	1	Front support panel <i>Distorted</i>		\$320.00	✓
20	1	front support garnish <i>NE</i>		\$98.10	+
21	1	Front Wiper Panel (Canter) <i>NE</i>		\$280.20	+
22	1	Front panel wiper arm <i>NE</i>		\$161.40	+
23	1	Front side panel-LH <i>Dented</i>		\$291.40	✓
24	1	Front LH size mirror <i>NE</i>		\$225.20	+
Subtotal :-				\$9,117.73	

5591.33
4493.49

Labour charges

To remove & re-fix front windscreen

\$120.00 X

Gum

\$50.00 X

To Remove & refix radiator , radiator fan motor
air-con blower & top up gas

~~\$250.00~~ 120

To Check Wiring System

~~\$60.00~~ 30

Tuff kote

~~\$100.00~~ 50

Wheel alignment (computer)

1800

\$120.00 X

Panel beating

\$800.00 ✓

Spray painting

\$800.00 ✓

Subtotal :- \$2,300.00

Total:- \$11,417.73

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6293.49
4/s: 5K
OT Days

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Business
Owner ID:	6013C

Vehicle Details

Vehicle No.:	GBA2209Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	06 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	1KD1613121
Chassis No.:	JTFHT02P400003222
Maximum Power Output:	-
Open Market Value:	\$24,590.00
Original Registration Date:	12 Apr 2007
First Registration Date:	12 Apr 2007
Transfer Count:	3
Actual ARF Paid:	\$0.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	11 Apr 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
HQP Paid:	\$24,005.00
COE Rebate Amount:	\$13,922.00
Total Rebate Amount:	\$13,922.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 06 Jun 2019

OK