

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120**Our File No:** CC3/AIG19010083/ASD3E2**Date:** 24/04/2020**REFERENCE**

Insured/Claimant:	ZULAIHA BINTI YUSUF	Policy No:	1800126076
Date of Loss:	05/06/2019	Nature of Claim:	OD Claim No: 3566980924SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF275M		
Make & Model:	AUDI A3, 1.4 TFSI (A)	Engine No:	CZE697739
Reg. Date:	25/10/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V9J1080215
Colour:	White	Odometer:	11841 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$100,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,392.04	13,898.96	13,493.08	49.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,552.00	5,602.00	4,950.00	46.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	37,944.04	19,500.96	18,443.08	48.61
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	37,344.04	18,900.96	18,443.08	49.39
+ GST 7.00/7.00% (\$\$)	2,614.08	1,323.07	1,291.01	49.39
Nett Amount (\$\$)	39,958.12	20,224.03	19,734.09	49.39

INSPECTION

Date of Assignment:	07/06/2019	
Date Inspected:	06/06/2019	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	8.0 days	

Adjuster: ADRIAN LING**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,830.00 FS	*1,464.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - LH	Damaged	35.00 FS	*27.52 FS
4	1		*FRONT BUMPER GRILLE - CENTER	Cracked	146.00 FS	*116.40 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	488.00 FS	*390.00 FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LH / RH	N/S Deformed	540.00 FS	*216.00 FS
7	1		*FRONT BUMPER COVER TRIM - LH / RH	N/S Deformed	296.00 FS	*118.40 FS
8	2		*FRONT BUMPER ADAPTER - LH / RH	Not Necessary	68.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,304.00 FS	*1,040.80 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	174.00 FS	*138.80 FS
11	1		*FRONT AIR GRILLE - LH / RH	N/S Damaged	342.00 FS	*136.40 FS
12	1		*FRONT CARRIER	Bent	660.00 FS	*527.60 FS
13	1		*FOAM FILLER PIECE	Deformed	172.00 FS	*137.60 FS
14	1		*FRONT CARRIER COVER	Deformed	111.00 FS	*88.80 FS
15	1		*A/C STICKER	Necessary	7.00 FS	*5.12 FS
16	1		*CAUTION STICKER	Necessary	13.00 FS	*9.76 FS
17	1		*BONNET	Dented	2,898.00 FS	*2,318.40 FS
18	1		*BONNET ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
19	2		*BONNET HINGE - LH / RH	Not Necessary	112.00 FS	*- FS
20	1		*BONNET ABSORBER	Not Necessary	109.00 FS	*- FS
21	1		*BONNET CATCH - TOP	Damaged	81.00 FS	*64.72 FS
22	2		*BONNET STRIKER	Bent	200.00 FS	*159.04 FS
23	1		*BONNET EDGE PROTECTION	Necessary	25.00 FS	*19.92 FS
24	1		*BONNET CATCH - BOTTOM	Bent	58.00 FS	*45.76 FS
25	2		*BONNET LOCK	Not Necessary	367.00 FS	*- FS
26	1		*BONNET BOWDEN CABLE	Not Necessary	53.00 FS	*- FS
27	1		*BONNET BOWDEN CABLE COVER	Not Necessary	9.00 FS	*- FS
28	1		*BONNET LOCK CABLE	Not Necessary	67.00 FS	*- FS
29	1		*FRONT FENDER - LH	Not Necessary	778.00 FS	*- FS
30	1		*FRONT FENDER RIVET	Not Necessary	15.00 FS	*- FS
31	1		*FRONT FENDER ATTACHMENT PARTS - LH	Not Necessary	65.00 FS	*- FS
32	2		*FRONT FENDER BRACKET	Not Necessary	60.00 FS	*- FS
33	1		*FRONT FENDER BRACE - LH	Not Necessary	88.00 FS	*- FS
34	1		*FRONT WHEEL HOUSING LINER SEAL - LH	Not Necessary	31.00 FS	*- FS
35	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	158.00 FS	*- FS
36	1		*HEADLIGHT - LH / RH	N/S Cracked	10,058.00 FS	*4,023.20 FS
37	1		*LIFT CYLINDER HOSE	Not Necessary	61.00 FS	*- FS
38	1		*LIFT CYLINDER - LH	Not Necessary	128.00 FS	*- FS
39	1		*LIFT CYLINDER - RH	Not Necessary	128.00 FS	*- FS
40	1		*HORN - LOW / HIGH TONE	Not Necessary	364.00 FS	*- FS
41	1		*LOCK CARRIER	Deformed	663.00 FS	*530.40 FS
42	1		*A/C CONDENSER	Bent	503.00 FS	*402.00 FS
43	1		*RADIATOR	Bent	878.00 FS	*702.40 FS
44	1		*COOLANT	Necessary	84.00 FS	*67.20 FS
45	1		*FAN RING	Not Necessary	181.00 FS	*- FS
46	1		*RADIATOR FAN WITH FAN RING	Not Necessary	1,046.00 FS	*- FS
47	2		*RADIATOR AIR GUIDE - LH / RH	Deformed	44.00 FS	*34.24 FS
48	1		*RADIATOR SEAL - RIGHT OUTER	Necessary	8.00 FS	*5.68 FS
49	1		*RADIATOR AIR GUIDE - CENTRE	Deformed	11.00 FS	*8.32 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*FRONT NO. PLATE	Bent	40.00 FS	*40.00 FS
51	1		*SUNDRIES	Necessary	300.00 FS	*11.84 FS
52	1		*FRONT BUMPER GUIDE SECTION RHS	Cracked	27.52 FS	*27.52 FS
53	1		*BONNET LID LOCK WITH MICRO SWITCH	Bent	293.60 FS	*293.60 FS
54	1		*FRONT BUMPER BRACKET	Bent	13.04 FS	*13.04 FS
55	1		*RADIATOR BUSH	Necessary	14.24 FS	*14.24 FS
56	1		*RADIATOR BRACKET	Damaged	30.64 FS	*30.64 FS
57	1		*ADDITIONAL COOLER	Bent	837.00 FS	*669.60 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					27,392.04	13,898.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,200.00	1,200.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND BOTH HEADLIGHTS. REMOVE AND RENEW LOCK CARRIER AND ALIGN CONSOLE TO POSITION. REINSTALL ALL PARTS REMOVED	New	5,600.00	2,750.00
4	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND HINGES	New	3,200.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			10,552.00	5,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >