

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19010211/GCD3E2

Date: 14/08/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SGW856T

**Insured Vehicle No :** SMK806E

Date of Loss: 31/05/2019

Nature of Claim: TP

Claim No: 6532377450SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGW856T**

Make &amp; Model: HONDA STREAM, 1.8 (A)

Engine No: R18A1741556

Reg. Date: 04/07/2007 (Man. Year: 2007)

Chassis No: RN61036852

Colour: Black

Odometer: 167683 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/50Z R17

Rear Tyre Size: 215/50Z R17

Front Left Side: Roadstone 6 mm

Rear Left Side: Roadstone 6 mm

Front Right Side: Roadstone 6 mm

Rear Right Side: Roadstone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 10/06/2019

Date Inspected: 10/06/2019 Inspected At:

53 DEFU LANE 12

Repairer : Auto Gear Pte Ltd (HQ)

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER RH	Deformed	0.00 F	*- F
4	1		*FRT BUMPER LOWER SPOILER	Cut	0.00 F	*- F
5	1		*FRT GRILLE	Broken	0.00 F	*- F
6	1		*FRT RH HEADLAMP ASSY	Scratched	0.00 F	*- F
7	1		*FRT RH FENDER INNER SHIELD	Torn	0.00 F	*- F
F=Franchise part.						
<b>Total Parts (S\$)</b>					<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**