

TPA 16. SLB3269U.
 Honda Civic
 Khanchana
 JHMF D16306S208027

Front Number Plate	Bent	30(SN). ✓
Front Number Plate Garnish	Deland	66.80 ✓
Front Bumper	Deland	638 ✓
Front Bumper Clips	new	30 ✓
Front Bumper Side Holder x 02	new	$24.5 \times 2 = 49.$ ✓
Front Bumper Reinforcement	Bent	218.80 ✓
Front Bumper Fog Lamp x 02	RH Cand	$303.8 \times 2 = 607.60$ 303.80
Front Bumper Fog Lamp Cover x 02	RH new	$65.2 \times 2 = 130.40.$ X
Front Grille	Cracked	282.50 ✓
Front Grille Chrome Moulding	at	185.30 ✓
Front Grille Logo	Xec	30.20 ✓
Front Grille Clips	new	15 ✓
Headlamp x 02	RH cancelled	$912.3 \times 2 = 1824.60$ 912.30
Headlamp Lower Bracket x 02	RH Bent	$29.4 \times 2 = 58.80$ 29.40
		2734.4
		2187.52

SLB3269U.

Panel Beating

Spray Painting.

Wiring.

~~500~~ 400

~~500~~ 300

~~50~~ 30

730

total: 2917.52.

H/s: 231K.

04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: