

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19010285/KRA3Q2
Date: 18/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No : SHD480G	Insured Vehicle No :	SLE5315R
Date of Loss: 05/06/2019	Nature of Claim: TP	Claim No: 8653021847SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD480G		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C003292
Reg. Date:	03/07/2017 (Man. Year: 2016)	Chassis No:	VF1ABL15AUC283456
Colour:	Metallic White/Red	Odometer:	202192 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,255.06	3,526.42	16,728.64	82.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,950.00	1,260.00	13,690.00	91.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	35,205.06	4,786.42	30,418.64	86.40
+ GST 7.00/7.00% (\$\$)	2,464.35	335.05	2,129.30	86.40
Nett Amount (\$\$)	37,669.41	5,121.47	32,547.94	86.40
+ Loss of Use (5.0 x S\$50.00/day) (\$\$)		250.00		
+ Car Rental (5.0 x S\$103.41/day) (\$\$)		517.05		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		5,896.01		

INSPECTION

Date of Assignment:	10/06/2019	
Date Inspected:	10/06/2019	Inspected At: Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	4.0 days	

3/18/2021

Adjuster Report

Adjuster: KENNETH KONG

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER PANEL FRT RH	Repair	783.83 FL	*- FL
2	1		*WHEELARCH FRT RH	Serviceable	278.84 FL	*- FL
3	1		*FENDER BRACKET LOWER RH	Repair	15.79 FL	*- FL
4	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
5	1		*FRONT BRACE PANEL	Repair	177.22 FL	*- FL
6	1		*DOOR PANEL FRT RH	Bent	2,844.66 FL	*2,844.66 FL
7	1		*DOOR HINGE UPPER RH	Repair	261.28 FL	*- FL
8	1		*DOOR HINGE LOWER RH	Repair	300.55 FL	*- FL
9	1		*DOOR CHECK FRT RH	Serviceable	194.77 FL	*- FL
10	1		*DOOR LOCK FRT RH	Repair	908.75 FL	*- FL
11	1		*DOOR CATCH FRT RH	Repair	131.23 FL	*- FL
12	1		*DOOR WEATHERSTRIP FRONT RH	Serviceable	410.66 FL	*- FL
13	1		*DOOR MOULDING FRONT RH	Serviceable	176.82 FL	*- FL
14	1		*DOOR FINISHER INNER FRONT RH	Serviceable	323.44 FL	*- FL
15	1		*DOOR FINISHER FRONT RH	Serviceable	423.10 FL	*- FL
16	1		*DOOR HANDLE OUTER FRT RH	Serviceable	477.76 FL	*- FL
17	1		*DOOR HANDLE COVER FRT RH	Serviceable	13.22 FL	*- FL
18	1		*DOOR HANDLE MODULE FRT RH	Serviceable	133.60 FL	*- FL
19	1		*DOOR REGULATOR FRT RH	Serviceable	505.19 FL	*- FL
20	1		*DOOR REGULATOR MOTOR FRT RH	Serviceable	796.46 FL	*- FL
21	1		*DOOR REGULATOR GUIDE FRT RH	Serviceable	120.97 FL	*- FL
22	1		*DOOR CASING FRONT RH	Serviceable	1,509.06 FL	*- FL
23	1		*DOOR GRAB HANDLE FRONT RH	Serviceable	210.96 FL	*- FL
24	1		*DOOR BLIND FRONT RH	Serviceable	741.80 FL	*- FL
25	1		*DOOR SEAL FRONT RH	Serviceable	162.02 FL	*- FL
26	1		*DOOR GLASS RUNNER SEAL FRONT RH	Serviceable	229.31 FL	*- FL
27	1		*DOOR WAIST SEAL OUTER FRONT RH	Serviceable	334.69 FL	*- FL
28	1		*DOOR WAIST SEAL INNER FRONT RH	Serviceable	115.64 FL	*- FL
29	1		*DOOR MIRROR ASSY RH	Serviceable	1,483.40 FL	*- FL
30	1		*DOOR MIRROR GLASS RH	Serviceable	148.20 FL	*- FL
31	1		*DOOR MIRROR BACK COVER RH	Serviceable	218.46 FL	*- FL
32	1		*ROCKER PANEL INNER GARNISH RH	Serviceable	466.51 FL	*- FL
33	1		*ROCKER PANEL INNER RH	Repair	1,024.79 FL	*- FL
34	1		*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
35	1		*ROCKER PANEL CENTER RH	Bent	990.25 FL	*990.25 FL
36	1		*DOOR CHASSIS WIRE RH	Serviceable	2,670.00 FL	*- FL
37	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*15.00 FS
38	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*60.00 FS
39	1		*WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	*- FS
40	1		*FRONT RIGHT TYRE	Serviceable	300.00 FS	*- FS
41	1		*FRONT RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS
42	1		*WINDSCREEN SEALANT	Not Necessary	253.80 FS	*- FS
43	1		*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FS	*- FS
44	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
45	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
46	1		*DOOR GUIDE SCREW	Not Necessary	10.85 FS	*- FS
47	1		*DOOR HINGE BOLT	Not Necessary	10.85 FS	*- FS
48	1		*DOOR HINGE NUT RH	Not Necessary	14.60 FS	*- FS
49	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
50	1		*DOOR CHECK NUT	Not Necessary	3.75 FS	*- FS
51	1		*DOOR LOCK SCREW L70Y	Not Necessary	6.12 FS	*- FS

Report was unsubmitted during this print-out.

3/18/2021

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*DOOR CATCH SCREW L70Y	Not Necessary	10.06 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					22,344.97	3,909.91
- List Item Discount on L Items 10.00/10.00% (\$)					2,089.91	383.49
Total Parts (\$)					20,255.06	3,526.42
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	6,000.00	600.00
2	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00
5	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	80.00
8	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	60.00
9	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
11	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
12	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
13	TOWING FEES	New	150.00	0.00
Gross Labour Cost (\$\$)			14,950.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >