12/29/22, 3:57 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19010287/KPA3Q2

Date: 29/12/2022

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle SJR195H Insured Vehicle No: SLB3941L

Date of Loss: 06/06/2019 Nature of Claim: TP Claim No: 7474287123SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR195H

Make & Model: HONDA CROSSROAD, 1.8 (A) Engine No: HIDDEN
Reg. Date: 01/06/2009 (Man. Year: 2009) Chassis No: RT11008245
Colour: Metallic Pearl White Odometer: 218992 km

Engine Capacity: 1799 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Goodride 8 mm Rear Left Side: Falken 4 mm
Front Right Side: Goodride 8 mm Rear Right Side: Falken 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,236.88	2,541.68	695.20	21.48
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,510.00	500.00	1,010.00	66.89
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,746.88	3,041.68	1,705.20	35.92
	Approved Total (Overridden) (S\$)		2,450.00		
	Nett Amount (S\$)	4,746.88	2,450.00	2,296.88	48.39
	+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
		(S\$)	2,850.00		
	Liable Amount (50.00%) (S\$)		1,425.00		
	+ Doc/S	Search Fee (S\$)	7.45		
	Nett Liability (S\$)		1,432.45		
	Global Sum Settlement (S\$)		1,450.00		

INSPECTION

Date of Assignment: 10/06/2019

Guan Motor Works (HQ)

Date Inspected: 11/06/2019 Inspected At: 176 Sin Ming Drive #02-03 Sin Ming Autocare

Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*REAR RH DOOR WHEEL ARCH GARNISH	Dented / Cut	325.00 FL	*325.00 FL
1		*REAR RH FENDER WHEEL ARCH GARNISH (REAR)	Serviceable	159.00 FL	*- FL
1		*SET REAR RH FENDER WHEEL ARCH GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
1		*REAR RH SHOCK ABSORBER	Bent	300.00 FL	*300.00 FL
1		*REAR RH UPPER ARM	Distorted	195.00 FL	*195.00 FL
1		*REAR RH TRAILING ARM	Bent	453.10 FL	*453.10 FL
1		*REAR RH KNUCKLE ARM	Bent	325.00 FL	*325.00 FL
1		*REAR RH WHEEL HUB & BEARING	Necessary	387.10 FL	*387.10 FL
1		*REAR STABILIZER BAR	Serviceable	200.00 FL	*- FL
1		*REAR STABILIZER BAR RH LINK ROD	Distorted	85.90 FL	*85.90 FL
1		*REAR RH SPORTS RIMS	Bent	956.00 FL	*956.00 FL
1		*FRONT RH DOOR GARNISH	Not Necessary	225.00 FL	*- FL
1		*REAR RH TYRE (40%)	Punctured	300.00 FS	*120.00 FS
anchise	part. S=Spc	Nett. L=ListItemDisc.	,		
			Sub Total (S\$)	3,971.10	3,147.10
		- List Item Discount on L Items	20.00/20.00% (S\$)	734.22	605.42
			Total Parts (S\$)	3,236.88	2,541.68
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1	1 *REAR RH FENDER WHEEL ARCH GARNISH (REAR) 1 *SET REAR RH FENDER WHEEL ARCH GARNISH CLIPS 1 *REAR RH SHOCK ABSORBER 1 *REAR RH UPPER ARM 1 *REAR RH TRAILING ARM 1 *REAR RH KNUCKLE ARM 1 *REAR RH WHEEL HUB & BEARING 1 *REAR STABILIZER BAR 1 *REAR STABILIZER BAR RH LINK ROD 1 *REAR STABILIZER BAR RH LINK ROD 1 *REAR RH SPORTS RIMS 1 *FRONT RH DOOR GARNISH 1 *REAR RH TYRE (40%) Inchise part. S=SpcNett. L=ListItemDisc.	1 *REAR RH DOOR WHEEL ARCH GARNISH Dented / Cut 1 *REAR RH FENDER WHEEL ARCH GARNISH (REAR) Serviceable 1 *SET REAR RH FENDER WHEEL ARCH GARNISH CLIPS Not Necessary 1 *REAR RH SHOCK ABSORBER Bent 1 *REAR RH UPPER ARM Distorted 1 *REAR RH TRAILING ARM Bent 1 *REAR RH KNUCKLE ARM Bent 1 *REAR RH WHEEL HUB & BEARING Necessary 1 *REAR STABILIZER BAR Serviceable 1 *REAR STABILIZER BAR Serviceable 1 *REAR STABILIZER BAR RH LINK ROD Distorted 1 *REAR RH SPORTS RIMS Bent 1 *FRONT RH DOOR GARNISH Not Necessary 1 *REAR RH TYRE (40%) Punctured 1 *REAR RH TYRE (40%) Punctured 1 *REAR RH TYRE (40%) Sub Total (S\$) - List Item Discount on L Items 20.00/20.00% (S\$)	1 *REAR RH DOOR WHEEL ARCH GARNISH Dented / Cut 325.00 FL 1 *REAR RH FENDER WHEEL ARCH GARNISH (REAR) Serviceable 159.00 FL 1 *SET REAR RH FENDER WHEEL ARCH GARNISH CLIPS Not Necessary 60.00 FL 1 *REAR RH SHOCK ABSORBER Bent 300.00 FL 1 *REAR RH UPPER ARM Distorted 195.00 FL 1 *REAR RH TRAILING ARM Bent 453.10 FL 1 *REAR RH KNUCKLE ARM Bent 325.00 FL 1 *REAR RH WHEEL HUB & BEARING Necessary 387.10 FL 1 *REAR STABILIZER BAR Serviceable 200.00 FL 1 *REAR STABILIZER BAR RH LINK ROD Distorted 85.90 FL 1 *REAR RH SPORTS RIMS Bent 956.00 FL 1 *FRONT RH DOOR GARNISH Not Necessary 225.00 FL 1 *REAR RH TYRE (40%) Punctured 300.00 FS Sub Total (\$\$) 3,971.10 - List Item Discount on L Items 20.00/20.00% (\$\$\$) 734.22

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING /WELDING AN REPLACEMENT OF DAMAGES	D New	500.00	300.00
2	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES	New	600.00	0.00
3	TO REMOVE ,REFIT REAR RH UNDER CARRIAGE DAMAGES	New	280.00	200.00
4	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT TEST	New	80.00	0.00
5	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	50.00	0.00
	Gross Labo	our Cost (S\$)	1,510.00	500.00
	Report was unsubmitted during th	is print-out.		

< END OF ESTIMATES >