



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2005166
INV Date 24/07/2020
Reference CC6/CTI19010310/Aka3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SLF 5476D
Insured Veh. YM 821H
Claim No. SNM19D202480C02
Policy No. DMCVSN1713651902
Accident Date 29/05/2019
Inspection Date 10/06/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19010310/Aka3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 24-07-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 821H	Veh. Inspected	SLF 5476D
Policy No.	DMCVSN1713651902	Coverage (\$)	0.00
Claim No.	SNM19D202480C02	Excess (\$)	0.00
Assign From		Assign Date	10/06/2019

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET ORLANDO	c.c	1362
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KL1YA7589HK604697	Colour	SILVER
Odometer	35422	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
L/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/05/2019	Inspection Date	10/06/2019
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 5476D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	1,806.00	1,806.00
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	75.00	-
1	FRONT BUMPER LOWER	NOT NECESSARY	616.00	-
1	FRONT BUMPER LOWER GARNISH (SILVER COLOUR)	NOT NECESSARY	333.00	-
1	FRONT BUMPER SIDE RETAINER LH ,SUPPORT	NOT NECESSARY	133.00	-
1	FRONT BUMPER SIDE RETAINER RH ,SUPPORT	NOT NECESSARY	133.00	-
1	FRONT BUMPER ABSORBER	NOT NECESSARY	263.00	-
1	FRONT BUMPER REINFORCEMENT IMPACT BAR	NOT NECESSARY	927.00	-
1	FRONT BUMPER LOGO	NECESSARY	158.00	158.00
1	FRONT BUMPER FOG LAMP RH	NOT NECESSARY	330.00	-
1	FRONT BUMPER FOG LAMP LH	NOT NECESSARY	330.00	-
1	FRONT BUMPER NUMBER PLATE GARNISH	NOT NECESSARY	95.00	-
1	FRONT GRILLE UPPER	NOT NECESSARY	380.00	-
1	FRONT GRILLE LOWER	CRACKED	311.00	311.00
1	RH HEADLAMP	NOT NECESSARY	983.00	-
1	LH HEADLAMP	NOT NECESSARY	983.00	-
	LESS 10% DISCOUNT		-785.60	-227.50
			7,070.40	2,047.50
<u>SPECIAL NETT ITEMS</u>				
10	FRONT BUMPER CLIP (SN)	NECESSARY	65.00	50.00
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
			110.00	50.00
<u>LABOUR</u>				
	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING, RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS.		2,200.00	550.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA .		1,800.00	450.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		80.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT FRT H/LIGHT ALIGNMENT.	NOT NECESSARY	80.00	-
			4,160.00	1,030.00
GRAND TOTAL			11,340.40	3,127.50
RECOMMENDED COST OF REPAIRS				3,127.50

Report Ref No. CC6/CTI19010310/Aka3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 5476D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 5476D

RE-INSPECTION

