



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 5277L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (CONSISTENT)	BUCKLED	450.80	450.80
10	FRONT BUMPER CLIP (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	DISTORTED	107.20	107.20
1	FRONT BUMPER SIDE RETAINER LH (CONSISTENT)	SERVICEABLE	107.20	-
1	RH FRONT FENDER (CONSISTENT)	BENT	868.70	868.70
1	RH FRONT FENDER UNDERSHIELD (CONSISTENT)	SERVICEABLE	185.64	-
10	RH FRONT FENDER UNDERSHIELD CLIP (CONSISTENT)	SERVICEABLE	25.00	-
1	RHF FENDER WORDING 'HYBRID' (CONSISTENT)	NECESSARY	44.17	44.17
1	RH FRONT LOWER ARM (CONSISTENT)	SERVICEABLE	492.65	-
1	RH FRONT SHOCK ABSORBER (CONSISTENT)	SERVICEABLE	462.70	-
1	RH FRONT SHOCK ABSORBER TOP MOUNTING (CONSISTENT)	SERVICEABLE	195.07	-
1	RH FRONT SHOCK ABSORBER STOPPER (CONSISTENT)	SERVICEABLE	37.02	-
1	RH FRONT KNUCKLE ARM (CONSISTENT)	SERVICEABLE	476.75	-
1	RH FRONT KNUCKLE BEARING (CONSISTENT) }	NOT NECESSARY	573.20	-
1	RH FRONT WHEEL HUB (CONSISTENT) }		-	-
1	RH FRONT WHEEL HUB LOCK NUT (CONSISTENT)	SERVICEABLE	28.02	-
1	RH FRONT TIE ROD (CONSISTENT)	SERVICEABLE	1,721.85	-
1	RH FRONT TIE ROD END (CONSISTENT)	SERVICEABLE	116.40	-
1	RH FRONT RIM (CONSISTENT)	DENTED	1,555.10	1,555.10
1	RH FRONT DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	1,226.70	-
1	RH FRONT DOOR HINGE TOP (CONSISTENT)	TO REPAIR SEE LABOUR	78.34	-
1	RH FRONT DOOR HINGE BOTTOM (CONSISTENT)	TO REPAIR SEE LABOUR	78.34	-
	LESS 25% DISCOUNT		-2,217.71	-766.49
			6,653.14	2,299.48
SPECIAL NETT ITEMS				
1	RH FRONT TYRE (CONSISTENT) (SN)	SERVICEABLE	250.00	-
			250.00	-

Report Ref No. CC4/ASM19010313/Kps3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA (FRONT BUMPER ,SUPPORT PANEL,RHF FENDER ,RHF DOOR).INCLUSIVE OF THE REPAIR OF RH FRONT DOOR ,RH FRONT DOOR HINGE TOP AND RH FRONT DOOR HINGE BOTTOM .		1,000.00	500.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA .(FRONT BUMPER,SUPPORT PANEL,RHF FENDER ,RHF DOOR).		1,000.00	660.00
	TO TUFF COAT.		150.00	30.00
	TO CHECK WIRING .		50.00	20.00
	TO DO WHEEL ALIGNMENT.		120.00	60.00
	TO REMOVE & REFIT DOOR TRIM ,DOOR GLASS ,WINDOW REGULATOR DOOR LOCK TO ASSIST WORK LOAD.	NOT NECESSARY	240.00	-
	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD.	NOT NECESSARY	250.00	-
			2,810.00	1,270.00
	GRAND TOTAL		9,713.14	3,569.48

RECOMMENDED COST OF REPAIRS			3,569.48
------------------------------------	--	--	-----------------

Report Ref No. CC4/ASM19010313/Kps3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.