

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19010322/APA3Q2

Date: 07/04/2020

REFERENCE

| | | |
|---|-----------------------------|-----------------------|
| Handling Insurer: India International Insurance Pte Ltd | Policy No: | MCOM0015 |
| Claimant | | |
| Vehicle No : SJH8856J | Insured Vehicle No : | SHB4305P |
| Date of Loss: 04/06/2019 | Nature of Claim: TP | Claim No: MCT19060093 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No: | SJH8856J | | |
| Make & Model: | TOYOTA ESTIMA, 2.4 AERAS (A) | Engine No: | 2AZC422092 |
| Reg. Date: | 27/08/2008 (Man. Year: 2008) | Chassis No: | ACR500073978 |
| Colour: | White | Odometer: | 173894 km |
| Engine Capacity: | 2362 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 225/45 R18 | Rear Tyre Size: | 225/45 R18 |
| Front Left Side: | Dayton 6 mm | Rear Left Side: | Dayton 6 mm |
| Front Right Side: | Dayton 6 mm | Rear Right Side: | Dayton 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 12,917.00 | 5,502.30 | 7,414.70 | 57.40 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,460.00 | 1,890.00 | 570.00 | 23.17 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 15,377.00 | 7,392.30 | 7,984.70 | 51.93 |
| Approved Total (Overridden) (S\$) | | 5,900.00 | | |
| Nett Amount (S\$) | 15,377.00 | 5,900.00 | 9,477.00 | 61.63 |
| + Car Rental (10.0 x S\$150.00/day) (S\$) | | 1,500.00 | | |
| + Doc/Search Fee (S\$) | | 7.45 | | |
| Nett Liability (S\$) | | 7,407.45 | | |
| Global Sum Settlement (S\$) | | 7,400.00 | | |

INSPECTION

Date of Assignment: 10/06/2019

Date Inspected: 10/06/2019 Inspected At:

Best Solution Autocare Pte Ltd (HQ)
53 UBI AVE 1 #03-01 PAYA UBI
INDUSTRIAL PARK
Singapore 408934

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$66,000.00(est) less LTA Rebate: \$32,225.00(est) = Nett Value :\$33,775.00(est)

Please note that third party vehicle COE expiry date is 26 Aug 2028..

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 07 Apr 2020) |
| Parts: | M1-MPV | TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJH8856J) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-----|-----|--|---------------|------------|--------------|
| 1 | 1 | *REAR BUMPER | Deformed | 685.00 F | *685.00 FL |
| 2 | 2 | *REAR BUMPER SIDE RETAINER | Necessary | 194.00 F | *194.00 FL |
| 3 | 2 | *REAR BUMPER BRACKET | Not Necessary | 170.00 F | *- FL |
| 4 | 1 | *REAR BUMPER REFLECTOR | Missing | 78.00 F | *78.00 FL |
| 5 | 1 | *SET REAR BUMPER REVERSE SENSOR | Damaged | 200.00 F | *200.00 FL |
| 6 | 1 | *REAR BUMPER INNER SPONGE | Cracked | 110.00 F | *85.00 FL |
| 7 | 1 | *TAILGATE | Dented | 1,865.00 F | *1,585.00 FL |
| 8 | 1 | *TAILGATE CENTRE EMBLEM | Necessary | 87.00 F | *87.00 FL |
| 9 | 1 | *TAILGATE OUTER CHROME HANDLE | Not Necessary | 355.00 F | *- FL |
| 10 | 1 | *REVERSE CAMERA | Not Necessary | 300.00 F | *- FL |
| 11 | 1 | *TAILGATE CENTRE REFLECTOR | Not Necessary | 276.00 F | *- FL |
| 12 | 1 | *TAILGATE REFLECTOR | O/S Cracked | 674.00 F | *337.00 FL |
| 13 | 1 | *TAIL LAMP | O/S Cracked | 704.00 F | *352.00 FL |
| 14 | 1 | *TAILGATE INNER LOCK (TOP) | Damaged | 485.00 F | *398.60 FL |
| 15 | 1 | *TAILGATE INNER LOCK (LOWER) | Not Necessary | 54.00 F | *- FL |
| 16 | 1 | *TAILGATE WINDSTRIP | Cut | 456.00 F | *299.80 FL |
| 17 | 1 | *TAILGATE GLASS SEALANT | Necessary | 80.00 F | *80.00 FL |
| 18 | 1 | *TAILGATE GLASS MOULDING | Necessary | 250.00 F | *250.00 FL |
| 19 | 1 | *TAILGATE INNER TRIM BOARD | Cracked | 565.00 F | *565.00 FL |
| 20 | 1 | *SET TAILGATE INNER TRIM BOARD CLIP | Necessary | 50.00 F | *30.00 FL |
| 21 | 1 | *SET REAR BUMPER CLIP | Necessary | 50.00 F | *30.00 FL |
| 22 | 1 | *TAILGATE INNER TOP GARNISH | Not Necessary | 197.00 F | *- FL |
| 23 | 1 | *REAR END PANEL | Dented | 785.00 F | *785.00 FL |
| 24 | 1 | *REAR END PANEL TOP GARNISH | Deformed | 286.00 F | *286.00 FL |
| 25 | 1 | *SET REAR END PANEL TOP GARNISH CLIP | Necessary | 50.00 F | *20.00 FL |
| 26 | 1 | *SET TAILGATE INNER GARNISH CLIP | Not Necessary | 50.00 F | *- FL |
| 27 | 1 | *REAR END PANEL INNER LOWER GARNISH | Deformed | 387.00 F | *235.00 FL |
| 28 | 1 | *SET REAR END PANEL INNER LOWER GARNISH CLIP | Necessary | 50.00 F | *20.00 FL |
| 29 | 1 | *N/S REAR FENDER INNER GARNISH | Not Necessary | 795.00 F | *- FL |
| 30 | 1 | *N/S TAILGATE ABSORBER | Not Necessary | 272.00 F | *- FL |
| 31 | 1 | *REAR BUMPER TOW COVER | Deformed | 47.00 F | *47.00 FL |
| 32 | 1 | *REAR COMPARTMENT TOP COVER | Damaged | 1,390.00 F | *687.00 FL |
| 33 | 1 | *REAR WIPER MOTOR | Not Necessary | 860.00 F | *- FL |
| 34 | 1 | *REAR NUMBER PLATE | Not Necessary | 60.00 F | *- FL |

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) 12,917.00 7,336.40
- List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 1,834.10

Total Parts (\$\$) 12,917.00 5,502.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO DISMANTLE DAMAGED PARTS ,PANEL BEAT ,REPAIR | New | 1,000.00 | 800.00 |
| 2 | TO PUTTY AND SPRAY PAINTING ON AFFECTED AREA | New | 1,000.00 | 800.00 |
| 3 | ANTI RUST | New | 150.00 | 60.00 |
| 4 | TAILGATE GLASS | New | 180.00 | 120.00 |
| 5 | TRANSFER TAILGATE | New | 80.00 | 80.00 |
| 6 | WIRING CHECK | New | 50.00 | 30.00 |
| Gross Labour Cost (\$\$) | | | 2,460.00 | 1,890.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >