

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille broken / crack			\$ 1,110.10
	Radiator Grille H Emblem n/c			\$ 120.30
	Front Bumper Cover distorted / mainly crack			\$ 1,052.20
	Front Bumper Sponge torn			\$ 99.20
	Front Bumper Reinforcement Dent/d			\$ 402.10
	Front Bumper Bracket Top (LH/RH) NN		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) NN		\$ 24.60	\$ 49.20
	Headlamp Support Top Cover NN			\$ 222.60
	Headlamp Support Panel Assy ST			\$ 907.40
	Headlamp (LH/RH) crack / mounting		\$ 1,388.00	\$ 2,776.00
	Horn Unit (LH/RH) NN		\$ 73.80	\$ 147.60
	SUB TOTAL			\$ 6,931.50
	LESS 20%			\$ 1,386.30
	DISCOUNTED TOTAL			\$ 5,545.20
	Front Number Plate crack			\$ 25.00
	Front No Plate Trim Cover NN			\$ 30.00
				\$ 55.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	Towing Charge			\$ 50.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	TOTAL LABOUR			\$ 1,980.00

SHD 7202Y

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>VA</i>			\$ 2,174.90	✓
	Boot Lid Rubber <i>Nuc</i>			\$ 96.50	✓
	Boot Lid Lock Upper <i>NH</i>			\$ 102.60	X
	Boot Lid Lock Lower <i>NH</i>			\$ 31.70	X
	Boot Lid 'H' Emblem <i>Nuc</i>			\$ 28.70	✓
	Boot Lid CRDI Plate <i>Nuc</i>			\$ 27.90	✓
	Boot Lid Trimboard <i>NH</i>			\$ 116.40	X
	Boot Lid Trimboard Clips (10pcs) <i>NH</i>			\$ 11.00	X
	Bootlid Moulding <i>NH</i>			\$ 85.00	X
	Bootlid i40 Emblem <i>SVL</i>			\$ 27.90	X
	Bootlid Lower Garnish <i>NH</i>			\$ 227.90	X
	Rear Bumper <i>distal</i>			\$ 553.00	✓
	Rear Bumper Reinforcement <i>Crack</i>			\$ 428.40	✓
	Rear Bumper Reinforcement Bracket (LH/RH) <i>BT</i>	\$	80.30	\$ 160.60	✓
	Rear Bumper Clip 10 pcs <i>Nuc</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>NH</i>	\$	35.60	\$ 71.20	X
	Rear Bumper Sponge <i>form</i>			\$ 118.40	✓
	Rear Bumper Under Cover <i>distal</i>			\$ 228.00	✓
	Rear Bumper Reflector Lamp (LH/RH) <i>NH</i>	\$	30.60	\$ 61.20	X
	Rear Panel <i>upper Distal</i>			\$ 526.70	X
	Rear Panel Garnish <i>NH</i>			\$ 57.70	X
	Rear Panel Lower Panel <i>Distal</i>			\$ 495.50	X
	Member Assy- Rear Floor Centre <i>NH</i>			\$ 570.40	X
	Exhaust Pipe Insulator <i>NH</i>	\$	58.55	\$ 117.10	X
	Exhaust Silencer <i>N/S BT o/s NH</i>	\$	967.70	\$ 1,935.40	✓
	Exhaust Pipe Hanger <i>NH</i>	\$	58.55	\$ 117.10	X
	Exhaust Pipe Centre <i>NH</i>			\$ 730.10	X
				\$ 9,123.30	
				\$ 1,824.66	
				\$ 7,298.64	
	Boot Lid Comfort Logo & Tel No. Sticker <i>Nuc</i>			\$ 30.00	Nett ✓
	Boot Lid Advertisement Logo <i>Nuc</i>			\$ 100.00	Nett ✓
	Rear Bumper Reverse Sensor <i>Down</i>			\$ 135.70	Nett ✓
	Rear Bumper Advertisement Logo <i>Nuc</i>			\$ 50.00	Nett ✓
	Rear Bumper Rubber Mat <i>Nuc</i>			\$ 50.00	Nett ✓
				\$ 365.70	
	Labour Charge			\$ 1,000.00	600/-
	Panel Beating			\$ 1,000.00	600/-
	Spray Painting Charge			\$ 50.00	30/-
	Wiring Charge			\$ 50.00	40/-
	Tuff Kote			\$ 120.00	40/-
	Remove/Refix Reverse Sensor			\$ 300.00	60/-
	Remove/Refix Exhaust Pipe				
				\$ 2,520.00	
				\$ 17,764.54	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE TOTAL

12/06/2019 @ 0915h

NA Antina

LKK

LKK Auto

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHD 7202Y (Supplementary)

DATE : 12.06.2019

TEL : 6542 5119

FAX : 6542 6039

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Tail Lamp (LH/RH) <i>crack handy</i>		\$ 697.80	\$ 1,395.60 ✓
	SUB TOTAL			\$ 1,395.60
	LESS 20%			\$ 279.12
	DISCOUNTED TOTAL			\$ 1,116.48
	<i>1</i> <i>yan</i> <i>2kk Auto</i> <i>8</i>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				