

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19010384/KPA3Q2

Date: 28/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLC785K	Insured Vehicle No :	SHA5955L
Date of Loss: 08/06/2019	Nature of Claim: TP	Claim No: MCT19060214

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC785K	Engine No:	R18A13042237
Make & Model:	HONDA CIVIC, 1.8 L (A)	Chassis No:	JHMF16308S219450
Reg. Date:	16/09/2008 (Man. Year: 2008)	Odometer:	175781 km
Colour:	Metallic Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Goodyear 8 mm	Rear Left Side:	Goodyear 8 mm
Front Right Side:	Goodyear 8 mm	Rear Right Side:	Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,668.96	550.40	1,118.56	67.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	410.00	850.00	67.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,928.96	960.40	1,968.56	67.21
Approved Total (Overridden) (S\$)		750.00		
(S\$)	2,928.96	750.00	2,178.96	74.39
+ GST 7.00/7.00% (S\$)	205.03	52.50	152.53	74.39
Nett Amount (S\$)	3,133.99	802.50	2,331.49	74.39
+ Loss of Use (2.0 x S\$60.00/day) (S\$)		120.00		
Nett Liability (S\$)		922.50		
Global Sum Settlement (S\$)		920.00		

INSPECTION

Date of Assignment:	12/06/2019	
Date Inspected:	18/06/2019 Inspected At:	Hui Yang Motor Pte Ltd (HQ)
		176 Sin Ming Drive #04-02, Sin Ming
		AutoCare
		Singapore 575721
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2020)
Parts:	143	HONDA CIVIC 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC785K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	638.00 FL	*638.00 FL
2	10		*FRONT BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
3	1		*FRONT BUMPER RH SIDE RETAINER	Serviceable	48.50 FL	*- FL
4	1		*FRONT BUMPER RH FOG LAMP	Serviceable	355.50 FL	*- FL
5	1		*FRONT BUMPER RH FOG LAMP SIDE GARNISH	Serviceable	58.50 FL	*- FL
6	1		*FRONT RH HEADLAMP	Serviceable	903.20 FL	*- FL
7	1		*FRONT RH HEADLAMP LOWER BEAM	Repair	32.50 FL	*- FL
					Sub Total (S\$)	2,086.20
					- List Item Discount on L Items 20.00/20.00% (S\$)	417.24
					Total Parts (S\$)	1,668.96
						550.40

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRING	New	60.00	10.00
2	SPRAY PAINTING	New	600.00	200.00
3	LABOUR CHARGES	New	600.00	200.00
Gross Labour Cost (S\$)			1,260.00	410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >