

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19010388/APS3Q2

**Date:** 29/04/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SLZ8567A	<b>Insured Vehicle No :</b>	SHA1711A
Date of Loss: 11/06/2019	Nature of Claim: TP	Claim No: MCT19060268

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLZ8567A</b>		
Make & Model:	MERCEDES-BENZ C200, 1.8 Kompressor (A)	Engine No:	27195031299009
Reg. Date:	05/02/2010 (Man. Year: 2009)	Chassis No:	WDD2040412A352823
Colour:	Black	Odometer:	149308 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,679.30	1,728.90	950.40	35.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,140.00	500.00	640.00	56.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>3,819.30</b>	<b>2,228.90</b>	<b>1,590.40</b>	<b>41.64</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,750.00</b>		
<b>(\$\$)</b>	3,819.30	1,750.00	2,069.30	54.18
<b>+ GST 7.00/7.00% (\$\$)</b>	267.35	122.50	144.85	54.18
<b>Nett Amount (\$\$)</b>	<b>4,086.65</b>	<b>1,872.50</b>	<b>2,214.15</b>	<b>54.18</b>
<b>+ Loss of Use (3.0 x S\$100.00/day) (\$\$)</b>		300.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>2,179.95</b>		

### INSPECTION

Date of Assignment:	12/06/2019	
Date Inspected:	12/06/2019	Inspected At:
		Joo Hak Kee Auto Pte Ltd (HQ)
		Blk 3007 Ubi Road 1, #01-406
		Singapore 408701
Estimated Period of Repair:	3.0 days	

---

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Apr 2020)
<b>Parts:</b>	143	MERCEDES-BENZ C200 1.8 Kompressor (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLZ8567A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,360.00 FL	*1,360.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	660.00 FL	*- FL
3	1		*REAR BUMPER CHROME MOULDING CENTER	Necessary	105.00 FL	*105.00 FL
4	2		*REAR BUMPER CHROME MOULDING SIDE	Necessary	196.00 FL	*196.00 FL
5	2		*TAILLAMP LOWER RETAINER	Not Necessary	136.00 FL	*- FL
6	2		*REAR PARKING SENSOR	Damaged (1 PCS ONLY)	520.00 FL	*260.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,977.00</b>	<b>1,921.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	297.70	192.10
<b>Total Parts (\$\$)</b>	<b>2,679.30</b>	<b>1,728.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO STRAIGHTEN REAR EXHAUST	New	180.00	0.00
2	TO REMOVE & REPLACE ALL DAMAGED PARTS	New	580.00	250.00
3	TO SAND DOWN ,PUTTY AND SPRAY PAINT ON NECESSARY PARTS	New	380.00	250.00
<b>Gross Labour Cost (S\$)</b>			<b>1,140.00</b>	<b>500.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**