

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 7371H

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BOOT (CONSISTENT) | BENT | 874.50 | 874.50 |
| 1 | REAR BOOT EMBLEM (CONSISTENT) | NECESSARY | 40.70 | 40.70 |
| 1 | REAR BOOT W/S MOULDING (CONSISTENT) | NECESSARY | 118.30 | 118.30 |
| 1 | REAR BOOT LOCK (CONSISTENT) | BENT | 175.10 | 175.10 |
| 1 | REAR BUMPER (CONSISTENT) | DEFORMED | 492.60 | 492.60 |
| 10 | REAR BUMPER CLIPS @\$3.90 (CONSISTENT) | NECESSARY | 39.00 | 39.00 |
| 1 | REAR PANEL (NPA) (CONSISTENT) | TO REPAIR SEE LABOUR | - | - |
| | LESS 20% DISCOUNT | | -348.04 | -348.04 |
| | | | 1,392.16 | 1,392.16 |
| | SPECIAL NETT ITEMS | | | |
| 1 | REAR BOOT W/S SEALANT (SN) (CONSISTENT) | NECESSARY | 60.00 | 60.00 |
| 1 | REAR BUMPER SENSOR (SN) (CONSISTENT) | NOT WORKING | 180.00 | 180.00 |
| | | | 240.00 | 240.00 |
| | <u>LABOUR</u> | | | |
| | TO REPAIR REAR PANEL ,REMOVE & REFIX DAMAGED PARTS.STRAIGHTEN AND REALIGN AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF REAR PANEL . | | 600.00 | 500.00 |
| | TO SPRAY PAINT AFFECTED AREAS. | | 750.00 | 550.00 |
| | TO REMOVE & REFIX REAR W/S GLASS . | | 180.00 | 120.00 |
| | TO REMOVE & REFIX REAR WIPER MOTOR AND CENTRE LOCKING SYSTEM. | | 60.00 | 40.00 |
| | TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE. | | 40.00 | 30.00 |
| | TO RUST PROOF AFFECTED AREAS. | | 40.00 | 30.00 |
| | | | - | - |
| | | | - | - |
| | | | - | - |
| | | | 1,670.00 | 1,270.00 |
| | GRAND TOTAL | | 3,302.16 | 2,902.16 |

Report Ref No. CC4/ASM19010402/Kga3q2



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 2,300.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | · |

Report Ref No. CC4/ASM19010402/Kga3q2

KONG SENG CHEONG

Licensed Appraiser