

ASS. REC. BY

REF: CS/FCI/901042/Dvd3n2 Special Instructions:

Assigner: Dryan

ASSIGNMENT (Office)

Cus

From (Person):

Joanne Yang

of

FCI

Date/Time:

11/6/19 @ 3:37pm

Estimated Cost:

DRI to

OD - TP - FWS - TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 8584P

Insured:

SHA 7557P

at Workshop m/s

Chenni Motor

Tel:

65425119

of

Mark Anderson # 01-05/06

Policy No:

Claim No:

D191003768 MF&H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/6/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:13am @ 12/6/19

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate

SHC 8584T - 23/CAI/3022778/H/06392

DVA: 2/12/13

SHA 7557P - NA/FCI/3012428/13

DVA: 7/7/13

17/6/19

Email preli revised to FCI

REF:

ASSIGNMENT

COE 2023 Dec

Dec 2015

From

Date

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

86

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 8584T

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai I40

C.C. 1685

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

324600

T/Radio: Insured / Std / NI / NA

Eng/No:

D4PDFU577484

C/No:

KMHLB41UMGU082905

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: R/P / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

P/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

10/06/2019

D.O.I.

12/06/2019

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First Capital SHIA 7557P

03/07/19 prupr 2/3 5700/- with 8 days of rev (Red 5913.48, 5190)

RECEIVED 04 JUL 2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

4/7 - typst

Report Format :

CWS

Lump Sum / I.B.I. (\$) :

5700/-

Days Of Repair:

8

Resurvey No. of Trip:

2

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

5 x RS. 34

Photo

8A115

TOTAL

170+15

50

50+50

104

439



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19003768MFSH

Our ref: CS/FCI1901042/Dvd3

Date: 17/6/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO SHC 8584T


We thank you for your instruction on 11/6/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/6/2019 at the premises of M/s CHUNNI MOTOR WORK PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$11,613.48
Revised Estimate Amount	: S\$7,145.08
"Check" Items Amount	: S\$
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Bryan Ang
Automotive Assessor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	10-06-2019	Our Ref No. D19003768MFSH
Accident Date	10-06-2019	Claim Type. Third Party
Insured Vehicle	SHA7557P	Third Party Vehicle. SHC8584T
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65425119/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 17 June 2019 12:11 PM
To: 'CWS Motor Claims'
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19003768MFSH/1, SHC 8584P
Attachments: SHC 8584P PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHC 8584P
Date of survey: 12/6/2019
Number of days : 6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 12 June 2019 12:40 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003768MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 11 June 2019 3:37 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003768MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHC 8584T

DATE : 10.06.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

402 C1921

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>distorted</i> / <i>at</i>			\$ 553.00	✓
	Rear Bumper Clip 10 pcs <i>new</i>			\$ 22.00	✓
	Rear Bumper Bracket, RH <i>SVC</i>			\$ 35.60	X
	Rear Fender With Housing (RH) <i>Distorted</i>		2020.00	\$ 4236.80	✓
	Rear Fender Inner Lining (RH) <i>new</i>			\$ 169.30	X
	Rear Windscreen Moulding <i>new</i>			\$ 28.30	✓
	Rear Tyre Rim (RH) <i>2 dist / distorted</i>			\$ 325.30	✓
	Rear Wheel Hub-Cap (RH) <i>new</i>			\$ 107.10	✓
	Rear Wheelbearing ING & Hub <i>2 Down</i>			\$ 362.00	✓
	Rear Trailing Arm (RH) <i>2 distorted</i>			\$ 192.00	✓
	Rear Assist (RH) <i>2 distorted</i>			\$ 145.70	✓
	Rear Shock Absorber (RH) <i>2 distorted</i>			\$ 276.30	✓
	Rear Shock Absorber Mounting (RH) <i>new</i>			\$ 81.30	X
	Rear Crossmember <i>2 distorted</i>			\$ 1,021.50	✓
	Stabilizer Bar <i>2 distorted</i>			\$ 199.60	✓
	Stabilizer Link <i>2 distorted</i>			\$ 85.90	✓
	Rear Upper Arm (RH) <i>2 distorted</i>			\$ 335.75	✓
	Rear Lower Arm (RH) <i>2 distorted</i>			\$ 353.80	✓
	Rear Knuckle Arm (RH) <i>2 distorted</i>			\$ 545.60	✓
			6573.85		
			5259.08		
	SUB TOTAL			\$ 9,576.85	
	LESS 20%			\$ 1,915.37	
	DISCOUNTED TOTAL			\$ 7,661.48	
	Rear Bumper Advertisement Logo <i>new</i>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>new</i>		\$ 100.00	\$ 200.00	Nett ✓
	Rear Windscreen Sealant <i>new</i>			\$ 46.00	Nett ✓
	Rear Tyre (RH) <i>SVC</i>		296.00	\$ 216.00	Nett X
				\$ 512.00	
	Labour Charge				
	Panel Beating			\$ 1200.00	500/-
	Spray Painting Charge			\$ 750.00	500/-
	Wiring Charge			\$ 50.00	new
	Tuff Kote			\$ 50.00	30/-
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Reverse Sensor			\$ 120.00	40/-
	Remove/Refix Undercarriage (RR)			\$ 200.00	150/-
	Rear Wheel Alignment			\$ 120.00	60/-
	Re-set Rear ABS System			\$ 200.00	
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	150/-
			7145.08		
			1590.00		
	TOTAL LABOUR			\$ 3,440.00	
	ESTIMATE TOTAL			\$ 11,613.48	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2KK Ando

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHC 8584 T

Technician:

Mileage: 324600

Time Printed 12.6.19 1:01 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°48'		-3°00' 3°00'
3°33'		-0°19' 5°41'
0°53'		-1°30' 1°30'
16°31'		
15°43'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°24'		-3°00' 3°00'
3°38'		-0°19' 5°41'
0°20'		-1°30' 1°30'
20°59'		
20°35'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°24'		-3°00' 3°00'
-0°05'		-3°00' 3°00'
-4°29'		-3°00' 3°00'
1°14'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-0°42'		-3°30' 2°30'
0°16'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°17'		-3°30' 2°30'
3°24'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
0°35'		-3°00' 3°00'
3°41'		-3°00' 3°00'
-1°34'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd
 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
 TEL: 6256 3561 FAX: 6256 4315
 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19010424/Dvd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-07-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7557P	Veh. Inspected	SHC 8584T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003768MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	11/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHLB41UMGU082905	Colour	BLUE	
Odometer	324600	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HANKOOK	5 mm	
L/H Front Tyre	205/60 R16	HANKOOK	5 mm	
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/06/2019	Inspection Date	12/06/2019	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8584T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DISTORTED / BENT	553.00	553.00
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER BRACKET,RH	SERVICEABLE	35.60	-
1	REAR FENDER (RH)	DENTED	4,736.80	2,020.00
1	REAR FENDER INNER LINING (RH)	NOT NECESSARY	169.30	-
1	REAR WINDSCREEN MOULDING	NECESSARY	28.30	28.30
1	REAR TYRE RIM (RH)	BENT / DISTORTED	325.30	325.30
1	REAR WHEEL HUP-CAP (RH)	CUT	107.10	107.10
1	REAR WHEELBEARING ING & HUB	DAMAGED	362.00	362.00
1	REAR TRAILING ARM (RH)	DISTORTED	192.00	192.00
1	REAR ASSIST (RH)	DISTORTED	145.70	145.70
1	REAR SHOCK ABSORBER (RH)	DISTORTED	276.30	276.30
1	REAR SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	81.30	-
1	REAR CROSSMEMBER	DISTORTED	1,021.50	1,021.50
1	STABILIZER BAR	DISTORTED	199.60	199.60
1	STABILIZER LINK	DISTORTED	85.90	85.90
1	REAR UPPER ARM (RH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (RH)	DISTORTED	353.80	353.80
1	REAR KNUCKLE ARM (RH)	DISTORTED	545.60	545.60
	LESS 20% DISCOUNT		-1,915.37	-1,314.77
			7,661.48	5,259.08
SPECIAL NETT ITEMS				
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR TYRE (RH)(SN)	SERVICEABLE	216.00	-
			512.00	296.00
LABOUR				
	PANEL BEATING.		1,200.00	500.00

Report Ref No. CS/FCI19010424/Dvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING CHARGE.	NOT NECESSARY	750.00	500.00
	WIRING CHARGE.		50.00	-
	TUFF KOTE.		50.00	30.00
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE. }		480.00	150.00
	RE-SET REAR ABS SYSTEM. }		200.00	-
			3,440.00	1,590.00
	GRAND TOTAL		11,613.48	7,145.08
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,700.00

Report Ref No. CS/FCI19010424/Dvd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.